

ASS. REC. BY:

REF: CS/TMI18009868/K/d35

Special Instruction:

Surveyor:

Mummen

Kelvin

ASSIGNMENT (Office)

From (Person):

Fiona Chan

of

TMI

Date/Time:

30/5/18

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 1011M

Insured:

SKR 274B

at Workshop m/s

Comfort Delgro

Tel:

62148300

of

59 Loyang Drive

Policy No:

MV003144

Claim No:

M1802668

Sum Insured:

Excess:

Make of Veh:

D.O.A.

26/5/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 1011M - X
	SKR 274B - X

108 (11/3)

Q Name: Karin

REF:

## ASSIGNMENT

Frm:

Date:

Estimate Cost:

O/I/P/RES / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No:

at Workshop m/s

of

Insured:

Policy No

Claims No

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 1011 B

Yr Regn:

25 May 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c. 1798

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

140710

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

J701CB3F4003557200

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modi: Nil / SI/Rim / STD/Rim or

Tyre Size:

F:

195/65R15

R:

BS/DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

26/5/12

D.O.I.

28/5/12

Survey held at

CPGE (Layang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/6/12

Interview P/P \$4498/30g. (Road: 2265-251 3301-) T.O.K. P/P

RECEIVED 13 JUN 2012

Date/Time, File Pass to?

: Prel. Report

1) 1316 Typist

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

44981-

10

## ...CLAIM SUBFOLDER...(New Assignment)

Pre-Repair Survey

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2018 18:31 <a href="#">Sendback Est</a>	28 May 2018 18:35 <b>S\$6,713.25</b>	30 May 2018 09:46 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS

Insured: <b>CTPL</b> , Co. Reg. No.: 199303821R	
Main Claimant: <b>CTPL</b>	
Vehicle Reg. No.: <b>SHC1011B</b>	Date of Loss: 26/05/2018 18:00 - :59 [12 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type: <b>TP / M1802668</b>	Policy/Cover Note No.: MV003144 (Comprehensive) Coverage: 19/04/2018 - 18/04/2019
Vehicle Reg. No. (Insured): <b>SKR274B</b>	Policy No. (Claimant):
	Excess: S\$0.00
Repairer: <b>ComfortDelGro Engineering Pte Ltd (Loyang)</b> 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300	
Handling Insurer: <b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111 ... [Handled by <b>Fiona Gan Bee Song</b> - 65926378]	
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Final Rpt due 08/06/2018]	
Adj Asg. Remarks: PLS. CHECK CONSISTENCY OF THE DAMAGE.THKS	

#### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS ☐

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

already survey 28/5/18  
by Calvin

# OMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

Tokio Marine  
LKK

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Maritime + 65 6383 8280 Facsimile + 65 6285 9755

### Workshops

59 Loyang Drive Singapore 508939

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 090886

520 Hill Road Singapore 110099

24 Serangoon Road Singapore 730155

7 Sungai Kadut Way Singapore 728791

6 Delta Avenue 1 Singapore 509537

Date/Time: 28.05.2018 09:14

Page : 1

am: ARC Repair TP(CLS0)1

**JOB CARD** Sales Order:

JC NO305165121

OMER

IS COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

IESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

JUNT CARD NO.

REGN NO.:

SHC1011B

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)27.05.2018 08:40

DATE/TIME IN

YR OF MANU.

25.05.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU003557200

COMPLETION DATE/TIME:

### JOB DESCRIPTION

ccident Date: 26.05.2018

NATURE: 3P 26.05.18/C

/NO

LABOR CODE

DESCRIPTION

WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHC1011B

LIMITS

Vehicle No.:

SHC1011B

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/05/2018 08:31
Date Of Accident	26/05/2018 18:30
Exact Location Of Accident	BLK 401A FAJAR RD MSCP
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC1011B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	CHUA SANG HEE
NRIC No	S1114020C
Date Of Birth	03/06/1955
Occupation	OUTDOOR
Date Of Driving Pass	08/06/1978
Driving Experience	39 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96666825
Fax Number	
Contact Number	
Email Address	HEEHE@SINGNET.COM.SG

Address	173 03-12 GANGSA ROAD
Postcode	670173
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE (Head to side)
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

SEE ATTACH.

#### Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR274B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT RHT
No. Of Passenger (Including Driver)	

# Sketch Plan Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26/5/18 @ abt 1830hrs, I was driving straight at above location. Suddenly a car SKR274B drove out of the parking lot hit the front left portion of my taxi. No pax on board & no one is injured at the point of accident.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD.  
CO. REG NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)

Reporting Centre Personnel's Signature  
Name:

Teo Yen Yee



**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
 REG. NO. 100303821R  
 Policyholder's Signature \_\_\_\_\_  
 Date & Time: \_\_\_\_\_  
 Driver's Signature \_\_\_\_\_  
 (If driver is not the policyholder)  
 Date & Time: \_\_\_\_\_

Teo Yee Yee  
 Reporting Centre Personnel's Signature  
 Name: \_\_\_\_\_  
 NRIC/FIN No.: \_\_\_\_\_



REPAIR ESTIMATE

VEHICLE NO : SHC 1011B

MAKE :

MODEL : TOYOTA PRIUS

T. K. K.

28/5/2018 15:55

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
LAMP ASSY, FOG, LH Xsu			\$ 920.00
FRONT BUMPER COVER / <i>Adrenal</i>			\$ 495.50
FRONT BUMPER REINFORCEMENT Xsu			\$ 691.50
FRONT BUMPER REINFORCEMENT ABSORBER Xsu			\$ 115.70
FRONT BUMPER SPONGE Xsu			\$ 78.80
FRONT BUMPER CENTRE GRILLE Xsu			\$ 301.90
FRONT BUMPER LOWER GRILLE Xsu			\$ 148.60
FRONT BUMPER CLIPS / <i>na</i>			\$ 22.00
FRONT BUMPER SIDE RETAINER Xsu			\$ 77.00
UNIT ASSY, HEADLAMP, LH (LED) - <i>ca</i>			\$ 3,413.40
FENDER SUB-ASSY, FRONT LH - <i>Del</i>			\$ 933.10
FRONT FENDER SHIELD Xsu			\$ 198.50
SUB TOTAL			\$ 7,391.00
LESS 25%			\$ 1,847.75
DISCOUNTED TOTAL			\$ 5,543.25
LABOUR CHARGE			
Panel Beating			\$ 560.00 <i>400</i>
Spray Painting Charge			\$ 500.00 <i>400</i>
Wiring Charge			\$ 50.00 <i>20</i>
Tuff Kote			\$ 50.00 <i>20</i>
Towing Charge			\$ 60.00 <i>X17</i>
<i>Mariner Fee \$10</i>			
TOTAL LABOUR			\$ 1,220.00
ESTIMATE TOTAL			\$ 6,763.25
<i>Kalvin</i> <i>28/5/8 1720h</i> <i>3 Prius</i> <i>P/P</i> <i>Before Part phs</i>			<div> LKK Auto Consultants hence notify the Repairer of the following:  • To resurvey before/after spray painting  • To display damaged part(s) during resurvey  • Parts prices are subject to confirmation  • Third party survey is on a "Without Prejudice" basis  • No illegal modification(s) is allowed  • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company    Acknowledged by Repairer  Signature:  Date: </div>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305165121  
Date : 01/06/18


## FINALIZATION FORM


To : LKK Fax :  
Attn : KALVIN ANG  
Vehicle Reg No. : SHC1011B Date of Accident : 26-May-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: TOKIO MARINE --- SKR 274B
- The finalized amount shall be:
  - Spare Parts after List discount \$3,648.00
  - Labour Charges \$850.00
  - Total for Part-By-Part Repair Cost \$4,498.00**
  - Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
**Final Lumpsum Repair cost**
- Estimated normal period for repairs: 3 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
- Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM T S  
Tel : 62148398  
Fax : 65468156

Signature :   
Name : KALVIN  
Date : 12/6/18

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	-----			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## COMFORTDELGRO ENGINEERING PTE LTD

Date: 31.05.2018

Time: 18:14:39

## REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305165121  
REGN NO : SHC1011B  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4)  
DATE OF REGN : 25.05.2017  
DATE/TIME IN : 27.05.2018 08:40  
ACCIDENT DATE : 26.05.2018

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0302-2292-G	FRT BUMPER	1	495.50	25.00	371.62
0002 04-01-0302-2267-G	FRT BUMPER CLIPS	10	22.00	25.00	16.50
0003 04-01-0302-2815-G	HEADLAMP LH	1	3,413.40	25.00	2,560.05
0004 04-01-0302-0574-G	FRT FENDER LH	1	933.10	25.00	699.82

SUB-TOTAL : 3,647.99

## JOB NATURE

0000 L	PANEL BEATING	400.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	400.00
0002 17-01	CHECK ALL LIGHTING	20.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	20.00
0004 20-05	TP MERIMEN	10.00

SUB-TOTAL : 850.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 31.05.2018

Time: 18:14:39

REPAIR ESTIMATE

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305165121  
REGN NO : SHC1011B  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(C  
DATE OF REGN : 25.05.2017  
DATE/TIME IN : 27.05.2018 08:40  
ACCIDENT DATE : 26.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 4,497.99

  
MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Pre-Repair Survey

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2018 18:31 <a href="#">Sendback Est</a>	28 May 2018 18:35 <b>S\$6,713.25</b>	30 May 2018 09:46 <a href="#">Edit Adj Rpt</a>	<b>S\$4,498.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,498.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	CTPL, Co. Reg. No.: 199303821R		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHC1011B	Date of Loss:	26/05/2018 18:00 - :59 [12 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1802668	Policy/Cover Note No.:	MV003144 (Comprehensive) Coverage: 19/04/2018 - 18/04/2019
Vehicle Reg. No. (Insured):	SKR274B	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 08/06/2018]		
Adj Asg. Remarks:	PLS. CHECK CONSISTENCY OF THE DAMAGE.THKS		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.



## Claim Documents



**SHC1011B (M1802668)**  
**[SKR274B]**  
**TP**  
**CTPL**  
**May 26 2018 6:00PM**  
**[CTPL]**  
**ComfortDelGro Engineering Pte Ltd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View**
[View in Browser](#)

### Assessment Reports

1 per page
 ☒

No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	28/05/18 18:35	<b>Repairer Estimates</b>	 Load HTM	<input type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	30/05/18 09:47	<b>Accident Statement</b> From: SC - Reg. No: SKR274B, Claimant: TOH YEW HOCK	 Load HTM	<input type="checkbox"/>

### Photos/Images

3 per page
 ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
24	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
25	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
26	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
27	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
28	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
29	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
30	01/06/18 07:54	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>



Assessment Reports				✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
31	01/06/18 07:54	General View	 Load JPG	✓
32	02/07/18 15:06	Reinspection Photo	 Load JPG	✓
33	02/07/18 15:06	Reinspection Photo	 Load JPG	✓
34	02/07/18 15:06	Reinspection Photo	 Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	02/07/18 14:26	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee	 Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	28/05/18 18:36	E-filed GIA report	 Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/TMI18009868/K1TD3S2  
**Date:** 02/07/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MV003144
Claimant Vehicle No :	SHC1011B	Insured Vehicle No :	SKR274B
Date of Loss:	26/05/2018	Nature of Claim:	TP
		Claim No:	M1802668

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1011B	Engine No:	2ZRS043859
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU003557200
Reg. Date:	25/05/2017 (Man. Year: 2017)	Odometer:	140710 km
Colour:	Blue		
Engine Capacity:	1800 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,543.25	3,648.00	1,895.25	34.19
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	1,160.00	840.00	320.00	27.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,713.25</b>	<b>4,498.00</b>	<b>2,215.25</b>	<b>33.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>469.93</b>	<b>314.86</b>	<b>155.07</b>	<b>33.00</b>
<b>Nett Amount (S\$)</b>	<b>7,183.18</b>	<b>4,812.86</b>	<b>2,370.32</b>	<b>33.00</b>

INSPECTION

Date of Assignment:	30/05/2018	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	28/05/2018	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

**Adjuster:** KALVIN ANG WEI KUN**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jul 2018)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC1011B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LOGLAMP LH	Serviceable	920.00 FL	*- FL
2	1		*FRT BUMPER	Deformed	490.50 FL	*495.50 FL
3	1		*FRT BUMPER REINFORCEMENT	Serviceable	691.50 FL	*- FL
4	1		*FRT BUMPER REINFORCEMENT ABSORBER	Serviceable	115.70 FL	*- FL
5	1		*FRT BUMPER SPONGE	Serviceable	78.80 FL	*- FL
6	1		*FRT BUMPER CENTRE GRILLE	Serviceable	301.90 FL	*- FL
7	1		*FRT BUMPER LOWER GRILLE	Serviceable	148.60 FL	*- FL
8	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
9	1		*FRT BUMPER SIDE RETAINER	Serviceable	77.00 FL	*- FL
10	1		*HEADLAMP LH	Cracked	3,413.40 FL	*3,413.40 FL
11	1		*FRT FENDER LH	Dented	933.10 FL	*933.10 FL
12	1		*FRT FENDER SHIELD LH	Serviceable	198.50 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,391.00</b>	<b>4,864.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,847.75</b>	<b>1,216.00</b>
<b>Total Parts (\$\$)</b>	<b>5,543.25</b>	<b>3,648.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	10.00	10.00
<b>Sub Total (S\$)</b>			<b>10.00</b>	<b>10.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	560.00	400.00
2	SPRAY PAINTING	New	500.00	400.00
3	WIRING CHECK	New	50.00	20.00
4	TUFF KOTE	New	50.00	20.00
5	TOWING CHARGE.	New	-	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,160.00</b>	<b>840.00</b>

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;