

ASS. REC. BY:

REF:

es/MSG18009869/ASD3⁰²

Special Instruction:

Surveyor:

remin

Adrian

ASSIGNMENT (Office)

From (Person):

Jasmine Lok

of

MSG

Date/Time:

30/5/18 @ 4.20pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SG1 7015 B

Insured:

818 56448

at Workshop m/s

You Yi Automobile

Tel:

67895155

of

23 Kaki Bukit Ave 4 #03-01

Policy No:

A29030841ARW

Claim No:

559381

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/5/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

11.06am @ 31/5/18

Person Contacted:

Huey Lee

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SG1 7015 B - NAI/AXA 08013281 / e1

DOA: 26/4/2008

818 56 448 - X

04/06/18

@ 16.32 p.m. revert pending estimate to Jasmine Lok via remin

04/07/18

@ 13.53 p.m. revised IA to Jasmine Lok Kheng Kwei via remin.

11s \$4,500/- / 10 days

(\$11,009.40 - Red 71%)

ASS. REC. BY: Adrian King

ASSIGNMENT

19/7/2006

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SG5701SB Yr Regn: _____

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Vio C.C. 1497

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 243570 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053HY 420 4195268

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R: 195/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 31/05/18

Survey held at Yee Yi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MSIG

MV: 18.8K

PV: 14.3K

Nett: 4.5K

RECEIVED 04 JUL 2018

Date/Time, File Pass to?

04/07/18

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

200
10
210

Report Format :

Lump Sum / I.B.I. (\$) 4,500.00 L/S

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 May 2018		30 May 2018 16:20 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Chia Joong Luang, ID: S1319115H		
Main Claimant:	LEE CHEE KIN, ID: S8857709D		
Vehicle Reg. No.:	SGJ7015B	Date of Loss:	23/05/2018 21:00 - :59 [78 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 559381	Policy/Cover Note No.:	A29030841AVW (Comprehensive) Coverage: 27/09/2017 - 26/09/2018
Vehicle Reg. No. (Insured):	SLS5644S	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	You Yi Automobile (HQ) 23 KAKI BUKIT AVE 4, #03-01 AAS KAKI BUKIT CENTRE, 466665 Kaki Bukit - Tel: 67895155		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/05/2018]		
Driver/Custodian (Insured):	DAN YEE LIN (29 / Female), NRIC: S8905069C, Tel: +6598624630		
Adj Asg. Remarks:	on WP, SJE Agree Please appoint Mr.Adrian Ling from LKK Auto Consultancy and contact Kai Siang @ 6842 7213 Vehicle at w/shop: 8 Kaki Bukit Ave 4#08-46 Premier @ Kaki Bukit Singapore 415875		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18009869/Avd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 31-05-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 5644S	Veh. Inspected	SGJ 7015B
Policy No.	A29030841AVW	Coverage (\$)	0.00
Claim No.	559381	Excess (\$)	0.00
Assign From	MERIMEN (JASMINE LOK)	Assign Date	31/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/05/2018	Inspection Date	31/05/2018
Survey held at	YOU YI AUTOMOBILE 23 KAKI BUKIT AVE 4 (SOUTH WING) #04-01 SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 04 Jul 2018

Preliminary Advice

Insured Vehicle No	: SLS5644S	Accident Date	: 23/05/2018
TP Vehicle No	: SGJ7015B	Assignment Date	: 30/05/2018
Make	: TOYOTA VIOS	Est. Duration of Repair	: 10 days
Date of Inspection	: 31/05/2018		
Inspection At	: You Yi Automobile (HQ) 23 KAKI BUKIT AVE 4, #03-01 AAS KAKI BUKIT CENTRE Singapore 466665		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,509.40
Revised Amount	:S\$	6,589.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,589.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

MCD318067820 / ComfortDelGro Engineering Pte Ltd - Ubl
 ENTRY DATE & TIME: 24/05/2018 18:36
 SUBMITTED BY: Chung King Lye Jazmine

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 24/05/2018 18:36
 Date Of Accident 23/05/2018 21:30
 Exact Location Of Accident PIE TOWARDS CHANGI BEFORE EUNOS EXIT
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGJ7015B
Insured/Policyholder
 Name Of Registered Owner LEE CHEE KIN
 NRIC No S8857709D
 Email Address JULIE@SKAUTO.COM.SG
 Mobile Phone No (LOCAL) +65-97375656
 Alternative Phone No OTHERS-97375656

Vehicle Particulars

Manufacturer TOYOTA
 Model VIOS 1.5E

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company ERGO INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE

Fleet Policy NO
 Policy Number T/20180524/2008

Cover Note Number

Driver

Name of Driver LEE CHEE KIN
 NRIC No S8857709D
 Date Of Birth 25/10/1988
 Occupation INDOOR
 Date Of Driving Pass 27/07/2014
 Driving Experience 3 YEARS AND 9 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-97375656
 Fax Number
 Contact Number OTHERS-97375656
 Email Address JULIE@SKAUTO.COM.SG

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions RAINING

Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name GEYLANG N.P.C

Police Station Address ROAD: 132 PAYA LEBAR ROAD, POSTCODE: 409014, COUNTRY: SINGAPORE

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLS5644S

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHD4520Z
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SKU8355X
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SKR6816Z
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number SHC7967D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

29 Nov. 2017 8:35

No. 8922 P. 2

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and to be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

29. Nov. 2017 8:35

No. 8922 P. 3

SKETCH PLAN

P18 known
Chang
before fence
exit

A	SGJ70153
B	SL556445
C	SHD45202
D	SKU4385X
E	SKR6816Z
F	SMC7967D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report
1/20180524/2008

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 3



**SINGAPORE
POLICE FORCE**



T/20180524/2008

1 of 6

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

Report No. T/20180524/2008

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/05/2018 01:53			Vide Report No.:		Station Diary No.: 23
Informant's Particulars					
Name of Informant: LEE CHEE KIN			Address: APT BLK 801D KEAT HONG CLOSE #06-53 SINGAPORE 684801		
ID Type / ID No.: NRIC NO / S8857709D			Contact No.: Home/Office:		Mobile: 97375656
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 29	Date of Birth: 25/10/1988	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: CREATIVE DIRECTOR			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 23/05/2018 21:25	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY				
PAN ISLAND EXPRESSWAY TOWARDS CHANGI AIRPORT. BEFORE EUNOS FLYOVER				
Weather: Raining		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control:		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGJ7015B	Car				Slightly Damaged	1
SHC7967D	Car				Slightly Damaged	1
SHD4520Z	Car				Slightly Damaged	1
SKR6816Z	Car				Slightly Damaged	0
SKU6355X	Car				Slightly Damaged	0

Sketch Plan Pg. 4



**SINGAPORE
POLICE FORCE**



T/20180524/2008

2 of 5

Police Station Of Origin:

Gaylang N.P.C

132 Paya Lebar Road SINGAPORE 409014

Tel No: 1800-8486999

Report No. T/20180524/2008

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLS5644S	Car				Slightly Damaged	0

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	LEE WAN JUAN	ID No.	S8518342G
Related Vehicle	SGJ7015B (Car)	Contact No.	90114485
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LEE CHEE KIN	ID No.	S8857709D
Related Vehicle	SGJ7015B (Car)	Contact No.	97375856
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	JASON TAY	ID No.	S8118028H
Related Vehicle	SHC7967D (Car)	Contact No.	97214372
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Sketch Plan Pg. 5



SINGAPORE
POLICE FORCE



T/20180524/2008

3 of 5

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

Report No. T/20180524/2008

CONTINUATION OF REPORT

Driver			
Name	NG MAN KEONG	ID No.	S1465253A
Related Vehicle	SHD4520Z (Car)	Contact No.	98366665
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	RAPHAEL LOW	ID No.	S8422817E
Related Vehicle	SKR6816Z (Car)	Contact No.	94754755
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	SERENE TAY	ID No.	S7706679J
Related Vehicle	SKU6355X (Car)	Contact No.	92214400
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	VIVIAN DAN	ID No.	S8905069C
Related Vehicle	SLS5644S (Car)	Contact No.	98624630
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Sketch Plan Pg. 6

**SINGAPORE
POLICE FORCE**

T/20180524/2008

4 of 5

Police Station Of Origin:

Geylang N.P.C

132 Paya Lebar Road SINGAPORE 409014

Tel No: 1800-8486999

Report No. T/20180524/2008

CONTINUATION OF REPORT

Brief Details.

On 23/05/2018 at about 2125hrs, I was driving my car, a red colour Toyota Vios, bearing registration number SGJ7015B on lane one, along the Pan Island Expressway, heading towards Changi Airport. As I was approaching the Eunos flyover, the car that was travelling in front of me, SHC7967D, suddenly jammed brake. I managed to stop my car in time and my car did not hit onto the rear of the said vehicle. Suddenly, I felt a hard impact from the rear of my car. There was a second impact and it caused my car to hit onto the car in front of my car. I made a check and realized that the car that was travelling behind my car, bearing registration number SLS5644S, had hit onto the rear of my car. The impact caused my car to hit onto the rear of the car that was in front of me. I immediately alighted from my car to make a check and I realized that my car was involved in a chain collision involving a total of six cars. My car is the fourth from the front. The sixth car, a taxi bearing registration number SHD4520Z did not manage to stop in time and had hit onto the fifth car and that had caused the chain collision. I am not injured at the point of the accident. LTA enforcement officer came to scene to assist and took down all the driver's particulars and left. I have since reported this accident to my insurance company to assist me with the claims.

Sketch Plan Pg. 7

**SINGAPORE
POLICE FORCE**

T/20180524/2008

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

5 of 5

Report No. T/20180524/2008

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Sgt 2 ABDUL SARHAN BIN ABDUL RIFFIN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:

TR / GIA /
SINGAPORE
POLICE FORCE
SIEW PING
Contact No.: 65476430

Authentication Stamp

NP158

SIGNATURE

Signature Of Informant:

Date/Time:
24/05/2018 01:53

Classification Of Case:



Low Mileage, 113k. Selling Due To Underutilised And Work Assignment In Overseas. Car Is Still In Good Condition. Smooth And Stable. Original Paint, Rims. New Battery, Rear Shock Absorber Changed, New T...

Posted: 15-May-2018 Tags: 2006 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 03/2021) **\$18,000** \$6,320 /yr 31-Mar-2006 1,497 cc 190,000 km Sedan Available

Free Road Tax Till 30 Sep 2018. Owner Upgraded To A New Car. Servicing Done At Reputable Car Repair Shop, Servicing Records Can Be Shared With Keen Buyers. 2 Owners With Current Owner Driving Close To...

DIRECT OWNER

Posted: 13-Apr-2018 Tags: 2006 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 05/2021) **\$17,500** \$5,840 /yr 24-May-2006 1,497 cc - Sedan Available

New Road Tax. Very Well Maintained. Powerful And Low Fuel Consumption. Very Reliable Car. Trade In Welcome.

Posted: 23-May-2018 Tags: 2006 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 05/2021) **\$18,800** \$5,260 /yr 26-May-2006 1,497 cc 191,000 km Sedan Available

Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only!

Boekl Auto & Marine

Posted: 07-May-2018 Tags: 2006 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



How much is your car really worth?

Find out how much your car can sell for. Quotz helps owners like you, sell their cars at the HIGHEST PRICE guaranteed! If we fail, you'll get \$100 CASH! Free valuation via phone/online. Absolutely No obligations!

Find out more!



Toyota Vios 1.5A E (COE till 06/2021) **\$18,800** \$6,060 /yr 13-Jul-2006 1,497 cc 80,000 km Sedan Available

1 Owner Till Date, Low Mileage Diamond Black Vios Of Depreciation At Only \$6K/Year. A Car Known For Its Fuel Efficiency And Reliability. Loan/Trade In Available, Call To Scrutinize.

Posted: 23-May-2018 Tags: 2006 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 06/2021) **\$18,499** \$5,960 /yr 06-Sep-2006 1,497 cc 218,000 km Sedan Available

Depreciation Less Than \$6k Yearly, Second Owner For 6 Years, Major Servicing Completed During COE Renewal, Good Condition As Owner Is Prepared To Drive Till 2021 But Upgrading Due To VES, Price Reduce...

DIRECT OWNER

Posted: 22-May-2018 Tags: 2006 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 08/2021) **\$19,500** \$5,960 /yr 27-Sep-2006 1,497 cc 132,000 km Sedan Available

2 Owner Only. Very Well Maintained Car. Trusted And Dependable Toyota. Flexible Loan Arrangement. Act Now.

Posted: 25-May-2018 Tags: 2006 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 11/2021) **\$22,800** \$6,500 /yr 27-Nov-2006 1,497 cc - Sedan Available

Full Loan Available, Excellent Petrol Consumption, View To Believe! Hurry! Trade In Welcome, Available In Showroom For Viewing Now. Contact For More Details.

Posted: 20-May-2018 Tags: 2006 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 06/2026) **\$43,388** \$5,350 /yr 13-Dec-2006 1,497 cc 150,198 km Sedan Available

We Are The COE Specialists, No Gimmicks, Honest Dealing. 2 Owners With Low Mileage Clocked, Car In Superb Condition Interior And Exterior, No Repairs Needed. High Loan With \$4000 Down Payment Drive A...

PREMIUM

Posted: 14-Apr-2018 Tags: 2006 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 12/2021) **\$22,000** \$6,180 /yr 15-Dec-2006 1,497 cc 213,000 km Sedan Available

Superb Well Maintained By Previous Owner. View And Test Drive To Believe. Own This Reliable Yet Fuel Economical Popular Japanese Midsize Sedan For Your Daily Needs. Cheap And Good. Value For Money. Re...

DIRECT OWNER

Posted: 18-May-2018 Tags: 2006 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A J (COE till 04/2022) **\$25,838** \$6,570 /yr 07-May-2007 1,497 cc 128,000 km Sedan Available

Beautiful Vios Among It's Class. Beautiful Leather Seat No Repairs Needed, 2 Years Free Servicing, We Deliver Our Promise! Serviced Regularly Without Fail, Suitable For All Ages, Non Smoker Unit. 6 Mo...

ARF/COE Rebate Enquiry

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:

Foreign Identification Number

Owner ID:

1282P

Vehicle Details

Vehicle No.:

SGJ7015B

Vehicle to be Exported:

No

Intended De-registration Date:

31 May 2018

Vehicle Make:

TOYOTA

Vehicle Model:

VIOS 1.5E A

Primary Colour:

Red

Manufacturing Year:

2006

Engine No.:

1NZX450985

Chassis No.:

MR053HY4204195268

Maximum Power Output:

80.0 kW (107 bhp)

Open Market Value:

\$12,707.00

Original Registration Date:

19 Jul 2006

First Registration Date:

19 Jul 2006

Transfer Count:

1

Actual ARF Paid:

\$13,978.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

30 Jun 2021

COE Category:

A - Car (1600cc & below)

COE Period(Years):

5

PQP Paid:

\$23,227.00

COE Rebate Amount:

\$14,323.00

Total Rebate Amount:

\$14,323.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 May 2018

YOU YI
23 Kaki Bukit Ave 4 (South Wing)
#03-01 Singapore 415933

TO	: MSIG	DATE	: 25-May-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	: Shirley	VEHICLE NO	: SGJ7015B
ADDRESS	:	MODEL	: TOYOTA VIOS
TEL. NO.	:	CHASSIS NO	: MR053HY420H5268
OWNER'S INSURANCE :			
POLICY NO. :			
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT: DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Debon</i>	1	\$ 465.20	\$ 465.20
2	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 267.40	\$ 267.40
3	FRONT BUMPER SIDE RETAINER <i>Ne</i>	2	\$ 45.30	\$ 90.60
4	FRONT BUMPER CENTRE BRACKET <i>X66</i>	1	\$ 384.00	\$ 384.00
5	FRONT BUMPER LOWER GRILLE <i>Ne</i>	1	\$ 184.00	184
6	FRONT BUMPER FOG LAMP <i>2 FOG LAMP</i>	2	\$ 312.00	624
7	FRONT BUMPER FOG LAMP COVER <i>2 FOG LAMP COVER</i>	2	\$ 145.00	290
8	FRONT BUMPER UNDER COVER <i>HH</i>	1	\$ 112.00	\$ 112.00
9	FRONT GRILLE <i>Grille</i>	1	\$ 133.00	\$ 133.00
10	FRONT GRILLE LOGO <i>n</i>	1	\$ 43.00	\$ 43.00
11	FRONT SUPPORT PANEL <i>Rg 5</i>	1	\$ 569.60	\$ 569.60
12	HORN SET <i>Ne</i>	1	\$ 341.00	341
13	RADIATOR <i>2</i>	1	\$ 695.00	\$ 695.00
14	RADIATOR MOUNTING <i>2</i>	2	\$ 50.00	\$ 100.00
15	AIR CONDENSOR	1	\$ 1,168.00	\$ 1,168.00
16	AIR CONDENSOR MONTING <i>Ne</i>	2	\$ 55.00	\$ 110.00
17	HEADLAMP <i>Grille</i>	2	\$ 389.20	\$ 778.40

6355.2

18	REAR BUMPER <i>Disbled</i>	1	\$ 598.00	\$ 598.00
19	REAR BUMPER SIDE RETAINER <i>h</i>	2	\$ 53.50	\$ 107.00
20	REAR BUMPER BRACKET <i>men</i>	1	\$ 68.00	\$ 68.00
21	BOOT LID <i>Brudeed</i>	1	\$ 698.60	\$ 698.60
22	BOOT LID HINGE <i>men</i>	1	\$ 51.30	\$ 51.30
23	BOOT LID LOCK ASSY <i>2x</i>	1	\$ 189.60	\$ 189.60
24	BOOT LID STRIKER <i>men</i>	1	\$ 61.20	\$ 61.20
25	BOOT LID WEATHERSTRIP <i>6x</i>	1	\$ 188.30	\$ 188.30
26	BOOT LID EMBLEM <i>7</i>	1	\$ 70.10	\$ 70.10
27	BOOT LID EMBLEM "VIOS" <i>h</i>	1	\$ 32.20	\$ 32.20
28	BOOT LID EMBLEM "SPORT"	1	\$ 55.10	\$ 55.10
29	BOOT LID EMBLEM "E"	1	\$ 36.40	\$ 36.40
30	BOOT LID LOGO	1	\$ 65.60	\$ 65.60
31	REAR END PANEL <i>Deited</i>	1	\$ 661.00	\$ 661.00
32	REAR FLOOR PANEL <i>Byis</i>	1	\$ 858.00	\$ 858.00
33	TAIL LAMP <i>Omited</i>	2	\$ 423.00	\$ 846.00
34	TAIL LAMP PANEL <i>TH Deited</i>	2	\$ 410.00	\$ 820.00
35	REAR END PANEL TOP GARNISH <i>Deited</i>	1	\$ 314.30	\$ 314.30
36	REAR FLOOR PANEL TOP BOARD <i>men</i>	1	\$ 264.70	\$ 264.70
37	EXHAUST SILENCER <i>men</i>	1	\$ 758.00	\$ 758.00
38	EXHAUST SILENCER MOUNTING <i>men</i>	2	\$ 35.80	\$ 71.60

4892
3669.00

TOTAL PRICE \$ 11,731.20
LESS 25% \$ 2,932.80
SUB TOTAL PRICE \$ 8,798.40

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS <i>men</i>	10	\$ 6.50	\$ 65.00
2	FRONT BUMPER LOWER SIDE GRILLE CLIP RH	4	\$ 6.50	\$ 26.00
3	BONNET SEALANT <i>men</i>	1	\$ 80.00	\$ 80.00
4	REAR BUMPER CLIP SET <i>men</i>	1	\$ 65.00	\$ 65.00
5	BOOT LID OUTER MOULDING CLIP SET <i>7</i>	1	\$ 40.00	\$ 40.00
6	REAR FENDER INNER SHIELD CLIP SET <i>men</i>	1	\$ 45.00	\$ 45.00
7	REAR FENDER INNER TRIM CLIP SET	1	\$ 65.00	\$ 65.00
8	TAIL LAMP CLIP SET <i>men</i>	1	\$ 20.00	\$ 20.00
9	TAIL LAMP BULB <i>men</i>	1	\$ 10.00	\$ 10.00
10	TAIL LAMP PANEL SEALANT <i>men</i>	1	\$ 90.00	\$ 90.00
11	REAR END PANEL TOP GARNISH CLIP SET <i>men</i>	1	\$ 55.00	\$ 55.00
12	REAR END PANEL SEALANT <i>men</i>	1	\$ 90.00	\$ 90.00
13	REVERSE SENSOR SET <i>Dranged</i>	1	\$ 250.00	\$ 250.00

350

TOTAL \$ 901.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$800.00	400	
2	SPRAY PAINTING TO AFFECTED AREA	\$800.00	200	
3	TUFF COAT	\$150.00	x	
4	WIRING CHECK	\$80.00	30	
8	REFOCUS HEADLAMP BEAM	\$80.00	x	

630

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL, FLOOR PANEL AND REAR RHS FENDER. STRAIGHTEN, REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS.	\$ 1,800.00	900	
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$ 1,400.00	900	
3	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING.	\$ 150.00	50	
4	DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS.	\$ 120.00	x	
5	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUCTION.	\$ 80.00	30	
6	INSTALL BODYKIT AND ATTACHMENT	\$ 100.00	x	
7	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA.	\$ 100.00	x	
8	DISMENTLE AND INSTALL REAR SEATS, SPEAKER BOARD AND BOOT TRIMMING.	\$ 150.00	60	

1940

TOTAL

\$ 5,810.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,699.40
 TOTAL LABOUR COST : \$ 5,810.00
 TOTAL REPAIR COST : \$ 15,509.40

16588.65

Admin King
 4/5 31/05/18
 10 days

6589
 total: 6589.22
 c/s: ASK

APPROVED DETAILS

EXCESS :

NO. OF WORKING DAYS :

RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :

SURVEYED BY :

CONTACT NUMBER :

FAX NUMBER :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18009869/ASD3N2

Date: 09/07/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29030841AVW
Claimant Vehicle No :	SGJ7015B	Insured Vehicle No :	SLS5644S
Date of Loss:	23/05/2018	Nature of Claim:	TP
		Claim No:	559381

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGJ7015B	Engine No:	1NZX450985
Make & Model:	TOYOTA VIOS, 1.5 E (M)	Chassis No:	MR053HY4204195268
Reg. Date:	19/07/2006 (Man. Year: 2006)	Odometer:	243570 km
Colour:	Red		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,778.65	4,019.00	6,759.65	62.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,810.00	2,570.00	3,240.00	55.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,588.65	6,589.00	9,999.65	60.28
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	16,588.65	4,500.00	12,088.65	72.87

INSPECTION

Date of Assignment:	30/05/2018	
Date Inspected:	31/05/2018	Inspected At:
		You Yi Automobile (HQ) 23 KAKI BUKIT AVE 4, #03-01 AAS KAKI BUKIT CENTRE Singapore 466665
Estimated Period of Repair:	10.0 days	

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Jul 2018)
Parts: 143	TOYOTA VIOS 1.5 E (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGJ7015B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	465.20 FL	*367.10 FL
2	1	*FRONT BUMPER REINFORCEMENT	Bent	267.40 FL	*267.40 FL
3	2	*FRONT BUMPER SIDE RETAINER	Necessary	90.60 FL	*66.00 FL
4	1	*FRONT BUMPER CENTRE BRACKET	Not Necessary	384.00 FL	*- FL
5	1	*FRONT BUMPER LOWER GRILLE	Not Necessary	184.00 FL	*- FL
6	1	*FRONT BUMPER FOG LAMP	O/s Cracked	624.00 FL	*210.00 FL
7	1	*FRONT BUMPER FOG LAMP COVER	O/s Cracked	290.00 FL	*64.00 FL
8	1	*FRONT BUMPER UNDER COVER	Not Necessary	112.00 FL	*- FL
9	1	*FRONT GRILLE	Cracked	133.00 FL	*133.00 FL
10	1	*FRONT GRILLE LOGO	Necessary	43.00 FL	*43.00 FL
11	1	*FRONT SUPPORT PANEL	Repair	569.60 FL	*- FL
12	1	*HORN SET	Cracked	341.00 FL	*65.00 FL
13	1	*RADIATOR	Not Necessary	695.00 FL	*- FL
14	2	*RADIATOR MOUNTING	Not Necessary	100.00 FL	*- FL
15	1	*AIR CONDENSOR	Not Necessary	1,168.00 FL	*- FL
16	2	*AIR CONDENSOR MOUNTING	Not Necessary	110.00 FL	*- FL
17	2	*HEADLAMP	Cracked	778.40 FL	*778.40 FL
18	1	*REAR BUMPER	Distorted	598.00 FL	*381.10 FL
19	2	*REAR BUMPER SIDE RETAINER	Necessary	107.00 FL	*68.00 FL
20	1	*REAR BUMPER BRACKET	Not Necessary	68.00 FL	*- FL
21	1	*BOOT LID	Buckled	698.60 FL	*590.00 FL
22	1	*BOOT LID HINGE	Not Necessary	51.30 FL	*- FL
23	1	*BOOT LID LOCK ASSY	Damaged	189.60 FL	*53.10 FL
24	1	*BOOT LID STRIKER	Not Necessary	61.20 FL	*- FL
25	1	*BOOT LID WEATHERSTRIP	Cut	188.30 FL	*71.50 FL
26	1	*BOOT LID EMBLEM	Necessary	70.10 FL	*38.00 FL
27	1	*BOOT LID EMBLEM VIOS	Necessary	32.20 FL	*32.20 FL
28	1	*BOOT LID EMBLEM SPORT	Necessary	55.10 FL	*55.10 FL
29	1	*BOOT LID EMBLEM E	Necessary	36.40 FL	*36.40 FL
30	1	*BOOT LID LOGO	Necessary	65.60 FL	*65.60 FL
31	1	*REAR END PANEL	Dented	661.00 FL	*661.00 FL
32	1	*REAR FLOOR PANEL	Repair	858.00 FL	*- FL
33	2	*TAIL LAMP	Cracked	846.00 FL	*574.00 FL
34	1	*TAIL LAMP PANEL	O/s Dented	820.00 FL	*206.20 FL
35	1	*REAR END PANEL TOP GARNISH	Deformed	314.30 FL	*65.90 FL
36	1	*REAR FLOOR PANEL TOP BOARD	Not Necessary	264.70 FL	*- FL
37	1	*EXHAUST SILENCER	Not Necessary	758.00 FL	*- FL
38	2	*EXHAUST SILENCER MOUNTING	Not Necessary	71.60 FL	*- FL
39	10	*FRONT BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
40	4	*FRONT BUMPER LOWER SIDE GRILLE CLIP RH	Not Necessary	26.00 FS	*- FS
41	1	*BONNET SEALANT	Not Necessary	80.00 FS	*- FS
42	1	*SET REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
43	1	*SET BOOT LID OUTER MOULDING CLIP	Not Necessary	40.00 FS	*- FS
44	1	*SET REAR FENDER INNER SHIELD CLIP	Not Necessary	45.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	65.00 FS	*- FS
46	1		*SET TAIL LAMP CLIP	Necessary	20.00 FS	*20.00 FS
47	1		*TAIL LAMP BULB	Not Necessary	10.00 FS	*- FS
48	1		*TAIL LAMP PANEL SEALANT	Not Necessary	90.00 FS	*- FS
49	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	55.00 FS	*10.00 FS
50	1		*REAR END PANEL SEALANT	Necessary	90.00 FS	*60.00 FS
51	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	14,071.20	5,242.00
				- List Item Discount on L Items 25.00/25.00% (S\$)	3,292.55	1,223.00
				Total Parts (S\$)	10,778.65	4,019.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	800.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	800.00	200.00
3	TUFF COAT	New	150.00	-
4	WIRING CHECK	New	80.00	30.00
5	REFOCUS HEADLAMP BEAM	New	80.00	-
6	PANEL, FLOOR PANEL AND REAR RHS FENDER, STRAIGHTEN, REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS	New	1,800.00	900.00
7	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA	New	1,400.00	900.00
8	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING	New	150.00	50.00
9	DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS	New	120.00	-
10	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUNCTION	New	80.00	30.00
11	INSTALL BODYKIT AND ATTACHMENT	New	100.00	-
12	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA	New	100.00	-
13	DISMENTLE AND INSTALL REAR SEATS, SPEAKER BOARD AND BOOT TRIMMING	New	150.00	60.00
Gross Labour Cost (\$\$)			5,810.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >