

ASS. REC. BY:

REF:

CS/MSG18009873/Ard3et

Special Instruction:

Surveyor
Mehmen

Adrian

ASSIGNMENT (Office)

From (Person):

Christine Wong

of

MS19

Date/Time:

31/5/2018 9:28am

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 3242

Insured:

GBE 4377 L

at Workshop m/s

Tik Motor Workshop

Tel:

67466896

of

Blk 1, Kaki Bukit Ave 6 # 02-56 Autobay

Policy No:

28857437 MKC

Claim No:

559777

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/5/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:17am @ 31/5/18

Person Contacted:

Vehicle

☒ IN ☐ OUT

Date/Time	Action/Instruction	
	(✓) Estimate	
	SLS 3242 - NA/INC18009632/h4	DOA: 28/5/2018
	GBE 4377L - NA/INC18009632/h4	DOA: 26/5/2018

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLS324Z Yr Regn: 2011 JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C200 c.c. 1796Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 101817 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD20404824550847Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/40R18R: 235/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 31/05/18Survey held at T.K.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orFront o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP MS16</u>
<u>4/10</u>	<u>Continued LR \$6950/- and 6 days with repairer by Adrian. (Led 10063/-, 59%).</u>
	<u>MV: 64K</u>
	<u>PV: 48.4K</u>
	<u>Nett: 15.6K</u>
	<u>RECEIVED 25 OCT 2018</u>
	<u>24/10/2018</u>

Date/Time, File Pass to?

☐ : Preli. Report1) typist☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 6Resurvey No. of Trip: 1Report Format: TPLump Sum / I.B.I: (\$ 6950/-)Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 200

Transportation: _____

Photos _____

Others 10

TOTAL

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18009873/Ard3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 31-05-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 4377L	Veh. Inspected	SLS 324Z
Policy No.	28857437MKC	Coverage (\$)	0.00
Claim No.	559777	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	31/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/05/2018	Inspection Date	31/05/2018
Survey held at	T K MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-56 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 May 2018		31 May 2018 09:28 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KIAN CHUE HWA (INDUSTRIES) PTE LTD, Co. Reg. No.: 200702148H		
Main Claimant:	TAN CHUAN CHOON, ID: S8102505C		
Vehicle Reg. No.:	SLS324Z	Date of Loss:	26/05/2018 00:00 - :59 [82 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 559777	Policy/Cover Note No.:	28857437MKC Coverage: 08/12/2017 - 07/12/2018
Vehicle Reg. No. (Insured):	GBE4377L	Policy No. (Claimant):	
		Excess:	
Repairer:	Tk Motor Workshop (HQ) Blk 1 Kaki Bukit Ave 6 #02-56, Autobay @ Kaki Bt, 417883 Kaki Bukit - Tel: 67466896		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/06/2018]		
Adj Asg. Remarks:	on WP. Unable to comment on liability. Non Reporting. TP agree to use LKK as the SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2505C
Vehicle Details	
Vehicle No.:	SLS324Z
Vehicle to be Exported:	Yes
Intended De-registration Date:	31 May 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 200
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	27186030248430
Chassis No.:	WDD2040482A550847
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$44,578.00
Original Registration Date:	01 Jul 2011
First Registration Date:	01 Jul 2011
Transfer Count:	1
Actual ARF Paid:	\$44,578.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jun 2021
PARF Rebate Amount:	\$28,975.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$63,000.00
COE Rebate Amount:	\$19,425.00
Total Rebate Amount:	\$48,400.00

The information contained herein is correct as at 31 May 2018

OK





FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

 Post an Ad  Advertiser Login  Ways of Selling

New 5 Years COE Renewal Toyota Altis 1.6A.

 \$2800 Down Payment Monthly From \$688 Onwards. Lowest 3.68% P.A. @ GV Cars Financing. GV Credit Pte Ltd - StarAd 

 **HIN LUNG AUTO**
HoBee Group **30 years of car sale**

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

Browse by Category  Save Search  Print Sort by Date Posted 20 results/page

7 vehicles | **Search** c200 Advanced Search Search View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status


Search Selection	c200	Any	Any	2011	Any	Any	Any	Any	Available
------------------	------	-----	-----	------	-----	-----	-----	-----	-----------

 ☐ **Mercedes-Benz C-Class C200 CGI** **\$61,800** **\$14,440 /yr** **15-Feb-2011** **1,796 cc** **80,000 km** **Luxury** **Available**

1 Owner, Very Low Mileage Done At 79,000km, Accident Free! Absolutely No Repair Require, Perfect Driving Condition! View To Believe. Just Serviced!
In House Financing Available. Call For Viewing/ Test...


Horizon Motoring


 Posted: 31-May-2015 Tags: 2011 Mercedes-Benz C200, Mercedes-Benz C200, Mercedes-Benz, C200, Used Mercedes-Benz

 ☐ **Mercedes-Benz C-Class C200 CGI** **\$63,500** **\$14,260 /yr** **12-Apr-2011** **1,796 cc** **120,000 km** **Luxury** **Available**


Rare C200 CGI BlueEfficiency With Full Accessories From Factory! Various Attractive Loan Scheme Available Ranging From 0 Or Low Down Payment, Balloon Schemes. All Our Cars Have Been Preinspected By Ou...


Privilege Motors Pte Ltd

 Posted: 26-May-2015 Tags: 2011 Mercedes-Benz C200, Mercedes-Benz C200, Mercedes-Benz, C200, Used Mercedes-Benz


 ☐ **Mercedes-Benz C-Class C200 CGI** **\$62,000** **\$14,120 /yr** **04-May-2011** **1,796 cc** **92,616 km** **Luxury** **Available**


Cheapest In The Market! CGI Model! Low Mileage Done At 13000km/year Only. Fully Agent Serviced And Maintained By C&C With Servicing Just Done! New Road Tax Till November 18! 100% Accident Free! Superb...

 Posted: 18-May-2015 Tags: 2011 Mercedes-Benz C200, Mercedes-Benz C200, Mercedes-Benz, C200, Used Mercedes-Benz

 ☐ **Mercedes-Benz C-Class C200 CGI** **\$65,000** **\$14,420 /yr** **16-May-2011** **1,796 cc** **70,000 km** **Luxury** **Available**

Lowest Depreciation In The Market! Accident Free, Very Well Maintained And Under-utilized By Expat Owner. Workshop Evaluation Welcomed. No Expenses Spared To Preserve It's Condition. Cam Gear Replaced...


 Posted: 13-Apr-2015 Tags: 2011 Mercedes-Benz C200, Mercedes-Benz C200, Mercedes-Benz, C200, Used Mercedes-Benz



 Car Buying  Car Selling  Car Ownership


 Car Aftermarket  On The Move  Lifestyle


 **Bidding Car**
12233E **Bidded Carplates For Sale!**


 ☐ **Mercedes-Benz C-Class C200 CGI Avantgarde** **\$63,988** **\$14,250 /yr** **01-Jun-2011** **1,796 cc** **148,460 km** **Luxury** **Available**

Superb Condition CGI Avantgarde. Lady Owner. Well Kept Condition. Selling At This Price. Either You Choose A New Set Of Paint Or New Set Of Rims Or 1 Year Extended Warranty From Reputable Workshop. My...


Car Search


 Posted: 06-May-2015 Tags: 2011 Mercedes-Benz C200, Mercedes-Benz C200, Mercedes-Benz, C200, Used Mercedes-Benz




 ☐ **Mercedes-Benz C-Class C200K** **\$66,800** **\$13,370 /yr** **18-Oct-2011** **1,796 cc** **124,800 km** **Luxury** **Available**

Beautifully Styled New Facelift, Nicely Built And Oozing Quality Inside, The C200 Certainly Delivers The Trademark Benz Appeal And Is Sure To Impress, Competitively Priced In The Market, Be The Owner ...


 Posted: 15-May-2015 Tags: 2011 Mercedes-Benz C200K, Mercedes-Benz C200K, Mercedes-Benz, C200K, Used Mercedes-Benz



 ☐ **Mercedes-Benz C-Class C200** **\$74,800** **\$15,020 /yr** **15-Dec-2011** **1,796 cc** **53,000 km** **Luxury** **Available**

1 Owner, Full C&C Service History! Genuine Low Mileage Done! 95% Loan Scheme Available. Accident Free! Immaculate Condition! View To Believe It. Well Kept Condition. My Loss Is Your Gain. Call For App...

Hua Yang Credit Pte Ltd



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/05/2018 14:32
Date Of Accident	26/05/2018 14:40
Exact Location Of Accident	BLK 124 HOUGANG AVE 1 CARPARK LOT NO 294
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS324Z
Insured/Policyholder	
Name Of Registered Owner	TAN CHUAN CHOON
NRIC No	S8102505C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90995265
Alternative Phone No	OFFICE-90995265

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C 200
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094379384
Cover Note Number	-

Driver

Name of Driver	TAN CHUAN SHENG
NRIC No	S8845819B
Date Of Birth	19/10/1988
Occupation	INDOOR
Date Of Driving Pass	20/11/2009
Driving Experience	8 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90995265
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 297B COMPASSVALE ST #06-18
Postcode	542297
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO POLICE DIVISIONAL HQ (F DIVISION)
Police Station Address	ROAD: 51 ANG MO KIO AVENUE 9 , POSTCODE: 569929 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2180000 - FAX NO: 64814246
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

Details of Witness 1

Name	LAMBERT
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE4377L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan

Blk 124, Honggang Ave 1 Carpark Lot No: 294.

(A) SLS 324 Z

(B) GBE 4377 L



Grass

Accident Sketch Plan


Describe Circumstances of the Accident


Refer To police Report No: F/2018 0527/7017


I wish to highlight my vehicle SLS 324 Z have
a video footage in my vehicle.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date &
Time


Driver's Signature (if driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel



SINGAPORE POLICE FORCE

POLICE REPORT (NP299)

Police Station Of Origin
Ang Mo Kio Police Divisional HQ
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-2180000

16532 2007

1/ 4



F/20180527/7017

1 of 2

Report No. F/20180527/7017

Date/Time Report Made 27/05/2018 14:18		Vide Report No.		Station Diary No.	
Name Of Informant TAN CHUAN SHENG		Address APT BLK 297B COMPASSVALE STREET #06-18 SINGAPORE 542297			
ID Type / ID No. NRIC NO / S8845819B		Contact No. Home/Office: Mobile: 90995265			
Nationality SINGAPORE CITIZEN		Email Address im.hymenbreaker@hotmail.com			
Occupation Self-Employed		Sex Male	Age 29	Date of Birth 19/10/1988	Race Chinese
Institution/School Name		Language English			
Date/Time Of Incident 26/05/2018 14:39 - 26/05/2018 14:45		Location Of Incident 124 HOUGANG AVENUE 1 #01-1446 HDB-HOUGANG SINGAPORE 530124			

Brief details.

On 26/05/18 approximately 1320hrs, I parked my vehicle s1s324z at the carpark in front of the said address, in the lot of 294, next to me in the lot 293 was a blue lorry GBE4377L. I left the vehicle after it's was parked properly within the lot.

At about 1446hrs I was informed by my neighbours that they heard a loud crash and followed by the lorry trying to maneuver out of the lot of 293 and eventually turned right (instead of left) to exit. The driver did

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required. Date/Time: 27/05/2018 14:18 Classification Of Case:
Signature Of Interpreter: Not applicable	
Officer In-Charge Of Case:	
Authentication Stamp	



**SINGAPORE
POLICE FORCE**



F/20180527/7017

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20180527/7017

not alight and proceed to drive away .

The lorry damaged my front right side and my bonnet of my vehicle .

Subjects Involved			
Victim			
Person Name	TAN CHUAN SHENG		
ID Type	NRIC NO	ID No	S8845819B
Gender	Male	Age	29
Race	Chinese	Language	English
Occupation	Self-Employed	Address Type	
Address	APT BLK 297B COMPASSVALE STREET #06- 18 SINGAPORE 542297	Mobile No	90995265
Is Informant A Victim?	Yes		
Person Name	TAN CHUAN SHENG (Informant)		

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 27/05/2018 14:18
Officer In-Charge Of Case:	Classification Of Case:
Authontication Stamp	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/06/2018 14:38
Date Of Accident	26/05/2018 14:50
Exact Location Of Accident	BLOCK 124 HOUGANG AVENUE 1 OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE4377L
Insured/Policyholder	
Name Of Registered Owner	KIAN CHUE HWA (INDUSTRIES) PTE. LTD.
Co Reg No	200702148H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-68469989

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 1.5T-3.0 (M)
Exact Purpose for which vehicle was being used at time of accident	Commercial Use
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A28857437MKC
Cover Note Number	

Driver

Name of Driver	NEO KHENG BEE
NRIC No	S1613778B
Date Of Birth	11/04/1963
Occupation	OUTDOOR
Date Of Driving Pass	13/09/1983
Driving Experience	34 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96320573

Fax Number	
Contact Number	
Email Address	NOEMAIL
Address	BLOCK 124 HOUGANG AVENUE 1 #06-1454
Postcode	530124
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 26.05.2018 at about 1450hours, I was driving my vehicle (A: GBE4377L) along Block 124 Hougang Avenue 1 Open Carpark. While I was making a left turn, a vehicle (B: SLS324Z) which parked very close to my vehicle, I accidentally hit onto right front portion of vehicle B. It was rainy day I could not able to leave any note to owner of vehicle B. However, after all I was waiting for the owner of vehicle to come but yet to shown. Vehicle A (GBE4377L): No passenger on board. Vehicle B (SLS324Z): No passenger on board.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS324Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:




2-6-2018
13-10pm

anyun
b2204060r

A: GBE4377L

B: SLS 3248



Block 124
Hougang Avenue 1
car park.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GFA Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

2-6-2018
13.10 pm.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Caylan
608596460.

Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo





CHASSIS NO	: JTFAT35Y60K205457
U.L.W.	: 1680 KG
M.L.W.	: 3500 KG
PASS. CAP	: 02
TYRE SIZE	: F.195/75R.15
	: R.155R.12.8(D)

T K MOTOR WORKSHOP T/P: MS16 Ins.

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 96273323 FAX: 68442641
CO. REG NO: 53049097L

Lump Sum: 7 day
By Hand: 16/7/2018

DATE: 15/06/2018

TAN CHUAN CHOON
BLK 297B COMPASSVALE ST #06-18
SINGAPORE 542297

TP MS16
Janice

LKK: Adrian
WDD20404824550847

ACCIDENT DATE: 26/05/2018

ESTIMATE COST OF REPAIRS BILL TO MERCEDES-BENZ CAR NO: SLS324Z

1	PC	FRONT NO. PLATE (EMBOSS)	not new	S\$	30.00	30.00	S/NETT	+
1	PC	FRONT R/H 18 INCH SPORT RIM	cut		850.00	850.00	S/NETT	✓
1	PC	FRONT R/H TYRE 235/40/R18	cut		800.00	800.00	S/NETT	380 (sn)
1	PC	FRONT BONNET	Dented.		2,650.00	2,650.00	NETT	1655
1	PC	FRONT BONNET EMBLEM	new		72.00	72.00	NETT	✓
2	PC	FRONT BONNET STOPPER	not new		112.00	112.00	NETT	✓
1	PC	FRONT R/H HEADLAMP	cracked		952.00	952.00	NETT	✓
1	PC	FRONT R/H HEADLAMP PANEL	3 are new		350.00	350.00	NETT	x
2	PC	FRONT R/H HEADLAMP BRACKET			244.00	244.00	NETT	x
1	PC	FRONT R/H HEADLAMP LED BULB & BALAR	not new		600.00	600.00	S/NETT	+
1	PC	FRONT R/H FENDER	Dented		952.00	952.00	NETT	✓
1	PC	FRONT R/H FENDER EMBLEM	new		56.00	56.00	NETT	✓
1	PC	FRONT FENDER R/H INNER SHIELD	torn		68.00	68.00	NETT	✓
6	PC	FRONT FENDER R/H INNER SHIELD CLIP	new		30.00	30.00	NETT	✓
1	PC	FRONT BUMPER (C63 AMG KIT)	Deformed		1,800.00	1,800.00	S/NETT	1680k
8	PC	FRONT BUMPER CLIP	new		40.00	40.00	NETT	✓
2	PC	FRONT BUMPER SIDE HOLDER RETAINER	RH end		224.00	224.00	NETT	68
2	PC	FRONT BUMPER INNER BASE GARNISH	not new		444.00	444.00	NETT	x
1	PC	FRONT BUMPER REINFORCEMENT BEAM	Bent		575.00	575.00	NETT	✓
1	PC	FRONT BUMPER REINFORCEMENT BEAM R/H SIDE BEACKET	Bent		36.00	36.00	NETT	✓
2	PC	FRONT BUMPER PARKING SENSOR	1 piece damaged		340.00	340.00	NETT	200
1	PC	FRONT SUPPORT PANEL GARNISH	not new		190.00	190.00	NETT	x
26	PC	R/H SIDE SKIRT CLIP	not new		130.00	130.00	NETT	x
2	PC	FRONT BONNET LOCK	not new		152.00	152.00	NETT	x
1	PC	FRONT R/H LOWER ARM			745.00	745.00	NETT	x
1	PC	FRONT R/H KNUCKLE ARM			1,060.00	1,060.00	NETT	x
1	PC	FRONT R/H KNUCKLE HUP & BEARING			508.00	508.00	NETT	x
1	PC	FRONT R/H SHOCK ASBORBER			603.00	603.00	NETT	x

S/N 2910

TO WHEEL ALIGHTMENT.	90.00	-90.00	S/NETT	80
TO CHECK WRING.	50.00	-50.00		30
TO SPRAY PAINTING.	750.00	-750.00		650
TO TOP-UP AIR- CON GAS	100.00	100.00	x	
TO RESET FAULT CODE & CARRY OUT DIAGNOSTIC CHECK.	120.00	-120.00		100
TO MEASURE, DRILL THE REPLACED BUMPER, POSITION & RESTALL FRONT PARKING SENSOR, CONTROL UNIT, CHECK & TEST FOR FUNCTIONING.	80.00	80.00		50
TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION.	80.00	80.00	x	
TO LABOUR CHARGE FOR PANEL BEATING, WELDING, REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC.	850.00	-850.00		600
TO REMOVE & REFIX FRONT UNDER CARRIAGE.	280.00	280.00	x	

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

TOTAL S\$

17,013.00

Total 868960
1/5: 6950 06 days

06 days

6950



































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 May 2018		31 May 2018 09:28 Edit Adj Rpt	S\$6,950.00 Edit Estimates	S\$6,950.00 View Rpt		Pending for Survey Report Cancel Case































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: KIAN CHUE HWA (INDUSTRIES) PTE LTD , Co. Reg. No.: 200702148H									
Main Claimant: TAN CHUAN CHOON , ID: S8102505C									
Vehicle Reg. No.: SLS324Z		Date of Loss: 26/05/2018 00:00 - :59 [82 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 559777		Policy/Cover Note No.: 28857437MKC Coverage: 08/12/2017 - 07/12/2018							
Vehicle Reg. No. (Insured): GBE4377L		Policy No. (Claimant):							
		Excess:							
Repairer: Tk Motor Workshop (HQ) Blk 1 Kaki Bukit Ave 6 #02-56, Autobay @ Kaki Bt, 417883 Kaki Bukit - Tel: 67466896									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Imm.Advice due 01/06/2018]									
Adj Asg. Remarks: on WP. Unable to comment on liability. Non Reporting. TP agree to use LKK as the SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLS324Z (559777)**
[GBE4377L]
TP
TAN CHUAN CHOON
May 26 2018 12:00AM
[KIAN CHUE HWA (INDUSTRIES) PTE LTD]
Tk Motor Workshop

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/06/18 09:31	Accident Statement From: SC - Reg. No: GBE4377L, Claimant: KIAN CHUE HWA (INDUSTRIES) PTE. LTD.	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
2	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
3	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
4	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
5	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
6	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
7	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
8	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
9	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
10	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
11	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
12	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
13	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
14	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
15	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
16	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
17	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
18	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
19	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
20	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
21	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
22	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
23	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
24	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
25	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
26	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
27	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
28	04/10/18 14:34	General View	 Load JPG	<input checked="" type="checkbox"/>
29	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	04/10/18 14:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/05/18 15:58	Email frm TP - PRI	 Load PDF	
2	30/05/18 15:59	TP Police Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18009873/ARD3E2

Date: 25/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28857437MKC

Claimant Vehicle No : SLS324Z

Insured Vehicle No : GBE4377L

Date of Loss: 26/05/2018

Nature of Claim: TP

Claim No: 559777

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS324Z

Make & Model: MERCEDES-BENZ C200, 1.8 (A)

Engine No: 27186030248430

Reg. Date: 01/07/2011 (Man. Year: 2011)

Chassis No: WDD2040482A550847

Colour: Silver

Odometer: 101817 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40 R18

Rear Tyre Size: 235/40 R18

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,613.00	7,179.60	7,433.40	50.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,510.00	890.00	37.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,013.00	8,689.60	8,323.40	48.92
Approved Total (Overridden) (S\$)		6,950.00		
Nett Amount (S\$)	17,013.00	6,950.00	10,063.00	59.15

INSPECTION

Date of Assignment: 31/05/2018

Date Inspected: 31/05/2018 Inspected At:

Tk Motor Workshop (HQ)
Blk 1 Kaki Bukit Ave 6 #02-56, Autobay @
Kaki Bt
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2018)
Parts:	143	MERCEDES-BENZ C200 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS324Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NO. PLATE (EMBOSS)	Not Necessary	30.00 FS	*- FS
2	1		*FRONT R/H 18 INCH SPORT RIM	Cut	850.00 FS	*850.00 FS
3	1		*FRONT R/H TYRE 235/40/R18	Cut	800.00 FS	*380.00 FS
4	1		*FRONT BONNET	Dented	2,650.00 F	*1,695.00 FN
5	1		*FRONT BONNET EMBLEM	Necessary	72.00 F	*72.00 FN
6	2		*FRONT BONNET STOPPER	Not Necessary	112.00 F	*- FN
7	1		*FRONT R/H HEADLAMP	Cracked	952.00 F	*952.00 FN
8	1		*FRONT R/H HEADLAMP PANEL	Not Necessary	350.00 F	*- FN
9	2		*FRONT R/H HEADLAMP BRACKET	Not Necessary	244.00 F	*- FN
10	1		*FRONT R/H HEADLAMP LED BULB & BALAR	Not Necessary	600.00 FS	*- FS
11	1		*FRONT R/H FENDER	Dented	952.00 F	*952.00 FN
12	1		*FRONT R/H FENDER EMBLEM	Necessary	56.00 F	*56.00 FN
13	1		*FRONT FENDER R/H INNER SHIELD	Torn	68.00 F	*68.00 FN
14	6		*FRONT FENDER R/H INNER SHIELD CLIP	Necessary	30.00 F	*30.00 FN
15	1		*FRONT BUMPER (C63 AMG KIT)	Deformed	1,800.00 FS	*1,680.00 FS
16	8		*FRONT BUMPER CLIP	Necessary	40.00 F	*40.00 FN
17	1		*FRONT BUMPER SIDE HOLDER RETAINER	O/S Damaged	224.00 F	*68.00 FN
18	2		*FRONT BUMPER INNER BASE GARNISH	Not Necessary	444.00 F	*- FN
19	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	575.00 F	*575.00 FN
20	1		*FRONT BUMPER REINFORCEMENT BEAM R/H SIDE BRACKET	Bent	36.00 F	*36.00 FN
21	1		*FRONT BUMPER PARKING SENSOR (2PCS)	Damaged - 1pc only	340.00 F	*200.00 FN
22	1		*FRONT SUPPORT PANEL GARNISH	Not Necessary	190.00 F	*- FN
23	1		*R/H SIDE SKIRT CLIP (26PCS)	Not Necessary	130.00 F	*- FN
24	2		*FRONT BONNET LOCK	Not Necessary	152.00 F	*- FN
25	1		*FRONT R/H LOWER ARM	Not Necessary	745.00 F	*- FN
26	1		*FRONT R/H KNUCKLE ARM	Not Necessary	1,060.00 F	*- FN
27	1		*FRONT R/H KNUCKLE HUP & BEARING	Not Necessary	508.00 F	*- FN
28	1		*FRONT R/H SHOCK ABSORBER	Not Necessary	603.00 F	*- FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	14,613.00	7,654.00
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	474.40
Total Parts (\$\$)	14,613.00	7,179.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WHEEL ALIGNMENT	New	90.00	80.00
2	TO CHECK WIRING	New	50.00	30.00
3	TO SPRAY PAINTING	New	750.00	650.00
4	TO TOP-UP AIR-CON GAS	New	100.00	0.00
5	TO RESET FAULT CODE & CARRY OUT DIAGNOSTIC CHECK	New	120.00	100.00
6	TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION	New	80.00	0.00
7	TO LABOUR CHARGE FOR PANEL BEATING, WELDING, REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC	New	850.00	600.00
8	TO REMOVE & REFIX FRONT UNDERCARRIAGE	New	280.00	0.00
9	TO MEASURE, DRILL THE REPLACED BUMPER, POSITION & RESTALL FRONT PARKING SENSOR, CONTROL UNIT, CHECK & TEST FOR FUNCTIONING	New	80.00	50.00
Gross Labour Cost (\$\$)			2,400.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >