

ASS. REC. BY:

REF:

C83/AIG18009889/A24d362

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

30/5/2018 4:56pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SBC 81817

Insured:

SJ 728M

at Workshop m/s

Alpha Car Services

Tel:

6509 8258

of

Kaki Bukit Ave 6 # 01-54 Bk C

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/5/2018

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

Rpm 31/5/18

Person Contacted:

ceiling

H.O.D. Endorsement:

Vehicle

IN

OUT

Date/Time	Action/Instruction	(X) Estimate
	SBC 81817-X	
	SJ 728M-X	
1/6/18	Dismantled	
4/6/18	After Repair	

**** LOGS ****

SID : LKK

Number : 62564315

Date : 18-05-18 14:10

TRANSMISSION

Date/Time	Subscriber	Mode	Pages	Durat.	Status	Note
18-05 8:28	67439006	NORMAL	1	1'50"	Correct	Manual communication
18-05 9:49	64834882	NORMAL	2	0'43"	Correct	Manual communication
11-05 14:19	62718802	NORMAL	1	0'54"	Correct	Manual communication
11-05 18:03	62718802	NORMAL	1	0'51"	Correct	Manual communication
15-05 8:14	65551184	NORMAL	4	1'11"	Correct	Manual communication
15-05 9:00	67528669	NORMAL	2	0'44"	Correct	Manual communication
15-05 15:37	65551184	NORMAL	4	1'14"	Correct	Manual communication
16-05 10:32	62815767	NORMAL	6	1'06"	Correct	
17-05 13:46	62718802	NORMAL	1	0'52"	Correct	Manual communication

RECEPTION

Date/Time	Subscriber	Mode	Pages	Durat.	Status	Note
18-05 8:55	62212263	FINE	2	0'26"	Correct	

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SJJ728M AND SBC8181T (AC) ON 30/05/2018**

From: Chin, Lee-Ying

To: assignments@lkkauto.com, Admin A

Cc: Fong, Andy-SY

Sent: 30/5/2018 4:56:35 PM

Attachments:  Alpha Car - Pre-Repair Notice (AIG)(SBC8181T).pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CROSSBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.AC (SBC8181T)
Your Ref: SJJ728M

30 May 2018

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16 AIG Building
Singapore 079120

Attn: Motor Claims Department

BY FAX: 6835 7416 ONLY

URGENT

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSEH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
CLAIMANT: RACHEL WANG MANMAN
TRAFFIC ACCIDENT ON 30 MAY 2018 AT 09:45 HRS ALONG BUKIT BATOK EAST
AVENUE 2 INVOLVING VEHICLES NO. SBC8181T & SJJ728M & SKD6822D.

We are instructed by Rachel Wang Manman to notify you of a road accident on 30 May 2018 at about 09:45 hrs along Bukit Batok East Avenue 2 involving our client's vehicle registration number SBC8181T and vehicle registration number SJJ728M driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Alpha Car Services Pte. Ltd.
Address: Blk C, #01-59
Kaki Bukit Avenue 6 @ KB
Singapore 417883
Contact: Cai Ling (6509 8258) / Ah Yap (9807 3304) /
Ah Hwa (9136 8884)

Please liaise with the above workshop directly.

Yours faithfully

Amerjeet Singh

Email: corene@crossbordersllc.com /

huiting@crossbordersllc.com

encs

**PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION**

.....

CONFIDENTIALITY CAUTION
THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE
SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CROSSBORDERS LLC

A LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18009889/Az4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 31-05-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJJ 728M	Veh. Inspected	SBC 8181T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	31/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	30/05/2018	Inspection Date	31/05/2018
Survey held at	LUSH AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-47 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 30/05/2018 15:49
Date Of Accident 30/05/2018 09:45
Exact Location Of Accident BUKIT BATOK EAST AVE 2
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SBC8181T
Insured/Policyholder
Name Of Registered Owner RACHEL WANG MANMAN
NRIC No S8472605B
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-98253946
Alternative Phone No OFFICE-98253946

Vehicle Particulars

Manufacturer TOYOTA
Model CAMRY
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number GA317057
Cover Note Number

Driver

Name of Driver POH ZIHAN
NRIC No S8235370D
Date Of Birth 27/10/1982
Occupation OUTDOOR
Date Of Driving Pass 17/05/2001
Driving Experience 17 YEARS AND 0 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-90276543
Fax Number
Contact Number
Mail Address NOEMAIL

Address	BLK 421 CLEMENTI AVE 1 #24-371
Postcode	120421
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : RACHEL WANG MANMAN GENDER: : FEMALE
Passenger 2	NAME: : STELLA POH YU XUAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE ABOVE MENTIONED DATE AND TIME, I WAS TRAVELLING ALONG BUKIT BATOK EAST AVE 2. THE CAR WAS AT A STAND STILL WAITING FOR TRAFFIC LIGHT TO TURN GREEN WHEN MY CAR WAS BEING KNOCKED BY THE CAR BEHIND US. THE IMPACT OF THE CRASH WAS GREAT AS ALL PASSENGERS (MY WIFE AND DAUGHTER) INCLUDING MYSELF KNOCKED OUR HEADS AGAINST HEAD REST / SIDE OF THE CAR. ALL OF US EXPERIENCED SOME LEVEL OF UNCOMFORT AND MY WIFE COMPLAINED OF DIZZY SPELL. I WAS EXPERIENCING HEAD AS WELL AS BACKACHE. IT WAS DRIZZLING AT THE MOMENT OF THE ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ728M
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	TAN SIEW HOW
NRIC/Passport Number	
Contact Number	98285498

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name
Approximate Age
Injuries Sustain
Injured person in which vehicle?
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 2

Name
Approximate Age
Injuries Sustain
Injured person in which vehicle?
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 3

Name
Approximate Age
Injuries Sustain
Injured person in which vehicle?
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

30 May 2018
1:35pm

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above mentioned date and time, I was travelling along Butir Babok East Ave 2. The car was at a standstill waiting for traffic light to turn green when ~~the~~^{my} car was being knocked by the car behind us. The impact of the crash was great as all passengers (my wife and my daughter) including myself knocked our heads against the headrests and/or side of the car. All of us experienced some level of discomfort and my wife complained a dizzy spell. I was experiencing headache as well as backache. ~~The~~ It was drizzling at the moment of the accident,

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time:
30 May 2018.
1:35pm.


Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


LETTER OF UNDERTAKING

I/We, Rachel Wang Mannan, the owner of vehicle no. SBC 81817

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, ALPHA CAR

Signed and Acknowledge by:

 S847265B
Nric no. and signature of policyholder

.....
Company Stamp

30/05/2018
.....
Date

Identification Card

IDENTIFICATION CARD NO. SB472605B



RACHEL WANG MANMAN

1 1 1

RACE
CHINESE

DATE OF BIRTH
01-09-1964

COUNTRY OF BIRTH
CHINA

01-09-1964



SB472605B



RECEIVED BY: [Signature]
DATE: 10/11/01
TIME: 10:11

Identification Card

REPUBLIC OF CHINA
IDENTITY CARD NO. S8235370D



POH ZIHAN
(FU ZIHAN)

Birth Date: 27 Oct 1962
Birth Place: 10 May 1963



REPUBLIC OF CHINA
IDENTITY CARD NO. S8235370D



POH ZIHAN
(FU ZIHAN)

CHINESE

27 Oct 1962



Driving License

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)


Class 3

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

17 May 2001

NP 428A



Licence No. S8235370D



S181392

NRIC No. S8235370D



Date of issue

11-05-2013

APT BLK 421 CLEMENTI AVENUE 1 #24-371
SINGAPORE 120421

S8235370D

01/01/2014

INSURANCE



redefining / insurance

AXA Insurance Pte Ltd
1400 280 4444 (Within Singapore)
(65) 6880 4584 (International)
(65) 6880 2700
customer.care@axa.com.sg
www.axa.com.sg

Date:
27/01/2018

Policy Number
VA1 / GA317057

Account number
14885

Certificate of Insurance

AXA Insurance Pte Ltd is a member of AXA Group of Companies. The information provided herein is for informational purposes only. It does not constitute an offer of insurance or any other financial product. Please refer to the actual policy document for full details.

Policy details

Policyholder name	RACHEL WANG KIANHUI	Certificate number	GA317057 / 1
Cover	Comprehensive	Chassis number	NR053AK5004011629
Plan name	Toyota Prestige	Engine number	24RU354602
ACD applicable	0%		
Vehicle registration number	SBC8161T		
Period of Insurance	11/13/03/2018 to 12/03/2020 (12/13/2018 to 12/03/2019)		
Finance loan company			

Authorized Drivers

1. The following driver is authorized to drive the Motor Vehicle under the Policy:
The person who is named as the Policyholder or the authorized driver of the Motor Vehicle.
2. The person who is named as the Policyholder or the authorized driver of the Motor Vehicle must be at least 21 years old and must hold a valid driving license issued by the relevant authority.
3. The person who is named as the Policyholder or the authorized driver of the Motor Vehicle must not be disqualified by order of a Court of Law or by order of any competent authority from driving the Motor Vehicle.

Limitation as to use*

- Use of the Motor Vehicle is permitted to the Policyholder for business.
- Use of the Motor Vehicle is permitted for pleasure.
- Use of the Motor Vehicle is permitted for hire or reward.

The Policyholder agrees:

- Use of the Motor Vehicle is restricted to the authorized driver.
- Not to use the Motor Vehicle for any purpose other than the authorized driver.
- Not to use the Motor Vehicle for any purpose other than the authorized driver.

*Limitations on use of the Motor Vehicle are subject to the terms and conditions of the Policy. The Policyholder agrees to indemnify AXA Insurance Pte Ltd for any loss or damage to the Motor Vehicle or to any third party caused by the use of the Motor Vehicle for any purpose other than the authorized driver.

EXCESS

Basic Excess: \$500
Optional Excess: \$1000

AXA Insurance Pte Ltd
1400 280 4444

Additional clauses & endorsements to your policy

1. The Policyholder agrees to pay the excess amount in full for any claim made under the Policy.
2. The Policyholder agrees to pay the excess amount in full for any claim made under the Policy.
3. The Policyholder agrees to pay the excess amount in full for any claim made under the Policy.
4. The Policyholder agrees to pay the excess amount in full for any claim made under the Policy.
5. The Policyholder agrees to pay the excess amount in full for any claim made under the Policy.

AXA Insurance Pte Ltd

AXA Insurance Pte Ltd
1400 280 4444
1400 280 4444
1400 280 4444
1400 280 4444

CHILD'S BIRTH CERT

112418411

THOMSON MEDICAL LTD

SHEN POEYI XUAN

FEMALE

傅 羽 暄

11/12/2003

DR 11

THOMSON MEDICAL LTD

RACHEL WANG KUANMAN

N.PINK 88472605H

01/09/1983

SINGAPORE CITIZEN

CHINESE

MANDARIN

400-KILBAUK STREET S241402
SINGAPORE 659246

CHINA

POH ZHAN HU ZHANG

N.PINK 88217470H

CHINESE

HOKKIAN

SINGAPORE CITIZEN

SINGAPORE

POH ZHAN HU ZHANG

N.PINK 88217470H

FATHER


400-KILBAUK STREET S241402
SINGAPORE 659246

KEE HEE HOE

400-KILBAUK STREET S241402
SINGAPORE 659246

NOTED FOR REGISTRATION

Accident Photo



TOYOTA MOTOR CORPORATION

J-EIETK 2494


5004011839

SEP 16

SEP 16

TOYOTA MOTOR TRADING CO., LTD. MADE IN JAPAN

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



MOTORCAR (Rear)

Rear Portion

Vehicle No: SBC 8181T

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	BT	✓	
1138	993627	Rear Number Plate Base	BR	✓	
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	CUT	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	SCR	R	
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993491	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Jun 2018 Edit Reg		30 May 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	TAN SIEW HOW, ID: S2564402F		
Main Claimant:	RACHEL WANG MANMAN, ID: S8472605B		
Vehicle Reg. No.:	SBC8181T	Date of Loss:	30/05/2018 09:00 - :59 [14 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0423501611SG	Policy/Cover Note No.:	2100479019 (Comprehensive)
Vehicle Reg. No. (Insured):	SJJ728M	Policy No. (Claimant):	
		Excess:	
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/06/2018]		
Claimant's Solicitor:	CROSSBORDERS LLC - Tel: 64381323		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail






































- AIG_SG (05/06/2018): Request To Upload TP GIA Report






















ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SBC8181T (0423501611SG)
[SJJ728M]
TP
RACHEL WANG MANMAN
May 30 2018 9:00AM
[TAN SIEW HOW]
Alpha Car Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	01/06/18 15:37	General View														Load JPG <input checked="" type="checkbox"/>		
2	01/06/18 15:37	General View														Load JPG <input checked="" type="checkbox"/>		
3	01/06/18 15:37	General View														Load JPG <input checked="" type="checkbox"/>		
4	01/06/18 15:37	General View														Load JPG <input checked="" type="checkbox"/>		
5	01/06/18 15:37	General View														Load JPG <input checked="" type="checkbox"/>		
6	01/06/18 15:37	General View														Load JPG <input checked="" type="checkbox"/>		
7	01/06/18 15:38	General View														Load JPG <input checked="" type="checkbox"/>		
8	01/06/18 15:38	General View														Load JPG <input checked="" type="checkbox"/>		
9	01/06/18 15:38	General View														Load JPG <input checked="" type="checkbox"/>		
10	01/06/18 15:38	General View														Load JPG <input checked="" type="checkbox"/>		
11	01/06/18 15:38	General View														Load JPG <input checked="" type="checkbox"/>		
12	01/06/18 15:38	General View														Load JPG <input checked="" type="checkbox"/>		
13	01/06/18 15:38	General View														Load JPG <input checked="" type="checkbox"/>		
14	01/06/18 15:38	General View														Load JPG <input checked="" type="checkbox"/>		
15	01/06/18 15:38	General View														Load JPG <input checked="" type="checkbox"/>		
16	01/06/18 15:38	General View														Load JPG <input checked="" type="checkbox"/>		
17	01/06/18 15:38	General View														Load JPG <input checked="" type="checkbox"/>		
18	01/06/18 15:38	General View														Load JPG <input checked="" type="checkbox"/>		
19	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
20	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
21	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
22	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
23	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
24	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
25	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
26	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
27	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
28	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
29	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
30	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
31	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
32	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
33	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
34	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
35	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
36	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		
37	01/06/18 15:38	Dismantled Parts														Load JPG <input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	01/06/18 15:38	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	01/06/18 15:38	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	01/06/18 15:38	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	01/06/18 15:38	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	01/06/18 15:38	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	07/06/18 12:15	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/06/18 08:34	OI GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009889/AZ4D3E2

Date: 08/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100479019
 Claimant Vehicle No: SBC8181T Insured Vehicle No: SJJ728M
 Date of Loss: 30/05/2018 Nature of Claim: TP Claim No: 0423501611SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBC8181T
 Make & Model: TOYOTA CAMRY, 2.4 (A) Engine No: 2ARU354802
 Reg. Date: 13/03/2017 (Man. Year: 2016) Chassis No: MR053AK5004011839
 Colour: Blue Odometer: 0 km
 Engine Capacity: 2494 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/05/2018
 Date Inspected: 31/05/2018 Inspected At: Alpha Car Services Pte Ltd (HQ)
 Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit
 Autobay
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Broken	0.00 F	*- F
3	1		*REAR BUMPER	Cut	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*BOOTLID	Repair	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

