

15/03/2007

ASS. REC. BY:

REF: CS3/AIG18009894/Azadzka Special Instruction:

Surveyor Number: Adnan ASSIGNMENT (Office)

From (Person): Chin lee ying of AIG Date/Time: 30/5/18 @ 3:58pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: S GQ 7328L Insured: SLP 2532S

at Workshop m/s: Jush Automotive Tel: 979 66 979

of No. 8 Kelki Bukit Ave 4 # 03-47

Policy No: \_\_\_\_\_ Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 27/5/2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS Imp H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 11:40am @ 31/5/18 Person Contacted: Hans Vehicle:  IN /  OUT

Date/Time	Action/Instruction (X) Estimate
	<u>S GQ 7328L - X</u>
	<u>SLP 2532S - X</u>
<u>1/6/18</u>	<u>Disassembled</u>
<u>5/6/18</u>	<u>After Repair</u>

ASS. REC. BY: Adrian King

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

/	
N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 04/8/18 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: S6Q7328L Yr Regn: 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish c.c

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 164992 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 31/05/18

Survey held at Lush

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP A/G PRS.</u>
<u>1/6/18</u>	<u>Submit DAR Report.</u>
<b>RECEIVED 01 JUN 2018</b>	

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: \_\_\_\_\_

1) \_\_\_\_\_  
Date/Time, File Return to?

: Final Report

Resurvey No. of Trip: \_\_\_\_\_

2) \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_ )

Survey Fee: 180

Transportation: \_\_\_\_\_

Report Format : \_\_\_\_\_

: Interview (\$ \_\_\_\_\_ )

Photos

Lump Sum / I.B.I: (\$ \_\_\_\_\_ )

: Tech. Invs (\$ \_\_\_\_\_ )

Others

: Weekend (\$ \_\_\_\_\_ )

TOTAL

200

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE  
SLP2532S AND SGQ7328L ON DOA 27/5/2018**

From: Chin, Lee-Ying  
To: assignments@lkkauto.com, Admin A  
Cc: Fong, Andy-SY  
Sent: 30/5/2018 3:58:44 PM  
Attachments:  180530-GIA report SGQ7328L(NEW).pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947 | Fax +(65) 6835 7416  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

---

**From:** Yvonne [<mailto:yvonne@ealc.com.sg>]  
**Sent:** Wednesday, May 30, 2018 3:47 PM  
**To:** Chan, Yoke Shi  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina  
**Subject:** PRI AIG Insured SLP2532S [EAL.2018.5693.MK.ya - SGQ7328L]

Our ref : 2018.5693.MK.ya - **SGQ7328L**  
Your ref : **SLP2532S**

PLEASE REPLY VIA EMAIL ([yvonne@ealc.com.sg](mailto:yvonne@ealc.com.sg))

AIG Asia Pacific Insurance Pte Ltd  
No. 78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Motor Claims Department  
**2 DAYS' PRE-REPAIR NOTICE**

Surveyor from M/s AIG Asia Pacific Insurance Pte Ltd		
Vehicle <b>SGQ7328L</b> inspected as follows by Name:		
Before repair	Parts removed	After repair
_____	_____	_____
Signature	Signature	Signature
Date/ Time:	Date/ Time:	Date/ Time:

Dear Sir/Madam,

**NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE**  
**CLAIMANT: MASRUPE BIN SULAIMAN**  
**ACCIDENT INVOLVING SGQ7328L & SLP2532S ON 27 MAY 2018 ALONG EXITING MALAYSIA CUSTOMS TOWARDS WOODLANDS CHECKPOINT AT ABOUT 1515 HOURS**

We refer to the above matter wherein we are instructed to act for **MASRUPE BIN SULAIMAN**, the owner of vehicle no. **SGQ7328L**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **SGQ7328L** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Lush Automotive Pte Ltd  
No. 8 Kaki Bukit Avenue 4,  
#03-47 Premier@Kaki Bukit,  
Singapore 415875  
Tel: 97966979 (Mr Max)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,  
Yvonne Ang

East Asia Law Corporation  
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413  
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Affiliated to Federation Internationale Des Experts En Automobile

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 31-05-2018



Code : AIG

**1. Policy Particulars :- (THIRD PARTY CLAIM)**

Insured Veh.	SLP 2532S	Veh. Inspected	SGQ 7328L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	31/05/2018

**2. Vehicle Particulars & Condition**

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

**4. Description of Damages**

--

**5. General Information**

Accident Date	27/05/2018	Inspection Date	31/05/2018
Survey held at	LUSH AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-47 PREMIER @ KAKI BUKIT SINGAPORE 415875		

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	30/05/2018 12:17
Date Of Accident	27/05/2018 03:15
Exact Location Of Accident	EXITING MALAYSIA CUSTOMS TWDS WOODLANDS CHECKPOINT
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGQ7328L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MASRUPE BIN SULAIMAN
NRIC No	S1533591B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91906711
Alternative Phone No	OFFICE-91906711

#### Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

#### Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPC17S004904
Cover Note Number	

#### Driver

Name of Driver	MUHAMMAD NAILI BIN MASRUPE
NRIC No	S9111469J
Date Of Birth	19/03/1991
Occupation	INDOOR
Date Of Driving Pass	26/02/2016
Driving Experience	2 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91906711
Fax Number	
Contact Number	
EEmail Address	MDNAILI_91@HOTMAIL.COM

Address	BLK 150 JALAN TECK WHYE #06-51
Postcode	680150
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	6
Passenger 1	NAME: : MASRUPE GENDER: : MALE
Passenger 2	NAME: : SALBIAH GENDER: : FEMALE
Passenger 3	NAME: : HAYATI GENDER: : FEMALE
Passenger 4	NAME: : RASHIKA GENDER: : FEMALE
Passenger 5	NAME: : AYIE GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHOA CHU KANG NPC
Police Station Address	ROAD: 20 CHOA CHU KANG ST 52 #01-02 , POSTCODE: 689286 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO

Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SLP2532S
Vehicle Make/Model/Colour	NA
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	GOH HENG HOCK
NRIC/Passport Number	S2006824H
Contact Number	93884516
Address	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	NA
No. Of Passenger (Including Driver)	

# Accident Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

 30 May 18 11:50am  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:







**SINGAPORE  
POLICE FORCE**



T/20180527/2012

1 of 3

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999

Report No. T/20180527/2012

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/05/2018 04:57	Vide Report No.:	Station Diary No.: 18
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: MUHAMMAD NAILI BIN MASRUPE		Address: APT BLK 150 JALAN TECK WHYE #06-51 SINGAPORE 680150	
ID Type / ID No.: NRIC NO / S9111469J		Contact No.: Home/Office: Mobile: 98341226	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 27	Date of Birth: 19/03/1991	Type of Informant: Driver
Race: Boyanese		Language:	Institution / School Name:
Occupation: PEST CONTROL		Driving Licence Information: Class: 2B,3	Date of Expiry:

**General Information of the Accident**

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 27/05/2018 03:15	Type of Location: Straight Road
Location: Along Road 1 WOODLANDS ROAD				
Exiting Malaysia Customs towards Woodlands Checkpoint				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGQ7328L	Car				Slightly Damaged	5
SLP2532S	Car				Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20180527/2012

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999

2 of 3

Report No. T/20180527/2012

CONTINUATION OF REPORT

Driver			
Name	MUHAMMAD NAILI BIN MASRUPE	ID No.	S9111469J
Related Vehicle	NIL	Contact No.	98341226
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the above mentioned date, time and location, 2 lanes exiting Malaysia Customs were closed. Thus, all the cars were merging into one lane. When I was in the lane, there was another vehicle on my right trying to squeeze into the lane. Subsequently, he scratched my vehicle from the right passenger door to the rear bumper. After that we exchanged particulars and left the place.

I wish to state that I have in vehicle camera in my car and the car behind me belongs to my cousin which have captured the whole incident. The estimated cost for repair is between \$200-300. There is a scratch and dent on the right side of my car.

The driver's particulars are as follows:

Goh Heng Hock  
S2006824H  
Hp: 93884516



**SINGAPORE  
POLICE FORCE**



T/20180527/2012

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999

3 of 3

Report No. T/20180527/2012

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/

Sgt 1 ABAYA PRITHA D/O SELVAM  
ARUMUGAM

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /  
Staff Sgt TANG SIEW PING  
Contact No.: 65476430

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

27/05/2018 04:57

Classification Of Case:

**MOTOR CAR (RH)**

**Right Portion**

Vehicle No: **SGQ 7328 L**

NAC	INC	Item	CON	AC	Qty
1316	991517	Fit RH Door			
1317	991654	Fit RH Door Protector			
1318	991601	Fit RH Door Hinge			
1319	991685	Fit RH Door Wing Mirror			
1320	991583	Fit RH Door Garnish			
1321	991639	Fit RH Door Glass Outer Moulding			
1322	991588	Fit RH Door Glass Inner Moulding			
1323	991584	Fit RH Door Glass			
1324	991595	Fit RH Door Glass Regulator			
1325	991596	Fit RH Door Glass Regulator Motor			
1326	991662	Fit RH Door Rubber			
1327	991636	Fit RH Door Outer Handle			
1328	991607	Fit RH Door Inner Handle			
1329	991625	Fit RH Door Lock w/Key			
1330	991624	Fit RH Door Lock			
1331	991562	Fit RH Door Central Lock			
1332	991675	Fit RH Door Switch			
1333	991617	Fit RH Door <del>Inner</del> <del>Panel</del> Board			
1334	991568	Fit RH Door Checker			
1335	991575	Fit RH Door Felt			
1336	991688	Fit RH Door Wire Harness			
1337	991683	Fit RH Door Window Glass Pillar			
1338	991640	Fit RH Door Outer Pillar			
1339	991613	Fit RH Door Inner Pillar			
1340	991646	Fit RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Fit RH Door Step Garnish			
1346	994058	Rocker Panel RH <b>Rear</b>	CUT	✓	
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1000	991300	Fit Bumper			
1006	991325	Fit Bumper Bracket			
1007	991462	Fit Bumper Side Retainer			
1008	991433	Fit Bumper Reinforcement			
1010	991468	Fit Bumper Sponge			
1013	991427	Fit Bumper Protector			
1014	991301	Fit Bumper Moulding			
1015	991407	Fit Bumper Lower Spoiler			
1050	991821	Fit RH Headlamp Assy			
1072	995089	Fit RH Side Lamp			
1105	995071	Fit RH Fender			
1107	991744	Fit RH Fender Lamp			
1108	991752	Fit RH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door			
1351	993284	Rear RH Door Protector	CUT	✓	
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993279	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door <del>Inner</del> <del>Panel</del> Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1371	994070	Roof Top Panel			
1372	994098	Roof Top Moulding			
1373	994085	Roof Top Air-bag			
1374	994084	Roof Top Air-bag Sensor			
1375	994083	Roof Top Air-bag Control Unit			
1376	992958	Rear Bumper			
1377	992976	Rear Bumper Bracket			
1378	993068	Rear Bumper Side Retainer			
1379	993045	Rear Bumper Reinforcement			
1381	993077	Rear Bumper Sponge			
1382	993040	Rear Bumper Protector			
1383	993026	Rear Bumper Moulding			
1384	993023	Rear Bumper Lower Spoiler			
1385	995116	Rear RH Taillamp			
1388	993456	Rear RH Fender			
1389	993450	Rear RH Fender Protector	SCR	R	
1390	990247	Sticker			
		Rear RH wheel Rim	CUT	✓	

No of Items:

Assessor:

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Jun 2018 <a href="#">Edit Reg</a>		30 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	LCRF Pte Ltd, Co. Reg. No.: 201624597K		
Main Claimant:	MASRUPEE BIN SULAIMAN, ID: S1533591B		
Vehicle Reg. No.:	SGQ7328L	Date of Loss:	27/05/2018 03:00 - :59 [136 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2156222536SG	Policy/Cover Note No.:	0999994796 (Comprehensive)
Vehicle Reg. No. (Insured):	SLP2532S	Policy No. (Claimant):	
		Excess:	
Repairer:	LUSH AUTOMOTIVE PTE LTD (HQ) No. 8 Kaki Bukit Avenue 4,, #03-47 Premier@Kaki Bukit,, 415875 Kaki Bukit - Tel: 86662345		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Olea, Maricel] Maricel.Olea@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/06/2018]		
Claimant's Solicitor:	EAST ASIA LAW CORPORATION - Tel: 63232565		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>AIG_SG (05/06/2018): Request To Upload TP GIA Report</li> </ul>			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

## Claim Documents

\*SGQ7328L (2156222536SG)  
 [SLP2532S]  
 TP  
 MASRUPEE BIN SULAIMAN  
 May 27 2018 3:00AM  
 [LCRF Pte Ltd]  
 LUSH AUTOMOTIVE PTE LTD

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			View	View in Browser
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
2	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
3	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
4	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
5	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
6	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
7	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
8	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
9	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
10	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
11	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
12	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
13	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
14	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
15	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
16	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
17	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
18	01/06/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
19	01/06/18 15:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
20	01/06/18 15:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
21	01/06/18 15:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
22	01/06/18 15:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
23	01/06/18 15:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
24	01/06/18 15:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
25	01/06/18 15:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
26	01/06/18 15:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
27	01/06/18 15:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	01/06/18 15:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	01/06/18 15:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	01/06/18 15:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	01/06/18 15:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	01/06/18 15:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	07/06/18 12:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
34	07/06/18 12:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
35	07/06/18 12:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
36	07/06/18 12:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
37	07/06/18 12:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
38	07/06/18 12:12	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
39	07/06/18 12:12	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
40	07/06/18 12:12	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
41	07/06/18 12:12	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
42	07/06/18 12:12	Photo After Spray		Load JPG <input checked="" type="checkbox"/>

  

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	05/06/18 12:49	OI GIA REPORT		Load PDF <input checked="" type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG18009894/AZ4D3E2  
**Date:** 08/06/2018

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994796
<b>Claimant Vehicle No :</b> SGQ7328L	<b>Insured Vehicle No :</b>	SLP2532S
Date of Loss: 27/05/2018	Nature of Claim: TP	Claim No: 2156222536SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGQ7328L</b>	Engine No:	1ZZ2724757
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100332112
Reg. Date:	23/01/2007 (Man. Year: 2006)	Odometer:	164992 km
Colour:	Silver		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	30/05/2018	LUSH AUTOMOTIVE PTE LTD (HQ) No. 8 Kaki Bukit Avenue 4., #03-47 Premier@Kaki Bukit, Singapore 415875
Date Inspected:	31/05/2018 Inspected At:	
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING

**Manager:** Ho Zhao Tian

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ROCKER PANEL RH REAR	Cut	0.00 F	*- F
2	1		*REAR RH DOOR	Cut	0.00 F	*- F
3	1		*REAR RH FENDER	Repair	0.00 F	*- F
4	1		*REAR RH WHEEL RIM	Cut	0.00 F	*- F
<b>Total Parts (S\$)</b>					<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >