

COMFORTDELGRO ENGINEERING PTE LTD

Date: 30.05.2018

REPAIR ESTIMATE

Time: 15:57:29

Page: 1

China Taiping (P)

TS

COMPANY: THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS: COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305166339
 REGN NO : SHD3672A
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 07.09.2017
 DATE/TIME IN : 30.05.2018 11:45
 ACCIDENT DATE : 30.05.2018

LKK - Kalvin

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 03-01-0302-2020-G REAR WHEEL RIM RH 1 1,570.60 25.00 1,177.95 ✓

hanged

0002 28-01-0103-2013-A REAR DOOR APPS STICKER RH 1 80.00 ~~250~~ 80.00 ✓

me

SUB-TOTAL : 1,257.95

JOB NATURE

0000 L PANEL BEATING
 0001 23-502 SPRAYPAINT ON AFFECTED AREA
 0002 20-00 TUFF COAT ON AFFECTED PARTS.
 0003 L REAR WHEEL ALIGNMENT

~~560.00~~ 400
~~800.00~~ 720
~~40.00~~ X 17
~~120.00~~ X 11

SUB-TOTAL : 1,520.00

TOTAL : 2,777.95

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

Kalvin 11/05/18
 30/5/18 1600 L.
 2 By
 PIP
 After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting;
- To display damaged part(s) during resurvey;
- Parts prices are subject to confirmation;
- Third party survey is on a "Without Prejudice" basis;
- No illegal modification(s) is allowed;
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
 Signature:
 Date: