

Satima

CC3 / MG1800 9901, Kpa3 9

LKK IDAC

Surveyor:

Kalin

DOI:

ASSIGNMENT

31/05/2018

Date / Time:

31/05/2018

Registered in Merimen:

31/05/2018

Pre-assign / CCU / FTE

SLK 9010 L



Insured Vehicle No.:

Ngui Chiao Yun

Claim No.:

210044324

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

93837388

Make / Model:

1. AHD

Excess Sec II :SS

D.O.A.:

30/05/2018

Place of Accident:

TW Boon Lay

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SH 8243 X



INSRS:

WSP:

Tel:

Liability:

RMKS:

CDL6 69423



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

1/6/18

SH 8243 X - X: SLK 9010 L - X

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

24/4/18

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

FIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

11/6/18 - Email to Satima: Request for OI video.

20/6/18 - OI video ✓ Merimen

31/8/18 @ 12.30pm Called OI, Mr Ngui. Not pick up.

4/9/18 @ 3.30pm Called OI, Mr Ngui. Not pick up.

6/9/18 - Sent letter to OI.

24/11/18 - DV sent

26/12/18 - File -> Merimen to close

PRELIMINARY ADVICE	Date/Time:	Sent By:	Post-Repair Photos:	<input type="checkbox"/>	<input type="checkbox"/>
FINALIZATION	Date/Time:	Confirm with:	Others:	<input type="checkbox"/>	<input type="checkbox"/>
Repair Cost:	\$S	() days) Reduction:	%	Email <input type="checkbox"/>	Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 24/12/18	Confirm with: Cecilia	Confirm by:	Email <input type="checkbox"/>	Call <input type="checkbox"/>
Final Liability:	% 50	(Agreed / Assessed) BOLA S/N No.:	19.	NO or B 28, Ass. Lia:	
Repair Cost:	\$S 4600.14	\$S 23w.07			
Loss of Rental (LOR):	\$S 313.50	\$S 156.75 (2.5 days)	X \$125.40		
Loss of Use (LOU):	\$S -	(\$ - x - days)			
Loss of Income (LOI):	\$S 125	\$S 62.50 (\$ 50 x 2.5 days)			
LOR only <input type="checkbox"/>	LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LOI <input checked="" type="checkbox"/>	[Tick only one]	
GIA/LTA Search	\$S 7.49				
Medical:	\$S -				
Disbursement:	\$S -	(e.g. Tow/Independent)			
Legal Cost	\$S -				
Total:	\$S 2526.81	Global Sum \$S:	2520.00		
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/>	Call <input type="checkbox"/>	
Payee 1:	\$S 2520.00	Name 1:	Comfort Dergro Engineering Pte Ltd		
Payee 2: (Strike if N.A.)	\$S -	Name 2:			
Payee 3: (Strike if N.A.)	\$S -	Name 3:			

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format: P

3) Survey fee: \$320 + \$20

08/11/13

Q. inv. Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimate/ Cost: _____

OD / ITP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop/ m/s _____

of _____

Insured: _____

Policy No _____

Claims No _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / .REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH 8243X Yr Regn: 15 Jun, 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / T~~r~~ / Prime Mover /
Truck / Trailer or

Make: Toyota Prius c.c. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 197363 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 5TPKBJF450355855

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inop~~r~~ / Jammed / Leaked / Burnt or

Brake: Inop~~r~~ / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / RIm or

Tyre Size; F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wedsite

Front 7 mm Rear 7 mm

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 20/5/18 D.O.I. 3/5/18

Survey held at CPGE (Layang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PIP # 4299.20 (Red # 803.23 / 177.1) AZK PIC

Date/Time, File Pass to? : Prell. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:	_____
Transportation:	_____
_____ \$ + RS _____	_____
Photos	_____
Others	_____
TOTAL	_____

member of COMFORTDELGRO

Date/Time: 31.05.2018 15:00 Page : 1

Job: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO 305167696

CUSTOMER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (C) (P)	REGN NO: SH 8243X	MILEAGE
	MAKE: TOYOTA	FUEL E.....1/2.....F
	MODEL: PRIUS HYBRID(G4)30.0	DATE/TIME IN 05.2018 21:20
	YR OF MANU: 15.06.2017	TARGET DATE
	CHASSIS CODE: JTDKB3FU503558553	COMPLETION DATE/TIME:

AIG

Customer Date: 30.05.2018
 Duration: 3P 30.06.2018

JOB DESCRIPTION

NO	LABOR CODE	DESCRIPTION
----	------------	-------------

WORKED & PASSED OUT BY: _____

 SERVICE ADVISOR

 CUSTOMER'S SIGNATURE

Recognition Slip

No.: SH 8243X LKE

 Signature/Date

Returned to Service Reception upon collection

Exit Pass

Vehicle No.: SH 8243X

 Name of Service Advisor Date

To be kept by Security Guard

COMFORTDELGRO ENGINEERING

Our Job Ref No 305167696
Date : 11/06/18

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax : _____
Attn : Mr KALVIN ANG
Vehicle Reg No. SH8243X CTPL 30.05.18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: AIG — SLK9010L
- The finalized amount shall be:

(a) Spare Parts after List discount	<u>\$3,679.20</u>
(b) Labour Charges	<u>\$620.00</u>
Total for Part-By-Part Repair Cost	<u>\$4,299.20</u>
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	<u> </u>
Final Lumpsum Repair cost	<u> </u>

- Estimated normal period for repairs: 2 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
- Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature : 
Name : Kati
Date : 11/6/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305167696
 REGN NO : SH 8243X
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 15.06.2017
 DATE/TIME IN : 30.05.2018 21:20
 ACCIDENT DATE : 30.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-4891-G	PRIG4 LAMP ASSY FOG LH	1	910.20	25.00	682.65
0002	04-01-0302-2292-G	PRIG4 COVER FRONT BUMPER	1	495.50	25.00	371.62
0003	04-01-0302-2270-G	PRIG4 PLATE-BACK DOOR NAM	1	86.50	25.00	64.87
0004	04-01-0302-2815-G	PRIG4 UNIT ASSY HEADLAMP	1	3,413.40	25.00	2,560.05

SUB-TOTAL : 3,679.19

JOB NATURE

0000	L	PANEL BEATING				200.00
0001	23-502	SPRAYPAINT ON AFFECTED AREA				400.00
0002	17-01	CHECK ALL LIGHTING				20.00

SUB-TOTAL : 620.00

TOTAL : 4,299.19

 MVA NAME & SIGNATURE
 DATE :

 SURVEYOR NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO : SH 8243X

MAKE :

MODEL : TOYOTA PRIUS

LKR/kawin Pby

31/5/2018 14:58

Like AIG

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
LAMP ASSY, FOG, LH <i>int</i>			\$ 920.00 <i>910.20</i>
FRONT BUMPER COVER <i>Whit</i>			\$ 496.50
FRONT BUMPER REINFORCEMENT <i>sun</i>			\$ 691.50
FRONT BUMPER REINFORCEMENT ABSORBER <i>sun</i>			\$ 115.70
FRONT BUMPER SPONGE <i>sun</i>			\$ 78.80
UNIT ASSY, HEADLAMP, LH (LED) <i>sun</i>			\$ 3,413.40
<i>Front LH fender x repair</i>			
<i>Front Fender Emblem LH sun \$86.50</i>			
SUB TOTAL			\$ 5,709.90
LESS 25%			\$ 1,427.48
DISCOUNTED TOTAL			\$ 4,282.43
LABOUR CHARGE			
Panel Beating			\$ 350.00 <i>200</i>
Spray Painting Charge- Bumper/Fender			\$ 500.00 <i>400</i>
Wiring Charge			\$ 50.00 <i>20</i>
TOTAL LABOUR			\$ 900.00
ESTIMATE TOTAL			\$ 5,182.43

Kahng Uen
31/5/18 152042
2/5/18
P/P
Before Paint & Ue

LKR Auto Consultants hence notify the Repairer of the following:

- To resurvey before later party painting
- To resurvey damaged part during resurvey
- Parts prices are subject to resurvey
- Third party survey is on a "Without Prejudice" basis
- No legal proceedings are allowed
- Supplementary items may be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 11 June 2018 4:03 PM
To: Syed-Yusoff, Saliha
Subject: <Request for OI Video> Your Ref: 45346261875G *Our Ref: CC3/AIG18009901/K1pa3 [ACCIDENT INVOLVING SLK 9010L(OI) & SH 8243X(TP) ON 30/05/2018]

Your Ref: **45346261875G**
Our Ref: CC3/AIG18009901/K1pa3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLK 9010L(OI) & SH 8243X(TP) ON 30/05/2018

We refer to the above matter.

Kindly assist to upload OI's video in Merimen for our viewing.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>
Sent: Wednesday, 20 June 2018 5:33 PM
To: Hsiao Tong (LKKAuto)
Subject: RE: <Request for OI Video> Your Ref: 4534626187SG *Our Ref: CC3/AIG18009901/K1pa3 [ACCIDENT INVOLVING SLK 9010L(OI) & SH 8243X(TP) ON 30/05/2018]

Dear Hsiao Tong,

please check in merimen

thank you

PLEASE NOTE THAT CONTENTS OF THIS EMAIL SHOULD NOT BE CONSTRUED AS ANY ADMISSION OF LIABILITY ON THE PART OF OUR INSURED AND/OR INSURERS. WE HEREBY MAINTAIN FULL RESERVATION OF RIGHTS AND ALL DEFENCES AVAILABLE TO US

Saliha Syed Yusoff
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1917 | Fax +(65) 68357416

saliha.syed-yusoff@aig.com | www.aig.com.sg

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]
Sent: 11 June 2018 16:03
To: Syed-Yusoff, Saliha
Subject: <Request for OI Video> Your Ref: 4534626187SG *Our Ref: CC3/AIG18009901/K1pa3 [ACCIDENT INVOLVING SLK 9010L(OI) & SH 8243X(TP) ON 30/05/2018]

Your Ref: **45346261875G**

Our Ref: CC3/AIG18009901/K1pa3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLK 9010L(OI) & SH 8243X(TP) ON 30/05/2018

We refer to the above matter.

Kindly assist to upload OI's video in Merimen for our viewing.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 5 December 2018 11:04 AM
To: cecilialee@sparkcarcare.com; Jasmine Cai Yuyan
Subject: <Request for Video Footage> Your Ref: T 0518/ SH 8243X/ CL(st) *Our Ref: CC3/AIG18009901/K1pa3 [ACCIDENT INVOLVING SLK 9010L(AIG) & SH 8243X ON 30/05/2018]
Attachments: Statement of SLK 9010L.pdf

Your Ref: T 0518/ SH 8243X/ CL(st)
Our Ref: CC3/AIG18009901/K1pa3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SLK 9010L(AIG) & SH 8243X ON 30/05/2018

We refer to the above matter.

Please be informed that our insured driver reported that he was driving straight, your client changed lane and hit onto his car. Attached is a copy of report for your easy reference.

We would like to request a copy of your client's video footage as stated in his GIA report for our necessary action.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Our Ref : T 0518 / SH 8243X /CL(st)
 Your Ref:
 Date : 3-Jul-18

CDGE Taxi Claims Dept
 59 Loyang Drive 4th Floor
 Singapore 508969

ComfortDelGro Engineering Pte Ltd
 205 Braddell Road Singapore 579701
 Mobile: +65 6383 6280
 Facsimile: +65 6280 9755
 www.cdge.com.sg

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS Building
78 Shenton Way
#07-16
Singapore 079120

Attn : Motor Claims Department WITHOUT PREJUDICE

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SH 8243X YOUR INSURED SLK9010L
 AND OTHER _____ ON 30.05.18**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : SH 8243X which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving SLK9010L we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 4,600.14
2	<u>2.5</u> days Loss of Rental @ \$ 125.40 per day	\$ 313.50
3	Survey Report Fees (<i>Surveyed by M/s LKK</i>)	\$ -
4	GIA / LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transporation	\$ -
Sub Total :		\$ 4,921.13

HIRER'S CLAIM

7	<u>2.5</u> days Loss of Income @ \$ 80.00 per days	\$ 200.00
Total Claims :		\$ 5,121.13

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 4 pcs.
- b) LTA search slip/s of : SLK9010L
- c) GIA / Police report/s of : SH 8243X
- d) Letter of authority from owner / hirer / operator
 - (X) Photograph/s of Accident Scene () Certificate of Insurance
 - () Witness statement/s (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully
 Cecilia Lee

Executive
 CDGE Claims Department
 Tel : 6214 8354 Fax: 6214 1843 Email : cecilialee@sparkcarcare.com

This is a computer generated letter. No signature is required.

Hsiao Tong (LKKAuto)

From: Cecilia Lee Peng Geok <cecilialee@sparkcarcare.com>
Sent: Wednesday, 5 December 2018 2:49 PM
To: Hsiao Tong (LKKAuto); Jasmine Cai Yuyan
Subject: Re: <Request for Video Footage> Your Ref: T 0518/ SH 8243X/ CL(st) *Our Ref: CC3/AIG18009901/K1pa3 [ACCIDENT INVOLVING SLK 9010L(AIG) & SH 8243X ON 30/05/2018]

Without Prejudice

Dear Hsiao Tong

Your insured reported he filtered to right lane, which is consistent with our taxi's report.

Taxi insurer had settled AIG's claim at 50/50. Therefore, we are seeking for 50/50 settlement too. Please revert with your offer soon.

Thank you.

Best Regards
Cecilia Lee
Claims Department | ComfortDelGro Engineering Pte Ltd
Off: 6214 8354 | Fax: 6214 1843

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Wednesday, 5 December 2018 11:04 AM
To: Cecilia Lee Peng Geok; Jasmine Cai Yuyan
Subject: <Request for Video Footage> Your Ref: T 0518/ SH 8243X/ CL(st) *Our Ref: CC3/AIG18009901/K1pa3 [ACCIDENT INVOLVING SLK 9010L(AIG) & SH 8243X ON 30/05/2018]

Your Ref: **T 0518/ SH 8243X/ CL(st)**
Our Ref: CC3/AIG18009901/K1pa3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SLK 9010L(AIG) & SH 8243X ON 30/05/2018

We refer to the above matter.

Please be informed that our insured driver reported that he was driving straight, your client changed lane and hit onto his car. Attached is a copy of report for your easy reference.

We would like to request a copy of your client's video footage as stated in his GIA report for our necessary action.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 21 December 2018 2:53 PM
To: Cecilia Lee Peng Geok; Jasmine Cai Yuyan
Subject: RE: <Request for Video Footage> Your Ref: T 0518/ SH 8243X/ CL(st) *Our Ref: CC3/AIG18009901/K1pa3 [ACCIDENT INVOLVING SLK 9010L(AIG) & SH 8243X ON 30/05/2018]

Without Prejudice

Hi Cecilia,

We refer to the above matter.

We propose settlement at a global sum of \$2,520.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cecilia Lee Peng Geok <cecilialee@sparkcarcare.com>
Sent: Wednesday, 5 December 2018 2:49 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Jasmine Cai Yuyan <jasminecai@cedge.com.sg>
Subject: Re: <Request for Video Footage> Your Ref: T 0518/ SH 8243X/ CL(st) *Our Ref: CC3/AIG18009901/K1pa3 [ACCIDENT INVOLVING SLK 9010L(AIG) & SH 8243X ON 30/05/2018]

Without Prejudice

Dear Hsiao Tong

Your insured reported he filtered to right lane, which is consistent with our taxi's report.

Taxi insurer had settled AIG's claim at 50/50. Therefore, we are seeking for 50/50 settlement too. Please revert with your offer soon.

Hsiao Tong (LKKAuto)

From: Cecilia Lee Peng Geok <cecilialee@sparkcarcare.com>
Sent: Monday, 24 December 2018 9:37 AM
To: Hsiao Tong (LKKAuto); Jasmine Cai Yuyan
Subject: Re: <Request for Video Footage> Your Ref: T 0518/ SH 8243X/ CL(st) *Our Ref: CC3/AIG18009901/K1pa3 [ACCIDENT INVOLVING SLK 9010L(AIG) & SH 8243X ON 30/05/2018]

Without Prejudice

Dear Sir/Madam

Strictly without admission of any liability and solely for quick amicable settlement, we confirm settlement at \$2,520.00 for property damage only. Please note that the contents of this document apply to vehicle damages only. It is condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/driver/claimant.

Please forward Discharge Voucher for execution and your cheque made payable to : COMFORTDELGRO ENGINEERING PTE LTD

Thank you.

Best Regards
Cecilia Lee
Claims Department | ComfortDelGro Engineering Pte Ltd
Off: 6214 8354 | Fax: 6214 1843

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Friday, 21 December 2018 2:53 PM
To: Cecilia Lee Peng Geok; Jasmine Cai Yuyan
Subject: RE: <Request for Video Footage> Your Ref: T 0518/ SH 8243X/ CL(st) *Our Ref: CC3/AIG18009901/K1pa3 [ACCIDENT INVOLVING SLK 9010L(AIG) & SH 8243X ON 30/05/2018]

Without Prejudice

Hi Cecilia,

We refer to the above matter.

We propose settlement at a global sum of \$2,520.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18009901/K1pa3

06 SEPT 2018

NGU CHIAO YUN
BLK 508A WELLINGTON CIRCLE
#05-41
SINGAPORE 751508

Dear Sir/Madam,

**ACCIDENT INVOLVING SLK 9010L & SH 8243X ALONG/AT JALAN BOON LAY
TOWARDS JURONG ISLAND ON 30/05/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SH 8243X against your motor insurance policy.

Based on all the available information on hand, we are of the view that the case would be settled at equal liability as both parties were changing lane. Under Motor Accident Guide, both vehicles should exercise caution when changing lanes. Therefore, we will proceed to negotiate for an amicable settlement with the Third Party.

If you have evidence/information to proof that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 17/09/2018, after we shall proceed with negotiation with Third Party claimant on the without prejudice basis and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
Email: chewht@lkkauto.com

*e.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING ALONG **TOYOTA PRIUS SH8243X , SLK9010L** **ON 30-May-18 17:20**
JALAN BOON LAY .
(NEXT X JUNCTION INT'L RD)
Necor

I / We **HAHADI BIN MANAS** (Hirer) NRIC No.: **S6933142D**

and/or (Relief) NRIC No.:

Taxi Number **SH8243X**

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date **31-May-2018**

Name of Hirer **HAHADI BIN MANAS**

Hirer NRIC **S6933142D**

Signature :



Address **180A BOON LAY DRIVE #12-680**
641180

Contact No. **93235066**

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **COMFORTDELGRO ENGINEERING PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **SS2,520.00** (Global Sum) for vehicle no. **SH 8243X** that was damaged pursuant to the accident which occurred on **30/05/2018** (date) along **JALAN BOON LAY** (location) involving vehicle no/s **SLK 9010L**.

This is pursuant to the inspection conducted on **31/05/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **COMFORT TRANSPORTATION PTE LTD** ("the third party claimant") of vehicle no. **SH 8243X** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SH 8243X** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this _____ (day) of **26 DEC 2018** (month) **20** (year)



Signed by appointed surveyor

CLAIMS DEPARTMENT
COMFORTDELGRO ENGINEERING PTE LTD
205 BRADDELL ROAD
SINGAPORE 679701

Signed by "the workshop" (with chop)

Please forward your cheque made payable to:
COMFORTDELGRO ENGINEERING PTE LTD

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

A member of **COMFORTDELGRO**

GST REG. NO. M2-8921817-3

TAX INVOICE

(COMPANY REG. NO.): 199506048W
Page: 1

8010004
ATG ASIA PACIFIC INSURANCE PTE LTD
#08-16 78 SHENTON WAY, CHARTIS BUILD
SINGAPORE SG 079120
CONTACT NO: 64193000 3225094

VEHICLE NO: SH 8243X
MAKE: TOYOTA
MODEL: PRIUS HYBRID(G4)
DATE OF REG: 15.06.2017
CHASSIS CODE: JTDKR3PU1503558553
INV. NO/DATE: 91381202 30.06.2018
JOB NO.: 305167696
DIAGNOSTIC READING
DATE/TIME IN: 30.05.2018 21:20

Description : 3P 30.05.2018

S/No	Part No.	Qty	Unit Price	Discount	Net
PART REQUISITION					
0001	04-01-0302-4891	1	910.20	25.00	682.65
0002	04-01-0302-2292	1	495.50	25.00	371.62
0003	04-01-0302-2270	1	86.51	25.00	64.88
0004	04-01-0302-2815	1	3,413.40	25.00	2,560.05
SUB-TOTAL				3,679.20	

JOB NATURE

0001	L	PANEL HEATING	200.00	200.00
0002	23-502	SPRAYPAINT ON AFFECTED AREA	400.00	400.00
0003	17-01	CHECK ALL LIGHTING	20.00	20.00
SUB-TOTAL				620.00

1. WEH/3I TAKING ALL RESPONSIBLE SITUATIONS WITHOUT ANY COST OR ADDITIONAL EXPENSES TO THE COMPANY. I ACCEPTED THE COMPANY'S RESPONSIBILITY FOR DAMAGE OR SYSTEM PROPERTIES, INCLUDING, TO ALL WORKERS AND VISITORS AND WITHOUT THE COMPANY OWNERS RISK.
2. CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL NOTIFY THE COMPANY OF ANY DAMAGE OR NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS IMMEDIATELY. THE VEHICLE WILL BE ACCEPTED AS IS AND THE COMPANY IS NOT RESPONSIBLE FOR DAMAGE TO THE VEHICLE.
3. INTEREST OF 1% PER MONTH SHALL BE CHARGED ON A DAILY BASIS FROM THE DATE OF DELIVERY TO THE CUSTOMER UNTIL THE COMPANY IS FULLY PAID BY THE CUSTOMER AND NOT PAID ON THE DATE OF DELIVERY TO THE CUSTOMER FROM THE DATE OF DELIVERY TO THE CUSTOMER.
4. PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON DELIVERY AND ADVISE THE COMPANY OF ANY DAMAGE TO THE VEHICLE WITHIN 24 HOURS OF RECEIPT. IF THE COMPANY DOES NOT NOTIFY YOU OF ANY DAMAGE TO THE VEHICLE WITHIN 24 HOURS OF RECEIPT, IT IS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd
A member of **COMFORTDELGRO**

Head Office:
205 Braddell Road
Singapore 379701

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHO No.
8010004	91381202	4,600.14	

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT18050895

Date: 12 June 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 30/05/2018 @ 17:20 hrs
ALONG JALAN BOON LAY .
INVOLVING SLK9010L

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SH8243X** (the "Taxi"). The Taxi was hired to **HAHADI BIN MANAS IC NO S6933142D** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$125.40** per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

DATE	NAME OF DRIVER	MILEAGE READING		MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)		DATE	NAI
		FROM	TO		FROM	TO		
27/05/18	SH8243X Raman (Sun)	1955	587	229	1000	1800		
27/05/18	Raman (Sun)	1958	84	297	1805	0600		
28/05/18	Raman (Mon)	1961	06	287	0600	1800		
28/05/18	Raman (Mon)	1963	96	290	1800	0715		
29/05/18	Raman (Tues)	1966	85	288	0730	1715		
29/05/18	Raman (Tues)	1969	36	252	1800	0615		
30/05/18	Raman (Wed)	1973	83	446	0645	715		
30/05/18	Accident	Repair		Layang	2120	—		
01/06/18	Repair	41111111111111111111		—	—	1530		

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SLK9010L	30 May 2018 / 17:20:00	Successful	A04	AIG ASIA PACIFIC INSURANCE PTE. LTD.

Previous

OK

SH 8-43X

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 May 2018 Edit Reg		31 May 2018 00:00 Edit Adj Rpt	S\$4,299.20 Edit Estimates	S\$4,299.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Ngu Chiao Yun , ID: 57279268H								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303621R								
Vehicle Reg. No.:	SH8243X	Date of Loss:	30/05/2018 17:00 - :59 [11 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4534626187SG	Policy/Cover Note No.:	2100499324 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLK9010L	Policy No. (Claimant):	MCOM0015						
		Excess:							
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 11/06/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (01/06/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SH8243X (4534626187SG)
[SLK9010L]
TP
COMFORT TRANSPORTATION PTE LTD
May 30 2018 5:00PM
[Ngu Chiao Yun]
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Video															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print				
1	20/06/18 17:32	Video - Accident From: OD - Reg. No: SLK9010L, Claimant: NGU CHIAO YUN											Load AVI				
Letters/Correspondences															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	(Draft)	Third Party Express Settlement - Payment Breakdown											Edit				
Photos/Images															3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
2	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
3	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
4	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
5	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
6	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
7	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
8	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
9	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
10	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
11	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
12	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
13	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
14	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
15	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
16	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
17	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
18	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
19	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
20	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
21	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
22	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
23	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
24	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
25	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
26	01/06/18 08:07	General View											Load JPG	<input checked="" type="checkbox"/>			
27	04/06/18 17:36	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
28	04/06/18 17:36	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
29	04/06/18 17:36	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			
30	04/06/18 17:36	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
31	04/06/18 17:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	04/06/18 17:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/06/18 12:38	TP GIA REPORT	 Load PDF	
2	07/06/18 09:30	TP ESTIMATE - MARKED	 Load PDF	
3	28/12/18 12:02	WORKSHOP INVOICE	 Load PDF	
4	28/12/18 12:02	AUTHORISATION TO ACT FORM	 Load PDF	
5	28/12/18 12:02	Release Voucher	 Load PDF	
6	28/12/18 12:02	RENTAL RECEIPT	 Load PDF	
7	28/12/18 12:02	RENTAL MILEAGE	 Load PDF	
8	28/12/18 12:02	LTA SEARCH	 Load PDF	
9	28/12/18 12:02	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	01/06/18 10:52	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLK9010L (Insd veh)	Model:	TOYOTA PRIUS HYBRID 1.8 CVT (A)
	SH8243X (TP veh)		
Date of Accident:	30/05/2018		

Global Sum Settlement	: [X] Yes	[] No
Repair Estimate	: \$	5,618.62
Final Repair Cost	: \$	2,520.00
Loss of Use	: \$	2.50 days at \$50.00 per day
Rental (if any)	: \$	2.50 days
LTA / GIA Search Fee	: \$	
Others:	: \$	
	: \$	
Final Settlement Sum (Global Sum)	: \$	2,520.00
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)		
A) For Non GIA Registered Workshop: Agreed Liability _____ (%)		
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ 50 _____ (%) Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks _____		

Payment Instruction: Payee's Breakdown		
1)	ComfortDelGro Engineering Pte Ltd	: \$ 2,520.00
2)		: \$
3)		: \$
4)		: \$
5)		: \$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

28 Dec
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18009901/K1PA3Q2
Date: 28/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100499324
Claimant Vehicle No : SH8243X	Insured Vehicle No :	SLK9010L
Date of Loss: 30/05/2018	Nature of Claim: TP	Claim No: 4534626187SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8243X	Engine No:	2ZRS047658
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU503558553
Reg. Date:	15/06/2017 (Man. Year: 2017)	Odometer:	197383 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,351.05	3,679.20	671.85	15.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	620.00	280.00	31.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,251.05	4,299.20	951.85	18.13
+ GST 7.00/7.00% (S\$)	367.57	300.94	66.63	18.13
Nett Amount (S\$)	5,618.62	4,600.14	1,018.48	18.13
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (2.5 x S\$125.40/day) (S\$)		313.50		
		(S\$) 5,038.64		
Liabile Amount (50.00%) (S\$)		2,519.32		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,526.81		
Global Sum Settlement (S\$)		2,520.00		

INSPECTION

Date of Assignment: 31/05/2018

Date Inspected: 31/05/2018 Inspected At: ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY ,FOG ,LH	Cut	920.00 FL	*910.20 FL
2	1		*FRONT BUMPER COVER	Deformed	495.50 FL	*495.50 FL
3	1		*FRONT BUMPER REINFORCEMENT	Serviceable	691.50 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT ABSORBER	Serviceable	115.70 FL	*- FL
5	1		*FRONT BUMPER SPONGE	Serviceable	78.80 FL	*- FL
6	1		*UNIT ASSY ,HEADLAMP ,LH (LED)	Cracked	3,413.40 FL	*3,413.40 FL
7	1		*FRONT LH FENDER (NPA)	Repair	0.00 FL	*- FL
8	1		*FRONT FENDER EMBLEM LH	Necessary	86.50 FL	*86.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,801.40	4,905.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,450.35	1,226.40
Total Parts (\$\$)	4,351.05	3,679.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	350.00	200.00
2	SPRAY PAINTING CHARGE-BUMPER /FENDER	New	500.00	400.00
3	WIRING CHARGE	New	50.00	20.00
Gross Labour Cost (\$\$)			900.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >