

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	6	REAR WINDSCREEN SEALANT	Reviewing	46	NECESSARY	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC OUNT%	SALV AGE%	PART PRICE/NET
<input type="checkbox"/>	11	10			BOOT LID TRIMBOARD CLIPS			Serviceable	0		20		0
<input type="checkbox"/>	12	1			REAR BUMPER			Deformed	576.4		20		462.72
<input type="checkbox"/>	13	1			REAR BUMPER REINFORCEMENT			Serviceable	0		20		0
<input type="checkbox"/>	14	10			REAR BUMPER CLIP			Necessary	2.2		20		17.6
<input type="checkbox"/>	15	1			REAR BUMPER SPONGE			Serviceable	0		20		0
<input type="checkbox"/>	16	1			REAR BUMPER UNDER COVER			Serviceable	0		20		0
<input type="checkbox"/>	17	1			REAR BUMPER PROTECTOR (RH)			Cracked	38		20		30.4
<input type="checkbox"/>	18	1			TAIL LAMP (RH)			Cracked	344		20		275.2
<input type="checkbox"/>	19	1			REAR PANEL			Repair	0		20		0
<input type="checkbox"/>	20	1			REAR PANEL GARNISH			Serviceable	0		20		0
<input type="checkbox"/>	21	1			REAR FENDER (RH)			Dented	1935.9		20		1548.72
<input type="checkbox"/>	22	1			REAR FENDER INNER LINING (RH)			Serviceable	0		20		0
<input type="checkbox"/>	23	1			REAR WINDSCREEN MOULDING			Necessary	60		20		48
Labour													
EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT					

Yes No

Detailed Assessment

Inspection Date *

05/31/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Front Tyre Size

215/60R16

Spare wheel

Rear Tyre Size

215/60R16

FNOL INFORMATI... BLK 166A YUNG KUANG ROAD, #15-10,
611166, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Female

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S7863325E

POLICY INFORMAT... TPVD HYUNDAI

ASSESSMENT INFO... HYUNDAI

CATEGORY Model

POLICY INFORMAT... SONATA-2.0(A)

ASSESSMENT INFO... SONATA NF 2.0 CRDI AT ABS 2WD 4D

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT...

ASSESSMENT INFO... KMHET41VMB810274

CATEGORY Date of Birth

FNOL INFORMATI... April 9, 1978

POST SURVEY INF... mm/dd/yyyy



CATEGORY Age

FNOL INFORMATI... 40

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

Pending verification -
Direct Settlement

Claim Handler

CHAN Kian Chuan
 6568804269
 kianchuan.chan@axa.com.sg

Messages Invoices History Documents
 Assessment Metrics Notes

Additional Instructions

NON-REPORT

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	7/11/18 1:20 PM	3500	3500	Open	<input type="button" value="Share"/>	<input type="button" value="Clone"/>
NIKAM Santosh Pandurang	5/28/18 3:46 PM	4376.08	4376.08	Open	<input type="button" value="Share"/>	<input type="button" value="Clone"/>

Pending verification -
Direct Settlement

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

Messages Invoices History Documents

Assessment Metrics Notes

NON-REPORT

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
LETTER TO OI.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 26, 2018
TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	June 5, 2018