

ASS. REC. BY:

REF: CS3/AIG18009908/A24d3et

Special Instruction:

Surveyor
Menmen

Adrian

ASSIGNMENT (Office)

From (Person):

ehin la ying

of

AIG

Date/Time:

31/5/18 @ 11:03am

Estimated Cost:

Bill to:

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLR143J

Insured:

SLB 8227H

at Workshop m/s

N-51 Automotive

Tel:

6482 0051

of

Blk 2 Kaki Bukit Ave # 01-17/18

Policy No.:

Claim No.:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/05/2018

CA / REV / REP. / REV 24 HRS (w/p)

Date/Time:

11:17am @ 31/5/18

Person Contacted:

Melody

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (x) Estimate	
	SLR143J - NA / INC18009773/24	DOA: 30/5/18
	SLB 8227H - NA / INC18009773/24	DOA: 30/5/18
1/6/18	Dismantled	
5/6/18	After Repair	

ASS. REC. BY: Adrian King

REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04.885 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLR143J Yr Regn: 2014, Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Golf c.c. 197

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 48830 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW222AU2EW38460

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 3/05/18

Survey held at Twickenham

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP ALG PRS</u>
<u>1/6/18</u>	<u>submit DAR report</u>
RECEIVED 01 JUN 2018	

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Report Format :

Lump Sum / I.B.I.: (\$ _____)

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: 180

Transportation: _____

S + RS. _____

Photos _____

Others 20

TOTAL 200

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SLB8227H AND SLR143J ON 30/05/2018**

From: Chin, Lee-Ying

To: assignments@lkkauto.com, Admin A

Cc: Fong, Andy-SY

Sent: 31/5/2018 11:03:48 AM

Attachments:  [30052018173740-0001.pdf](#)  [31052018095109.pdf](#)  [31052018105238.pdf](#)

Hi LKK,

Kindly assist to survey, vehicle is in.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18009908/Az4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 01-06-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLB 8227H	Veh. Inspected	SLR 143J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	01/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	30/05/2018	Inspection Date	31/05/2018
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/05/2018 17:51
Date Of Accident	30/05/2018 11:45
Exact Location Of Accident	SLIP RD MARINE PARADE RD TWDS STILL RD S
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR143J
Insured/Policyholder	
Name Of Registered Owner	KOH CHOON HUAT
NRIC No	S7011590E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98426542
Alternative Phone No	OFFICE-98426542

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	GOLF A7 1.2 TSI AT 5G12DZ
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095734245
Cover Note Number	

Driver

Name of Driver	ANG SIEW HUAY LENA
NRIC No	S7004471D
Date Of Birth	15/02/1970
Occupation	INDOOR
Date Of Driving Pass	10/09/1993
Driving Experience	24 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90885484
Fax Number	
Contact Number	OFFICE-90885484
EEmail Address	NOEMAIL

Address	7 SIGLAP ROAD #19-55
Postcode	448909
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB8227H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MANAP BIN RAJIB
NRIC/Passport Number	
Contact Number	83067164
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2
Passenger 1	NAME: : GENDER: :

DETAILS OF INJURED PERSON 1

Name	ANG SIEW HUAY LENA
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SLR143J
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



A - SLR143J
B - SLB8227H

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving on Slip road from marine parade road to Still Road S on 30/5/2018 at 1147hrs. As I was approaching the stop line on slip road, I felt an huge impact on the rear portion of my vehicle (A) so I exited my car and check and realised that vehicle (B) collided onto the rear portion of my vehicle. The whole accident was captured by my in-car camera.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's signature
Date & Time:


Driver's signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's signature
Name:
NRIC/TIN No:

(1)Front (2)Denied (3)Returned (4)Not used (5)OK (6)Scratched
 (7)Returned (8)Not used (9)Not used (10)Broken (11)Necessary
 (12)Missing (13)Not (14)Not returned (15)Not Working

MOTORCAR (Rear)

A. (1)Replace (✓) (2)Repair (3)Check (4)
 (5)Not Consider (6)

Vehicle No: *SLR 143 J*

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	Dmg	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	SCR	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	CUT	✓	
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	CRK	✓	
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	SC	✓	
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	SCR	R	
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector	Defrm	✓	
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993491	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Jun 2018 Edit Reg		31 May 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	KOH CHOON HUAT, ID: S7011590E								
Vehicle Reg. No.:	SLR143J	Date of Loss:	30/05/2018 14:00 - :59 [42 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6527425663SG	Policy/Cover Note No.:	0999994768 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLB8227H	Policy No. (Claimant):							
		Excess:							
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/06/2018]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (05/06/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR143J (6527425663SG)
 [SLB8227H]
 TP
 KOH CHOON HUAT
 May 30 2018 2:00PM
 [LCRF PTE LTD]
 N-51 Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value=""/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="button" value="Print"/>
1	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
2	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
3	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
4	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
5	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
6	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
7	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
8	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
9	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
10	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
11	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
12	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
13	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
14	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
15	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
16	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
17	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
18	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
19	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
20	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
21	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
22	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
23	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
24	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
25	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
26	01/06/18 16:16	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
27	01/06/18 16:17	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
28	01/06/18 16:17	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
29	01/06/18 16:17	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
30	01/06/18 16:17	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
31	01/06/18 16:17	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
32	01/06/18 16:17	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
33	01/06/18 16:17	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
34	01/06/18 16:17	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
35	01/06/18 16:17	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
36	01/06/18 16:17	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
37	01/06/18 16:17	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	01/06/18 16:17	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	07/06/18 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	07/06/18 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	07/06/18 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	07/06/18 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	07/06/18 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	07/06/18 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	07/06/18 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	07/06/18 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	07/06/18 12:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	07/06/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	07/06/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	07/06/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	07/06/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	07/06/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	07/06/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	07/06/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	07/06/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	07/06/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	07/06/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	07/06/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	07/06/18 12:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	05/06/18 14:58	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009908/AZ4D3E2

Date: 08/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994768
Claimant Vehicle No : SLR143J **Insured Vehicle No :** SLB8227H
 Date of Loss: 30/05/2018 Nature of Claim: TP Claim No: 6527425663SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR143J**
 Make & Model: VOLKSWAGEN GOLF, 1.2 (A7) TSI (A) Engine No: CJZ500176
 Reg. Date: 18/11/2014 (Man. Year: 2014) Chassis No: WVVZZZAUZEW381160
 Colour: Red Odometer: 48830 km
 Engine Capacity: 1197 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 31/05/2018
 Date Inspected: 31/05/2018 Inspected At: N-51 Automotive Pte Ltd (HQ)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI
 BUKIT AUTOHUB
 Singapore 417921
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Damaged	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Scratched	0.00 F	*- F
3	1		*REAR BUMPER TOW COVER	Cut	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER SIDE RETAINER	Cracked	0.00 F	*- F
6	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	1		*REVERSE SENSOR	Shorted	0.00 F	*- F
8	1		*BOOTLID	Repair	0.00 F	*- F
9	1		*REAR RH FENDER PROTECTOR	Deformed	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >