

Surveyor: Taufikh. ASSIGNMENT DOI: 16/18 Date/Time: 21/5/18 Registered in Merimen: 16/18

Pre-assign / CCU / FTE: SLJ 2A78X
 Insured Vehicle No.: _____ Claim No.: 815710254266
 Name of Insured: UP Policy No.: 999995008
 Insured Tel No.: _____ HP: _____ Make / Model: KAWAII
 Excess Sec II :SS _____ D.O.A.: 14/5/18 Place of Accident: VISUM ST 22
 Is driver the owner? (YES / NO) Nature of Accident: _____
 If NO, Driver Name / Age: ONY BENY LANG. OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
 Driver Tel No.: _____ (V/L: YES / NO) Insured Liability: % Final ? Yes / No

Fbm 16694 → → → →
 INSRs: WSP: Southern Motor INSRs: WSP: 720FIK INSRs: WSP: INSRs: WSP:
 Tel: Tel: 9949 Tel: Tel:
 Liability: Liability: 5749 Liability: Liability:
 RMKS: RMKS: RMKS: RMKS:

Date/Time	STAGE	DATE / PIC
5/6/18 JOM	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI:	NA JUY 6-6-18
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OI	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice	<input checked="" type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others: COE/REB.	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Repair Cost:	SS _____	(_____ days) Reduction:	% _____	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 28-6-18	Confirm with: SM	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	5	If NO or B 28. Ass. Lia :
Repair Cost:	SS 2,675			
Loss of Rental (LOR):	SS -	(_____ days)		
Loss of Use (LOU):	SS 125	(\$25 x 5 days)		
Loss of Income (LOI):	SS -	(\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]		
GIA/LTA Search:	SS -			
Medical:	SS -			1) Claim status: Normal/Reject/Private Settle
Disbursement:	SS -	(e.g. Tow/Independent)		2) Report Format:
Legal Cost:	SS -			3) Survey fee:
Total:	SS 2,800	Global Sum SS:		
FINAL PAYMENT	Date/Time:	Confirm with:	Confirm by:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS 2,800	Name 1:	SOUTHERN MOTOR	
Payee 2: (Strike if N.A.)	SS X	Name 2:	X	
Payee 3: (Strike if N.A.)	SS	Name 3:	X	

COPY SENT 26/6/18

RECEIVED 28 JUN 2018

Signature: Tanjun

REF: AIG

ASSIGNMENT

CoE 2026 July

From: _____ Date: 01/06/18

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBM 16694

at Workshop m/s: Southern Motor

of Blk 1006, Blk merah June 2 #01-10

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 6273 0369

Veh No: FBM 16694 Yr Regn: 2006 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Suzuki DRZ 400 cc 398

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JS/B8/11200103523

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3.Val.: Yes or No

CA / REV / REP. / 24 HRS ^{wp}

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Tyre Size: F: 120/70K12 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front	Rear
R/Bal. 5 mm	R/Bal. 5 mm
L/Bal. mm	L/Bal. mm

D.O.A. _____ D.O.I. 1/6/18 @ 1230

Survey held at Southern Motor.

Des. of Damages: Frt / Rsr / O/S / N/S / UIC / Rooftop or _____

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
4/5	\$2,500
	R (\$2,843.40/5390)

Date/Time. File Pass to? Preli. Report Final Report

1) _____

Date/Time. File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

1) \$ + RE. \$ _____

2) Photos _____

3) Others _____

Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

TOTAL _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/LCR18009922/T1jb3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 01-06-2018



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLJ 2978X	Veh. Inspected	FBM 1669Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	01/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/05/2018	Inspection Date	01/06/2018
Survey held at	SOUTHERN MOTOR BLOCK 1006 BUKIT MERAH LANE 2 #01-10 SINGAPORE 159762		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



南方摩哆
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel:62730369 Fax:62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters, **Link Auto Credit** Hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date: 25th May 2018

Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way # 07-16 AIG Building
Singapore 079120

Dear Sirs

Re: Cost of repair to Suzuki DRZ 400SM - FRM 1669Y

1 pc of Handle bar	S\$ 1	21000 ² MV
" Clutch lever		4500 cut
" Clutch cable		6500 dis
2 pc of Handle grips		2200 fr
" Handle switch LH		14500 dis
" Front fairing headlamp cord		22500 cut
" Front rim sliders		11000 cut
" Clutch lever		9500 cut
2 pcs of Rear fairing		32000 cut
1 pc of Rear signal		2500 dis
" Body sliders		14000 cut
" Rear rim sliders		11000 cut
" Magneto cover		28500 dis
" Brake pedal		11500 bf
" Rear brake pump		23500 dis
" Rear Footrest bracket		2500 bf
" Side bar Rear RH fender		36000 cut
" Clutch cover		32000 dis
	2828	303200
		30320
		272420

Tanpin 97495749

01/06/18 @ 1230

Working after repair
5 days

Sue Meanbaum

Yours faithfully,
SOUTHERN MOTOR

Less 10%

10% 2545.20

Nett

Transport basket	30.00	✓
4 litre oil	25.00	✓
1 set of No plates	25.00	180
4 Jack body Jack body	25.00	X
2 x 2000 MV	14000	100
2 Jack fork & alignment	25000	200
Labour	3609.20	630
Jack fork & alignment	3175.20	
Labour	4/3 92500	

Tel 64193006
Fax 64153727

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0944H
Vehicle Details	
Vehicle No.:	FBM1669Y
Vehicle to be Exported:	No
Intended De-registration Date:	04 Jun 2018
Vehicle Make:	SUZUKI
Vehicle Model:	DRZ400SMK6
Primary Colour:	Yellow
Manufacturing Year:	2005
Engine No.:	K419149203
Chassis No.:	JS1B8111200103523
Maximum Power Output:	-
Open Market Value:	\$6,536.00
Original Registration Date:	28 Jul 2006
First Registration Date:	28 Jul 2006
Transfer Count:	7
Actual ARF Paid:	\$981.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jul 2026
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$6,369.00
COE Rebate Amount:	\$5,187.00
Total Rebate Amount:	\$5,187.00

The information contained herein is correct as at 04 Jun 2018

OK

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Wednesday, 6 June 2018 10:57 AM
To: Eileen, May Hwee Yap
Cc: 'Insurance LCR SG'; Admin A; Vivian Lau (LKKAuto); Hsiao Tong (LKKAuto)
Subject: ACCIDENT INVOLVING SLJ 2978X (LCR) & FBM 1669Y ON 19/05/2018 (03:45) YISHUN ST. 72

05 June 2018

LION CITY RENTALS PTE LTD

Policy Holder

Your Ref: SLJ 2978X
Our Ref: CC4/LCR18009922/T1jb3

Dear Sir/Madam,

ACCIDENT INVOLVING SLJ 2978X (LCR) & FBM 1669Y ON 19/05/2018 (03:45) YISHUN ST. 72

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from **FBM 1669Y** against your insurance policy.

Based on the information on hand, we are of the opinion that we cannot be absolved from liability. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, SHAH FIRMAN BIN SALIMAN ("the third party claimant")
of Blk 731 Yishun St 72 #01-51 Singapore 760731 (address),
owner of FRM 16694 (vehicle no.) hereby authorize
Southern Motor
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. FRM 16694 that was
damaged pursuant to the accident which occurred on 19-05-2018 (date) along
Yishun St 72 Singapore (location)
involving vehicle no/s SLJ 2978x ("the accident").


I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment furtherto settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 27th day of June (month) 2018 (year)



Signed by "the third party claimant"



Signed by "the workshop"
 **SOUTHERN MOTOR**
Blk 1006, Bukit Merah Lane 2
#01-10 Singapore 159752
Tel: 62730309 Fax: 6746614

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

"We/I, SOUTHERN MOTOR ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. Mr. Muhamad Taufiqul Hafid (name of surveyor) with respect to the amount claimed for S\$ 2,675.00 (repair costs), S\$ 125.00 (loss of use/rental) S\$ - (search fees) for vehicle no. FAM1669Y that was damaged pursuant to the accident which occurred on 19-05-2018 (date) along Yishun St 72 Singapore (location) involving vehicle no/s SLJ 2978 X

This is pursuant to the inspection conducted on 01-06-2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SHAH FIRMAN BIN SALIMAN ("third party claimant") of vehicle no. FAM1669Y to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to FAM1669Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 28th day of June (month) 20 18 (year)


Signed by AIG appointed surveyor

Chopped & Signed by "the workshop"



SOUTHERN MOTOR
Blk 1006, Bukit Merah Lane 2
#01-10 Singapore 159762
Tel: 62730369 Fax: 62746614



SOUTHERN MOTOR

Blk 1006, Bukit Merah Lane 2 #01-10 Singapore 159762

Tel:62730369 Fax:62746614 CO/GST Reg No:23414700L

TAX INVOICE NO : INV27922
Invoice Date : 27th June 2018
Payment Terms : CASH
Vehicle No. : FBM1669Y - SUZUKI DRZ
400SM
Mechanic : CASH

AIG ASIA PACIFIC INSURANCE PTE LTD - AA002
78 SHENTON WAY #07-16 AIG BUILDING Singapore 079120

Tel: 64193000 Fax: 64153727

<u>S/No</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>U/PRICE</u>	<u>Amount</u>
1	7% GST ON COST OF LUMP SUM REPAIR	1	\$175.00	\$175.00
2	COST OF LUMP SUM REPAIR	1	\$2,500.00	\$2,500.00
3	LOSS OF USE FOR 5 DAYS AT \$25.00 PER DAY	1	\$125.00	\$125.00


TOTAL : \$2,800.00

BALANCE : \$2,800.00

INCLUSIVE 7.00% GST : \$183.18

Goods Sold Are Not Returnable. Deposit Paid Are Not Refundable. All cheques should be made payable to "SOUTHERN MOTOR".
Interest Rate of ___% per month will be imposed on overdue Accounts. Thank you.

Received by



Issued by

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastiane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jun 2018 Edit Reg		31 May 2018 00:00 Edit Adj Rpt	S\$2,500.00 Edit Estimates	S\$2,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Main Claimant:	SHAH FIRMAN BIN SALIMAN, ID: S9330944H		
Vehicle Reg. No.:	FBM1669Y	Date of Loss:	19/05/2018 03:00 - :59 [141 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8153103542SG	Policy/Cover Note No.:	0999994826 (Comprehensive)
Vehicle Reg. No. (Insured):	SLJ2978X	Policy No. (Claimant):	
		Excess:	
Repairer:	Southern Motor (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10, 159762 Bukit Merah - Tel: 62730369		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Yong, Ivy-AV] Ivy-VA.Yong@aig.com		
Claimant's Insurer:	Great American Insurance Company (HQ) - Tel: 6804 6047		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 12/06/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBM1669Y (8153103542SG)
[SLJ2978X]
TP
SHAH FIRMAN BIN SALIMAN
May 19 2018 3:00AM
[LCRF PTE LTD]
Southern Motor

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
Letters/Correspondences											1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit			
Photos/Images											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	28/06/18 16:38	General View							Load JPG	<input checked="" type="checkbox"/>		
2	28/06/18 16:38	General View							Load JPG	<input checked="" type="checkbox"/>		
3	28/06/18 16:38	General View							Load JPG	<input checked="" type="checkbox"/>		
4	28/06/18 16:38	General View							Load JPG	<input checked="" type="checkbox"/>		
5	28/06/18 16:38	General View							Load JPG	<input checked="" type="checkbox"/>		
6	28/06/18 16:38	General View							Load JPG	<input checked="" type="checkbox"/>		
7	28/06/18 16:38	General View							Load JPG	<input checked="" type="checkbox"/>		
8	28/06/18 16:38	General View							Load JPG	<input checked="" type="checkbox"/>		
9	28/06/18 16:38	General View							Load JPG	<input checked="" type="checkbox"/>		
10	28/06/18 16:38	General View							Load JPG	<input checked="" type="checkbox"/>		
11	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
12	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
13	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
14	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
15	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
16	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
17	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
18	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
19	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
20	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
21	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
22	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
23	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
24	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
25	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
26	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
27	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
28	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
29	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
30	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
31	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
32	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
33	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
34	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
35	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
36	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
37	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
38	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
39	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		
40	28/06/18 16:39	General View							Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
42	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
43	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
44	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
45	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
46	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
47	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
48	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
49	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
50	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
51	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
52	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
53	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
54	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
55	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
56	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
57	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
58	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
59	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
60	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
61	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
62	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
63	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
64	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
65	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
66	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
67	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
68	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
69	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
70	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
71	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
72	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
73	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
74	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
75	28/06/18 16:39	General View		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/06/18 13:59	TP GIA REPORT		Load PDF
2	04/06/18 17:56	TP ESTIMATE- MARKED		Load PDF
3	29/06/18 09:23	WORKSHOP INVOICE		Load PDF
4	29/06/18 09:23	AUTHORISATION TO ACT FORM		Load PDF
5	29/06/18 09:23	Release Voucher		Load PDF
6	29/06/18 09:23	LETTER TO OI		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/06/18 14:46	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

↑
↓

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLJ2978X (Insd veh)	Model:	SUZUKI DRZ 398CC 400SM (M)
	FBM1669Y (TP veh)		
Date of Accident:	19/05/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	3,861.84	
Final Repair Cost	:	\$	2,675.00	
Loss of Use	:	\$	125.00	5.00 days at \$25.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	0.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	2,800.00	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)				
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Southern Motor	\$	2,800.00
2)		\$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

29 Jun
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18009922/T1JB3Q2

Date: 29/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994826
 Claimant FBM1669Y Insured Vehicle No: SLJ2978X
 Vehicle No: FBM1669Y Insured Vehicle No: SLJ2978X
 Date of Loss: 19/05/2018 Nature of Claim: TP Claim No: 8153103542SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBM1669Y**
 Make & Model: SUZUKI DRZ, 398cc 400SM (M) Engine No: K419149203
 Reg. Date: 28/07/2006 (Man. Year: 2005) Chassis No: JS1B8111200103523
 Colour: Black Odometer: 0 km
 Engine Capacity: 398 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/70 R12 Rear Tyre Size: 120/70 R12
 Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,879.20	2,665.20	214.00	7.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	730.00	510.00	220.00	30.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,609.20	3,175.20	434.00	12.02
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	3,609.20	2,500.00	1,109.20	30.73
+ GST 7.00/7.00% (S\$)	252.64	175.00	77.64	30.73
Nett Amount (S\$)	3,861.84	2,675.00	1,186.84	30.73
+ Loss of Use (5.0 x S\$25.00/day) (S\$)		125.00		
Nett Liability (S\$)		2,800.00		

INSPECTION

Date of Assignment: 31/05/2018
 Date Inspected: 01/06/2018 Inspected At: Southern Motor (HQ)
 BLK 1006 BUKIT MERAH LANE 2,
 #01-10
 Singapore 159762
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Not Necessary	210.00 FL	*- FL
2	1		*CLUTCH LEVER	Cut	45.00 FL	*45.00 FL
3	1		*CLUTCH CABLE	Distorted	65.00 FL	*65.00 FL
4	1		*HANDLE GRIPE	Torn	28.00 FL	*28.00 FL
5	1		*HANDLE SWITCH LH	Distorted	145.00 FL	*145.00 FL
6	1		*FRONT FAIRING HEADLAMP COWLING	Cut	225.00 FL	*225.00 FL
7	1		*FRONT RIM SLIDES	Cut	110.00 FL	*110.00 FL
8	1		*CLUTCH LEVER	Cut	95.00 FL	*95.00 FL
9	2		*CENTRE FAIRING	Cut	380.00 FL	*380.00 FL
10	1		*REAR SIGNAL	Distorted	25.00 FL	*25.00 FL
11	1		*BODY SLIDES	Cut	140.00 FL	*140.00 FL
12	1		*REAR RIM SLIDES	Cut	110.00 FL	*110.00 FL
13	1		*MAGNET COVER	Dented	285.00 FL	*285.00 FL
14	1		*BRAKE PEDAL	Bent	115.00 FL	*115.00 FL
15	1		*REAR BRAKE PUMP	Distorted	235.00 FL	*235.00 FL
16	1		*REAR FOOTREST BRACKET	Bent	85.00 FL	*85.00 FL
17	1		*SIDE BOX REAR RH FENDER	Cut	360.00 FL	*360.00 FL
18	1		*CLUTCH COVER	Dented	380.00 FL	*380.00 FL
19	1		*GASKET	Necessary	35.00 FS	*35.00 FS
20	1		*SET OF NO PLATE	Bent	25.00 FS	*25.00 FS
21	1		*BUMPER OIL	Necessary	60.00 FS	*60.00 FS
22	1		*COOLANT	Not Necessary	25.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,183.00	2,948.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	303.80	282.80
Total Parts (\$\$)	2,879.20	2,665.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT	New	30.00	30.00
2	JACK BODY	New	280.00	180.00
3	JACK FORK & ALIGNMENT	New	140.00	100.00
4	LABOUR	New	280.00	200.00
Gross Labour Cost (\$\$)			730.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >