

A member of COMFORTDELGRO

Date/Time: 21.05.2018 17:36

Page : 1

Team: ARC Repair OD(CFSO)

JOB CARD Sales Order:

JC NO305162796

CUSTOMER
CITYCAB PTE LTD
7010070
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188
L (R) (O)
(P)

788628

REGN NO: SHB3237J	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 19.05.2018 12:15
YR OF MANU. 08.12.2016	TARGET DATE
CHASSIS CODE KMHLB41UMHU097854	COMPLETION DATE/TIME:

SCOUNT CARD NO.

JOB DESCRIPTION

NATURE: OD 19.05.2018 STK
S/NO LABOR CODE

OD / FRONT / LH

791113

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHB3237J CHIANG

Vehicle No.: SHB3237J

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard



SINGAPORE POLICE FORCE
ACKNOWLEDGEMENT SLIP

Ref: Report No: D/20180519/0081

1. Sgt T01189 Ma Heidir
(Recipient's Name, NRIC or Passport No. / Rank and No.)

of TP
(Address / Police Station / NPC / NPP)

hereby acknowledge receipt of the below mentioned items of:


- 1 One 'Transcend Premium 400x' micro SD 64GB.
- 2 _____
- 3 _____
- 4 _____
- 5 _____
- 6 _____
- 7 _____
- 8 _____
- 9 _____
- 10 _____

from Teo Ang Kau S0105235G
(Name, NRIC or Passport No. / Rank and No.)

of B/452 Jurong West St 42 #07-166 S(640452)
(Address / Police Station / NPC / NPP)


on 19/05/2018 at 1340hrs
(Date) (Time)

Witnessed by / * Handed over by:
(* Delete if applicable)


(Signature)

Teo Ang Kau S0105235G
(Name, NRIC or Passport No. / Rank and No.)

Received by:


(Signature)

Sgt T01189
(Name, NRIC or Passport No. / Rank and No.)

Other Remarks: IO: Bei Feng Tel: 65476415

- To lodge NP168 (Traffic Accident Report).

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Loke Wei Yieng
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per attached Police Report.

T/20180519/2145.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20180519/2145

1 of 3

Police Station Of Origin:
Jurong West N.P.C
70 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No. T/20180519/2145

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/05/2018 21:21	Vide Report No.: D/20180519/0081	Station Diary No.: 91
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: TEO ANG KAU			Address: APT BLK 452 JURONG WEST STREET 42 #07-166 SINGAPORE 640452	
ID Type / ID No.: NRIC NO / S0105235G			Contact No.: Home/Office:	Mobile: 96513306
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 70	Date of Birth: 25/04/1948	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:	

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 19/05/2018 12:15	Type of Location: X-Junction
Location: Along Road 1 YUAN CHING ROAD				
X-Junction of Yuan Ching Rd and Tah Ching Rd				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 20 Km/h
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB3237J	taxi				Seriously Damaged	3
SKV5165D	Car				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE POLICE FORCE



T/20180519/2145

2 of 3

Police Station Of Origin:

Jurong West N.P.C

700 Corporation Road SINGAPORE 649818

Tel No: 1800-2689999

Report No. T/20180519/2145

CONTINUATION OF REPORT

Driver			
Name	TEO ANG KAU		ID No. S0105235G
Related Vehicle	SHB3237J (taxi)		Contact No. 96513306
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

Brief Details.

On 19/05/2018 at about 1214hrs, I was driving my taxi, SHB3237J along Yuan Ching Rd towards AYE in right lane. Upon reaching the X Junction of Yuan Ching Rd and Tah Ching Rd, I turned on the right signal light and make right turn. Upon making the right turn, a car, SKV5165D coming from Yuan Ching towards Boon Lay Way, hit onto my front left wheel. My taxi suffered front bumper broken, front left signal light broken, front left wheel dented, headlight broken and plate number broken. My taxi towed away. I suffered back pain. Ambulance came and conveyed the car driver and three of my passenger to hospital. Traffic police came. Police report no: D/20180519/0081



**SINGAPORE
POLICE FORCE**



T/20180519/2145

3 of 3

Report No. T/20180519/2145

Police Station Of Origin:

Jurong West N.P.C

700 Corporation Road SINGAPORE 649818

Tel No: 1800-2689999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Staff Sgt MUHAMMAD HAIRIN BIN JAMIL

Signature Of Interpreter:

Not applicable

Signature Of Informant:

Date/Time:

19/05/2018 21:21

Officer In Charge Of Case:

TP / GIT /

SI YEO CHUN JIAN

Contact No.: 65476213

Classification Of Case:

SN 126

Authentication Stamp

NP 168

Signature :

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 3237J

MAKE :

MODEL : HYUNDAI i40

LKK - 2nd Opinion 30

LC

DATE 24/5/2018 14:23

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet			\$ 1,526.00
	Bonnet Lock			\$ 50.90
	Bonnet Absorber	\$	73.90	\$ 147.80
	Bonnet Insulator			\$ 243.00
	Bonnet Insulator Clips			\$ 8.40
	Radiator Grille			\$ 294.35
	Radiator Grille H Emblem			\$ 113.65
	Front Bumper Cover			\$ 562.30
	Front Bumper Sponge			\$ 142.20
	Front Bumper Reinforcement			\$ 526.10
	Front Bumper Grille (LH/RH)	\$	40.30	\$ 80.60
	Front Bumper Lip			\$ 62.50
	Front Bumper Bracket Top (LH/RH)	\$	22.40	\$ 44.80
	Front Bumper Side Bracket	\$	14.30	\$ 28.60
	Headlamp Support Top Cover			\$ 398.00
	Headlamp Support Panel Assy			\$ 1,067.50
	Headlamp (LH/RH)	\$	1,388.00	\$ 2,776.00
	Radiator			\$ 850.20
	Radiator Fan Blade, Cowling, Motor Assy			\$ 792.95
	Radiator Bracket (RH/LH)	\$	6.50	\$ 13.00
	Radiator Hose Upper			\$ 47.40
	Radiator Hose Lower			\$ 47.40
	Radiator Guard	\$	35.00	\$ 70.00
	Horn Unit (LH/RH)	\$	86.75	\$ 173.50
	Front Fender (LH/RH)	\$	619.00	\$ 1,238.00
	Front Fender Apron Panel (LH/RH)	\$	1,575.50	\$ 3,151.00
	Front Fender Shield (LH/RH)	\$	169.80	\$ 339.60
	Front Fender Retainer	\$	9.20	\$ 18.40
	Aircon Condenser			\$ 1,137.35
	Front Door (LH)			\$ 1,403.00
	Rocker Panel Outer Garnish			\$ 483.60
	Rear Door (LH)			\$ 1,351.00
	Rear Door Outer Handle (LH)			\$ 41.40
	Front Wheel Rim (LH/RH)	\$	351.90	\$ 703.80
	Front Wheel Hub Cap (LH/RH)	\$	150.70	\$ 301.40
	Front Wheel Bearing	\$	258.50	\$ 517.00
	Front Shock Absorber (Assy) (LH/RH)	\$	342.20	\$ 684.40
	Front Shock Absorber Mounting (LH/RH)	\$	75.10	\$ 150.20
	Front Drive Shaft (LH/RH)	\$	1,069.55	\$ 2,139.10
	Rack & Pinion Assy			\$ 2,184.00
	STG Tie End	\$	69.50	\$ 139.00
	Stabilizer Bar			\$ 252.30
	Stabilizer Bar Bush (LH/RH)	\$	16.10	\$ 32.20
	Stabilizer Bar Link	\$	81.70	\$ 163.40
	Stabilizer Bracket	\$	24.00	\$ 48.00

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Suspension Lower Arm (LH/RH)		\$ 715.10	\$ 1,430.20	
	Front Chasis Member (LH/RH)		\$ 1,575.85	\$ 3,151.70	
	Knuckle Arm (LH/RH)		\$ 582.95	\$ 1,165.90	
	Engine Crossmember			\$ 2,236.90	
	Gearbox			\$ 14,808.00	
	Gearbox Mounting			\$ 342.50	
	Inter Cooler			\$ 921.90	
	Inter Cooler Mounting (2 PCS)			\$ 25.90	
	Hose B To Inter Cooler			\$ 229.70	
	Hose C To Inter Cooler Inlet			\$ 113.30	
	ABS Sensor		\$ 261.50	\$ 523.00	
	SUB TOTAL			\$ 51,494.30	
	LESS 20%			\$ 10,298.86	
	DISCOUNTED TOTAL			\$ 41,195.44	
	Front Number Plate			\$ 25.00	Nett
	Front No Plate Trim Cover			\$ 30.00	Nett
	Front Door Comfort Logo (LH)			\$ 75.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (LH)			\$ 80.00	Nett
	Front Tyre (LH/RH)		\$ 216.00	\$ 432.00	Nett
				\$ 642.00	
	Labour Charge				
	Panel Beating			\$ 2,500.00	
	Spray Painting Charge			\$ 2,000.00	
	Wiring Charge			\$ 100.00	
	Tuff Kote			\$ 100.00	
	Towing Charge			\$ 60.00	
	Front Chassis Alignment Charge			\$ 400.00	
	Transfer of Door			\$ 240.00	
	Remove/Refix Undercarriage (FRT)		120.00	\$ 400.00	
	FRT Wheel Alignment			\$ 120.00	
	Remove/Refix Aircon & Refill Gas			\$ 150.00	
	Remove/Refix Engine			\$ 550.00	
	Remove/Refix Dashboard			\$ 450.00	
	Remove/Refix Fuse Box			\$ 180.00	
	TOTAL LABOUR			\$ 7,250.00	
	ESTIMATE TOTAL			\$ 49,087.44	
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					

LKK Auto Consultants hence notify S
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

TOTAL LABOUR

Signature:

Date:

ESTIMATE TOTAL

1/10/14
30/5/8 1135h
Front Btyl chasis Damage
unsafe to Repair to 50%



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Our Ref : CS/QW18009939/K1rbs2

Date: 05th June 2018

Comfort Transportation Pte Ltd
383 Sin Ming Drive
Singapore 575717

Attn: Doris Lim

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO.: SHB 3237J
ACCIDENT ON 19/05/2018**

Instruction was received to inspect the vehicle Reg. No. SHB 3237J. The inspection was conducted on 30/05/2018 at the premises of M/s Comfortdelgro Engineering Pte Ltd, 59 Loyang Drive Singapore 508969.

The following vehicle information was recorded:

Registration Number	: SHB 3237J
Make/Model	: Hyundai I40
Year of Registration	: 2016
Body Colour	: Yellow
Chassis Number	: KMHLB41UMHU097854

The following are our comments:-

- (a) The vehicle sustained damages at the front n/s windscreen and n/s body. (Details see photographs enclosed)

- (b) In view of this, we are of the opinion that it would be **unsafe** to proceed with the repairs due to extensive damages on the chassis under the category of **the section 2 of THE ROAD TRAFFIC ACT on THE MOTOR VEHICLES (CONSTRUCTION AND USE) (AMENDMENT NO.2) RULES 1989**, that:
no vehicle shall be fitted with a replacement chassis or any body part where the chassis is an integral part of the vehicle.
 and we therefore recommend it to be written off as **"Total Loss"**

Vehicle Inspected By:



KALVIN ANG WEI KUN
Automotive Assessor / Investigator



K.K.LAU
 MSc(Eng M), B Eng(Hons), Peng(UK),
 MASME(USA), B Bus(Aust), MBA(UK),
 IEng(UK), MIE(mech), MinstAEA, MFIEA,
 MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
 AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
 Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.