



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

TPVD NISSAN CABSTAR (GW8062P)

Date of Loss

28 May 2018

Time of Loss

13.00

Loss Description

GBC5714B (INSD) C/W GW8062P (TP)

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *

08/07/2018



Days of work completion *

39



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

GW8062P

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

06/11/2003



Mileage

504540

Age of Vehicle

14

Driver Details

CATEGORY

Manufacturing Year

CATEGORY

Driver Name

POLICY INFORMAT...

ASSESSMENT INFO...

2003

FNOL INFORMATI...

K RAVINDRAN

CATEGORY

Make

POST SURVEY INF...

POLICY INFORMAT... TPVD NISSAN

ASSESSMENT INFO... NISSAN

CATEGORY Model

POLICY INFORMAT... CABSTAR

ASSESSMENT INFO... CABSTAR

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT...

ASSESSMENT INFO... JN1SF4F23Z0844478

CATEGORY

Date of Birth

FNOL INFORMATI...

14 January 1964

POST SURVEY INF...

dd/mm/yyyy



CATEGORY

Age

FNOL INFORMATI...

54

POST SURVEY INF...

CATEGORY

Occupation

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Education Qualification

FNOL INFORMATI...

Other

POST SURVEY INF...

CATEGORY

Driving Experience

CATEGORY Engine No

POLICY INFORMAT...

ASSESSMENT INFO... QD32183509

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 3153

CATEGORY Sum Insured

POLICY INFORMAT...

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT...

ASSESSMENT INFO... 0

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S1673240J

POST SURVEY INF...

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

05/06/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

195R15

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

155R12

Front left side

CONDOR7mm

Front right side

CONDOR7mm

Rear left side

CONDOR5/5mm

Rear right side

CONDOR5/5mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

☒ Yes☐ No

Part Supplied by AXA

Yes

No

Save

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD

Ref: CS3/ASM18009945/R1z4be2

8 SHENTON WAY #24-01 AXA TOWER
SINGAPORE 068811

Date: 18-06-2018



ATTN : RUTH CHUA

Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBC 5714B	Veh. Inspected	GW 8062P
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00IWX	Excess (\$)	0.00
Assign From	RUTH CHUA	Assign Date	30/05/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN CABSTAR	c.c	3153
Engine No.	HIDDEN	Year of Reg.	2003
Chassis No.	JN1SF4F23Z0844478	Colour	GREY
Odometer	504540 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	CONDOR	7 mm
L/H Front Tyre	195 R15	CONDOR	7 mm
R/H Rear Tyre	155 R12 (D)	CONDOR	5/5 mm
L/H Rear Tyre	155 R12 (D)	CONDOR	5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.	
---	--

5. General Information

Accident Date	28/05/2018	Inspect Date / Time	05/06/2018 (02:28 PM)
Survey held at	7A JLN PAPAN		
Repairer	THIAM HENG MOTOR		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Report Ref No. CS3/ASM18009945/R1z4be2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.