



PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM18009945/R1z4be2		
8 SHENTON WAY #24-01 AXA TOWER		Date: 18-06-2018		
SINGAPORE 068811				
ATTN : RUTH CHUA		Code: ASM		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBC 5714B	Veh. Inspected	GW 8062P
	Policy No.		Coverage (\$)	0.00
	Claim No.	S8M00IWX	Excess (\$)	0.00
	Assign From	RUTH CHUA	Assign Date	30/05/2018
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN CABSTAR	c.c	3153
	Engine No.	HIDDEN	Year of Reg.	2003
	Chassis No.	JN1SF4F23Z0844478	Colour	GREY
	Odometer	504540 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	CONDOR	7 mm
	L/H Front Tyre	195 R15	CONDOR	7 mm
	R/H Rear Tyre	155 R12 (D)	CONDOR	5/5 mm
	L/H Rear Tyre	155 R12 (D)	CONDOR	5/5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.			
5. General Information				
	Accident Date	28/05/2018	Inspect Date / Time	05/06/2018 (02:28 PM)
	Survey held at	7A JLN PAPAN		
	Repairer	THIAM HENG MOTOR		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/ASM18009945/R1z4be2

Inspected By



MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.