

22/03/2002

ASS. REC. BY:

REF:

08/MSG18009947/KH/b3eb

Special Instruction:

Surveyor:

Menmen

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

MSG

Date/Time:

31/05/18 @ 5.04pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 8301Z

Insured:

FU 8431E

at Workshop m/s

Premier Taxis

Tel:

of

23 Chungi Ave 2 # 03-02

Policy No:

MSD / VMT / 18-31507-CA

Claim No:

MSC / V / 18-000739 ...

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/05/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

5.31pm 03/5/18

Person Contacted:

Garry

Vehicle IN

OUT

Date/Time	Action/Instruction	Estimate
	SHB 8301Z - NA / MSG1800994756/h4	DOA: 30/5/18
	FU 8431E - NA / MSG1800994756/h4	DOA: 30/5/18
06/6/18 @	10.16am revised to Lionel Tan via Menmen.	

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2018		31 May 2018 17:04 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LEE ZENG FENG, ID: S8528263H, Tel: +6591838845			
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H			
Vehicle Reg. No.:	SHB8301Z	Date of Loss:	30/05/2018 08:00 - :59 [10 Months and 4 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / MSC/V/18-000739	Policy/Cover Note No.:	MSD/VMT/18-381507-CA (Third Party Only) Coverage: 24/04/2018 - 23/04/2019	
Vehicle Reg. No. (Insured):	FU8431E	Policy No. (Claimant):		
		Excess:		
Repairer:	Premier Taxis Pte Ltd - Changli (HQ) 23 Changli South Ave 2 #03-02, 486443 Changli - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/06/2018]			
Driver/Custodian (Insured):	LEE ZENG FENG (32 / Male), NRIC: S8528263H, Tel: +6591838845			
Adj Asg. Remarks:	SJE : AGREED Please appoint LKK AUTO to conduct the survey .Kindly contact the workshop directly @ 6544 6676 or 6544 6689 Liability : 50%			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 06 Jun 2018

Preliminary Advice

Insured Vehicle No	: FU8431E	Accident Date	: 30/05/2018
TP Vehicle No	: SHB8301Z	Assignment Date	: 31/05/2018
Make	: HYUNDAI I30 GDH	Est. Duration of Repair	: 2.00
Date of Inspection	: 04/06/2018		
Inspection At	: PREMIER TAXIS PTE LTD - CHANGI (HQ) 23 CHANGI SOUTH AVE 2 #03-02 SINGAPORE 486443		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,062.89
Revised Amount	:S\$	1,032.89
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,032.89

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
Owner ID Type: Company
Owner Name: PREMIER TAXIS PTE. LTD.
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: SHB8301Z
Previous Vehicle No.: -
Effective Date of Ownership: 26 Jul 2017
Original Regn Date: 26 Jul 2017
Registration Date: 26 Jul 2017
Year of Manufacture: 2016
Vehicle Type: Public Transport Taxi (Motor Car)
Vehicle Scheme: Taxi (Company)
Vehicle Attachment 1: Air-Con (Taxi)
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: HYUNDAI
Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
Primary Colour: Silver
Secondary Colour: -
Passenger Capacity: 4
Chassis No.: TMAD281UVHJ129436
Engine No.: D4FBGZ127637
Engine Capacity/Power Rating: 1582 cc / -
Maximum Power Output: 100.0 kW (134 bhp)
Propellant: Diesel
Max Unladen Weight: 1496 kg
Maximum Laden Weight: 1940 kg
Open Market Value: \$20,527.00
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Jul 2025
Minimum PARF Benefit: \$7,942.00
No. of Transfers: 0
IU Label No.: 1050706648
COE No.: 2017072601003996H
COE Expiry Date: 25 Jul 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)
Quota Premium (QP) / Prevailing Quota Premium: - / \$48,200.00
PQP Paid: \$38,560.00
QP (Regn Cat): -
OPC Cash Rebate Eligibility: No

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/05/2018 14:28
Date Of Accident	30/05/2018 08:30
Exact Location Of Accident	ANG MO KIO ELECTRONIC PARK ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB8301Z
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I30 (FD)-1.6 DOHC (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5095103893
Cover Note Number	

Driver

Name of Driver	ABDUL RAHMAN BIN ABDUL KARIM
NRIC No	S1722822F
Date Of Birth	08/01/1965
Occupation	OUTDOOR
Date Of Driving Pass	04/04/1985
Driving Experience	33 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91010790
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 6 #14-70 MARSILING DIVE
Postcode	730006
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - OPENING DOOR OF VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PAX IN THE REAR LEFT SEAT - INDIAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

VEH. A - 1 PAX VEH. B - NO PILLION

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FU8431E
Vehicle Make/Model/Colour	M/CYCLE
Details Of Properties	VEH. B
Vehicle Category	MOTORCYCLE
Name of Driver	ZENG FENG
NRIC/Passport Number	
Contact Number	91838845
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF INJURED PERSON 1

Name	ZENG FENG - RIDER OF VEH. B
Approximate Age	
Injuries Sustain	CUTS ON HANDS
Injured person in which vehicle?	FU8431E
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

30 MAY 2018
31722822R SHA 8201 2
KQL 20/5/18

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: SHB 83012

B: FU 8431E.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

30 MAY 2018

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Describe Circumstance of the Accident.

ON 30/05/2018 @ 0830HRS, I WAS IN MY TAXI (SHB 8301 Z) – STATIONARY ALONG ANG MO KIO ELECTRONIC PARK ROAD (WITH HAZARD LIGHTS ON) – IN FRONT OF ST ENGINEERING, ALIGHTING MY PASSENGER – ON A SINGLE LANE OF DUAL CARRIAGE WAY.

WHILE MY PASSENGER WAS OPENING THE REAR LEFT DOOR, SUDDENLY VEHICLE B (FU 8431 E – M/CYCLE) WHICH WAS APPROACHING FROM THE REAR, SQUEEZED THROUGH THE LEFT & COLLIDED ONTO THE LEFT REAR DOOR OF MY TAXI.


DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE LEFT REAR DOOR AND VEHICLE B HAD DAMAGES ON THE FRONT PORTION.

RIDER HAD FALL OFF FROM HIS M/CYCLE & SUFFERED SOME CUTS ON HIS HANDS. NO AMBULANCE AT SCENE.

NO PILLION ONBOARD VEHICLE B.

*SCENE PHOTOS TAKEN.

DAMAGES FOUND ON VEHICLE A & VEHICLE B



PREMIER TAXI



FU 8431 E

THIRD PARTY VEHICLE



Driver's Signature & NRIC Number
Wednesday, May 30, 2018 @ 2:38:02 PM

S1722822 F

(attended by)

PREMIER AUTOMOTIVE SERVICES PTE LTD**23 Changi South Ave 2****#01-02, Singapore 486443****Assessment Number: MSIG0016****Version: PREMIERA/1****Assessor Report****Printed: 04/06/2018****Summary Information****Claim**

Claim Reference:	SHB8301Z	Insured:	
Policy Number:		Third Party:	
Date of Decision:	04/06/2018	Able to Authorise Repairs:	TBA
Repairer:		Repairs Authorised?	TBA
Estimated Repair Time (Working Days):	0.0		

Insured's Liability

Excess:	TBA
Customer Contribution:	\$0.00 (excl GST)

Vehicle Details**Vehicle**

Registration:	SHB8301Z	VIN/Chassis Number:	
Manufacturer:	HYUNDAI	Model:	i30
Registration Month:	July	Registration Year:	2017
Odometer:	Not Known	Colour:	
Build Date:			
Model Specs	5-DOOR (HATCHBACK) PAINTING OFF VEHICLE BASECOAT CLEAR		

Vehicle Condition**Vehicle Status**

Date of Incident:	30/05/2018	Market Value:	Unknown
Pre-Accident Condition:		Salvage Value:	Unknown
Pre-Accident Damage:		Date of Inspection:	04/06/2018
Steering Rim Ply:		Place of Inspection:	
Brake Pedal Travel:			
Vehicle Status:			
Damage Severity:			

Tyres Condition:

Tread Depth LHF:

Tread Depth LHR:

Tread Depth RHF:

Tread Depth RHR:

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$50.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
1481	REPAIR LEFT FRONT DOOR	20.0*	100.00
1781	REPAIR L/R DOOR	20.0*	100.00
2101	REPAIR L/SILL PANEL	20.0*	100.00
3481	REPAIR L/R SIDE PANEL	20.0*	100.00

LABOUR COST**Total Work Units****Corrosion Protection External Labour****Corrosion Protection Internal Labour****Sub Total****80.0****0.0HRS****0.0HRS****8.0HRS****0.00****0.00****\$400.00**

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 Changi South Ave 2

#01-02, Singapore 486443

Assessment Number: MSIG0016

Version: PREMIERA/1

Assessor Report

Printed: 04/06/2018

Paint Labour	7.5HRS	\$375.00
Total Labour	15.5HRS	\$775.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- PAINTING OFF VEHICLE		
	- BASECOAT CLEAR		
1481	LEFT FRONT DOOR REPAIR PAINTING <50%	17.0	
1781	L/R DOOR REPAIR PAINTING <50%	15.0	
2101	L/SILL PANEL REPAIR PAINTING <50%	9.0	
3481	L/R SIDE PANEL REPAIR PAINTING <50%	13.0	
LABOUR COST - PAINT			
TIME(PAINT)		54.0	
Preparation Main Work Metal		21.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		75.0	
Total Paintwork Labour		7.5HRS	\$375.00
MATERIAL COST - PAINT			Cost Price
Repair Painting			\$79.79
Material-Const Main Work Metal			\$18.10
Total Excluding Pearlescent Uplift			\$97.89
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$97.89

PARTS

Guide No. Qty Description		Part Number	Supplier	Price Valid: 01/06/2015	
				Bet.	Price (\$)
f: OEM Parts		Sub Total			\$0.00
g: Original		Deduction from RRP (35 %)			\$0.00
h: Secondhand		Total Parts			\$0.00
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description		Betterment		Price
N/S DOOR STICKER	SPECIALIST	0%	✓	\$100.00
FRONT FENDER	SPECIALIST			\$30.00
STICKER			X	
REAR FENDER	SPECIALIST	0%	✓	\$60.00
STICKER				
Total Extras				\$190.00

Final Calculation

Total Parts		\$0.00
Labour		
Total Panel/Mechanical	\$400.00	
Total Paintwork	\$375.00	
Total Labour		\$775.00
Additional Costs		
Corr Prot Materials External	\$0.00	

PREMIER AUTOMOTIVE SERVICES PTE LTD
23 Changi South Ave 2
#01-02, Singapore 486443

Assessment Number: MSIG0016
Version: PREMIERA/1

Assessor Report
Printed: 04/06/2018

Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$190.00	
Total of Additional Costs		\$190.00
Total Paint/Material Costs		\$97.89
Grand Total Excludes GST		\$1,062.89
GST @ 7 %		\$74.40
Grand Total Includes GST		\$1,137.29

Assessment Notes

Kahin 10/1/14
✓ 4/6/18 1000 Lm
2 Rpr.
P'P
Atta Rper phh

[Signature]
6/6/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 May 2018		31 May 2018 17:04 Edit Adj Rpt	S\$935.00 Edit Estimates	S\$935.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LEE ZENG FENG, ID: S8528263H, Tel: +6591838845								
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	SHB8301Z	Date of Loss:	30/05/2018 08:00 - :59 [10 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-000739	Policy/Cover Note No.:	MSD/VMT/18-381507-CA (Third Party Only) Coverage: 24/04/2018 - 23/04/2019						
Vehicle Reg. No. (Insured):	FU8431E	Policy No. (Claimant):							
		Excess:							
Repairer:	Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02, 486443 Changi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 30/06/2018]								
Driver/Custodian (Insured):	LEE ZENG FENG (32 / Male), NRIC: S8528263H, Tel: +6591838845								
Adj Asg. Remarks:	SJE : AGREED Please appoint LKK AUTO to conduct the survey .Kindly contact the workshop directly @ 6544 6676 or 6544 6689 Liability : 50%								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHB8301Z (MSC/V/18-000739)**
[FU8431E]
TP
PREMIER TAXIS PTE LTD
May 30 2018 8:00AM
[LEE ZENG FENG]
Premier Taxis Pte Ltd - Changi

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	06/06/18 10:16	Adjuster Immediate Advice	1 Load HTM		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
2	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
3	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
4	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
5	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
6	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
7	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
8	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
9	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
10	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
11	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
12	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
13	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
14	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
15	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
16	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
17	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
18	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
19	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
20	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
21	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
22	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
23	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
24	04/06/18 17:30	General View	1 Load JPG	<input checked="" type="checkbox"/>	
25	07/06/18 16:40	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>	
26	07/06/18 16:40	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>	
27	07/06/18 16:40	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>	
28	07/06/18 16:40	Reinspection Photo	1 Load JPG	<input checked="" type="checkbox"/>	

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	31/05/18 09:56	TPD SHB8301Z - PRI	1 Load PDF		
2	31/05/18 09:56	TPD SHB8301Z GIA REPORT	1 Load PDF		
3	31/05/18 09:56	OI FU8431E GIA REPORT	1 Load PDF		
4	31/05/18 10:50	REPLY FAX FROM TP WORKSHOP & LKK AUTO	1 Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18009947/K1TD3E2

Date: 20/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/MT/18-381507-CA
Claimant Vehicle No :	SHB8301Z	Insured Vehicle No :	FU8431E
Date of Loss:	30/05/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000739

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB8301Z		
Make & Model:	HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)	Engine No:	D4FBGZ127637
Reg. Date:	26/07/2017 (Man. Year: 2016)	Chassis No:	TMAD281UVHJ129436
Colour:	Silver	Odometer:	161340 km
Engine Capacity:	1582 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Maxxis 7 mm	Rear Left Side:	Maxxis 7 mm
Front Right Side:	Maxxis 7 mm	Rear Right Side:	Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	190.00	160.00	30.00	15.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	872.89	775.00	97.89	11.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,062.89	935.00	127.89	12.03
+ GST 7.00/7.00% (\$\$)	74.40	65.45	8.95	12.03
Nett Amount (\$\$)	1,137.29	1,000.45	136.84	12.03

INSPECTION

Date of Assignment:	31/05/2018	
Date Inspected:	04/06/2018	Inspected At: Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02 Singapore 486443
Estimated Period of Repair:	2.0 days	

Adjuster: KALVIN ANG WEI KUN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Jun 2018)	
Parts:	N/A	HYUNDAI I30 GDH 1.6 D TCI 5DR DCT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB8301Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S DOOR STICKER	Necessary	100.00 FS	*100.00 FS
2	1		*FRONT FENDER STICKER	Not Necessary	30.00 FS	*- FS
3	1		*REAR FENDER STICKER	Necessary	60.00 FS	*60.00 FS
Total Parts (S\$)					190.00	160.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOTAL PANEL / MECHANICAL	New	400.00	400.00
2	TOTAL PAINTWORK	New	375.00	375.00
3	TOTAL PAINT / MATERIAL COSTS	New	97.89	0.00
Gross Labour Cost (S\$)			872.89	775.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >