

22/03/2002

ASS. REC. BY:

REF:

03/ALG18009951/K/24d342

Special Instruction:

DAR. ✓

Surveyor:
Mennen

Kalin

ASSIGNMENT (Office)

From (Person):

chin lee ying

of

ALG

Date/Time:

31/5/18G 11:24am

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 1763K

Insured:

S2T 299H

at Workshop m/s

Cosmopolifun

Tel:

9026 4369

of

4 loyang walk

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/05/2018

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

11:30am @ 1/6/18

Person Contacted:

Michael

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	GBC 1763K -x
	S2T 299H -x.

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SLT299H AND GBC1763K ON 18/05/2018**

From: Chin, Lee-Ying

To: assignments@lkkauto.com, Admin A

Cc: Fong, Andy-SY

Sent: 31/5/2018 11:24:36 AM

Attachments:  9846788834SG 30 05 2018 RULINGS JUDGMENTS SENTENCES J40269-001.pdf

Hi LKK,

Kindly assist to survey, vehicle is in.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

499455

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS
 翠 NOTARY PUBLIC - 公证官
 玲 COMMISSIONER FOR OATHS - 宣誓官
 律

師 CATHERINE C. LIM
 馆 DIRECTOR

LL.B (HONS) SINGAPORE - 法律系 - 律師
 M.B.A. (BUSINESS LAW) - 商业系 - 碩士

Your Ref: SLT 299H
 Our Ref: CL/180539/T/COS.sg

25 May 2018

AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way
 #07-16
 Singapore 079120
 Attn: Motor Claims Department

Haryanto
 9 Sin Ming Walk
 #01-04
 Singapore 575578

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
 PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

ACCIDENT INVOLVING GBC 1763K / SLT 299H ON 18.05.2018 ALONG MARTIN PLACE

We are instructed by **Cosmopolitan Engrg Services Pte Ltd** to notify you of a road traffic accident involving our client's vehicle No. GBC 1763K and vehicle No. SLT 299H driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you/your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Venue: 4 Loyang Walk
 Singapore 508787

Tel: 6546 7728 Fax: 6546 7729

Yours faithfully


 cc: clients



Tel: (65) 6438 5500
 Fax: (65) 6438 0111
 www.catherinelimllc.com
 Email: info@catherinelimllc.com
 CATHERINE LIM LLC is a law corporation
 with limited liability



via fax: 6415 3727 & By Hand

CERTIFICATE OF POSTING
 (Please be informed that all supporting documents
 have been forwarded to your insurer.)

PDX Intercompany Exchange Pte Ltd



010808419998

FROM CATHERINE LIM LLC
 PDX Box No. 8004



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18009951/K1z4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 01-06-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLT 299H	Veh. Inspected	GBC 1763K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	01/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	18/05/2018	Inspection Date	01/06/2018
Survey held at	COSMOPOLITAN ENGRG. SERVICES PTE. LTD. 4 LOYANG WALK SINGAPORE 508787		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

ABC 1763/K

LH Metal Box Sliding Door — cut
LH Metal Box Rear Panel — cut
LH Metal Box Sliding Door Handle — Bent
1pc Rubber stopper — torn

Spray Paint \$400
Labour \$400

3 Days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jun 2018 Edit Reg		31 May 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	HARYANTO , ID: S68833151		
Main Claimant:	-		
Vehicle Reg. No.:	GBC1763K	Date of Loss:	18/05/2018 00:00 - :59
Claim Type:	TP / 9846788834SG	Policy/Cover Note No.:	2100471170 (Comprehensive) Coverage: 21/06/2017 - 20/06/2018
Vehicle Reg. No. (Insured):	SLT299H	Policy No. (Claimant):	
		Excess:	
Repairer:	Cosmopolitan Engineering Services Pte Ltd (HQ) NO. 4 LOYANG WALK SE(508787), 508787 Loyang - Tel: 65467728		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 12/06/2018]		
Claimant's Solicitor:	CATHERINE LIM LLC - Tel: 6438 5500		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (04/06/2018): **Request To Upload TP GIA Report**

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBC1763K (9846788834SG)

[SLT299H]

TP

-

May 18 2018 12:00AM

[HARYANTO]

Cosmopolitan Engineering Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
2	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
3	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
4	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
5	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
6	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
7	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
8	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
9	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
10	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
11	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
12	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
13	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
14	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
15	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
16	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
17	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
18	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
19	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
20	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
21	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
22	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
23	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
24	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
25	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
26	11/06/18 09:35		General View															Load JPG <input checked="" type="checkbox"/>		
Documentation															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail			Print		
1	04/06/18 17:10		OI GIA REPORT															Load PDF <input checked="" type="checkbox"/>		

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009951/K1Z4D3E2

Date: 27/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100471170
 Claimant Vehicle No: GBC1763K Insured Vehicle No: SLT299H
 Date of Loss: 18/05/2018 Nature of Claim: TP Claim No: 9846788834SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC1763K
 Make & Model: ISUZU CYZ52K, 15.7 D (M) Engine No: HIDDEN
 Reg. Date: (Man. Year:) Chassis No: HIDDEN
 Colour: White Odometer: 299392 km
 Engine Capacity: 0 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R13C (D)
 Front Left Side: OHTSU 4 mm Rear Left Side: Falken 4/4 mm
 Front Right Side: OHTSU 4 mm Rear Right Side: Falken 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 31/05/2018
 Date Inspected: 01/06/2018 Inspected At: Cosmopolitan Engineering Services Pte Ltd (HQ)
 NO. 4 LOYANG WALK SE(508787)
 Singapore 508787
 Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH METAL BOX SLIDING DOOR	Cut	0.00 F	*- F
2	1		*LH METAL BOX REAR PANEL	Cut	0.00 F	*- F
3	1		*LH METAL BOX SLIDING DOOR HANDLER	Bent	0.00 F	*- F
4	1		*RUBBER STOPPER	Torn	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >