

ASS. REC. BY:

REF: RS / msh 18009953 / 72462 Special Instruction:

Surveyor

612

ASSIGNMENT (Office)

Mwmm

From (Person): Monica Chung of msh Date/Time: 28/05/2018 4.12pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ 122A Insured: SGT 6906Dat Workshop n/s Alpha Car Services Tel: 6509 8258of Blk C Kaki Bukit Ave 6 #01-59Policy No: 28910812ANW Claim No: 559457

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 24052018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: Cai Ling Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SLQ 122A - X</u>
	<u>SGT 6906D - X</u>
<u>4/6/18</u>	<u>Dismantled</u>
<u>6/6/18</u>	<u>After Repair</u>

REF: MSG

6K >
Karl

ASSIGNMENT

(2017)

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s Alpha Auto
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured _____ Excess: _____
 (Client's Record)
 Make of Veh. _____

Veh No: SLQ 122A Yr Regn: 23 Jan 2007
 Type: G Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Estimo c.c. 2362
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 208337 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ACR 50000 777 3
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or _____
 Brake: Good / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 215/85 R17
 R: 16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. _____ D.O.I. 30-05-18
 Survey held at w/s _____ 3pm
 Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or _____
 The O/S Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	* Repair range : S\$ 19,000 - 21,000
	* 5 days
13/6/18	Submit PRS Report.
RECEIVED 13 JUN 2018	

Date/Time, File Pass to? : Prel. Report
 Date/Time, File Return to? : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Report Format : _____
 Lump Sum / I.B.I: (\$) _____

Add Fee: Site Insp (\$) _____
 Interview (\$) _____
 Tech. Invs (\$) _____
 Weekend (\$) _____

Survey Fee: _____
 Transportation: _____
 S + RE: _____
 Photos: _____
 Others: _____

120
50
10
180

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 May 2018		28 May 2018 16:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	Christoph Andre Riedweg, ID: 57369682H								
Main Claimant:	FONG MOTORS CAR RENTAL, Co. Reg. No.: 53371081B								
Vehicle Reg. No.:	SLQ122A	Date of Loss:	24/05/2018 10:00 - :59 [136 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 559457	Policy/Cover Note No.:	28910812AVW Coverage: 28/02/2018 - 27/02/2019						
Vehicle Reg. No. (Insured):	SGT6908D	Policy No. (Claimant):	Excess:						
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/05/2018]								
Adj Asp. Remarks:	TP Disagree on SJE - Please assign LKK AUTO OI non reporting - liability not clear. Contact Person / No: Hoo Yeong Hwa / 9136 8884 or 8226 5945								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/05/2018 11:26
Date Of Accident	24/05/2018 10:05
Exact Location Of Accident	AMK AVE 1 TOWARDS CTE EXIT TO WOODLANDS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ122A
Insured/Policyholder	
Name Of Registered Owner	FONG MOTORS CAR RENTAL
Co Reg No	53371081B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-85352515
Alternative Phone No	OFFICE-85352515
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ESTIMA
Exact Purpose for which vehicle was being used at time of accident	HIRER USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094712094
Cover Note Number	
Driver	
Name of Driver	ROSMAWATI BINTE ZAINAL SOIB
NRIC No	S68427811
Date Of Birth	20/12/1968
Occupation	OUTDOOR
Date Of Driving Pass	01/03/2011
Driving Experience	7 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-85352515
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	APT BLK 691 JURONG WEST CENTRAL 1 #01-183
Postcode	640691
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGT6908D
Vehicle Make/Model/Colour	VOLKSWAGEN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



SLG 122A
INDUSTRIAL PARK

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above mentioned date and time, I was driving the car bearing registration number [unclear] (Plate No. 1).

I was travelling on Lane 1 as indicated in which a lorry of my company and I check the traffic is clear that I decided to shift to the 2nd lane. Vehicle B was travelling in high speed (Lane 2) and it collided into the rear portion of my vehicle. My car is installed with an in-car camera.

DECLARATION

I declare the foregoing particulars are true in every respect.



Driver's Signature
Date & Time

[Handwritten signature]

Driver's Signature
(If Driver is not the policyholder)
Date & Time

[Handwritten signature]

Reporting Centre Personnel's Signature
Name
MARCH 2014

Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1081B
Vehicle Details	
Vehicle No.:	SLQ122A
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	2AZC065699
Chassis No.:	ACR500007773
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$33,296.00
Original Registration Date:	23 Jan 2007
First Registration Date:	23 Jan 2007
Transfer Count:	5
Actual ARF Paid:	\$36,626.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jan 2027
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$52,660.00
COE Rebate Amount:	\$45,383.00
Total Rebate Amount:	\$45,383.00

The information contained herein is correct as at 09 Jun 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 May 2018		28 May 2018 16:12 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	Christoph Andre Riedweg, ID: 57369682H								
Main Claimant:	FONG MOTORS CAR RENTAL, Co. Reg. No.: 53371081B								
Vehicle Reg. No.:	SLQ122A	Date of Loss: 24/05/2018 10:00 - :59 [136 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 559457	Policy/Cover Note No.: 28910812AVW Coverage: 28/02/2018 - 27/02/2019							
Vehicle Reg. No. (Insured):	SGT6908D	Policy No. (Claimant):							
		Excess:							
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 29/05/2018]								
Adj Asg. Remarks:	TP Disagree on SJE - Please assign LKK AUTO OI non reporting - liability not clear. Contact Person / No: Hoo Yeong Hwa / 9136 8884 or 8226 5945								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLQ122A (559457)**
[SGT6908D]
TP
FONG MOTORS CAR RENTAL
May 24 2018 10:00AM
[Christoph Andre Riedweg]
Alpha Car Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value=""/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
2	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
3	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
4	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
5	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
6	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
7	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
8	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
9	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
10	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
11	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
12	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
13	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
14	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
15	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
16	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
17	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
18	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
19	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
20	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
21	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
22	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
23	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
24	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
25	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
26	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
27	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
28	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
29	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
30	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
31	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
32	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
33	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
34	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
35	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
36	12/06/18 12:52	General View	Load JPG <input checked="" type="checkbox"/>
37	12/06/18 12:53	Dismantled Parts	Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	12/06/18 12:53	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	12/06/18 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	28/05/18 08:16	PRI Notice		Load PDF
2	28/05/18 09:39	TP List of surveyors & workshop details		Load PDF
3	28/05/18 09:39	TP Disagree on SJE		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18009952/GZ4BE2

Date: 14/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28910812AVW
Claimant Vehicle No : SLQ122A	Insured Vehicle No :	SGT6908D
Date of Loss: 24/05/2018	Nature of Claim:	TP
		Claim No: 559457

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ122A		
Make & Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Engine No:	2AZC065699
Reg. Date:	23/01/2007 (Man. Year: 2006)	Chassis No:	ACR500007773
Colour:	Black	Odometer:	208337 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	28/05/2018	
Date Inspected:	30/05/2018 Inspected At:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay Singapore 417883
Estimated Period of Repair:	0.0 days	

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$19,000.00 -\$21,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jun 2018)

Parts: M1-MPV TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLQ122A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

