

ASS. REC. BY:

REF

CS3/FCI18069959/G72403⁵²

Instruction:

Surveyor

GO

ASSIGNMENT (Office)

CWS

From (Person):

Fung Yin Min

of

FCI

Date/Time:

01/06/18 @ 9:28am

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKK 87364

Insured:

SHC 7066D

at Workshop m/s

Chuen Ho Auto

Tel:

9069 1985

of

1608in Ming Drive # 07-09

Policy No:

Claim No:

D18 UD 4349 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/05/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

12:23pm @ 1/6/18

Person Contacted:

Shavine

Vehicle

IN/OUT

Date/Time

Action/Instruction (Estimate

SKK 87364 -x

SHC 7066D - CS/FCI13017041/Tlvy3u2

D.O.A: 7/9/2013

x photos?

PRS

Xml

REF: FCI

59936

ASSIGNMENT

From: _____ Date: **4/6/18**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SKK 87364**

at Workshop m/s **Chun Hu Auto**

of **160 Sin Ming Drive # 07-09**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **\$ 56k**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{sup}

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

O	
N/S	O/S

Veh No: **SKK87364** Yr Regn: **10 Sep 2013**

Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: **KIA Forte 1.6 c.c 1591**

Colour: **Red** A/C: Insured / Std / NI / NA

Sp. Reading: **58625** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **KNAFZ 411 ME 511 8884**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **215/45 R17**

R: **11**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **FALKEN**

Front: _____ Rear: _____

R/Bal: **6** mm R/Bal: **6** mm

L/Bal: **6** mm L/Bal: **6** mm

D.O.A. _____ D.O.I. **04-06-18**

Survey held at **w/s** **4:30pm**

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
12/6/18	Submit PRS report

RECEIVED 13 JUN 2018

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

_____ \$ + RS _____ \$

Photos: _____

Others: _____

TOTAL _____

Add Fee: Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)

MOTOR SURVEY ASSIGNMENT

Date	31-05-2018	Our Ref No. D18004349MFSH
Accident Date	30-05-2018	Claim Type. Third Party
Insured Vehicle	SHC7066D	Third Party Vehicle. SKK8736U
Survey Location	160 SIN MING DRIVE #07-09	
Contact Person.	SHARINE LIM	
Contact No.	6456 1436/ 90691985	Fax No. 6457 9523
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUAN HO AUTO SERVICE	Attention. NIL
Cc : TP Solicitor	KURU & CO	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS3/FCI18009959/Gz4d3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-06-2018	
		Code : FCI2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHC 7066D	Veh. Inspected	SKK 8736U
Policy No.		Coverage (\$)	0.00
Claim No.	D18004399MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	01/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	30/05/2018	Inspection Date	
Survey held at	CHUAN HO AUTO SERVICE BLK 11 SECTOR B #01-85 SIN MING IND ESTATE SINGAPORE 575656.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/05/2018 14:21
Date Of Accident	30/05/2018 10:00
Exact Location Of Accident	ALEXANDRA RD (OUTSIDE KIA SERVICING CENTRE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK8736U
Insured/Policyholder	
Name Of Registered Owner	HO WEI SONG
NRIC No	S8935993G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82005032
Alternative Phone No	OFFICE-82005032

Vehicle Particulars

Manufacturer	KIA
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098628495
Cover Note Number	

Driver

Name of Driver	HO WEI SONG
NRIC No	S8935993G
Date Of Birth	12/10/1989
Occupation	INDOOR
Date Of Driving Pass	12/12/2008
Driving Experience	9 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82005032
Fax Number	
Contact Number	OFFICE-82005032
Email Address	NOEMAIL

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name HO WEI SONG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SKK8736U


Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 30/5/2018 AROUND 1000 HRS, I WAS TRAVELLING ALONG ALEXANDRA ROAD HEADING TO KIA SERVICING CENTRE WHEN SUDDENLY VEHICLE NO SAC 7066 D REVERSED AND KNOCK

ATTACH TO POLICE REPORT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Crash Report Form 1/18

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5993G
Vehicle Details	
Vehicle No.:	SKK8736U
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jun 2018
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	G4FGDH658286
Chassis No.:	KNAFZ411ME5118884
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$16,999.00
Original Registration Date:	10 Sep 2013
First Registration Date:	10 Sep 2013
Transfer Count:	1
Actual ARF Paid:	\$11,999.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Sep 2023
PARF Rebate Amount:	\$8,999.00
Intended COE Rebate Details	
COE Expiry Date:	09 Sep 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$75,556.00
COE Rebate Amount:	\$39,666.00
Total Rebate Amount:	\$48,665.00

The information contained herein is correct as at 09 Jun 2018

OK



Scoot to
Gold Coast

from **\$149***
ScootBiz from \$389*

Book Now

*Terms and conditions apply.

[SEARCH](#)

Price Range ▾
Depreciation ▾
Year Reg ▾
Vehicle Type ▾

Home » Used Cars » Inchcape Pre-Owned » Kia Forte K3 1.6A SX

- Resources**
- Car Buying ▾
 - Car Selling ▾
 - Car Ownership ▾
 - Car Aftermarket ▾
 - On The Move ▾
 - Lifestyle ▾

Commercial Vehicle



MORE THAN 1,000 FLEET UNIT
Daily, Weekly, Monthly & Yearly Fleet Available

▸ Kia Forte K3 1.6A SX


- [Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)



- [Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)

Car Details

Price	\$56,800
Depreciation	\$9,780 /yr ? <small>View models with similar depreciation</small>
Reg Date	24-Jul-2013 <small>(5yrs 1mth 14days COE left)</small>
Manufactured	2013 ?
Mileage	77,036 km (15.8k /yr)
Transmission	Auto
Engine Cap	1,591 cc
Road Tax	\$738 /yr ?
Power	95.3 kW (127 bhp) <small>View specs of the Kia Cerato Forte (2009-2013)</small>
Curb Weight	1,295 kg ?
Features	1.6L 4 Cylinder Inline DOHC Dual CVT. 6 Speed Auto Transmission. Airbags. Cruise Control. LED Day Running Lights. Large Boot Space.
Accessories	Rear Aircon. Multi Steering Function. Keyless Entry Push Start Button. Paddle Shifters. Electric Memory Seats. Ventilation Seats. Brown Leather Seats.
Description	One Year Inchcape Pre-Owned Warranty Provided. Fully Agent Maintain Since Day 1, 160 Points Check Done. C&C Warranty Till July 2018. One Owner. Top Popular Kia Sedan In The Market. No Repairs Needed. Beautiful Brown Exterior And Mint Leather Interior. Call/SMS Our Sales Consultant For More Enquires Now.
COE	\$73,989 ?



Seller Information

Company	Inchcape
Address	21 Selegie Road
Location	Inchcape

scoot

Scoot to Gold Coast from **\$149***
 ScootBiz from \$389*

Book Now

*Terms and conditions apply.

Queensland AUSTRALIA

OMV	\$18,433	?
ARF	\$13,433	?
Dereg Value	\$47,981 as of today (change)	?
No. of Owners	1	?
Type of Veh	Mid-Sized Sedan	
Category	PARF Car, Premium Ad Car	
Availability	Available	PREMIUM AD

[★ Add to Shortlist](#)
 [📄 Add to Compare](#)
 [📝 Add a Note](#)

Posted on: 09-Jun-2018 | Last Updated on: 09-Jun-2018
 Tags: Kia Forte, 2013 Kia Forte, Kia, Forte, Used Kia

Upfront Payment		» more Financial Info
Transfer Fee	\$25	?
Down Payment	\$17,040 (change)	Maximum 70% Loan ?
1st Instalment	\$751	?
Total Upfront Payment	\$17,816 (excluding insurance)	?

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.


Office No 63

Contact Person(s) Ja
CF

USED CAR LIST

STA Afraid of le
this car ev

Recommended for you



All new 2019 Kia Forte makes world debut



Kia and Thinkware at COMEX 2016



Anyone scrapping 2010 Kia forte with EPS?



Vehicle sales and transfers to go online




New 2017 Kia Forte K

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Res

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Audi, Kia, Hyundai, Volkswagen, Mitsubishi & BMW. There are cars, OPC cars, vans, luxury cars, sports cars, SUV, MPV, hatchback or stationwagons. You can also buy from a car auction and look up car loans, low mil carpark rates, car audio, car grooming, car rental, vehicle insurance, car insurance quotation, car blog, car accessories, car workshop & car sticker. Visit our jobs, real estate properties for sale, facebook marketing, mover, car performance parts, car discussion, forum discussion, commercial vehicle

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the a

Follow **sgCarMart.com**



About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Stateme

CHEAPEST CAR INSURANCE RENEWAL

Compare 10+ Insurers

GET A CHE

Home » Used Cars » Carro » Kia Forte K3 1.6A SX

- Resources**
- Car Buying
 - Car Selling
 - Car Ownership
 - Car Aftermarket
 - On The Move
 - Lifestyle

Car Tyres

MICHELIN PILOT SPORT 4
AS RESPONSIVE AS YOU ARE.

Kia Forte K3 1.6A SX

- [Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

CARRO THE BETTER AUTOMOTIVE EXPERIENCE FOR EVERYBODY

- [Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)

Car Details	
Price	\$55,000
Depreciation	\$7,980 /yr View models with similar depreciation
Reg Date	24-Jul-2014 (6yrs 1mth 14days COE left)
Manufactured	2014
Mileage	57,500 km (14.8k /yr)
Transmission	Auto
Engine Cap	1,591 cc
Road Tax	\$738 /yr
Power	95.3 kW (127 bhp)
Curb Weight	1,295 kg
Features	4 Cylinder Inline 16 Valves DOHC Dual CWT Engine Producing 127 Bhp, 6 Speed Auto Transmission, Front Wheel Drive, Front/Rear Disc Brakes, LED Lights.
Accessories	Sports Rims, Factory Audio System Aux/USB Port, Reverse Camera, Fog Lamps, Multi Zone/Rear Aircon, Auto Headlights, Airbags, ABS. Keyless Push Start.
Description	Kia Forte 1.6 Auto K3 SX Version With Brown Leather Seats. Immaculate Condition. Serviced By C&C. The Car Is Accident Free. Electric Memory Seats, Ventilation Seats. Schedule A Test Drive Today. Viewing Is Strictly By Appointment Only.
COE	\$61,990
OMV	\$17,212



Seller Information

Company C&C

CIMB RENOVATION LOAN

The key to your dream home.

Apply & receive complimentary home insurance coverage*.

FORWARD
Your Dream Home



*T&Cs apply. Homewell ISS is underwritten by Sampo Insurance and distributed by CIMB Bank Berhad.

CIMB Bank Berhad (13401-0)



ARF	\$12,212	?
Dereg Value	\$47,134 as of today (change)	?
No. of Owners	1	?
Type of Veh	Mid-Sized Sedan	
Category	PARF Car, Premium Ad Car	
Availability	Available	PREMIUM AD

☆ Add to Shortlist 📄 Add to Compare 📝 Add a Note

Posted on: 16-May-2018 | Last Updated on: 02-Jun-2018

Tags: Kia Forte, 2014 Kia Forte, Kia, Forte, Used Kia

Upfront Payment » more Financial info

Transfer Fee	\$25	?
Down Payment	\$16,500 (change)	Maximum 70% Loan ?
1st Instalment	\$623	?
Total Upfront Payment	\$17,148 (excluding insurance)	?

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.

»
av
Address 26
Se
Location Mi
Office No 67
Contact Person(s) Ja



Recommended for you



Eight useless 'performance' car mods




Tyre size for stock KIA Forte 17" rim



Kia launches upgraded 2017 Cerato Forte K3



New 2017 Kia Forte K3




Look good and feel beautiful with AFOND S

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Res

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Audi, Kia, Hyundai, Volkswagen, Mitsubishi & BMW. There are cars, OPC cars, vans, luxury cars, sports cars, SUV, MPV, hatchback or stationwagons. You can also buy from a car auction and look up car loans, low mil carpark rates, car audio, car grooming, car rental, vehicle insurance, car insurance quotation, car blog, car accessories, car workshop & car sticker. Visit our jobs, real estate properties for sale, facebook marketing, mover, car performance parts, car discussion, forum discussion, commercial vehicle

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the

Follow **sgCarMart.com**



About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
FIRST CAPITAL INSURANCE LTD		Ref:	CS3/FCI18009959/Gz4d3s2
36 ROBINSON ROAD		Date:	19-06-2018
#16-01 CITY HOUSES SINGAPORE 068877			
		Code:	FCI2
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHC 7066D	Veh. Inspected	SKK 8736U
Policy No.		Coverage (\$)	0.00
Claim No.	D18004399MFSH	Excess (\$)	0.00
Assign From	AUNG YIN MIN	Assign Date	01/06/2018
2. Vehicle Particulars & Condition			
Make & Model	KIA FORTE 1.6	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KNAFZ411ME5118884	Colour	RED
Odometer	58625 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/45R17	FALKEN	6 mm
L/H Front Tyre	215/45R17	FALKEN	6 mm
R/H Rear Tyre	215/45R17	FALKEN	6 mm
L/H Rear Tyre	215/45R17	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
5. General Information			
Accident Date	30/05/2018	Inspect Date / Time	04/06/2018 (04:30 PM)
Survey held at	CHUAN HO AUTO SERVICE 160 SIN MING DRIVE #07-09 SINGAPORE 575721		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) MARKET VALUE: \$56,000.00			

Report Ref No. CS3/FCI18009959/Gz4d3s2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.