

ASS. REC. BY:

REF:

es/AG18009966/Gld32

Special Instruction:

Supervisor

GG

ASSIGNMENT (Office)

From (Person):

Ehin Lee Ying

of

AIG

Date/Time:

1/6/18 @ 11:47am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SBH 3300Z

Insured:

at Workshop m/s

Motor Image

Tel:

90903323

of

19 Iong B Lee Payoh

Policy No:

Claim No:

Sum Insured:

Excess:

TBA 1400 06/6/18

Make of Veh:

D.O.A.

(Client's Record)

CA / (REV) / REP. / REV 24 HRS

5/6/18 @

H.O.D. Endorsement:

Date/Time:

2:10pm @ 1/6/18

Person Contacted:

Kuan

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

06/6/18 @

SBH 3300Z-003/AG18 003191/Kpu3q2
3-bpm informed via Loop & 1400 by email.

D.O.A: 15/2/2016

Part by Part \$4452.69 (Red: 4620.60 :50%)

YML

REF: ALH

0017J

ASSIGNMENT

From: Date: 05062018
Estimated Cost: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SBH 3300Z
at Workshop n/s: Motor Image
of: 19 Lorong 8 Tou Payoh
Insured:
Policy No:
Claims No:
Sum Insured: Excess: TBA / 400
(Client's Record)
Make of Veh:
(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: \$99k
IDAC Accident Report: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 8 days Res: Yes or No
Lump Sum: % 3 Val: Yes or No
☒ CA / ☒ REP. / 24 HRS
Date: Person Contacted: Vehicle: IN / OUT

Vehicle: SBH 3300Z Yr Regn: 22 Jan 2016
Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer n/s
Make: Subaru Forester 20XT 1998
Colour: Red A/C: Insured / Std / NI / NA
Sp Reading: 51888 T/Radio: Insured / Std / NI / NA
Eng/Tr:
C/No: JF1SJ GK 85 FG 060253
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: ☒ In order / Jammed / Leaked / Burnt or
Brake: ☒ In order / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/55R18
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Continental
Front: Rear:
R/Bal: 7 mm R/Bal: 7 mm
L/Bal: 7 mm L/Bal: 7 mm
D.O.A: D.O.I: 05-06-18
Survey held at: w/s 5:45pm
Des. of Damages: Fnt / Rear / O/S / ☒ N/S / U/C / Rooftop or
This U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
Sent manmen for offer to acceptance.

RECEIVED 30 NOV 2018

Draw/Time, File Pass to? ☐ : Prel. Report
3011 Typist ☒ : Final Report

Days Of Repair: 8
Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Insp (\$)
☐ Wheeling (\$)

Survey Fee: 200
Transport: 10
Total: 210

Report Format:
Lump Sum / I.B.f: 445269

From: Chin, Lee-Ying <Lee-Ying.Chin@aig.com>
Sent: Friday, 1 June 2018 11:47 AM
To: assignments@lkkauto.com; Admin A
Subject: - FW: SBH3300Z - OD CLAIMS - AIG - SURVEY - 05/06/2018 - 1000 HRS
Attachments: SecureMessageAtt.html



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ
เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을
읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2018-06-08 11:47 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 6 June 2018 3:40 PM
To: Kuan Wei Loong
Cc: SUR
Subject: EXCESS OF VEHICLE SBH 3300Z (DOA: 29/05/2018)

Dear Wei Loong,

Please be informed that the excess of above vehicle is \$1,400.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0017J
Vehicle Details	
Vehicle No.:	SBH3300Z
Vehicle to be Exported:	No
Intended De-registration Date:	06 Jun 2018
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0XT CVT AWD SR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	FA20K999910
Chassis No.:	JF1SJGK85FG060253
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$17,932.00
Original Registration Date:	22 Jan 2016
First Registration Date:	22 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$17,932.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jan 2026
PARF Rebate Amount:	\$13,449.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jan 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$60,001.00
COE Rebate Amount:	\$45,742.00
Total Rebate Amount:	\$59,191.00

The information contained herein is correct as at 06 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/05/2018 09:41
Date Of Accident	29/05/2018 15:45
Exact Location Of Accident	WOOD GROVE CAR PARK EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBH3300Z
Insured/Policyholder	
Name Of Registered Owner	ONG KENG ROSE
NRIC No	S1770017J
Email Address	ROSEONG26@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96861012
Alternative Phone No	HOME-63147882

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 AWD (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100449140
Cover Note Number	

Driver

Name of Driver	ONG KENG ROSE
NRIC No	S1770017J
Date Of Birth	26/02/1966
Occupation	INDOOR
Date Of Driving Pass	12/08/1995
Driving Experience	22 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96861012
Fax Number	
Contact Number	HOME-63147882
Email Address	ROSEONG26@GMAIL.COM

Address	5 ROSEWOOD DRIVE #17-09 S(737936)
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT BY FALLEN TREE / OTHER OBJECTS
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident


KINDLY REFER TO DOCUMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I came out from the car park lot (A), despite I reversed and adjust I turn left towards the car park port, I heard metal crumple sound. I car could not reverse and I drove forward and drove home to check. I realised my car was badly scratched.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 30/5/2018

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

PERSONAL PARTICULARS

TYPE OF CLAIM: ☒ OWN DAMAGE ☒ 3RD PARTY () ☐ REPORTING ONLY ()
DATE OF ACCIDENT: 29th May 2018 TIME OF ACCIDENT: 3-30 pm - 4 pm
LOCATION OF ACCIDENT: Woodgrove car park lot
VEHICLE REGISTRATION NO: QBH 3300 Z MANUFACTURER: SUBARU MODEL: Forester
NAME OF REGISTERED OWNER/INSURED: Ong Keng Rose NRIC NO: S17700 17-J
PURPOSE OF VEHICLE BEING USED AT THE TIME OF ACCIDENT: Leisure
INSURANCE COMPANY: AIG POLICY NO: 2100449140-02

DRIVER PARTICULARS

NAME OF DRIVER: Ong Keng Rose NRIC NO: S17700 17-J
GENDER: MALE ☒ FEMALE ☐
HOME TEL: 63147882 HP NO: 96261012 FAX NO: _____
E-MAIL: roseong26@gmail.com or roseong@motorcycle.net
ADDRESS: No 5 Rosewood Drive #17-09 POSTAL CODE: 737936
DATE OF BIRTH: 26-02-1966 DRIVING PASS DATE: 12 Aug 1995

(PLEASE TICK AND FILL THE RELEVANT CHOICES)

WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY ☐ YES ☒ NO
IF NO, RELATIONSHIP OF DRIVER WITH THE INSURED: _____
INSURANCE POLICY NO: _____
WEATHER CONDITION:
☒ CLEAR ☐ RAINING ☐ OTHERS: Carpark Dark
WAS ACCIDENT REPORTED TO THE POLICE:
☒ NO ☐ YES, WHICH POLICE STATION: _____
WAS ANYBODY INJURED IN THE ACCIDENT:
☒ NO ☐ YES NAME: _____ INJURIES SUSTAINED: _____
NO OF PASSANGERS INCLUDING DRIVER: Nil
VEHICLE NO OF INJURED/PASSANGER OF OTHERS: _____
CONVEYED TO HOSPITAL ☒ NO ☐ YES, TO WHICH HOSPITAL: _____

4/06/2018
arrange survey
~~1400 Hrs.~~
1400 Hrs.

(THIRD PARTY DRIVER'S PARTICULARS)


DRIVER NAME: _____ NRIC NO: _____ HP NO: _____
VEHICLE REGISTRATION NO: _____ MANUFACTURE: _____ MODEL: _____

WITNESS'S PARTICULARS

NAME: _____ NRIC: _____ HP NO: _____

****TO PROVIDE & ATTACH NRIC, DRIVING LICENSE FRONT / REAR COPY, VAILD INSURANCE CERT AND ACCIDENT SITE PHOTOS****

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I came out from the car park lot (A), despite I reversed and adjust I turn left towards the car park post, I heard metal crumple sound I car could not reverse and I drove forward and drove home to check. I realised my car was badly scratched.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 30/5/2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0786/2018
DATE : 30-MAY-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SEHNTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :

OWNER'S NAME : ONG KENG ROSE
ADDRESS : 5 ROSEWOOD DRIVE #17-09

TELEPHONE NO : 5(737936)
: 96861012

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 2100449140-02
VEHICLE NO : SBH3300Z
MODEL CODE : SJOCKER
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20R999910
CHASSIS NO : JF1SJKR85FG060253
MILEAGE : 51690 KM
DATE IN : 30/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 30/05/2018

Print Date : 30/05/2018
Print Time : 15:11:17

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SBH3300Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ODCLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM AT LOCATION: WOODGROVE CARPARK EXIT DATE: 29/05/2018 TIME: 1545HRS		
3	ZZ/002	REPAIR/REPLACE FRONT LHS DOOR, REAR LHS DOOR, REAR LHS FENDER AND REAR BUMPER	1250.00	1000. ✓
4	ZZ/003	RESPRAY FRONT LHS DOOR, REAR LHS DOOR, REAR LHS FENDER AND REAR BUMPER	1000.00	800 ✓
5	ZZ/004	DISMANTLE/REFIX UNDERCARRIAGE REAR LHS/RHS/CENTER TO FACILITATE REPAIR	684.00	X NN +
6	ZZ/005	REMOVE/REFIX EXHAUST	114.00	X NN +
7	ZZ/006	TRANSFER DOOR FRONT LHS AND REAR LHS MECHANISM	284.00	/ ✓
8	ZZ/007	WHEEL ALIGNMENT	171.00	/ ✓
9	ZZ/008	REMOVE/REFIX CARPET, SEATS TO FACILITATE REPAIRS	342.00	X { NN +
10	ZZ/009	REMOVE/INSTALL REAR LHS QUARTER GLASS	142.00	X { NN +
11	ZZ/011	SUNDRIES	100.00	30 ✓
12	ZZ/10	TO SUPPLY/INSTALL REAR LHS QUARTER GLASS TINTED FILM	145.00	X NN
TOTAL LABOUR CHARGES			4232.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SBH3300Z

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 PNL SD OUT QTR RPLH <i>X Repas</i>	51439SG0119P			864.00	X
2 BUMPER FACE R <i>- Cut</i>	57704SG012			540.00	✓
3 BRKT CORNER R RH <i>X NN</i>	57707SG060			18.00	X
4 BRKT CORNER R LH <i>- MC</i>	57707SG070			18.00	✓
5 REAR BUMPER BRACKET - RHS <i>X NN</i>	57707SG080			14.40	X
6 BRKT SD R LH <i>- MC</i>	57707SG090			14.40	✓
7 PNL COMPL DR F LH <i>X Repas</i>	60009SG0529P			720.00	X
8 PNL COMPL DR R LH <i>- BUC</i>	60409SG0119P			684.00	✓
9 COVER HDL OUT DR R <i>X</i>	61134FJ100TQ			15.90	X
10 HANDLE OUT DR <i>X</i>	61160FJ000EN			46.80	X
11 HANDLE OUT DR SMT <i>X</i>	61160FJ010E4			158.40	X
12 SPACER DR HANDLE OUT A <i>X</i>	61252FJ000			3.60	X
13 SPACER DR HANDLE OUT <i>X</i>	61252FJ010			3.60	X
14 WSTR OUT DR F LH <i>X</i>	61280SG030			100.80	X
15 WSTR OUT DR R LH <i>X NN</i>	62280SG030			100.80	X
16 WSTR DR F LH <i>X NN</i>	63511SG011			144.00	X
17 WSTR DR R LH <i>X NN</i>	63512SG011			144.00	X
18 GLASSRUN DR R LH <i>X NN</i>	63527SG030			72.00	X
19 GLASSRUN F DR LH <i>X NN</i>	63527SG110			72.00	X
20 WSTR BODY SD FLG F <i>X NN</i>	63571SG001			122.40	X
21 WSTR BODY SD FLG R <i>X NN</i>	63572SG001			72.00	X
22 WDW GL ASSY R QTR LH <i>X</i>	65209SG051			324.00	X
23 DAM RUBBER <i>X</i>	65245SG000			21.60	X
24 DAM RUBBER 1/4 GL RH/LH <i>X</i>	65245SG000			14.40	X
25 TAPE DR SASH F F LH <i>- MC</i>	90422SG010			5.40	✓

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
26	TAPE DR SASH F M LH	90422SG030			18.00	X
27	TAPE DR SASH F R LH	90422SG050			18.00	X
28	TAPE DR SASH R F LH	90422SG070			18.00	/
29	TAPE DR SASH R M LH	90422SG090			10.80	/
30	TAPE DR SASH R R LH	90422SG110			14.40	/
SUB TOTAL			0.00	0.00	0.00	4373.70
LESS DISCOUNT (S/LIST-30 %)			0.00	0.00	0.00	1312.11
GRAND TOTAL			0.00	0.00	0.00	3061.59
OVERALL TOTAL			3061.59			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

LH
 Rear ~~Part~~ Door Garish. / Gt.
 Rear LH Rim - Gt
 Rear ~~Part~~ LH Tender Rubber - TN

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SBR3300Z

TOTAL LABOUR CHARGES	4232.00
TOTAL SPARE PARTS CHARGES	3061.59
GRAND TOTAL	7293.59 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY :
REMARKS :

Guo Qiang - 82880282

Authorised.

before paint photos.

8 Days. 6xcess TBA


8/6/18

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

82880282

- Like Auto Consultants hence notify the Repairer of the following:
- To resurvey 3 days after body painting
 - To display damaged parts during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary dem(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0786/2018
DATE : 30-MAY-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :

OWNER'S NAME : ONG KENG ROSE
ADDRESS : 5 ROSEWOOD DRIVE #17-09
S(737936)
TELEPHONE NO : 96861012

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 2100449140-02
VEHICLE NO : S8H33002
MODEL CODE : SJGCC88
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20K999910
CHASSIS NO : JF1SJK885FG060253
MILEAGE : 31894 KM
DATE IN : 30/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 1400.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 29/05/2018

Print Date : 18/06/2018
Print Time : 09:46:42

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SBH300Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	00CLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM AIG LOCATION:WOODGROVE CARPARK EXIT DATE:29/05/2018 TIME:1545HRS		
3	ZZ/002	REPAIR/REPLACE FRONT LHS DOOR, REAR LHS DOOR, REAR LHS FENDER AND REAR BUMPER	1250.00	1000.00 /
4	ZZ/003	RESPRAY FRONT LHS DOOR, REAR LHS DOOR, REAR LHS FENDER AND REAR BUMPER	1000.00	800.00 /
5	ZZ/004	DISMANTLE/REFIX UNDERCARRIAGE REAR LHS/RES/CENTER TO FACILITATE REPAIR	684.00	.00
6	ZZ/005	REMOVE/REFIX EXHAUST	114.00	.00
7	ZZ/006	TRANSFER DOOR FRONT LHS AND REAR LHS MECHANISM	284.00	284.00 /
8	ZZ/007	WHEEL ALIGNMENT	171.00	171.00 /
9	ZZ/008	REMOVE/REFIX CARPET, SEATS TO FACILITATE REPAIRS	342.00	.00
10	ZZ/009	REMOVE/INSTALL REAR LHS QUARTER GLASS	142.00	.00
11	ZZ/011	SUNDRIES	100.00	30.00 /
12	ZZ/012	TRANSFER/BALANCE TYRE/RIM (SUPP)	28.00	28.00 / (CP) /
13	ZZ/10	TO SUPPLY/INSTALL REAR LHS QUARTER GLASS TINTED FILM	145.00	.00
TOTAL LABOUR CHARGES			4260.00	2313.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SBH3300Z

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 DISC WHEEL AL 18 18A (SUPP) / Cent	28111SG020			1500.00	OK / (A)
2 PNL SD OUT QTR RPLH	51439SG0119P			864.00	X
3 BUMPER FACE R	57704SG012			540.00	OK /
4 BRKT CORNER R RH	57707SG060			18.00	X
5 BRKT CORNER R LH	57707SG070			18.00	OK /
6 REAR BUMPER BRACKET - RRS	57707SG080			14.40	X
7 BRKT SD R LH	57707SG090			14.40	OK /
8 PNL COMPL DR F LH	60009SG0529P			720.00	X
9 PNL COMPL DR R LH	60409SG0119P			684.00	OK /
10 COVER HDL OUT DR R	61134FJ100TQ			15.90	X
11 HANDLE OUT DR	61160FJ000EN			46.80	X
12 HANDLE OUT DR SMT	61160FJ010E4			158.40	X
13 SPACER DR HANDLE OUT A	61252FJ000			3.60	X
14 SPACER DR HANDLE OUT	61252FJ010			3.60	X
15 WSTR OUT DR F LH	61280SG030			100.80	X
16 WSTR OUT DR R LH	62280SG030			100.80	X
17 WSTR DR F LH	63511SG011			144.00	X
18 WSTR DR R LH	63512SG011			144.00	X
19 WSTR BODY ARCH R LH (SUPP) / 7N	63526SG010			57.60	OK / (A)
20 GLASSRUN DR R LH	63527SG030			72.00	X
21 GLASSRUN F DR LH	63527SG110			72.00	X
22 WSTR BODY SD FLG F	63571SG001			122.40	X
23 WSTR BODY SD FLG R	63572SG001			72.00	X
24 WDW GL ASST R QTR LH	65209SG051			324.00	X
25 DAM RUBBER	65245SC000			21.60	X

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SBH3300Z

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
26	DAM RUBBER 1/4 CL RH/LH	65245SG000			14.40	X
27	TAPE DR SASH F F LH	90422SG010			5.40	OK ✓
28	TAPE DR SASH F M LH	90422SG030			18.00	X
29	TAPE DR SASH F R LH	90422SG050			18.00	X
30	TAPE DR SASH R F LH	90422SG070			18.00	OK ✓
31	TAPE DR SASH R M LH	90422SG090			10.80	OK ✓
32	TAPE DR SASH R R LH	90422SG110			14.40	OK ✓
33	GARNISH AY DR R LH (SUPP) / Cwt	91112SG252			194.10	OK ✓ (CP)
SUB TOTAL			0.00	0.00	0.00	3056.70
LESS DISCOUNT (S/LIST-30 %)			0.00	0.00	0.00	917.01
GRAND TOTAL			0.00	0.00	0.00	2139.69
OVERALL TOTAL			2139.69			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SBE3300Z

NETT ITEM	0.00
LESS 20 %	0.00
NETT AMOUNT	0.00
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	0.00
S/LIST ITEM	3056.70
LESS 30 %	-917.01
S/LIST AMOUNT	2139.69
TOTAL LABOUR CHARGES	2313.00
TOTAL SPARE PARTS CHARGES	2139.69
TOTAL CHARGES	4452.69
LESS EXCESS	1400.00
TOTAL	3052.69
ADD 7 % GST	213.69
GRAND TOTAL	3266.38

9073-21



Motor Image Enterprises Pte Ltd
19 Lorong 8 Ton Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO SBH 3300 Z

Surveyor: Goro Qiang

DESCRIPTION	PART NO	AMOUNT
1 Disc Wheel AL 18	28111SG020 (A) Cnt	\$1500
2 Rear LH Door Garnish	91112SG252 (A) Cnt	\$194.10
3 Rear LH Fender Rubber	63526SG010 (A) TN	\$57.60
4		
5		
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY LABOUR FOR VEHICLE REGISTRATION NO SBH 33007Z

Surveyor: _____

LABOUR DESCRIPTION


AMOUNT

1	Transfer / balance tyre and rim L/rear. /	\$ 28.00/- (A)
2		
3	General	
4	06/6/18	
5		
6		
7		
8		
9		
10		
11		
12		

MOTOR IMAGE ENTERPRISES PTE LTD
19, LORONG 8, TOA PAYOH, SINGAPORE 319255
MAIN LINE : (65) 6703 8333
FAX : (65) 6252 5655
SERVICE CENTRE TEL : 6703 8101/02
WEBSITE : www.motorimage.net

Work Order: R000585
 Name 2: ONG KENG ROSE
 Company: 5 ROSEWOOD DRIVE
 License: SBH3300Z
 Year: 16
 Technician: WAIFOONG
 Odometer: 51690
 Date: 6.6.18 15:43

Subaru 2016-18 Forester SJ
4-Wheel Total Alignment



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 07 Sep 2018

Preliminary Advice

Insured Vehicle No	: SGU7348H		
TP Vehicle No	: SHC6033E	Accident Date	: 31/08/2018
Make	: KIA OPTIMA	Assignment Date	: 04/09/2018
Date of Inspection	: 05/09/2018	Est. Duration of Repair	: 3 days
Inspection At	: Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02 Singapore 486443		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,000.74
Revised Amount	:S\$	1,213.09
Check Items (Estimated)	:S\$	507.65
Total	:S\$	1,720.74

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BOUN REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0786/2018
DATE : 30-MAY-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :

OWNER'S NAME : ONG KING ROSE
ADDRESS : 5 ROSEWOOD DRIVE #17-09

S(737936)
TELEPHONE NO : 96861012

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 2100449140-02
VEHICLE NO : SHE3300Z
MODEL CODE : SJGCKX8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20K999910
CHASSIS NO : JF1SJGK85PQ060253
MILEAGE : 51690 KM
DATE IN : 30/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 30/05/2018

Print Date : 30/05/2018
Print Time : 15:11:17

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SHH3300Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	00CLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT CD CLAIM AT LOCATION: WOODGROVE CARPARK EXIT DATE: 29/05/2018 TIME: 1545HRS		
3	ZZ/002	REPAIR/REPLACE FRONT LHS DOOR, REAR LHS DOOR, REAR LHS FENDER AND REAR BUMPER	1250.00	1000.
4	ZZ/003	RESPRAY FRONT LHS DOOR, REAR LHS DOOR, REAR LHS FENDER AND REAR BUMPER	1000.00	800
5	ZZ/004	DISMANTLE/REFIX UNDERCARRIAGE REAR LHS/RHS/CENTER TO FACILITATE REPAIR	684.00	X NN
6	ZZ/005	REMOVE/REFIX EXHAUST	114.00	X NN
7	ZZ/006	TRANSFER DOOR FRONT LHS AND REAR LHS MECHANISM	284.00	/
8	ZZ/007	WHEEL ALIGNMENT	171.00	/
9	ZZ/008	REMOVE/REFIX CARPET, SEATS TO FACILITATE REPAIRS	342.00	X
10	ZZ/009	REMOVE/INSTALL REAR LHS QUARTER GLASS	142.00	X
11	ZZ/011	SUNDRIES	100.00	30
12	ZZ/10	TO SUPPLY/INSTALL REAR LHS QUARTER GLASS TINTED FILM	145.00	X
TOTAL LABOUR CHARGES			4232.00	

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
26	TAPE DR SASH F M LH X	90422SG030				18.00
27	TAPE DR SASH F R LH X	90422SG050				18.00
28	TAPE DR SASH R F LH X /	90422SG070				18.00
29	TAPE DR SASH R M LH X / {mc	90422SG090				10.80
30	TAPE DR SASH R R LH /	90422SG110				14.40
SUB TOTAL			0.00	0.00	0.00	4373.70
LESS DISCOUNT (S/LIST-30 %)			0.00	0.00	0.00	1312.11
GRAND TOTAL			0.00	0.00	0.00	3061.59
OVERALL TOTAL			3061.59			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

Rear ~~RR~~ LH Door Garish. / Cct.
 Rear LH Rim - Cct
 Rear ~~RR~~ LH Tender Rubber - TR

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SBH3300Z

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 PNL SD OUT QTR RPLH <i>X Repair</i>	51439SG0119P				864.00
2 BUMPER FACE R <i>/ Cut</i>	57704SG0012				540.00
3 BRKT CORNER R RH <i>X</i>	57707SG0060				18.00
4 BRKT CORNER R LH <i>/ NCL</i>	57707SG0070				18.00
5 REAR BUMPER BRACKET - RRS <i>X</i>	57707SG0080				14.40
6 BRKT SD R LH <i>/ NCL</i>	57707SG0090				14.40
7 PNL COMPL DR F LH <i>X Repair</i>	60009SG0529P				720.00
8 PNL COMPL DR R LH <i>/ Bul</i>	60409SG0119P				684.00
9 COVER HDL OUT DR R <i>X</i>	61134FJ1007Q				15.90
10 HANDLE OUT DR <i>X</i>	61160FJ000EN				46.80
11 HANDLE OUT DR SMT <i>X</i>	61160FJ010E4				158.40
12 SPACER DR HANDLE OUT A <i>X</i>	61252FJ000				3.60
13 SPACER DR HANDLE OUT <i>X</i>	61252FJ010				3.60
14 WSTR OUT DR F LH <i>X</i>	61280SG0030				100.80
15 WSTR OUT DR R LH <i>?</i>	62280SG0030				100.80
16 WSTR DR F LH <i>X</i>	63511SG0011				144.00
17 WSTR DR R LH <i>?</i>	63512SG0011				144.00
18 GLASSHLD DR R LH <i>?</i>	63527SG0030				72.00
19 GLASSHLD F DR LH <i>X</i>	63527SG0110				72.00
20 WSTR BODY SD FLG F <i>X</i>	63571SG0001				122.40
21 WSTR BODY SD FLG R <i>?</i>	63572SG0001				72.00
22 WDW GL ASSY R QTR LH <i>X</i>	65209SG0051				324.00
23 DAM RUBBER <i>X</i>	65245SG0000				21.60
24 DAM RUBBER 1/4 GL RH/LH <i>X</i>	65245SG0000				14.40
25 TAPE DR BASH F F LH <i>/</i>	90422SG0010				5.40

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LOHENG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SRH300Z

TOTAL LABOUR CHARGES	4232.00
TOTAL SPARE PARTS CHARGES	3061.59
GRAND TOTAL	7293.59 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	:
LIABILITY	:
REMARKS	:

Guo Qiao - 82880282
Authorized.
before paint photo S.
8 Days. Excess TBA

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jun 2018		06 Jun 2018 11:58 Edit Adj Rpt	S\$4,452.69 Edit Estimates	S\$4,452.69 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: ONG KENG ROSE , ID: S1770017, Tel: +6596861012, Email: roseong26@gmail.com									
Vehicle Reg. No.: SBH3300Z		Date of Loss: 29/05/2018 15:00 - :59 [28 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 3121072362SG		Policy/Cover Note No.: 2100449140 (Comprehensive)							
		Excess: S\$1,400.00							
Repairer: Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038101									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 18/06/2018]									
Driver/Custodian: ONG KENG ROSE (52 / Female) , NRIC: S1770017, Tel: +6596861012									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (06/06/2018): SBH3300Z / OD / 29/05/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SBH3300Z (3121072362SG)
 OD
 May 29 2018 3:45PM
 [ONG KENG ROSE]
 Motor Image Enterprises Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		☐	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	06/06/18 15:35	General View													 Load JPG	☒				
2	06/06/18 15:35	General View													 Load JPG	☒				
3	06/06/18 15:35	Chassis Number													 Load JPG	☒				
4	06/06/18 15:35	Odometer Reading													 Load JPG	☒				
5	06/06/18 15:35	General View													 Load JPG	☒				
6	06/06/18 15:35	General View													 Load JPG	☒				
7	06/06/18 15:35	General View													 Load JPG	☒				
8	06/06/18 15:35	General View													 Load JPG	☒				
9	06/06/18 15:35	General View													 Load JPG	☒				
10	06/06/18 15:35	General View													 Load JPG	☒				
11	06/06/18 15:35	General View													 Load JPG	☒				
12	06/06/18 15:35	General View													 Load JPG	☒				
13	06/06/18 15:35	General View													 Load JPG	☒				
14	06/06/18 15:35	General View													 Load JPG	☒				
15	06/06/18 15:35	General View													 Load JPG	☒				
16	06/06/18 15:35	General View													 Load JPG	☒				
17	06/06/18 15:35	General View													 Load JPG	☒				
18	06/06/18 15:35	General View													 Load JPG	☒				
19	06/06/18 15:35	General View													 Load JPG	☒				
20	06/06/18 15:35	General View													 Load JPG	☒				
21	06/06/18 15:35	General View													 Load JPG	☒				
22	06/06/18 15:35	General View													 Load JPG	☒				
23	06/06/18 15:35	General View													 Load JPG	☒				
24	06/06/18 15:35	General View													 Load JPG	☒				
25	06/06/18 15:35	General View													 Load JPG	☒				
26	06/06/18 15:35	General View													 Load JPG	☒				
27	06/06/18 15:35	General View													 Load JPG	☒				
28	06/06/18 15:35	General View													 Load JPG	☒				
29	06/06/18 15:35	General View													 Load JPG	☒				
30	06/06/18 15:35	General View													 Load JPG	☒				
31	06/06/18 15:35	General View													 Load JPG	☒				
32	06/06/18 15:35	General View													 Load JPG	☒				
33	06/06/18 15:35	General View													 Load JPG	☒				
34	06/06/18 15:35	General View													 Load JPG	☒				
35	06/06/18 15:35	General View													 Load JPG	☒				
Documentation															1 per page		☐	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	06/06/18 15:35	ESTIMATE													 Load PDF					

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
2	05/12/18 12:13	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	1 per page	☒
1	30/05/18 10:05	Accident Statement	 Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	30/05/18 10:03	Accident Photo	 Load JPG	☒
2	30/05/18 10:03	Accident Photo	 Load JPG	☒
3	30/05/18 10:03	Accident Photo	 Load JPG	☒
4	30/05/18 10:03	Accident Photo	 Load JPG	☒
5	30/05/18 10:03	Accident Photo	 Load JPG	☒
6	30/05/18 10:03	Accident Photo	 Load JPG	☒
7	30/05/18 10:03	Accident Photo	 Load JPG	☒
8	30/05/18 10:03	Accident Photo	 Load JPG	☒
9	30/05/18 10:03	Accident Photo	 Load JPG	☒
10	30/05/18 10:03	Accident Photo	 Load JPG	☒
11	30/05/18 10:03	Accident Photo	 Load JPG	☒
12	30/05/18 10:03	Accident Photo	 Load JPG	☒
13	30/05/18 10:03	Accident Photo	 Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	30/05/18 10:01	Accident Sketch Plan	 Load JPG	☒
2	30/05/18 10:01	Accident Sketch Plan	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG18009966/GTD3E2

Date: 05/12/2018

REFERENCE

Insured/Claimant: ONG KENG ROSE Policy No: 2100449140
Date of Loss: 29/05/2018 Nature of Claim: OD Claim No: 3121072362SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBH3300Z**
Make & Model: SUBARU FORESTER, 2.0 AWD (A) Engine No: FA20K999910
Reg. Date: 22/01/2016 (Man. Year: 2015) Chassis No: JF1SJGK85FG060253
Colour: Red Odometer: 51888 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$99,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
Front Left Side: Continental 7 mm Rear Left Side: Continental 7 mm
Front Right Side: Continental 7 mm Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,387.78	2,169.69	2,218.09	50.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,160.00	2,283.00	1,877.00	45.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,547.78	4,452.69	4,095.09	47.91
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	7,147.78	3,052.69	4,095.09	57.29
+ GST 7.00/7.00% (S\$)	500.34	213.69	286.65	57.29
Nett Amount (S\$)	7,648.12	3,266.38	4,381.74	57.29

INSPECTION

Date of Assignment: 06/06/2018

Date Inspected: 05/06/2018 Inspected At:

Motor Image Enterprises Pte Ltd (Toa Payoh)
19 Lorong 8 Toa Payoh
Singapore 319255

Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
2	1		*PNL SD OUT QTR RPLH	Repair	864.00 FL	*- FL
3	1		*BUMPER FACE R	Cut	540.00 FL	*540.00 FL
4	1		*BRKT CORNER R RH	Not Necessary	18.00 FL	*- FL
5	1		*BRKT CORNER R LH	Necessary	18.00 FL	*18.00 FL
6	1		*REAR BUMPER BRACKET - RHS	Not Necessary	14.40 FL	*- FL
7	1		*BRKT SD R LH	Necessary	14.40 FL	*14.40 FL
8	1		*PNL COMPL DR F LH	Repair	720.00 FL	*- FL
9	1		*PNL COMPL DR R LH	Buckled	684.00 FL	*684.00 FL
10	1		*COVER HDL OUT DR R	Not Necessary	15.90 FL	*- FL
11	1		*HANDLE OUT DR	Not Necessary	46.80 FL	*- FL
12	1		*HANDLE OUT DR SMT	Not Necessary	158.40 FL	*- FL
13	1		*SPACER DR HANDLE OUT A	Not Necessary	3.60 FL	*- FL
14	1		*SPACER DR HANDLE OUT	Not Necessary	3.60 FL	*- FL
15	1		*WSTR OUT DR F LH	Not Necessary	100.80 FL	*- FL
16	1		*WSTR OUT DR R LH	Not Necessary	100.80 FL	*- FL
17	1		*WSTR DR F LH	Not Necessary	144.00 FL	*- FL
18	1		*WSTR DR R LH	Not Necessary	144.00 FL	*- FL
19	1		*GLASSRUN DR R LH	Not Necessary	72.00 FL	*- FL
20	1		*GLASSRUN F DR LH	Not Necessary	72.00 FL	*- FL
21	1		*WSTR BODY SD FLG F	Not Necessary	122.40 FL	*- FL
22	1		*WDW GL ASSY R QTR LH	Not Necessary	324.00 FL	*- FL
23	1		*DAM RUBBER	Not Necessary	21.60 FL	*- FL
24	1		*DAM RUBBER 1/4 GL RH/LH	Not Necessary	14.40 FL	*- FL
25	1		*TAPE DR SASH F F LH	Necessary	5.40 FL	*5.40 FL
26	1		*TAPE DR SASH F M LH	Not Necessary	18.00 FL	*- FL
27	1		*TAPE DR SASH F R LH	Not Necessary	18.00 FL	*- FL
28	1		*TAPE DR SASH R F LH	Necessary	18.00 FL	*18.00 FL
29	1		*TAPE DR SASH R R LH	Necessary	14.40 FL	*14.40 FL
30	1		*DISC WHEEL AL 18	Cut	1,500.00 FL	*1,500.00 FL
31	1		*REAR LH DOOR GARNISH	Cut	194.10 FL	*194.10 FL
32	1		*REAR LH FENDER RUBBER	Torn	57.60 FL	*57.60 FL
33	1		*WSTR BODY SD FLG R	Not Necessary	72.00 FL	*- FL
34	1		*TAPE DR SASH R M LH	Necessary	10.80 FL	*10.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	6,225.40	3,086.70
- List Item Discount on L Items 30.00/30.00% (\$\$)	1,837.62	917.01
Total Parts (\$\$)	4,387.78	2,169.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (S\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RESPRAY FRONT LHS DOOR, REAR LHS DOOR, REAR LHS FENDER AND REAR BUMPER	New	1,000.00	800.00
2	DISMENTLE / REFIX UNDERCARRIAGE REAR LHS/RHS/CENTER TO FACILITATE REPAIR	New	684.00	0.00
3	REMOVE / REFIX EXHAUST	New	114.00	0.00
4	TRANSFER DOOR FRONT LHS AND REAR LHS MECHANISM	New	284.00	284.00
5	WHEEL ALIGNMENT	New	171.00	171.00
6	REMOVE / REFIX CARPET, SEATS TO FACILITATE REPAIRS	New	342.00	0.00
7	REMOVE / INSTALL REAR LHS QUARTER GLASS	New	142.00	0.00
8	TO SUPPLY / INSTALL REAR LHS QUARTER GLASS TINTED FILM	New	145.00	0.00
9	TRANSFER / BALANCE TYRE AND RIM L/REAR	New	28.00	28.00
10	REPAIR / REPLACE FRONT LHS DOOR, REAR LHS DOOR, REAR LHS FENDER AND REAR BUMPER	New	1,250.00	1,000.00
Gross Labour Cost (S\$)			4,160.00	2,283.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >