

REF:

CC3/ALH18009968 / Agonz

ASS. REC. BY: Adrian Ling

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

04888 days

Res.: Yes or No

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLW2232X

Yr Regn:

2018, Feb.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A2

c.c 999

Colour:

Orange

A/C: Insured / Std / NI / NA

Sp. Reading

7017

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAU226A7JA048412

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F: 215/60R16

R: 215/60R16

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

01/06/18

Survey held at

Premium

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OO AIG

04/6/18 @

SLW 2232X - CC3/ALH18009968 / Agonz

05/6/18 @

2.33pm Informed Premium C/A's ex: TBA by email. (COR ≤ B8K)

09/11/18 @

10.54am Informed Premium ex: \$800 by email.
11.39am Confirmed with Mr Boo final Ag & \$324.64, 4 days.
(Red & \$8755.36, 62%)

RECEIVED 04 DEC 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) 03/12/18

☐

: Final Report

Date/Time, File Return to?

2)

Report Format

Lump Sum / L.B.E (%)

MKT-OD

5324.64

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) \$ + RS \$1

) Others:

) Others:

0/123

200
10

210

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 9 November 2018 11:39 AM
To: 'Boo seng yak'; SUR; Carrine Leong; jiajee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: RE: FINAL REVISION - SLW2232X - OD AIG - SURVEYED 1 JUN 18

Dear Mr Boo,

WITHOUT PREJUDICE

Confirm final fig \$5,324.64 before excess \$800.00 & GST and 4 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Monday, 23 July 2018 7:03 PM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiajee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SLW2232X - OD AIG - SURVEYED 1 JUN 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$5324.64 @ 4 days of repairs.

Your early closure is appreciated.

best regards - jb

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 5 June 2018 10:54 AM
To: Claims
Cc: SUR
Subject: RE: VEHICLE SLW 2232X (DOA: 28/05/2018)

Dear Sir/Madam,

Please be informed that the excess of above vehicle is \$800.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 4 June 2018 2:33 PM
To: Claims <claims@premiumauto.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: VEHICLE SLW 2232X (DOA: 28/05/2018)

Dear Sir/Madam,

Please proceed to repair the insured vehicle **SLW 2232X (Excess TBA)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 4 June 2018 2:33 PM
To: Claims
Cc: SUR
Subject: VEHICLE SLW 2232X (DOA: 28/05/2018)

Dear Sir/Madam,

Please proceed to repair the insured vehicle **SLW 2232X (Excess TBA)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9062Z
Vehicle Details	
Vehicle No.:	SLW2232X
Vehicle to be Exported:	No
Intended De-registration Date:	04 Jun 2018
Vehicle Make:	AUDI
Vehicle Model:	Q2 1.0 TFSI S TRONIC
Primary Colour:	Orange
Manufacturing Year:	2017
Engine No.:	CHZ614162
Chassis No.:	WAUZZZGA7JA048412
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$26,514.00
Original Registration Date:	01 Feb 2018
First Registration Date:	01 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$29,120.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Jan 2028
PARF Rebate Amount:	\$21,840.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,890.00
COE Rebate Amount:	\$35,620.00
Total Rebate Amount:	\$57,460.00

The information contained herein is correct as at 04 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/05/2018 15:20
Date Of Accident	28/05/2018 10:25
Exact Location Of Accident	30 SEGAR ROAD CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW2232X
Insured/Policyholder	
Name Of Registered Owner	ZHOU XUANMING
NRIC No	S8409062Z
Email Address	XM@LIVE.COM.SG
Mobile Phone No	(LOCAL) +65-96945854
Alternative Phone No	HOME-67177804

Vehicle Particulars

Manufacturer	AUDI
Model	Q2 1.0 TFSI S-TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800009810
Cover Note Number	

Driver

Name of Driver	ZHOU XUANMING
NRIC No	S8409062Z
Date Of Birth	09/04/1984
Occupation	INDOOR
Date Of Driving Pass	15/02/2011
Driving Experience	7 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96945854
Fax Number	
Contact Number	HOME-67177804
Email Address	XM@LIVE.COM.SG

Address	BLK 30 SEGAR ROAD #08-08
Postcode	677721
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WHILE TURNING OUT FROM MY PARKING LOT, I DIDNT NOTICE THE PILLAR BESIDE MY CAR AND SCRAPPED AGAINST IT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	PILLAR
Details Of Properties	
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Tony Fong
NRIC/FIN No.: 6204907X

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While turning out from my parking lot, I didn't notice the pillar beside my car and scraped against it.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time: 29/5/2018
1458 hrs.


Driver's Signature
(If driver is not the policyholder)

Date & Time: 29/5/2018
1458 hrs.



Reporting Centre Personnel's Signature

Name: Jay Fung
NRIC/FIN No.: 820401471

Accident Photo





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : ZHOU XUANMING
Period of Insurance : 01 Feb 2018 To 31 Jan 2019
Engine No. : CHZ614162
Chassis No. : WAUZZZGA7JA048412

Vehicle No. :
Policy No. : 1800009810
Endorsement No. : 000000000179056
Issued Date : 07 Feb 2018

ABOUT THE COVER

Make/Model	AUDI Q2/ Q2 Sport 1.0 TFSI S tronic	Sum Insured	Market Value	First Year of Registration	2018
Engine Capacity/Tonnage	999.00 CC	Off Peak Car	No	Insuring with COE/PAF	Yes
Driver Restriction	NA				

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 186) and Section 95 of the Road Transport Act, 1987 (Malaysia); are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen - \$100

Named Driver and Excess (where applicable)

ZHOU XUANMING - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 409599 63652323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 186), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1955 (Malaysia).

0504126208

PREMIUM LEASING - SLOH

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Sir Han Lim

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, make and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised reporters within 24 hours of the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, make and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised reporters within 24 hours of the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault of blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised reporters within 24 hours of the next working day of the accident.
- Submit MMR (Motor Claims) Correspondence (with third parties) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 5 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e. refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/636/2018/NK
Date	:	30-May-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Zhou XuanMing
Address	:	BLK 30 Segar Road #08-08 Singapore 677721
Telephone	:	HP +65 96945854
Type of Claim	:	Own Damage Claim
Policy No.	:	1800009810
Vehicle No	:	SLW 2232 X
Model Code	:	Audi Q2 1.0 TFSI
Model / Year	:	Feb-18
Engine No	:	CHZ 614162
Chassis No	:	WAUZZZGA7JA048412
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	28-May-18
Place of Accident	:	30 Segar Road Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 2232 X.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rhs front and rear door's multi-lock system abd power window devices.	S/N \$ 560.00	280 ✓
2	To dismantle and renew rhs front and rear doors, align to position. Repair rhs B-pillar and sill panel. Reinstall all parts removed.	\$ 2,800.00	1000 + 250 - B Pillar ✓
3	To respray rhs front and rear doors, door handle and ehs B-pillar and sill panel.	\$ 2,900.00	1100 + 550 ✓
4	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,452.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2232 X

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR RHS <i>Distorted</i>	\$ 2,174.00	✓ 1739.70
2	DOOR CATCH <i>new</i>	\$ 105.00	×
3	FRONT DOOR HANDLE RHS <i>Dist</i>	\$ 207.00	✓ 165.60
4	FRONT DOOR HANDING HOUSING RHS <i>Dist</i>	\$ 26.00	✓ 20.32
5	FRONT DOOR MOUNTING BAR RHS <i>new</i>	\$ 143.00	×
6	FRONT WINDOW GUIDE RHS <i>new</i>	\$ 359.00	×
7	FRONT WINDOW REGULATOR RHS <i>2 new NEC</i>	\$ 232.00	? X
8	FRONT WINDOW REGULATOR MOTOR RHS	\$ 212.00	? X
9	FRONT DOOR COVER FRONT RHS <i>Dist.</i>	\$ 226.00	✓ 180.40
10	EXTERIOR MOUNTING RHS <i>Dist</i>	\$ 446.00	✓ 360
11	MIRROR GLASS RHS <i>new</i>	\$ 274.00	×
12	MIRROR CAP <i>Distorted</i>	\$ 132.00	✓ 105.60
13	TURN SIGNAL INDICATOR RHS <i>new</i>	\$ 80.00	×
14	DOOR WINDOW FRONT RH <i>new</i>	\$ 183.00	×
15	DATA PLATE FOR TYRE PRESSURE <i>new</i>	\$ 25.00	✓ 19.76
16	REAR DOOR RHS <i>Dist</i>	\$ 1,975.00	×
17	REAR OUTER DOOR SEAL RHS <i>new</i>	\$ 113.00	×
18	BONDING AGENT <i>2 new</i>	\$ 43.00	? X
19	CLEANING SOLUTION	\$ 64.00	? X
20	APPLICATOR	\$ 6.00	? X
SUB SPARE PARTS		\$ 7,025.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2232 X

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	DOOR CATCH <i>phd</i>	\$ 105.00	+
22	REAR DOOR COVER RHS <i>lit</i>	\$ 198.00	✓ 158.40
23	SUNDRIES <i>Rec</i>	\$ 300.00	? 3.36 ✓
TOTAL SPARE PARTS		\$ 7,523.00	7628
TOTAL LABOUR CHARGES		\$ 6,452.00	
GRAND TOTAL		\$ 13,975.00	14080

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian King
: 01/06/18
:
:
:
:
: xre Authorised. 01 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/636/2018/PH
Date	:	30-Jun-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

4 days - ok - jb - 23 Jul 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Zhuo Xuan Ming
Address	:	Blk 30 Segar Road #08-08 Singapore 677721
Telephone	:	HP +65 96945854
Type of Claim	:	Own Damage Claim
Policy No.	:	1800009810
Vehicle No	:	SLW 2232 X
Model Code	:	Audi Q2 1.0 TFSI
Model / Year	:	Feb-18
Engine No	:	CHZ 614162
Chassis No	:	WAUZZZGA7JA048412
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	28-May-18
Place of Accident	:	30 Segar Road carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 2232 X.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer RHS front & rear door's device multi lock system and power window devices.	S/N	\$ 560.00	\$ 280.00
2	To dismantle and renew RHS front and rear doors, align to position. Repair RHS B-pillar and sill panel. Reinstall all parts removed.		\$ 2,800.00	\$ 1,000.00
3	To respray RHS front and rear doors, door handle and RHS B-pillar and sill panel.		\$ 2,900.00	\$ 1,100.00
4	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 6,452.00</u>	<u>\$ 2,572.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2232 X.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	DOOR - RH	\$ 2,174.00	\$ 1,739.20
2	DOOR CATCH	\$ 105.00	
3	FRONT DOOR HANDLE - RHS	\$ 207.00	\$ 165.60
4	FRONT DOOR HANDING HOUSING - RHS	\$ 26.00	\$ 20.32
5	FRONT DOOR MOUNTING BAR - RHS	\$ 143.00	
6	FRONT WINDOW GUIDE - RHS	\$ 359.00	
7	FRONT WINDOW REGULATOR - RHS	\$ 232.00	
8	FRONT WINDOW REGULATOR MOTOR - RHS	\$ 212.00	
9	FRONT DOOR COVER - FRONT RHS	\$ 226.00	\$ 180.40
10	EXTERIOR MOUNTING - RHS	\$ 446.00	\$ 360.00
11	MIRROR GLASS - RHS	\$ 274.00	
12	MIRROR CAP	\$ 132.00	\$ 105.60
13	TURN SIGNAL INDICATOR - RHS	\$ 80.00	
14	DOOR WINDOW - FRONT RH	\$ 183.00	
15	DATA PLATE FOR TYRE PRESSURE	\$ 25.00	\$ 19.76
16	REAR DOOR - RHS	\$ 1,975.00	
17	REAR OUTER DOOR SEAL - RHS	\$ 113.00	
18	BONDING AGENT	\$ 43.00	
19	CLEANING SOLUTION	\$ 64.00	
20	APPLICATOR	\$ 6.00	
SUB-TOTAL SPARE PARTS		\$ 7,025.00	\$ 2,590.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No. SLW 2232 X.

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLW 2232 X

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0636/2018/MAS

29 Nov 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLW 2232 X, Audi Q2 1.0 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SLW 2232 X**, claimant, **Mr. Zhou Xuanming**, please find the related document per attached.

1. A copy of the Original invoice no. 85013168 – S\$4,841.36
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLW 2232 X

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183










































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jun 2018		01 Jun 2018 17:17 Edit Adj Rpt	S\$5,324.64 Edit Estimates	S\$5,324.64 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ZHOU XUANMING, ID: S8409062Z, Tel: +6596945854, Email: XM@LIVE.COM.SG								
Vehicle Reg. No.:	SLW2232X	Date of Loss:	28/05/2018 10:00 - :59 [3 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 6924742432SG	Policy/Cover Note No.:	1800009810 (Comprehensive)						
		Excess:	S\$800.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/06/2018]								
Driver/Custodian:	ZHOU XUANMING (34 / Male), NRIC: S8409062Z, Tel: +6596945854								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (04/06/2018): SLW2232X / OD / 28/05/2018 / Coverage & Excess update 									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLW2232X (6924742432SG)
 OD
 May 28 2018 10:25AM
 [ZHOU XUANMING]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		Use Viewer		▼
Photos/Images															3 per page		▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
2	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
3	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
4	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
5	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
6	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
7	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
8	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
9	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
10	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
11	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
12	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
13	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
14	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
15	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
16	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
17	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
18	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
19	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
20	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
21	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
22	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
23	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
24	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
25	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
26	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
27	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
28	05/11/18 14:58	General View													Load JPG	<input checked="" type="checkbox"/>			
29	05/11/18 14:58	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>			
30	05/11/18 14:58	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>			
31	05/11/18 14:58	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>			
32	05/11/18 14:58	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>			
33	05/11/18 14:58	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>			
34	05/11/18 14:58	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>			
35	05/11/18 14:58	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>			
Documentation															1 per page		▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	04/06/18 14:29	Singapore Accident Statement													Load PDF				
2	04/06/18 14:29	Certificate of Insurance													Load PDF				
3	04/06/18 14:29	Driver's Driving License													Load PDF				
4	04/06/18 14:29	ESTIMATE													Load PDF				
5	05/12/18 08:50	WORKSHOP INVOICE													Load PDF				
6	05/12/18 08:50	DISCHARGE VOUCHER													Load PDF				

Linked Accident Report Documents

			View	Use Viewer	
Assessment Reports			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/05/18 15:54	Accident Statement	1	Load HTM	
Photos/Images			3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/05/18 15:43	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	28/05/18 15:43	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	28/05/18 15:43	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	28/05/18 15:43	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	28/05/18 15:43	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	28/05/18 15:43	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	28/05/18 15:43	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	28/05/18 15:43	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
9	28/05/18 15:43	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
10	28/05/18 15:43	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
11	28/05/18 15:43	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
12	28/05/18 15:43	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
13	28/05/18 15:43	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
14	28/05/18 15:43	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/05/18 15:46	Sketch Plan	1	Load JPG	<input checked="" type="checkbox"/>
2	28/05/18 15:46	Sketch Plan #2	1	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18009968/AQBN2

Date: 05/12/2018

REFERENCE

Insured/Claimant:	ZHOU XUANMING	Policy No:	1800009810	Claim No:	6924742432SG
Date of Loss:	28/05/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW2232X	Engine No:	CHZ614162
Make & Model:	AUDI Q2, 999cc TFSI S-TRONIC (A)	Chassis No:	WAUZZZGA7JA048412
Reg. Date:	01/02/2018 (Man. Year: 2017)	Odometer:	7017 km
Colour:	Orange		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$130,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,628.00	2,752.64	4,875.36	63.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,452.00	2,572.00	3,880.00	60.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,080.00	5,324.64	8,755.36	62.18
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	13,280.00	4,524.64	8,755.36	65.93
+ GST 7.00/7.00% (S\$)	929.60	316.72	612.88	65.93
Nett Amount (S\$)	14,209.60	4,841.36	9,368.24	65.93

INSPECTION

Date of Assignment:	01/06/2018	
Date Inspected:	01/06/2018	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RHS	Distorted	2,174.00 FS	*1,739.20 FS
2	1		*DOOR CATCH	Not Necessary	105.00 FS	*- FS
3	1		*FRONT DOOR HANDLE RHS	Damaged	207.00 FS	*165.60 FS
4	1		*FRONT DOOR HANDING HOUSING RHS	Damaged	26.00 FS	*20.32 FS
5	1		*FRONT DOOR MOUNTING BAR RHS	Not Necessary	143.00 FS	*- FS
6	1		*FRONT WINDOW GUIDE RHS	Not Necessary	359.00 FS	*- FS
7	1		*FRONT WINDOW REGULATOR RHS	Not Necessary	232.00 FS	*- FS
8	1		*FRONT WINDOW REGULATOR MOTOR RHS	Not Necessary	212.00 FS	*- FS
9	1		*FRONT DOOR COVER FRONT RHS	Deformed	226.00 FS	*180.40 FS
10	1		*EXTERIOR MOUNTING RHS	Damaged	446.00 FS	*360.00 FS
11	1		*MIRROR GLASS RHS	Not Necessary	274.00 FS	*- FS
12	1		*MIRROR CAP	Distorted	132.00 FS	*105.60 FS
13	1		*TURN SIGNAL INDICATOR RHS	Not Necessary	80.00 FS	*- FS
14	1		*DOOR WINDOW FRONT RH	Not Necessary	183.00 FS	*- FS
15	1		*DATA PLATE FOR TYRE PRESSURE	Necessary	25.00 FS	*19.76 FS
16	1		*REAR DOOR RHS	Repair	1,975.00 FS	*- FS
17	1		*REAR OUTER DOOR SEAL RHS	Not Necessary	113.00 FS	*- FS
18	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
19	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
20	1		*APPLICATOR	Not Necessary	6.00 FS	*- FS
21	1		*DOOR CATCH	Not Necessary	105.00 FS	*- FS
22	1		*REAR DOOR COVER RHS	Cut	198.00 FS	*158.40 FS
23	1		*SUNDRIES	Necessary	300.00 FS	*3.36 FS
					Total Parts (\$\$)	7,628.00 2,752.64

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER RHS FRONT AND REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	560.00	280.00
2	TO DISMANTLE AND RENEW EHS FRONT AND REAR DOORS ALIGN TO POSITION.REPAIR RHS B-PILLAR AND SILL PANEL.REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
3	TO RESPRAY RHS FRONT AND REAR DOORS,DOOR HANDLE AND EHS B-PILLAR AND SILL PANEL	New	2,900.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			6,452.00	2,572.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >