





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18009991/K1qb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 Date: 02-06-2018



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJL 1892D	Veh. Inspected	SHA 4472U
Policy No.	5100815955	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	01/06/2018

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	01/06/2018	Inspection Date	01/06/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/0997300-001	COMFORT TRANSPORTATION PTE LTD	SHA 4472U	SIL 1892D	01/06/2018	4:00	\$ 3,136.35

eBaoTech

GeneralClaim

Hello, NAC\_PAYA\_UB1\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="01/06/2018 14:50"/>						
Vehicle No.(For Motor)	<input type="text" value="S3L1892D"/>								
<input type="button" value="Search"/>									
Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	S100815955	KINETIC ALLIANCE PTE LTD	201613074E	GPC	Third Party	S3L1892D	S3L1892D	24/05/2018	23/02/2019
<input type="button" value="Continue"/>									

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

VEHICLE NO : SHA 4472U

1/6/2018 15:11

MAKE :

MODEL : TOYOTA PRIUS

NETUIC  
JH

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID LOGO(PRIUS) <i>me</i>			\$ 60.80
REAR TRUNK LID LOGO(HYBRID) <i>me</i>			\$ 52.40
REAR TRUNK LID LOGO(TOYOTA STAR) <i>me</i>			\$ 52.90
REAR BUMPER <i>1st</i>			\$ 458.60
REAR BUMPER RE-INFORCEMENT <i>X</i>			\$ 318.80
REAR BUMPER UNDER COVER <i>cl</i>			\$ 552.60
REAR BUMPER SIDE RETAINER, LH <i>X</i>			\$ 112.70
REAR BUMPER SPONGE <i>X</i>			\$ 143.40
REAR BUMPER UNDER SIDE COVER (LH) <i>me</i>			\$ 232.00
REAR BUMPER CLIPS <i>me</i>			\$ 22.00
ARM SUB-ASSY, REAR BUMPER, LH <i>X</i>			\$ 139.60
SEAL, REAR BUMPER SIDE, LH <i>X</i>			\$ 148.40
SUB TOTAL			\$ 2,294.20
LESS 25%			\$ 573.55
DISCOUNTED TOTAL			\$ 1,720.65
REAR TRUNK LID APPS STICKER <i>me</i>	<i>10%</i>		\$ 40.00
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>me</i>	<i>10%</i>		\$ 60.00
REAR BUMPER REVERSE SENSOR <i>shut</i>	<i>10%</i>		\$ 135.70
			\$ 235.70
LABOUR CHARGE			
Panel Beating			\$ 200
Spray Painting Charge			\$ 400.00
Wiring Charge			\$ 500.00
Tuff Kote			\$ 50.00
Towing Charge			\$ 50.00
Remove/Refix Reverse Sensor			\$ 60.00
			\$ 120.00
TOTAL LABOUR			\$ 1,180.00
ESTIMATE TOTAL			\$ 3,136.35

NETT 36  
NETT 54  
NETT 122.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- To be held in place until approval is allowed
- Resurvey must be resurveyed and subject to insurance approval from insurance company

Approved by Repairer

Kaluh (LKK)  
1/6/18 15:30hrs  
2 Pys  
PIP  
Before Paint photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Date/Time: 01.06.2018 14:50 Page : 1

ARC Repair TP(CLSO)1 JOB CARD Sales Order: JC NO305168183

COMFORT TRANSPORTATION PTE LTD NO. 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 55508755 (O)	REGN NO: SHA4472U	MILEAGE
	MAKE: TOYOTA	FUEL E.....1/2.....F
	MODEL PRIUS HYBRID(G4)01.06.2018 04:00	DATE/TIME IN
	YR OF MANU 25.05.2017	TARGET DATE
	CHASSIS CODE JTDKB3FUX03556930	COMPLETION DATE/TIME

ARD NO.

JOB DESCRIPTION

ent Date: 01.06.2018  
E: 3P 01.06.18

LABOR CODE DESCRIPTION

PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

int Slip

Exit Pass

SHA4472U JU NTUC

Vehicle No.: SHA4472U

Advisor Signature/Date

Name of Service Advisor Date

Service Reception upon collection

To be kept by Security Guard

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/06/2018 13:51
Date Of Accident	01/06/2018 04:00
Exact Location Of Accident	BUS STOP ALONG TAMPINES AVE 9 OUTSIDE TAMPINES JUN
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA4472U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 4G

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	NG KEH LAIN
NRIC No	S1511167D
Date Of Birth	31/01/1961
Occupation	OUTDOOR
Date Of Driving Pass	04/11/1980
Driving Experience	37 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81151245
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 95 BEDOK NORTH AVENUE 4 #11-1401
Postcode	460095
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJL1892D
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM JUN XIAN
NRIC/Passport Number	S9301088D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1



Name	NG KEH LAIN
Approximate Age	
Injuries Sustain	GIDDY
Injured person in which vehicle?	SHA4472U
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Loke Wei Yiang


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 1/6/18 at about 04:00 hrs, my taxi stopped at bus stop outside of Tampines Junior College along Tampines Ave 9. I was sat inside my taxi having rest.

Suddenly I felt an impact from my behind followed a jerk. Thereafter, I stepped out to have a check and found a car SJL 1892D collided onto the rear portion of my stationary taxi.

No passenger in my taxi. However, I felt giddy after accident/ will consult doctor later on.


## DECLARATION

I/We declare the foregoing particulars are true in every respect.  
COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 198303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Our Job Ref No : 305168183  
Date : 04/06/18

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
69 Loyang Drive Singapore 508969  
Fax: 6548 8156

### FINALIZATION FORM

To : LKK  
Attn : KALVIN  
: SHA4472U


Fax :


Date of Accident : 01/06/18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: NTUC --- SJL1892D  
###
- The finalized amount shall be:
  - Spare Parts after List discount \$1,285.6/
  - Labour Charges ### \$620.00
  - Total for Part-By-Part Repair Cost \$1,905.6/
  - Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
Final Lumpsum Repair cost
- Estimated normal period for repairs: 2 working days
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
- Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature :   
Name : JUMANI  
Tel : 6214 8315  
Fax : 65468156

Signature :   
Name : Kalvin  
Date : 4/6/18

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 04.06.2018  
Time: 17:42:00  
Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS: COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305168183  
REGN NO : SHA4472U  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4)  
DATE OF REGN : 25.05.2017  
DATE/TIME IN : 01.06.2018 04:00  
ACCIDENT DATE : 01.06.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1	458.60	25.00	343.95
0002	04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1	552.60	25.00	414.45
0003	04-01-0302-2267-G	PRIVC BUMPER PIECE	10	22.00	25.00	16.50
0004	04-01-0302-2865-G	PRIG4 FILLER-REAR BUMPER	1	232.00	25.00	174.00
0005	04-01-0302-2269-G	PRIG4 ORNAMENT SUB-ASSY B	1	52.90	25.00	39.67
0006	04-01-0302-2270-G	PRIG4 PLATE-BACK DOOR NAM	1	52.40	25.00	39.30
0007	04-01-0302-2271-G	PRIG4 PLATE-BACK DOOR NAM	1	60.80	25.00	45.60
0008	28-01-0302-0006-A	PRIVC REAR BOOT 65521111	1 N	30.00	10.00	27.00
0009	28-01-0302-2013-A	PRIVC REAR BONNET APP TAX	1 N	40.00	10.00	36.00
0010	28-01-0302-2015-A	PRIVC REAR BONNET COMFORT	1 N	30.00	10.00	27.00
0011	09-01-0302-2005-A	PRIG4 REVERSE SENSOR ASSY	1 N	135.70	10.00	122.13

SUB-TOTAL : 1,285.60

JOB NATURE

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Date: 04.06.2018

Time: 17:42:00

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS: COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305168183  
REGN NO : SHA4472U  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(C  
DATE OF REGN : 25.05.2017  
DATE/TIME IN : 01.06.2018 04:00  
ACCIDENT DATE : 01.06.2018

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 L	PANEL BEATING- REAR			200.00		
0001 23-502	SPRAYPAINT ON AFFECTED AREA			400.00		
0002 L	REMOVE/REFIX REVERSE SENSOR			20.00		
SUB-TOTAL :						620.00
TOTAL :						1,905.60

MVA NAME & SIGNATURE  
DATE:

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE:


**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18009991/K1qbe2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 07-06-2018	
Code: INC4				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJL 1892D	Veh. Inspected	SHA 4472U	
Policy No.	5100815955	Coverage (\$)	0.00	
Claim No.	MT/0997300-001	Excess (\$)	0.00	
Assign From		Assign Date	01/06/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FUX03556930	Colour	BLUE	
Odometer	91444	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	7 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	7 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	7 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	01/06/2018	Inspection Date	01/06/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR.		2 Working Days		



**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4472U**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	60.80	60.80
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.40	52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	52.90	52.90
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER RE-INFORCEMENT	SERVICEABLE	318.80	-
1	REAR BUMPER UNDER COVER	CUT	552.60	552.60
1	REAR BUMPER SIDE RETAINER, LH	SERVICEABLE	112.70	-
1	REAR BUMPER SPONGE	NOT NECESSARY	143.40	-
1	REAR BUMPER UNDER SIDE COVER (LH)	CRACKED	232.00	232.00
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	ARM SUB-ASSY, REAR BUMPER, LH	SERVICEABLE	139.60	-
1	SEAL, REAR BUMPER SIDE, LH	SERVICEABLE	148.40	-
	LESS 25% DISCOUNT		-573.55	-357.82
			1,720.65	1,073.48
<b><u>NETT ITEMS</u></b>				
1	REAR TRUNK LID APPS STICKER (N)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO. STICKER (N)	NECESSARY	60.00	60.00
1	REAR BUMPER REVERSE SENSOR (N)	SHORTED	135.70	135.70
	LESS 10% DISCOUNT		-	-23.57
			235.70	212.13
<b><u>LABOUR</u></b>				
	PANEL BEATING.		400.00	200.00
	SPRAY PAINT.		500.00	400.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.	NOT NECESSARY	50.00	-
	TOWING CHARGE.	NOT NECESSARY	60.00	-
	REMOVE / REFIX REVERSE SENSOR.		120.00	20.00
			-	-

Report Ref No. NS/INC18009991/K1qbe2



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
			-	-
			1,180.00	620.00
GRAND TOTAL			3,136.35	1,905.61
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,905.61

Report Ref No. NS/INC18009991/K1qbe2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted in any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.