

ASS. REC. BY:

REF: CS3/AIG18010044/G24d3<sup>2</sup>

Special Instruction:

Survivor:  
main

GG

## ASSIGNMENT (Office)

From (Person): chin lee ying

of

AIG

Date/Time: 4/6/18 @ 11.3

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKD 8899U

Insured:

SKG 7173X

at Workshop m/s

N-51 Automotive

Tel:

08420051

of

Blk 2 Kaki Bukit Ave 2 # 01-17 118

Policy No:

2100473514

Claim No:

6097407800SG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14/05/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lap

H.O.D. Endorsement:

Date/Time:

11.45am @ 4/6/18

Person Contacted:

Melody

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SKD 8899U -X
	SKG 7173X -X

10501/1/19  
Carvair

PRS  
Karl.

REF: A16

36471

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s N-51  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 81k  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 2 days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SKD88994 Yr Regn: 18 Oct 2011  
Type: ☒ M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Merce SK 250 c.c. 1796  
Colour: Silver A/C: Insured / Std / NI / NA  
Sp. Reading: 93329 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: WPD17244 RF 016271  
Gen. Cond: ☒ Good / Fair / Poor / Burnt  
Steering: ☒ In order / Jammed / Leaked / Burnt or  
Brake: ☒ In order / Jammed / Leaked / Burnt or  
Modi: ☒ Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 225/30 ZR19  
R: 11  
BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front Rear  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. \_\_\_\_\_ D.O.I. 04-06-18  
Survey held at w/s 1:20 pm  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
N/S Rear  
The ☒ U/C Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>21/6/18</u>	<u>Submit DAR Report</u>

RECEIVED 05 JUL 2018

Date/Time, File Pass to?	<input type="checkbox"/> : Preli. Report	Days Of Repair: <u>2</u>	Survey Fee: Transportation: S + RS \$ Photos Others TOTAL
1) Date/Time, File Return to?	<input type="checkbox"/> : Final Report	Resurvey No. of Trip: _____	
2)	Add Fee: <input type="checkbox"/> : Site Insp (\$ )	<input type="checkbox"/> : Interview (\$ )	
	<input type="checkbox"/> : Tech. Invs (\$ )	<input type="checkbox"/> : Weekend (\$ )	
	<input type="checkbox"/> : _____ (\$ )		
Report Format : <u>DAR</u>			
Lump Sum / I.B.I: (\$ )			



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18010044/Gz4d3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 04-06-2018



Code : AIG

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKG 7173X	Veh. Inspected	SKD 8899U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	04/06/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	14/05/2018	Inspection Date	04/06/2018
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--




**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED  
VEHICLE SKG7173X AND SKD8899U ON 14/05/2018**

From: Chin, Lee-Ying

To: assignments@lkkauto.com, Admin A

Cc: Fong, Andy-SY

Sent: 4/6/2018 11:31:12 AM

Attachments:  8899.pdf  21052018100218-0001.pdf  21052018122000.pdf

---

Hi LKK,

Vehicle is in, please assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Ave 2, #01-17

Singapore 417921

Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

Our Ref: **SKD 8899 U**

Your ref: **SKG 7173 X**

21 May 2018

**AIG ASIA PACIFIC INSURANCE PTE. LTD.**

NO: 78 SHENTON WAY

#07-16 CHARTIS BUILDING

SINGAPORE 079120

Attn: Motor Claims Department

BY EMAIL ShengYang.Lim@aig.com ONLY

Dear Sir/Madam,

**NAME OF CLAIMANT : NG KWANG SENG**

**VEHICLE NUMBER : SKD 8899 U**

**YOUR INSURED VEHICLE NUMBER : SKG 7173 X**

**ACCIDENT ON 14 May 2018 ALONG BISHAN ST 13 BLK 167 OPEN CARPARK**

**AT ABOUT 21:05 HOURS**


- 1) We refer to your fax / email of **21 May 2018** informing that you wish to conduct a pre-repair survey and to your List of Surveyors.
- 2) TAKE NOTICE that we object to all your surveyors stated in your said List, for appointment as the Single joint Expert.
- 3) Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following 10 surveyors for your consideration:-

(a) B J Loi  
(b) Patrick Ng  
(c) Sebastian Lim Yong Tian  
(d) Dave Chang Fuh Keong  
(e) Ng Cheng Meng  
(f) Danny Ho Joo Long  
(g) Lee Kok Weng  
(h) Philip Foo  
(i) Ong Ah Heng, Kent  
(j) Zali Saidi

PAR AUTOMOTIVE CONSULTANCY  
CARLINK CONSULTANCY  
CONSTANT APPRAISER SERVICES  
SINCERE APPRAISAL SERVICES  
CM AUTOMOTIVE CONSULTANCY  
HJL AUTO APPRAISER SERVICES  
LEE AUTOMOBILE APPRAISER SERVICES  
PRECISION APPRAISAL SERVICES  
KTO AUTOMOBILE ASSESSORS  
ISP MANAGEMENT PTE LTD

- 4) Please reply within 2 working days.

Yours faithfully



Twincarc Automotive Pte Ltd

MSME18063708 / SME Motor Pte Ltd - Kaki Bukit  
ENTRY DATE & TIME: 16/05/2018 12:27  
SUBMITTED BY: Chia Pei Ying

**Your NCD will be affected due to late reporting**  
**Actual e-Filing Submission Date & Time: 16/05/2018 12:36**

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/05/2018 12:27
Date Of Accident	14/05/2018 21:05
Exact Location Of Accident	OPEN CARPARK OF BLK 167
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD8899U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG KWANG SENG
NRIC No	S7923647J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96668889
Alternative Phone No	OFFICE-64558989

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	SLK250

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA068129
Cover Note Number	

### Driver

Name of Driver	NG KWANG SENG
NRIC No	S7923647J
Date Of Birth	12/08/1979
Occupation	INDOOR
Date Of Driving Pass	11/07/2002
Driving Experience	15 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96668889
Fax Number	
Contact Number	OFFICE-64558989
Email Address	NOEMAIL

Address	BLK 166 BISHAN ST 13 #07-248
Postcode	570166
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

I WAS STATIONARY STOPPED, QUEUING UP TO EXIT FROM THE OPEN CARPARK OF BLK 167 BISHAN ST 13. WHILE QUEUING UP, SUDDENLY I FELT AN IMPACT FROM THE LEFT REAR SIDE OF MY VEHICLE. I ALIGHTED FROM MY VEHICLE AND REALISED IT WAS A VEHICLE BEARING (SKG7133X) THAT COLLIDED ONTO THE LEFT REAR PORTION OF MY VEHICLE. WHEN I WAS IN A STATIONARY POSITION QUEUING UP TO EXIT FROM THE OPEN CARPARK, THE REPORTING WAS FILED IN LATE AS AT FIRST WAS PLANNED FOR PRIVATE SETTLEMENT. BUT END UP, HE REJECTED. SO I PROCEED TO FILE IN FOR ACCIDENT CLAIM.

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SKG7173X
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	LOUIS TAN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Sketch Plan Pg. 1

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS STATIONARY STOPPED, QUEUING UP TO EXIT FROM THE OPEN CARPARK OF BLK 167 BISHAN ST 13.

WHILE QUEUING UP, SUDDENLY I FELT A IMPACT FROM THE LEFT REAR SIDE OF MY VEHICLE.

ALIGHTED FROM MY VEHICLE AND REALIZED IT WAS A VEHICLE BEARING (SKA 7173X) THAT COLLIDED TO THE LEFT REAR PORTION OF MY VEHICLE, WHEN I WAS IN A STATIONARY POSITION, QUEUING UP TO EXIT FROM THE OPEN CARPARK.

VEHICLE A - SKD 889U

VEHICLE B - SKA 7173X

THE REPORTING WAS FILED IN LATER TIME AS AT FIRST WAS PLANNED FOR PRIVATE SETTLEMENT. BUT END UP HE REJECTED AND SO I PROCEED TO FILE IN FOR ACCIDENT CLAIM.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

16/5/18 10:50AM  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3647J
Vehicle Details	
Vehicle No.:	SKD8899U
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jun 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	SLK 250 A
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	27186130294898
Chassis No.:	WDD1724472F016271
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$51,451.00
Original Registration Date:	18 Oct 2011
First Registration Date:	18 Oct 2011
Transfer Count:	0
Actual ARF Paid:	\$51,451.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Oct 2021
PARF Rebate Amount:	\$33,443.00
Intended COE Rebate Details	
COE Expiry Date:	17 Oct 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$74,490.00
COE Rebate Amount:	\$24,322.00
<b>Total Rebate Amount:</b>	<b>\$57,765.00</b>

The information contained herein is correct as at 09 Jun 2018

OK

No of Items: \_\_\_\_\_ Assessor: \_\_\_\_\_

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2018 <a href="#">Edit Reg</a>		04 Jun 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	TAN GIM HOE, ID: S7234049C		
Main Claimant:	NG KWANG SENG, ID: S7923647J		
Vehicle Reg. No.:	SKD8899U	Date of Loss:	14/05/2018 21:00 - :59 [78 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6097407800SG	Policy/Cover Note No.:	2100473514 (Comprehensive)
Vehicle Reg. No. (Insured):	SKG7173X	Policy No. (Claimant):	
		Excess:	
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/06/2018]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (12/06/2018): Request To Upload TP GIA Report

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SKD8899U (6097407800SG)**  
**[SKG7173X]**

TP

NG KWANG SENG

May 14 2018 9:00PM

[TAN GIM HOE]

N-51 Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser					
Photos/Images															3 per page			<input checked="" type="checkbox"/>					
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print					
1	12/06/18 10:59		General View															Load JPG			<input checked="" type="checkbox"/>		
2	12/06/18 10:59		General View															Load JPG			<input checked="" type="checkbox"/>		
3	12/06/18 10:59		General View															Load JPG			<input checked="" type="checkbox"/>		
4	12/06/18 10:59		General View															Load JPG			<input checked="" type="checkbox"/>		
5	12/06/18 10:59		General View															Load JPG			<input checked="" type="checkbox"/>		
6	12/06/18 10:59		General View															Load JPG			<input checked="" type="checkbox"/>		
7	12/06/18 10:59		General View															Load JPG			<input checked="" type="checkbox"/>		
8	12/06/18 10:59		General View															Load JPG			<input checked="" type="checkbox"/>		
9	12/06/18 10:59		General View															Load JPG			<input checked="" type="checkbox"/>		
10	12/06/18 10:59		General View															Load JPG			<input checked="" type="checkbox"/>		
11	12/06/18 10:59		General View															Load JPG			<input checked="" type="checkbox"/>		
12	12/06/18 10:59		General View															Load JPG			<input checked="" type="checkbox"/>		
13	12/06/18 10:59		General View															Load JPG			<input checked="" type="checkbox"/>		
14	12/06/18 10:59		General View															Load JPG			<input checked="" type="checkbox"/>		
15	12/06/18 10:59		General View															Load JPG			<input checked="" type="checkbox"/>		
16	12/06/18 10:59		General View															Load JPG			<input checked="" type="checkbox"/>		
Documentation															1 per page			<input checked="" type="checkbox"/>					
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail			Print					
1	12/06/18 15:18		OI GIA REPORT															Load PDF					

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.				





# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG18010044/GZ4D3S2  
**Date:** 06/07/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100473514  
**Claimant Vehicle No :** SKD8899U **Insured Vehicle No :** SKG7173X  
 Date of Loss: 14/05/2018 Nature of Claim: TP Claim No: 6097407800SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKD8899U**  
 Make & Model: MERCEDES-BENZ SLK250, 1.8 BlueEFFICIENCY (R172) (A) Engine No: 27186130294898  
 Reg. Date: 18/10/2011 (Man. Year: 2011) Chassis No: WDD1724472F016271  
 Colour: Silver Odometer: 93329 km  
 Engine Capacity: 1796 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 275/30ZR19 Rear Tyre Size: 275/30ZR19  
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 04/06/2018  
 Date Inspected: 04/06/2018 Inspected At: N-51 Automotive Pte Ltd (HQ)  
 BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB  
 Singapore 417921  
 Estimated Period of Repair: 2.0 days

**Adjuster:** XING GUO QIANG

**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Scratched	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR LH FENDER	Repair	0.00 F	*- F
4	1		*REAR LH WHEEL RIM	Cut	0.00 F	*- F
				<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >