

22/03/2002

ASS. REC. BY:

REF: 053/EG I 18010048/G24d323

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Siti A' thikah

of

EG I

Date/Time: 1/6/18 @ 3.59pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKP 676 K

Insured:

XD 6247 K

at Workshop m/s

EM solution

Tel:

6456 0226

of

160 Sin Ming Drive # 03-18/19

Policy No:

Claim No:

XD 6247 K / SL / pl

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/05/2016

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

9:19am @ 4/6/18

Person Contacted:

Bernard

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction	(4) Estimate
	SKP 676 K-X	
	XD 6247 K-X	
5/6/18	Dismanfled	

Signature

PKS Karl.

REF: EGI

3042i

ASSIGNMENT

From:

Date:

4/6/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKP 676K
EM solution

at Workshop m/s

of 160 Sin Ming Drive #03-18/19

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$72K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SKP 676K

Yr Regn:

02 Feb 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda uezel 1.5 C.C 1496

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

32242

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU 1110 6065

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD/A/Rim or

Tyre Size:

F:

215/60R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

04-06-18

Survey held at

w/s

4:40pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

* Repair Estimate : S\$ 8000 - 10,000

* 6 days

13/6/18

submit PRS report.

RECEIVED 13 JUN 2018

Date/Time. File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time. File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

50

50

100

Report Format :

Lump Sum / I.B.I: (\$

Catherine Chong (LKK Auto)

From: Siti A Thikah AB Rahman <siti.rahman@ergo.com.sg>
Sent: Friday, 1 June, 2018 3:59 PM
To: Catherine Chong (LKK Auto) (admin-d@lkkauto.com)
Cc: Survey Report (ERGO Insurance Pte. Ltd.)
Subject: OI: XD 6247K | TP: SKP 676K | LKK | DOA: 31.05.2018 - PRI | OUR REF: XD6247K/SL/sa
Attachments: OIUR REF : E21-misc.2018 (SKP 676K @ 31/05/2018) // ERGO REF ... (13.7 KB); SKP676K - PRS FORM.pdf; XD6247K - SAS.pdf; TP - SAS.PDF
Importance: High

Dear Catherine,

With reference to the above matter.

We have rejected to their PRS list, please assist to conduct this survey request from Vision Law LLC, their client's vehicle can be survey at:-

Venue : E M SOLUTION PTE LTD
160, Sin Ming Drive, #03-18/19, Sin Ming Autocity,
Singapore 575722
Contact : Mr. Bernard (Tel.: 6456-0226 / 9101-8302)

Attached are the necessary documents for your further actions (**Note: Reports not to be released to any Third Party**).

Note: To survey on without prejudice basis and inform the repairer in writing, that you are require to conduct a post-repair inspection before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Kindly acknowledge receipt of this email.

NOTE: Please assist to quote our ref as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Warmest regards
Siti A'thikah
Claims Department
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9170
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.
Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.
ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

From: Sally Chong [mailto:sallychong@visionlawllc.com]

Sent: Thursday, 31 May, 2018 5:57 PM

To: ERGO Insurance Pte. Ltd. (Claims Department)

Cc: 'EM Solution Pte Ltd'; 'Judy Soh'

Subject: RE: OIUR REF.: E21-106916.2018 (SKP 676K @ 31/05/2018) // ERGO REF : XD 6247K

Importance: High

VERY URGENT

Dear Pei Li,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES
CLAIMANT: ANG KOK CHENG
ACCIDENT INVOLVING VEHICLE SKP 676K & XD 6247K ON 31 MAY 2018 ALONG KRANJI ROAD AT ABOUT 11:25 HRS

We refer to your email of even date below and your list of surveyors.

TAKE NOTICE that we object to your surveyor stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following List of Motor Surveyors for your consideration:-

<u>Name of Surveyor</u>	<u>Company Name</u>
Dennis Yap	Pal's Appraiser Pte Ltd
Michael Yap	Mc-coy Appraiser Pte Ltd
Andy Yap	LCW Appraiser Pte Ltd
B J Loi	Par Automotive Consultancy
Sebastian Lim	Constant Appraiser Services
Lee Yew Hok	Constant Appraiser Services
Alan Cheong	CL Appraiser Pte Ltd

Please be informed that the said vehicle can be inspected at:-

Venue : E M SOLUTION PTE LTD
160, Sin Ming Drive, #03-18/19, Sin Ming Autocity,
Singapore 575722
Contact : Mr. Bernard (Tel.: 6456-0226 / 9101-8302)

If you fail to conduct the pre-repair inspection within the next 2 working days, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Sally Chong

(Secretary)

VISION LAW LLC
133 NEW BRIDGE ROAD,
#18-01/02, CHINATOWN POINT,
SINGAPORE 059413
TEL.: 6534-2811 (ext 115)
FAX : 6535-6802

From: ERGO Insurance Pte. Ltd. (Claims Department) [mailto:claims@ergo.com.sg]
Sent: Thursday, 31 May, 2018 5:04 PM
To: 'Sally Chong'
Cc: EM Solution Pte Ltd; 'Judy Soh'
Subject: RE: OIUR REF.: E21-misc.2018 (SKP 676K @ 31/05/2018) // ERGO REF : XD 6247K

WITHOUT PREJUDICE

Dear Sirs,

Please find enclosed surveyor list for your action. Kindly indicate your selection in the box * upon completion, please email back for our action.

Await reply within 2 working days.

For PRS request, kindly reply via claims@ergo.com.sg.

Appreciated your co-operation.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

From: Sally Chong [mailto:sallychong@visionlawllc.com]
Sent: Thursday, 31 May, 2018 3:39 PM
To: ERGO Insurance Pte. Ltd.; ERGO Insurance Pte. Ltd. (Claims Department); Siti A Thikah AB Rahman; Steve Lim
Cc: EM Solution Pte Ltd; 'Judy Soh'
Subject: OIUR REF.: E21-misc.2018 (SKP 676K @ 31/05/2018) // ERGO REF : XD 6247K
Importance: High

URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES
CLAIMANT: ANG KOK CHENG

ACCIDENT INVOLVING VEHICLE SKP 676K & XD 6247K ON 31 MAY 2018 ALONG KRANJI ROAD AT ABOUT 11:25 HRS

We are instructed by **ANG KOK CHENG** to notify you of a road traffic accident **ON 31 MAY 2018 ALONG KRANJI ROAD AT ABOUT 11:25 HRS** involving our client's vehicle registration number **SKP 676K** and vehicle registration number **XD 6247K** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

Sally Chong

(Secretary)
VISION LAW LLC
133 NEW BRIDGE ROAD,
#18-01/02, CHINATOWN POINT,
SINGAPORE 059413
TEL.: 6534-2811 (ext 115)
FAX : 6535-6802

C.c.: VEHICLE OWNER OF XD 6247K
PENG CHUAN ENGINEERING CONTRUCTION PTE LTD
421, Tagore Industrial Avenue,
#04-06/07, Tagore 8,
Singapore 787805

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

ERGO

Date: 31.05.2018
Our Reference: XD 6247K/SL/pl
Your Reference: E21-misc.2018 (SKP 676K @ 31/05/2018)

Sent via Fax

or

Email

sallychong@visionlawllc.com /
emautosolution@singnet.com.sg /
judysoh@visionlawllc.com

To: VISION LAW LLC

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SKP 676K
Insured's Vehicle: XD 6247K
Date Of Accident: 31.05.2018

We acknowledge receipt of your request for PRS on: 31.05.2018


In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- ☒ Your request for inspection does not have your client's GIA report, kindly forward a copy.
- ☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- ☐ Our Insured's driver has not reported the accident to us todate.
- ☒ Others: WORKSHOP DETAILS NOT PROVIDED

OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				<u>FAX : 6829 9247</u>

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS3/EGI18010048/Gz4d3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 04-06-2018



Code : EGI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	XD 6247K	Veh. Inspected	SKP 676K
Policy No.		Coverage (\$)	0.00
Claim No.	XD6247K/SL/pl	Excess (\$)	0.00
Assign From	SITI A'THIKAH	Assign Date	04/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	31/05/2018	Inspection Date	04/06/2018
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/05/2018 15:37
Date Of Accident	31/05/2018 11:25
Exact Location Of Accident	KRANJI ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP676K
Insured/Policyholder	
Name Of Registered Owner	ANG KOK CHENG
NRIC No	S6913042I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98480055
Alternative Phone No	OFFICE-96628004

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA337578
Cover Note Number	

Driver

Name of Driver	ANG KOK CHENG
NRIC No	S6913042I
Date Of Birth	14/04/1969
Occupation	INDOOR
Date Of Driving Pass	22/06/1994
Driving Experience	23 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98480055
Fax Number	
Contact Number	OFFICE-96628004
EMail Address	NOEMAIL

Address	BLK 674A JURONG WEST STREET 65 #06-76
Postcode	641674
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TAN CHOON CHUAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Details of Witness 1

Name	TAN CHOON CHUAN
Phone Number	
Email Address	S1830783I

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD6247K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	WANG MINGHE
NRIC/Passport Number	G7784718P
Contact Number	82977156/90211212
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 31/5/2018 at about 11:25 AM I was driving my vehicle - SKP 676 K along Kranji Road. I was stationary at the Traffic junction to Kranji Road while waiting for Traffic to clear to move off. Out of a sudden, a Lorry - XD 6247 K from behind bang onto my vehicle and my car was badly damages on the rear portion.

I reporting this incident for Tlparty claim against XD 6247 K.

* Repair at other Workshop.

DECLARATION


I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3042I
Vehicle Details	
Vehicle No.:	SKP676K
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	L15B4026071
Chassis No.:	RU11106065
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,373.00
Original Registration Date:	02 Feb 2016
First Registration Date:	02 Feb 2016
Transfer Count:	1
Actual ARF Paid:	\$9,373.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Feb 2026
PARF Rebate Amount:	\$7,029.00
Intended COE Rebate Details	
COE Expiry Date:	01 Feb 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,301.00
COE Rebate Amount:	\$41,515.00
Total Rebate Amount:	\$48,544.00

The information contained herein is correct as at 09 Jun 2018

OK



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
ERGO INSURANCE PTE LTD		Ref: CS3/EG18010048/Gz4d3e2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER		Date: 14-06-2018		
FIVE SINGAPORE 038985				
Code: EGI				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	XD 6247K	Veh. Inspected	SKP 676K	
Policy No.		Coverage (\$)	0.00	
Claim No.	XD6247K/SL/pl	Excess (\$)	0.00	
Assign From	SITI A'THIKAH	Assign Date	01/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL 1.5	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11106065	Colour	BLACK	
Odometer	32242 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	31/05/2018	Inspect Date / Time	04/06/2018 (04:40 PM)	
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$10,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		

Report Ref No. CS3/EG18010048/Gz4d3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.