

ASS. REC. BY:

REF:

CS3/AIG18610051/Gzad36

Special Instruction:

Survivor:

Manner

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

1/6/18 @ 3:33pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKB 384B

Insured:

SLT 6244B

at Workshop m/s

N-51 Automotive

Tel:

68420051

of

No. 2 Keki Bkt Ave 2 #01-17/18

Policy No:

1700069512

Claim No:

150262693389

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/06/2018

CA / REV / REP. / REV 24 HRS ^{up}

H.O.D. Endorsement:

Date/Time:

9:45am @ 4/6/18

Person Contacted:

Melody

Vehicle:

☒ IN / OUT

Date/Time

Action/Instruction (X) Estimate

SKB 384B-NA/CTI 18009979/24

DOA: 1/6/18

SLT 6244B-NA/CTI 18009979/24

DOA: 1/6/18

4/6/18

Dismantled

8/6/18

After Repair

PKS
Xcel.

REF: A19

6859F


(2219)

ASSIGNMENT

From _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s: **N-51**
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **6** days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SKB384B** Yr Regn: **22 Jan 2009**
 Type: **C** M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Volkswagen Touran cc 1390**
 Colour: **Black** A/C: Insured / Std / NI / NA
 Sp.Reading: **172544** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **WVG8881T8 8W156617**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Mod: **Nil** / SRim / STD A/Rim or
 Tyre Size: F: **205/55 R16**
 R: **U**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A: _____ D.O.I: **01-06-18**
 Survey held at: **W/S** **4:50pm**
 Des. of Damages: Frt / **Rear** / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21/6/18	Submit DAR Report.

Date/Time, File Pass to? ☐ : Prel. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: **6**

Resurvey No. of Trip: **2**

Survey Fee:

Transportation:

3 - RS - 3

Photos:

Obst:

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : **DAR**

Lump Sum / I.B.I: (\$

180

20

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18010051/Gz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 04-06-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLT 6244B	Veh. Inspected	SKB 384B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	04/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	01/06/2018	Inspection Date	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SLT6244B AND SKB384B ON 01/06/2018**

From: Chin, Lee-Ying

To: assignments@lkkauto.com, Admin A

Cc: Fong, Andy-SY

Sent: Friday, 1 June, 2018 3:33:12 PM

Attachments:  01062018144529-0001.pdf  01062018150148.pdf  01062018151346.pdf

Hi LKK,

Kindly assist to survey, vehicle is in.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Ave 2, #01-17

Singapore 417921

Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

Our Ref: SKB 384 B
Your ref: SLT 6244 B

01 June 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD.

NO: 78 SHENTON WAY

#07-16 CHARTIS BUILDING

SINGAPORE 079120

Attn: Motor Claims Department

BY EMAIL yokeshi.chan@aig.com ONLY

Dear Sir/Madam,

NAME OF CLAIMANT : YA'COB BIN LAMRI

VEHICLE NUMBER : SKB 384 B

YOUR INSURED VEHICLE NUMBER : SLT 6244 B

**ACCIDENT ON 01 June 2018 ALONG BARTLEY RD EAST TWD BRADDELL RD B4
KAKI BUKIT AVE 4 AT ABOUT 09:15 HOURS**

We refer to your email/fax dated **01 June 2018** wherein there is no agreement to the appointment to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Avenue 2

#01-17

Singapore 417921

6842 0051 / 6744 0510 (Melody)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



TwinCar Automotive Pte Ltd

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6859F
Vehicle Details	
Vehicle No.:	SKB384B
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jun 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TOURAN 1.4 TSI 170HP
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	BLG039984
Chassis No.:	WVGZZZ1TZ8W156617
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$25,590.00
Original Registration Date:	22 Jan 2009
First Registration Date:	22 Jan 2009
Transfer Count:	1
Actual ARF Paid:	\$25,590.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jan 2019
PARF Rebate Amount:	\$12,795.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jan 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$2,693.00
COE Rebate Amount:	\$165.00
Total Rebate Amount:	\$12,960.00

The information contained herein is correct as at 09 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/06/2018 14:18
Date Of Accident	01/06/2018 09:15
Exact Location Of Accident	BARTLEY RD EAST BEFORE KAKI BUKIT AVE 4 EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB384B
Insured/Policyholder	
Name Of Registered Owner	MR YACOB BIN LAMRI
NRIC No	S7016859F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94517660
Alternative Phone No	OFFICE-94517660

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	TOURAN 1.4 TSI 170HP
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1113131706
Cover Note Number	

Driver

Name of Driver	MASLINDA BINTE MASORD
NRIC No	S7309091A
Date Of Birth	09/03/1973
Occupation	INDOOR
Date Of Driving Pass	16/04/1993
Driving Experience	25 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-93865496
Fax Number	
Contact Number	OFFICE-93865496
Email Address	NOEMAIL

Address	383 LOYANG RISE
Postcode	507277
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT6244B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBG2023K
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF INJURED PERSON 1

Name	MASLINDA BINTE MASORD
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SKB384B
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



(A) 32A 5846

(B) 3LT 6244B

(C) 66G 2023K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/06/18 at 0915 hrs I was travelling in my vehicle (32A 5846) along Bartley Road East towards Roadkill before Kali Sukit Ave. As I exit on the extreme left lane I slow down and stopped due to traffic jammed ahead. I saw the vehicle (3LT 6244B) behind of me stopped too far my rear mirror. Suddenly, I felt a great impact from the rear. I got down from my vehicle and found it was a chain collision involving 3 cars.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(if driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/INN No:

(1) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched
(7) Deformed (8) Shifted (9) Buckled (10) Broken (11) Necessary
(12) Missing (13) Tors (14) Unconfirmed (15) Not Working

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2018 Edit Reg		01 Jun 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	TAN YONG WEN IVAN, ID: S8610698A		
Main Claimant:	MR YACOB BIN LAMRI, ID: S7016859F		
Vehicle Reg. No.:	SKB384B	Date of Loss:	01/06/2018 09:00 - :59 [112 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1502626933SG	Policy/Cover Note No.:	1700069512 (Comprehensive)
Vehicle Reg. No. (Insured):	SLT6244B	Policy No. (Claimant):	
		Excess:	
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/06/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (12/06/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKB384B (1502626933SG)
[SLT6244B]
TP
MR YACOB BIN LAMRI
Jun 1 2018 9:00AM
[TAN YONG WEN IVAN]
N-51 Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	12/06/18 11:04	General View														Load JPG	☒			
2	12/06/18 11:04	General View														Load JPG	☒			
3	12/06/18 11:04	General View														Load JPG	☒			
4	12/06/18 11:04	General View														Load JPG	☒			
5	12/06/18 11:04	General View														Load JPG	☒			
6	12/06/18 11:04	General View														Load JPG	☒			
7	12/06/18 11:04	General View														Load JPG	☒			
8	12/06/18 11:04	General View														Load JPG	☒			
9	12/06/18 11:04	General View														Load JPG	☒			
10	12/06/18 11:04	General View														Load JPG	☒			
11	12/06/18 11:04	General View														Load JPG	☒			
12	12/06/18 11:04	General View														Load JPG	☒			
13	12/06/18 11:04	General View														Load JPG	☒			
14	12/06/18 11:04	General View														Load JPG	☒			
15	12/06/18 11:04	General View														Load JPG	☒			
16	12/06/18 11:04	General View														Load JPG	☒			
17	12/06/18 11:04	General View														Load JPG	☒			
18	12/06/18 11:04	General View														Load JPG	☒			
19	12/06/18 11:04	General View														Load JPG	☒			
20	12/06/18 11:04	General View														Load JPG	☒			
21	12/06/18 11:04	General View														Load JPG	☒			
22	12/06/18 11:04	General View														Load JPG	☒			
23	12/06/18 11:04	General View														Load JPG	☒			
24	12/06/18 11:04	General View														Load JPG	☒			
25	12/06/18 11:04	General View														Load JPG	☒			
26	12/06/18 11:04	General View														Load JPG	☒			
27	12/06/18 11:04	General View														Load JPG	☒			
28	12/06/18 11:04	General View														Load JPG	☒			
29	12/06/18 11:04	General View														Load JPG	☒			
30	12/06/18 11:05	General View														Load JPG	☒			
31	12/06/18 11:05	General View														Load JPG	☒			
32	12/06/18 11:05	General View														Load JPG	☒			
33	12/06/18 11:05	General View														Load JPG	☒			
34	12/06/18 11:05	General View														Load JPG	☒			
35	12/06/18 11:05	General View														Load JPG	☒			
36	12/06/18 11:05	General View														Load JPG	☒			
37	12/06/18 11:05	General View														Load JPG	☒			

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
39	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
40	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
41	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
42	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
43	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
44	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
45	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
46	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
47	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
48	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
49	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
50	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
51	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
52	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
53	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
54	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
55	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
56	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
57	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
58	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
59	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
60	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
61	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
62	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
63	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
64	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
65	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
66	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
67	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
68	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
69	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
70	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
71	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
72	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
73	12/06/18 11:05	Dismantled Parts	 Load JPG	☒
74	12/06/18 11:05	Photo After Spray	 Load JPG	☒
75	12/06/18 11:05	Photo After Spray	 Load JPG	☒
76	12/06/18 11:05	Photo After Spray	 Load JPG	☒
77	12/06/18 11:05	Photo After Spray	 Load JPG	☒
78	12/06/18 11:05	Photo After Spray	 Load JPG	☒
79	12/06/18 11:05	Photo After Spray	 Load JPG	☒
80	12/06/18 11:05	Photo After Spray	 Load JPG	☒
81	12/06/18 11:05	Photo After Spray	 Load JPG	☒
82	12/06/18 11:05	Photo After Spray	 Load JPG	☒
83	12/06/18 11:05	Photo After Spray	 Load JPG	☒
84	12/06/18 11:05	Photo After Spray	 Load JPG	☒
85	12/06/18 11:05	Photo After Spray	 Load JPG	☒
86	12/06/18 11:05	Photo After Spray	 Load JPG	☒
87	12/06/18 11:05	Photo After Spray	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	12/06/18 11:05	Photo After Spray	 Load JPG	☒
89	12/06/18 11:05	Photo After Spray	 Load JPG	☒
90	12/06/18 11:05	Photo After Spray	 Load JPG	☒
91	12/06/18 11:05	Photo After Spray	 Load JPG	☒
92	12/06/18 11:05	Photo After Spray	 Load JPG	☒
93	12/06/18 11:05	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/06/18 16:58	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18010051/GZ4D3E2

Date: 27/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700069512
 Claimant Vehicle No: SKB384B Insured Vehicle No: SLT6244B
 Date of Loss: 01/06/2018 Nature of Claim: TP Claim No: 1502626933SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKB384B
 Make & Model: VOLKSWAGEN TOURAN, 1.4 TSI (A) Engine No: BLG039984
 Reg. Date: 22/01/2009 (Man. Year: 2008) Chassis No: WVGZZZ1TZ8W156617
 Colour: Black Odometer: 172544 km
 Engine Capacity: 1390 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread's depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 01/06/2018
 Date Inspected: 01/06/2018 Inspected At: N-51 Automotive Pte Ltd (HQ)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI
 BUKIT AUTOHUB
 Singapore 417921
 Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
4	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
5	1		*REAR END PANEL	Dented	0.00 F	*- F
6	1		*REAR END PANEL TOP GARNISH	Distorted	0.00 F	*- F
7	1		*REAR LH TAILLAMP	Cut	0.00 F	*- F
8	1		*REAR RH TAILLAMP	Scratched	0.00 F	*- F
9	1		*TAILGATE	Buckled	0.00 F	*- F
10	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
11	1		*TAILGATE GARNISH	Bent	0.00 F	*- F
12	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
13	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
14	1		*TAILGATE LOCK	Bent	0.00 F	*- F
15	1		*TAILGATE RUBBER	Cut	0.00 F	*- F
16	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F
17	1		*REAR LH FENDER INNER TRIM	Cracked	0.00 F	*- F
18	1		*REAR RH FENDER INNER TRIM	Cracked	0.00 F	*- F
19	1		*FLOOR PANEL SPONGE	Cracked	0.00 F	*- F

F=Franchise part.

Total Parts (S\$) **0.00** **0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >