

ASS. REC. BY:

REF: CS/CTI18010064/V4d3ⁿ² Special Instruction:

Surveyor:

Mainmen: chong Boon Sen of CTI ASSIGNMENT (Office)From (Person): chong Boon Sen of CTI Date/Time: 01/06/18 @ 10:09am

Estimated Cost: _____ Bill to: _____

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKS 501R Insured: GBE 1381Tat Workshop m/s: Kah Motor Tel: 81006306of 1 Subi Rd 4Policy No: DMCVSN1655351701 Claim No: SNM18D02709C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 30/05/2018
(Client's Record)CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement: _____

Date/Time: 10:18am @ 4/6/18 Person Contacted: AnyVehicle-IN OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SKS 501R - X</u>
	<u>GBE 1381T - X</u>

(08/11/13) wef

ASS REC BY *Mercus*

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SKS 501 R*at Workshop m/s *14th Mar 10.30*of *Any*

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<i>B</i>	
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent?: Yes or No

GLC / PR Seen: *2*

Consistent?: Yes or No

Est. Repairs: *2*

days

Res.: Yes or No

Lum Sum: *131*

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

Date/Time, File Pass to?

12/7/17 Typist

Date/Time, File Return to?

2)

Report Format: *TP*Lump Sum / (I.B.): (\$ *1274.30*)Veh No: *SKS 501 R*Yr Regn: *9 / 17*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CA /*Make: *Honda civic*C.C. *1597*Colour: *white*A/C: *insured*

Std / NI / NA

Sp. Reading: *19775*T/Radio: *insured*

Std / NI / NA

Eng/No: _____

C/No: *MRHFCS650HT000266*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *2.5/55 R16*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *hankook*

Front

Rear

R/Bal: *6*

mm

R/Bal: *6*

mm

L/Bal: *6*

mm

L/Bal: *6*

mm

D.O.A. *30/5/18*D.O.I. *21/6/18*

Survey held at _____

Des. of Damages: *Fr* / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 24 JUL 2018

Date/Time, File Pass to?

12/7/17 Typist

Date/Time, File Return to?

2)

Report Format: *TP*Lump Sum / (I.B.): (\$ *1274.30*)Days Of Repair: *2*Resurvey No. of Trip: *1*

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ ~ RS. \$

Photos

Others

TOTAL

220

20/7/18 confirmed final by \$1274.30 with Any Cred: 3143.22 : 713

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 May 2018		01 Jun 2018 10:09 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	KHOO SONG HEE		
Vehicle Reg. No.:	SKS501R	Date of Loss:	30/05/2018 00:00 - :59
Claim Type:	TP / SNM18D02709C02	Policy/Cover Note No.:	DMCVSN1655351701
Vehicle Reg. No. (Insured):	GBE1381T	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/06/2018]		
Adj Asg. Remarks:	EST \$4726.75, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[» Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 3085D

Vehicle Details

Vehicle No.: SKS501R

Vehicle to be Exported: No

Intended De-registration Date: 21 Jun 2018

Vehicle Make: HONDA

Vehicle Model: CIVIC 1.6 VTI CVT

Primary Colour: White

Manufacturing Year: 2017

Engine No.: R16B22000585

Chassis No.: MRHFC5650HT000266

Maximum Power Output: 92.0 kW (123 bhp)

Open Market Value: \$19,683.00

Original Registration Date: 29 Sep 2017

First Registration Date: 29 Sep 2017

Transfer Count: 0

Actual ARF Paid: \$19,683.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 28 Sep 2027

PARF Rebate Amount: \$14,762.00

Intended COE Rebate Details

COE Expiry Date: 28 Sep 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$42,801.00

COE Rebate Amount: \$39,674.00

Total Rebate Amount: \$54,436.00

The information contained herein is correct as at 21 Jun 2018

OK



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Thursday
10.30 am 21 JUN 2018

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Livita: 8841972 Lf auto

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SKS501R
Chassis No : MRHFC5650HT000266
Model : CIVIC 1.6 VTI YM2017
Owner's Name : KHOO SONG HEE
Ins Policy No. : 17-MU010419-R00
Date of Accident : 30/5/2018

Document No. : SQT18002212 Page 1
Date : 30. May 2018
Customer No. : WZC008
Svc Advisor : ARY CHUA WAI NGEE
Engine No : R16B22000585
Date | Time : 30. May 2018 4:55:13 PM
Surveyor Name :
Survey Date :
Authorisation Date :
DID : +65 6846 5673
HP : +65 8100 6306
Email : arychua@honda.com.sg

0% GST Amount Amount
The Repairer of the following:
* To resurvey before after spray paint
* Parts prices are subject to confirmation
* Third party survey is on a "Without Prejudice" basis
* No illegal modification(s) is allowed
* Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Item	Description	Qty	Unit Price	Disc %	Amount	Amount	Amount	incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: KHOO SONG HEE OWNER INSURER: TOKIO MARINE INSURANCE LTD ACC DATE: 30/05/2018@08.30AM SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING INSURANCE (S'PORE) PTE L TP VEH: GBE1381T (LORRY/NISSAN/SILVER) (HIT &							

71101-TEA-T00ZZ	FACEFR.BUMPER	1	579.90	25	434.92	30.44	465.36	X
91505-TM8-003	CLIPBUMPER	14	2.00	25	21.00	1.47	22.47	
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35	
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35	
71121-TEA-T01	BASE.FR.GRILLE CHROME	1	71.60	25	53.70	3.76	57.46	
75700-TBA-A00	EMBLEM	1	14.60	25	10.95	0.77	11.72	
71125-TEA-T01	MOLDINGFR.GRILLE	1	97.40	25	73.05	5.11	78.16	
71130-TEA-T00	BEAM COMPFR.BUMPER	1	335.80	25	251.85	17.63	269.48	X
71150-TEA-T00	BEAM COMPFR.BUMPER CENTER UPP	1	208.60	25	156.45	10.95	167.40	X
Sum Item					1017.52	71.23	1,088.75	

BOSUN	SUNDRIES	1	100.00	10	100.00	7.00	107.00	
BML011	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	100.00	20	100.00	7.00	107.00	
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1400.00	450	1400.00	98.00	1498.00	
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1800.00	560	1800.00	126.00	1926.00	
Sum Labor					3400.00	238.00	3,638.00	

Survey By

Date & Time

marcus khal

21/6/18

take photo after rep -
2 day.
@ 10.30 am.

Total Amount 4,417.52 309.23 4,726.75



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: MRHFC5650HT000266
License No: SKS501R
Mileage: 18181
Engine No: R16B22000585

Document No: SVO18035663
Printed By: ARYCHUA
Order Date: 20. June 2018
Order Time: 12:32:28 PM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Incid GST
	TP DIRECT SETTLEMENT (J/NO: 70714) OWNER: KHOO SONG HEE OWNER INSURER: TOKIO MARINE INSURANCE LTD ACC DATE: 30/05/2018@08.30AM SURVEYED BY: <i>Marche</i> (LKKAUTO) DATE: 21/06/2018@10.30AM REF NO: SNM18D02709C02/1 (GBE1381T) TP INSURER: CHINA TAIPING INSURANCE PTE LTD TP VEH: GBE1381T (NISSAN/SILVER) (HIT & RUN)						
91505-TM8-003	CLIPBUMPER	14	2.00	25	21.00	1.47	22.47
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71121-TEA-T01	BASE,FR.GRILLE CHROME	1	71.60	25	53.70	3.76	57.46
75700-TBA-A00	EMBLEM	1	14.60	25	10.95	0.77	11.72
71125-TEA-T01	MOLDINGFR.GRILLE	1	97.40	25	73.05	5.11	78.16
	SUM PARTS:				174.30	12.21	186.51
BOSUN	0672	1	10.00		10.00	0.70	10.70
	SUNDRIES						
BML01I	EXT-YJ	1	80.00		80.00	5.60	85.60
	INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)						
BP02R	EXT-YBH	1	450.00		450.00	31.50	481.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(2P)						
BKBH01S	EXT-YJ	1	560.00		560.00	39.20	599.20
	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.						
	SUM LABOUR:				1,100.00	77.00	1,177.00
	TOTAL SGD				1,274.30	89.21	1,363.51

Total Payable (SGD)

1,363.51

GST Amount is calculated from individual line(s)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18010064/UTD3N2

Date: 24/07/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1655351701
Claimant Vehicle No :	SKS501R	Insured Vehicle No :	GBE1381T
Date of Loss:	30/05/2018	Nature of Claim:	TP
		Claim No:	SNM18D02709C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS501R	Engine No:	R16B22000585
Make & Model:	HONDA CIVIC, 1.6 (A)	Chassis No:	MRHFC5650HT000266
Reg. Date:	29/09/2017 (Man. Year: 2017)	Odometer:	19775 km
Colour:	White		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R16	Rear Tyre Size:	215/55R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,117.52	184.30	933.22	83.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	1,090.00	2,210.00	66.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,417.52	1,274.30	3,143.22	71.15
+ GST 7.00/7.00% (S\$)	309.23	89.20	220.03	71.15
Nett Amount (S\$)	4,726.75	1,363.50	3,363.25	71.15

INSPECTION

Date of Assignment:	01/06/2018	Inspected At:	Kah Motor Co Sdn Bhd (Ubi)
Date Inspected:	21/06/2018		15 Ubi Road 4
			Singapore 408610
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Jul 2018)
Parts: 143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKS501R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACEFR BUMPER	Repair	434.92 FS	*- FS
2	14		*CLIPBUMPER	Necessary	21.00 FS	*21.00 FS
3	1		*SPACERR FR BUMPER SIDE	Bent	7.80 FS	*7.80 FS
4	1		*SPACERL FR BUMPER SIDE	Bent	7.80 FS	*7.80 FS
5	1		*BASE FR GRILLE CHROME	Cracked	53.70 FS	*53.70 FS
6	1		*EMBLEM	Necessary	10.95 FS	*10.95 FS
7	1		*MOLDINGFR GRILLE	Cut	73.05 FS	*73.05 FS
8	1		*BEAM COMPFR BUMPER	Not Necessary	251.85 FS	*- FS
9	1		*BEAM COMPFR BUMPER CENTER UPP	Not Necessary	156.45 FS	*- FS
10	1		*SUNDRIES	Necessary	100.00 FS	*10.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					1,117.52	184.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	100.00	80.00
2	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	1,400.00	450.00
3	STRAIGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS	New	1,800.00	560.00
Gross Labour Cost (\$\$)			3,300.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >