

ASS. REC. BY:

REF: CS3 / AIG / 18010076 / G24d3⁵² Special Instruction:

Surveyor:

GB

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

4/6/18 @ 9:25am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJJ 4214C

Insured:

SKM 27192

at Workshop m/s

Topmax Auto Bodyshop

Tel:

6744 2653

of

Blk 3007 Ubi Rd 1 # 01-410

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/5/2018

CA / REV / REP. / REV 24 HRS

Lup

5/6/18 @ after 11am

H.O.D. Endorsement:

Date/Time:

10:36am @ 4/6/18

Person Contacted:

Carmen

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SJJ 4214C - X

SKM 27192 - X

6/6/18

Dismantled

PR3

XLR

REF: ALH

77467

(2021)

ASSIGNMENT

From:

Date:

05062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJJ 4214C

at Workshop m/s:

Topmax

of

31k 3007 Ubi Rd 1 #01-410

Insured:

SLV 583B

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

after 11pm

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

\$51k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJJ4214C

Yr Regn:

31 Mar 2011

Type:

M / C / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 320i

C.C.

1995

Colour:

white

A/C:

Insured / Std / NI / NA

Sp Reading

172011

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBAPG 56020NM 91184

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/35 R19

R:

6"

BS / DUN / EXNOVA / GY / FS / LIZA / M / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

05-06-18

Survey held at

w/s

2pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

ds Rt

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

21/6/18

Submit TAR Report

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SKM2719Z AND SJJ4214C ON 25/5/2018**

From: Chin, Lee-Ying

To: assignments@lkkauto.com, Admin A

Cc: Fong, Andy-SY

Sent: 4/6/2018 9:25:55 AM

Attachments:  FaxA021.tif  Notice to AIG to conduct PRI (SJJ4214C).pdf

Hi LKK,

Kindly assist to survey, vehicle will be available for survey after 11am today.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

C. YOGARAJAH LLC

ADVOCATES & SOLICITORS

883 North Bridge Road
#19-05 Southbank
Singapore 198785
T: 6292 6836
F: 6292 5936
(UEN No: 201333127N)
(GST Reg No: 201333127N)

Our Ref : CY(Topmax)SJJ4214C(AC)hh
Your Ref : Please email to: helen@yogas-legal.com
Your insured vehicle SKM2719Z

28th May 2018

Lee Sian Shin
c/o The Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120

Dear Sirs

By Fax No: 6835 7416

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
ACCIDENT INVOLVING SJJ4214C & SKM2719Z ON 25/06/2016 @ 13:30 HRS
ALONG CHANGI VILLAGE ROAD PARALLEL CARPARK

We are instructed by Ismadi Bin Mohammad Eksan to notify you of a road traffic accident on 25th May 2016 at about 13:30 hours along Changi Village Road parallel carpark involving our client's vehicle SJJ4214C and vehicle number SKM2719Z driven by you /your insured at the material time. A copy of our client's accident statement is attached.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

C. Yogarajah LLC

Enc

c.c. client

Ismadi Bin Mohammad Eksan

c/o M/s. Topmax Auto BodyShop

By email
(Attention: Carmen Chang)

For Surveyor
Please initial here after completion of pre-repair inspection.
Thank you.

Name:
Signature:

Date & Time of Pre-repair Inspection: /

Confidentiality & Privilege: This message is intended for the recipient to whom it is addressed. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not copy, use or circulate this communication. Discretionary effort has been made to ensure the confidentiality of this communication. If you are not the intended recipient, please contact the sender. Opinions, conclusions or other information in this message that do not relate to the official business of the firm shall be understood as neither given nor endorsed by C. Yogarajah LLC Advocates & Solicitors. Thank you

Our Ref : CY(Topmax)SJJ4214C(AC)hh
Please email to: helen@yoga-legal.com
Your Ref : Your insured vehicle SKM2719Z

28th May 2018

The Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120

By Email

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
ACCIDENT INVOLVING SJJ4214C & SKM2719Z ON 25/05/2018 @ 13:30 HRS
ALONG CHANGI VILLAGE ROAD PARALLEL CARPARK

We refer to your email of even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose M/r. Alan Cheong K.H of M/s. C L Appraiser Pte Ltd to conduct a Pre-Repair inspection.

Please be informed that the said vehicle can be inspected at:

Name of workshop : M/s. TopMax Auto BodyShop
Address : Block 3007 Ubi Road 1 #01-410
Singapore 408701
Contact person : Miss Carmen Chang
Telephone number : 67442653
Fax : 67441153

Please be informed that if we do not hear from you **within 2 working days** from the date hereof, we will assume, as per Protocol, that you have no objections to our abovenamed motor surveyor you will be deemed to have agreed as a 'single joint expert'.

If you object to our motor surveyor, we will accordingly inform the claimant to instruct his choice of motor Surveyor to conduct the pre-repair survey.

Yours faithfully,


C. Yogarajah LLC

c.c. client
Ismadi Bin Mohammad Eksan
M/s. Topmax Auto BodyShop (By email)

For Surveyor

Please initial here after completion of pre-repair inspection.
Thank you.

Name:
Signature:

Date & Time of Pre-repair inspection: /

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/05/2018 10:22
Date Of Accident	25/05/2018 13:30
Exact Location Of Accident	ALONG CHANGI VILLAGE ROAD PARALLEL CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ4214C
Insured/Policyholder	
Name Of Registered Owner	ISMADI BIN MOHAMAD EKSAN
NRIC No	S8017346F
Email Address	ISMADI0780@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96804214
Alternative Phone No	OTHERS-96804214

Vehicle Particulars

Manufacturer	BMW
Model	3200-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	18-MU006577-R01
Cover Note Number	

Driver

Name of Driver	ISMADI BIN MOHAMAD EKSAN
NRIC No	S8017346F
Date Of Birth	13/06/1980
Occupation	OUTDOOR
Date Of Driving Pass	07/04/2008
Driving Experience	10 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96804214
Fax Number	
Contact Number	OTHERS-96804214
EMail Address	ISMADI0780@GMAIL.COM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	7346F

Vehicle Details

Vehicle No.:	SJJ4214C
Vehicle to be Exported:	No
Intended De-registration Date:	06 Jun 2018
Vehicle Make:	B.M.W.
Vehicle Model:	320i AT ABS D/AB 2WD 4DR GAS/D SR
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	B444I849N46B20BD
Chassis No.:	WBAPG56020NM91184
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$38,214.00
Original Registration Date:	31 May 2011
First Registration Date:	31 May 2011
Transfer Count:	1
Actual ARF Paid:	\$38,214.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2021
PARF Rebate Amount:	\$22,928.00

Intended COE Rebate Details

COE Expiry Date:	30 May 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$57,100.00
COE Rebate Amount:	\$16,396.00
Total Rebate Amount:	\$39,324.00

The information contained herein is correct as at 06 Jun 2018

OK

MOTOR CAR (Frt)

Front Portion

NAC	INC	Item	CON	AC	QTY
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	DMG	✓	
1005	992341	Frt Bumper Clips	NEC	✓	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer RH	CUT	✓	
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	CRK	✓	
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler	SCR	✓	
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp	CRK	✓	
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	CRK	✓	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No: SJJ 4214 C

NAC	INC	Item	CON	AC	QTY
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	CUT	R	
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector	CUT	✓	
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim	CUT	✓	
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRJ

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jun 2018 Edit Reg		04 Jun 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LEE SIAN SHIN, ID: S7172719Z		
Main Claimant:	ISMADI BIN MOHAMAD EKSAN, ID: S8017346F		
Vehicle Reg. No.:	SJJ4214C	Date of Loss:	25/05/2018 13:00 - :59 [83 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9407628284SG	Policy/Cover Note No.:	2100364465 (Comprehensive)
Vehicle Reg. No. (Insured):	SKM2719Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Topmax Auto Bodyshop (HQ) BLK 3007 UBI ROAD 1, #01-410 Kampong Ubi Industrial Estate, 408701 Ubi - Tel: 67442653		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 18/06/2018]		
Claimant's Solicitor:	C YOGARAJAH LLC - Tel: 62925838		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (07/06/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SJJ4214C (94076282845G)**
[SKM2719Z]


























TP

ISMADI BIN MOHAMAD EKSAN

May 25 2018 1:00PM

[LEE SIAN SHIN]

Topmax Auto Bodyshop

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
2	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
3	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
4	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
5	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
6	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
7	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
8	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
9	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
10	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
11	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
12	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
13	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
14	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
15	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
16	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
17	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
18	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
19	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
20	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
21	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
22	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
23	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
24	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
25	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
26	07/06/18 11:13	General View	 Load JPG	<input checked="" type="checkbox"/>
27	07/06/18 11:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	07/06/18 11:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	07/06/18 11:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	07/06/18 11:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	07/06/18 11:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	07/06/18 11:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	07/06/18 11:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	07/06/18 11:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	07/06/18 11:13	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
36	07/06/18 11:13	Dismantled Parts		Load JPG	
37	07/06/18 11:13	Dismantled Parts		Load JPG	
38	07/06/18 11:13	Dismantled Parts		Load JPG	
39	07/06/18 11:13	Dismantled Parts		Load JPG	
40	07/06/18 11:13	Dismantled Parts		Load JPG	
41	07/06/18 11:13	Dismantled Parts		Load JPG	
42	07/06/18 11:13	Dismantled Parts		Load JPG	
43	07/06/18 11:13	Dismantled Parts		Load JPG	
44	07/06/18 11:13	Dismantled Parts		Load JPG	
45	07/06/18 11:13	Dismantled Parts		Load JPG	
46	07/06/18 11:13	Dismantled Parts		Load JPG	
47	07/06/18 11:13	Dismantled Parts		Load JPG	
Documentation					
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	07/06/18 16:04	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18010076/GZ4D3S2

Date: 02/07/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100364465
Claimant Vehicle No :	SJJ4214C	Insured Vehicle No :	SKM2719Z
Date of Loss:	25/05/2018	Nature of Claim:	TP
		Claim No:	9407628284SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ4214C	Engine No:	B4441849N46B20BD
Make & Model:	BMW 320I, 2.0 (A)	Chassis No:	WBAPG56020NM91184
Reg. Date:	31/05/2011 (Man. Year: 2011)	Odometer:	172011 km
Colour:	White		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/35R19	Rear Tyre Size:	235/35R19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	04/06/2018	Topmax Auto Bodyshop (HQ) BLK 3007 UBI ROAD 1, #01-410 Kampong Ubi Industrial Estate Singapore 408701
Date Inspected:	05/06/2018 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Damaged	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER RH	Cut	0.00 F	*- F
4	1		*FRT BUMPER GRILLE	Cracked	0.00 F	*- F
5	1		*FRT BUMPER LOWER SPOILER	Scratched	0.00 F	*- F
6	1		*FRT RH BUMPER FOG LAMP	Cracked	0.00 F	*- F
7	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
8	1		*FRT RH FENDER	Repair	0.00 F	*- F
9	1		*FRT RH FENDER PROTECTOR	Cut	0.00 F	*- F
10	1		*FRT RH WHEEL RIM	Cut	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)

0.00

0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >