

22/03/2007

ASS. REC. BY:

REF: CS3/AIG/18010078/D240302

Instruction:

Surveyor

Bmyun

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time: 04/06/18 @ 10:15am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJG 7600S

Insured:

SLS 4646T

at Workshop m/s

Verve Motor Clinic

Tel:

91595451

of

No. 25 Kaki Blk Rd 4 #03-32

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time

10:30am @ 4/6/18

Person Contacted:

Mr. Jaron

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

SJG 7600S - CS3/AIG/15012240/Y+bd/

DOA: 21/7/15

SLS 4646T - X.

6/6/18

Dismantled

14/6/18

After Repair

REF: AIG

## ASSIGNMENT

COE July 2018

From:

Date:

4/6/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJG 7600S

at Workshop m/s

Verve Motorclinic

of No. 25 Kaki Bkt Rd 4 #03-32

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Mrjawn @ 91595951

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 68 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Cup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SJG 7600S

Yr Regn:

2008 / July

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Vios

C.C. 1497

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

85633

T/Radio: Insured / Std / NI / NA

Eng/No:

1NZX766007

C/No:

MR053HY9305068584

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60 R15

R:

— — —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Michelin

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

01/06/2018

D.O.I.

04/06/2018

Survey held at Verve Motorclinic Kaki Bukit.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No. &amp; GIA provided

1st inspection 04/06/2018

2nd inspection 06/06/2018

3rd inspection 14/06/2018

MV 6K

LTA 5.1K

HL 900/-

paper value plus body value up 1 1/2 mtr at time of loss.

21/6/18 Submit DAR Report.

Date/Time: File Pass to?



Preli. Report

Days Of Repair:

1)



Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time: File Return to?

Transportation

2)

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

) \$ + PS \$

) Photos

) Others

TOTAL

Report Format :


Lump Sum / I.B.I: (\$)

180

20

200

**- FW: PRI AIG Insured SLS4646T [EAL.2018.5699.MK.ya - SJG7600S]**

From: Chin, Lee-Ying  
To: assignments@lkkauto.com, Admin A  
Cc: Fong, Andy-SY  
Sent: 4/6/2018 10:15:02 AM  
Attachments:  180601-GIA report SJG7600S(NEW).pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947 | Fax +(65) 6835 7416  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

---

**From:** Yvonne [<mailto:yvonne@ealc.com.sg>]

**Sent:** Friday, June 01, 2018 5:02 PM

**To:** Chan, Yoke Shi

**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina

**Subject:** PRI AIG Insured SLS4646T [EAL.2018.5699.MK.ya - SJG7600S]

Our ref : 2018.5699.MK.ya - **SJG7600S**

Your ref : **SLS4646T**

PLEASE REPLY VIA EMAIL ([yvonne@ealc.com.sg](mailto:yvonne@ealc.com.sg))

AIG Asia Pacific Insurance Pte Ltd  
No. 78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Motor Claims Department  
**2 DAYS' PRE-REPAIR NOTICE**

Surveyor from M/s AIG Asia Pacific Insurance Pte Ltd

Vehicle **SJG7600S** inspected as follows by Name:

Before repair

Parts removed

After repair

Signature

Signature

Signature

Date/ Time:

Date/ Time:

Date/ Time:

Dear Sir/Madam,

**NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE**

**CLAIMANT: KINETIC HOLDINGS PTE LTD**

**ACCIDENT INVOLVING SJG7600S & SLS4646T ON 01 JUNE 2018 ALONG U-TURN OF SENTOSA GATEWAY AT ABOUT 0830 HOURS**

We refer to the above matter wherein we are instructed to act for **KINETIC HOLDINGS PTE LTD**, the owner of vehicle no. **SJG7600S**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **SJG7600S** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Verve Motorclinic Pte Ltd

No. 25 Kaki Bukit Road 4,

#03-39 Synergy@KB, *#03-32*

Singapore 417800

Tel: 91595951 (Mr Jaron)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,

Yvonne Ang

East Asia Law Corporation

No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413

Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18010078/Dz4d3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 04-06-2018



Code : AIG

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLS 4646T	Veh. Inspected	SJG 7600S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	04/06/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	01/06/2018	Inspection Date	04/06/2018
Survey held at	VERVE AUTOCLINIC BLK 25 KAKI BUKIT ROAD 4 #03-39 SYNERGY @ KB SINGAPORE 417800		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

MVA318071188 / VAC - Kaki Bukit  
ENTRY DATE & TIME: 01/06/2018 15:03  
SUBMITTED BY: SITI FADHLON BTE ABDUL KADER

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/06/2018 15:03
Date Of Accident	01/06/2018 08:30
Exact Location Of Accident	U-TURN OF SENTOSA GATEWAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG7600S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KINETIC HOLDINGS PTE. LTD.
Co Reg No	201618392N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-84848585

### Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5100806956
Cover Note Number	

### Driver

Name of Driver	HO YEN TECK
NRIC No	S7917994I
Date Of Birth	23/06/1979
Occupation	OUTDOOR
Date Of Driving Pass	21/12/2001

6/19/2018

E-FILE

Driving Experience	16 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98363336
Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	9 TAGORE LANE #03-21 9 @ TAGORE
Postcode	787472
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : MERYLLYN NG JIA LI Gender: : Female

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS4646T
Vehicle Make/Model/Colour	NISSAN QASHAI
Details Of Properties	

6/19/2018

E-FILE

Vehicle Category	PRIVATE CAR
Name of Driver	RONG JIANG
NRIC/Passport Number	S7976602Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	•MERYLLYN NG JIA LI
Approximate Age	
Injuries Sustain	-5DAY MC-
Injured person in which vehicle?	SJG7600S
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	



6/19/2018

E-FILE

**Sketch Plan**

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

01 JUN 2018



Policyholder's Signature  
Date & Time:

*Handwritten signature*


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IDAC KAKI BUKIT (VAC)  
23 KAKI BUKIT AVE 4  
Singapore 415933

Reporting Centre Personnel's Signature  
Name: *Handwritten name*  
Fax: 67492305  
Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)  
NRIC/FIN No.:

## Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

WHILST MAKING A U-TURN WITH THE GREEN-ARROW IN MY FAVOUR, SUDDENLY  
 VEH 'B' WHICH EARLIER WAS ON THE OPPOSITE LANE BLATANTLY BEAT THE  
 RED LIGHTS AND COLLIDED ONTO MY LEFT HAND SIDE PORTION.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

01 JUN 2018 IDAC KAKI BUKIT(VAC)  
 23 KAKI BUKIT AVE 4

Reporting Centre Personnel's Signature  
 Name: Tel: 67416697  
 NRIC/FIN No.: Fax: 67492305  
 Email: vackb@singnet.com.sg

SSG 76008 DOA 01/06/2018

- 1.) LH Front Door x 1 Bnc
- 2.) LH Front Door chrome moulding x 1 Bt
- 3.) LH Front Door outer handle x 1 cnt
- 4.) LH Front Door rubber x 1 blk
- 5.) LH Front Door lock x 1 broken
- 6.) LH Rr Door x 1 Bnc
- 7.) LH Rr Door chrome moulding x 1 Bt
- 8.) LH Rr Door hinge x 2 Bt
- 9.) LH Rear Door rubber x 1 blk
- 10.) LH Rear Panel <sup>outer</sup> x 1 Bntn
- 11.) LH Rear Panel inner x 1 fcv
12.  
~~17.~~) LH Centre Pillar x 1 Bnc
- ~~18.) LH Rear Door st~~

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jun 2018 <a href="#">Edit Reg</a>		04 Jun 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------




































CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	RONG JIANG, ID: S7976602Z	
Main Claimant:	KINETIC HOLDINGS PTE.LTD, Co. Reg. No.: 201618392N	
Vehicle Reg. No.:	SJG7600S	Date of Loss: 01/06/2018 08:00 - :59 [118 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6997445153SG	Policy/Cover Note No.: 1700057035 (Comprehensive)
Vehicle Reg. No. (Insured):	SLS4646T	Policy No. (Claimant):
		Excess:
Repairer:	Verve Autoclinic (HQ) No. 25 Kaki Bukit Road 4, #03-39 Synergy@KB, 417800 Kaki Bukit - Tel: 91595951	
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 28/06/2018]	













































ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>AIG_SG (20/06/2018): Request To Upload TP GIA Report</li> </ul>		

ALL ASSOCIATED TASKS		<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJG7600S (6997445153SG)  
[SLS4646T]  
TP  
KINETIC HOLDINGS PTE.LTD  
Jun 1 2018 8:00AM  
[RONG JIANG]  
Verve Autoclinic

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
2	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
3	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
4	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
5	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
6	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
7	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
8	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
9	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
10	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
11	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
12	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
13	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
14	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
15	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
16	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
17	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
18	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
19	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
20	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
21	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
22	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
23	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
24	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
25	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
26	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
27	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
28	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
29	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
30	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
31	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
32	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
33	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
34	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
35	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
36	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	
37	21/06/18 14:11	General View														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	21/06/18 14:11	General View	 Load JPG	<input checked="" type="checkbox"/>
39	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	21/06/18 14:11	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	21/06/18 14:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	21/06/18 14:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	21/06/18 14:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	21/06/18 14:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	21/06/18 14:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	21/06/18 14:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	21/06/18 14:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	21/06/18 14:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	21/06/18 14:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	21/06/18 14:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	21/06/18 14:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	21/06/18 14:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	21/06/18 14:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	21/06/18 14:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	21/06/18 14:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	21/06/18 14:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	20/06/18 13:00	OI GIA REPORT	 Load PDF	

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer  
Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18010078/DZ4D3E2

Date: 27/06/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700057035  
 Claimant Vehicle No : SJG7600S Insured Vehicle No : SLS4646T  
 Date of Loss: 01/06/2018 Nature of Claim: TP Claim No: 6997445153SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJG7600S**  
 Make & Model: TOYOTA VIOS, 1.5 (A) Engine No: 1NZX766007  
 Reg. Date: 16/07/2008 (Man. Year: 2008) Chassis No: MR053HY9305068584  
 Colour: Red Odometer: 85633 km  
 Engine Capacity: 1497 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
 Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm  
 Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 04/06/2018  
 Date Inspected: 04/06/2018 Inspected At: Verve Autoclinic (HQ)  
 No. 25 Kaki Bukit Road 4, #03-39  
 Synergy@KB  
 Singapore 417800  
 Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT DOOR	Buckled	0.00 F	*- F
2	1		*LH FRONT DOOR CHROME MOULDING	Bent	0.00 F	*- F
3	1		*LH FRONT DOOR OUTER HANDLE	Cut	0.00 F	*- F
4	1		*LH FRONT DOOR RUBBER	Necessary	0.00 F	*- F
5	1		*LH FRONT DOOR LOCK	Broken	0.00 F	*- F
6	1		*LH REAR DOOR	Buckled	0.00 F	*- F
7	1		*LH REAR DOOR CHROME MOULDING	Bent	0.00 F	*- F
8	2		*LH REAR DOOR HINGE	Bent	0.00 F	*- F
9	1		*LH REAR DOOR RUBBER	Necessary	0.00 F	*- F
10	1		*LH ROCKER PANEL OUTER	Dented	0.00 F	*- F
11	1		*LH ROCKER PANEL INNER	Repair	0.00 F	*- F
12	1		*LH CENTRE PILLAR	Buckled	0.00 F	*- F
				<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >