

Surveyor: Taufik. ASSIGNMENT (Office)

From (Person): Rachel Tan of GAI Date/Time: 4/6/18 @ 2.28pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBG 6013M Insured:

at Workshop m/s: Leong Seng Motor Tel: 6273 7469

of: Blk 1006, Bkt Meruk Lane 2 # 01-08

Policy No: Claim No: CLMOMVM000000291

Sum Insured: Excess: \$ 750/-

Make of Veh: D.O.A. 27/05/2018

(Client's Record) 5/6/2018

CA / REV / REP. / REP. 24 HRS H.O.D. Endorsement:

Date/Time: 5.26pm @ 4/6/2018 Person Contacted: Cindy Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	FBG6013M - NBA/GAI 18009973/Y DOA: 27/5/2018
06/06/18 @ 15:11 p.m.	revert PA & Authorization requested to Rachel via email.
06/06/18 @ 15:59 p.m.	revert authorised repair to Mr. Teo (repairer) via email.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 06 June 2018

Our Ref: CS/GAI18010094/T1sd3

The Motor Claims Department
GREAT AMERICAN INSURANCE COMPANY

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. FBG 6013M

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05/06/2018 at the premises of M/s Leong Seng Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,671.60</u>
Revised Estimate Amount	: S\$ <u>4,032.10</u>
"Check" Items Amount	: S\$ <u>904.50</u>
Market Value	: S\$ <u>5,500.00</u>
LTA Reimbursement Value	: S\$ <u>768.00</u>
Nett Value	: S\$ <u>4,732.00</u>

Description of Damage:

The vehicle sustained damages at the front & o/s portion.



Comments/ Present Status:

Damage consistent
Repair cost Economical (Repairer agreed to repair not more than \$ 4,500.00)
Repair days: 4 Days

Yours faithfully

Mohamad Taufikh
Motor Surveyor

Shirley Hiew (LKK Auto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Wednesday, 6 June 2018 3:54 PM
To: Shirley Hiew (LKK Auto); General Claims
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: RE: FBG6013M O/D claim (DOA 27/5/2018)

Hi

Claim No: CLMOMVM000000291

Excess \$750. Please approve if damage is consistent.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, June 6, 2018 3:11 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>; General Claims <GeneralClaims@sg.gaig.com>
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>; ASSIGNMENTS@LKKAUTO.COM
Subject: [External] RE: FBG6013M O/D claim (DOA 27/5/2018)

Dear Rachel,

Enclosed herewith preliminary advice of FBG 6013M.

Kindly provide us claim no.

We have not authorise repair, kindly let us have the authorization.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Monday, 4 June 2018 5:29 PM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; 'General Claims' <GeneralClaims@sg.gaig.com>;
ASSIGNMENTS@LKKAUTO.COM
Cc: sur@lkkauto.com
Subject: RE: FBG6013M O/D claim (DOA 27/5/2018)

Dear Sir/Mdm,

Thank you for the assignment.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 6 June 2018 3:11 PM
To: 'Tan, Rachel'; 'General Claims'
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: FBG6013M O/D claim (DOA 27/5/2018)
Attachments: FBG 6013 - Preli Advise.pdf

Dear Rachel,

Enclosed herewith preliminary advice of FBG 6013M.

Kindly provide us claim no.

We have not authorise repair, kindly let us have the authorization.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Monday, 4 June 2018 5:29 PM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; 'General Claims' <GeneralClaims@sg.gaig.com>;
ASSIGNMENTS@LKKAUTO.COM
Cc: sur@lkkauto.com
Subject: RE: FBG6013M O/D claim (DOA 27/5/2018)

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Monday, 4 June 2018 2:28 PM
To: General Claims <GeneralClaims@sg.gaig.com>
Cc: LKK Assignments <assignments@lkkauto.com>
Subject: RE: FBG6013M O/D claim (DOA 27/5/2018)

Dear Mr Teo, We will arrange for LKK to conduct survey.

Dear LKK, please accept assignment for OD survey. Attached GIA report and estimates.

Nivitha (LKK Auto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Monday, 4 June 2018 2:28 PM
To: General Claims
Cc: LKK Assignments
Subject: RE: FBG6013M O/D claim (DOA 27/5/2018)
Attachments: FBG6013M_27052018.pdf; IMG_20180602_0002.pdf

Dear Mr Teo, We will arrange for LKK to conduct survey.

Dear LKK, please accept assignment for OD survey. Attached GIA report and estimates.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Ong, Joanna **On Behalf Of** General Claims
Sent: Monday, June 4, 2018 2:07 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: FW: [External] FBG6013M O/D claim request for survey

Hi Rachel,

FYNA on FBG6013M claim. Thanks!

Joanna

From: leongseng <leongsen@singnet.com.sg>
Sent: Saturday, June 02, 2018 10:11 AM
To: General Claims <GeneralClaims@sg.gaig.com>; Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: [External] FGB6013 O/D claim request for survey

Dear Sir/Mdm

Pls be informed that owner of FBG6013 (Certis Cisco) had appointed us to do a O/D ins claim for them.

Pls find enclosed accident report and our repair estimate.

Kindly arrange your appointed surveyor to conduct damage survey on the bike, at our workshop.

Pls be inform that our workshop is located at Blk 1006, Bukit Merah Lane 2, #01-08 S(159762).

Thanks

c s teo
Leong Seng Motor PL
62737469

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 6 June 2018 3:59 PM
To: 'leongseng'
Cc: sur@lkkauto.com
Subject: RE: FBG 6013M OD (GAI)

Dear Mr. Teo,

As instructed by our client, please proceed to repair the insured vehicle **FBG 6013M (Excess \$ 750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: leongseng [mailto:leongsen@singnet.com.sg]
Sent: Wednesday, 6 June 2018 2:48 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: Re: FBG 6013M OD (GAI)

Dear Shirley

Pls be informed that we are able to work on repair cost not more than S\$4500.

Thanks

c s teo

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, June 6, 2018 2:40 PM
To: leongsen@singnet.com.sg
Cc: sur@lkkauto.com
Subject: FBG 6013M OD (GAI)

Dear Mr. Teo,

Kindly check the repair cost whether you are able to repair the vehicle not over \$4,500.00

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/06/2018 17:17
Date Of Accident	27/05/2018 09:00
Exact Location Of Accident	EXIT 08 CTE TOWARDS OUTRAM ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBG6013M
Insured/Policyholder	
Name Of Registered Owner	CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD
Co Reg No	200900882K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94886591
Alternative Phone No	OFFICE-94886591
Vehicle Particulars	
Manufacturer	YAMAHA
Model	YBR125-123CC (M)
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	MT20171640
Driver	
Name of Driver	MUHAMMAD SHAHZARWAN BIN YACOB
NRIC No	S9142839C
Date Of Birth	17/11/1991
Occupation	OUTDOOR
Date Of Driving Pass	08/04/2010
Driving Experience	8 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94886591
Fax Number	
Contact Number	OTHERS-94886591
Email Address	NOEMAIL

Address	BLK 616 HOUGANG AVENUE 8 #02-370
Postcode	530616
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	1
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH AND ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF INJURED PERSON 1

Name	MUHAMMAD SHAHZARWAN BIN YACOB
Approximate Age	
Injuries Sustain	SLIGHT INJURY
Injured person in which vehicle?	FBG6013M
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material information from the insurer(s) entitles us to **re-evaluate policy liability**.
4. The issue and issuance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers to the GUA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Ministry of Transport, the Ministry of Police and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of such postal/packages) and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in the accident and the Insurers' lawyers/law firms may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
 - (c) my Personal Information may (can be disclosed) be any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) that may be located outside of Singapore for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to complete claim history for the purpose of fraud detection, investigation and management in present and future claims;
 - (e) the information collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud;
 - (ii) to regulatory, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (iii) for complying with inquiries from, under any regulatory, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(if Driver is not the policyholder)
Date & Time

Reporting Centre of Insurers' Signature
Name
NRIC/IN No.

Accident Sketch Plan

SKETCH PLAN

P-486601371

↑
↓
○
↑

CTE
32
outdoor
road

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attached

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time

31 July 2018 20:42
Driver's Signature
(If driver is not the policyholder)
Date & Time

01/06/2018
Reporting Centre Person's signature
Name
NRIC ID No.

Ref: 11/11/11/11

ATTACHMENT



INCIDENT REPORT FOR DUTY POST

Location of Duty Post	Type of Business (Bank/KINs/Embassy/ Residence/Factory)	Date of Incident	Time of Incident	Weather Condition
Singapore General Hospital	KINS	27 May 2018	0900hrs	Wet road
Person(s) Involved	Particulars of Witness(es)			
CPI 99214, Muhammad Shahrizan bin bin Yusoff, Singapore	nil			
Details of Incident (Who, What, Where, When, Why, How and Other Essential Details)				
<p>At about 0900hrs, CPI 99214 Muhammad Shahrizan bin Yusoff was deployed at Shift for mobile App. I was assigned to take the mobile App. I was riding along the axis of the expressway towards Singapore when the accident happened. I was the only person involved in the accident. No other person or other road user was involved. I was riding accurately and applied brake to slow down. The next moment I realised I was already sliding on the road due to wet condition. I had physical injuries on my right wrist and right knee due to the accident.</p>				
Reported by: CPI 99214, Muhammad (Rank/Svc No/Name) Shahrizan bin Yusoff	Signature 	Date 27 May 2018	Time 0900hrs	

01/06/2018
Resh, WATERS

ATTACHMENT



INCIDENT REPORT FOR DUTY POST

Location of Duty Post	Type of Business (Bank/KINs/Embassy/ Residence/Factory)	Date of Incident	Time of Incident	Weather Condition
Singapore General Hospital	KINs	27 May 2018	0900hrs	
Person(s) Involved		Particulars of Witness(es)		
CP 99214 Muhammad Shafiqulwan bin Khalid Shafiqulwan		N/A		
Details of Incident (Who, What, Where, When, Why, How and Other Essential Details)				
At about 0900hrs I (CP 99214) received statement from CP 99214 who reported at about 0800hrs on 27 May 2018 I was assigned to work as a Security Guard patrolling along the side of the expressway towards Sunway at about 0800hrs the accident happened I was the only person involved in the accident as I was on duty and was also involved I was driving recklessly and speeded down to slow down the next moment I realized I was already going at 100 km/h due to the concentration I had brought forward on the right side of the road was due to the accident				
Reported by: CP 99214, Muhammad (Rank/Svc No/Name) Shafiqulwan bin Khalid		Signature	Date	Time
		<i>[Signature]</i>	27 May 2018	0900hrs

[Handwritten signature]
 27/05/2018
 CP 99214

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	0882K

Vehicle Details

Vehicle No.:	FBG6013M
Vehicle to be Exported:	No
Intended De-registration Date:	05 Jun 2018
Vehicle Make:	YAMAHA
Vehicle Model:	YBR 125 MANUAL
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	E3J2E005430
Chassis No.:	LBPKE1786D0009064
Maximum Power Output:	-
Open Market Value:	\$1,276.00
Original Registration Date:	12 Sep 2012
First Registration Date:	12 Sep 2012
Transfer Count:	1
Actual ARF Paid:	\$192.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	11 Sep 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,801.00
COE Rebate Amount:	\$768.00
Total Rebate Amount:	\$768.00

The information contained herein is correct as at 05 Jun 2018

OK

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBG6013M

Model : YBR125

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Top cowling		\$ 180.00	cm ✓	
2	Wind shield		\$ 75.00	cm ✓	
3	Headlamp assy		\$ 220.00	cut ✓	
4	Headlamp stay		\$ 96.00	bb ✓	
5	Front signal lamp		\$ 30.00	cm ✓	
6	Meter assy		\$ 480.00	cut ✓	
7	Front fender		\$ 120.00	cut ✓	
8	Front wheel axle		\$ 85.00	dd ✓	
9	Front wheel rim		\$ 395.00	cut ✓	
10	Front wheel bearing	2	\$ 50.00	new	
11	Front fork assy		\$ 720.00	? bt ✓	
12	Fork under bracket		\$ 285.00	? ht ✓	
13	Handle bar		\$ 105.00	bt ✓	
14	Handle grip		\$ 25.00	tn ✓	
15	Brake lever		\$ 30.00	br ✓	
16	Mirror		\$ 40.00	br ✓	
17	Front footrest bar		\$ 120.00	bt ✓	
18	Front footrest rubber		\$ 30.00	tn ✓	
19	Brake pedal		\$ 90.00	dd ✓	
20	Fuel tank protector		\$ 195.00	Rp	
21	Tail cover		\$ 235.00	cm ✓	
22	Exhaust protector		\$ 98.00	cut ✓	
23	Exhaust pipe		\$ 520.00	dd ✓	
24	Rear footrest		\$ 25.00	X nn	
25	Rear shock absorber		\$ 325.00	X nn	
26	Front blinker lamp		cm ✓ \$100	\$ 150.00	
27	Front no plate		bb ✓	\$ 15.00	
28	Side box bracket		bt ✓	\$ 160.00	
29	Side box		ds ✓	\$ 280.00	
30	Respray front fender, tank protector, side cover		150.	\$ 250.00	
31	Repair alignment		150 130	\$ 250.00	
32	Towing 2 way		80.	\$ 100.00	
33	Labour		200.	\$ 350.00	
34			Parts -	4029	
35			100% discount	3626.10	
36			3N	555	
37			labour	580	
38				4761.10	
39			L/S \$	3800 *	
			\$ 4,574.00	\$ 1,555.00	
			\$ 457.40		
			\$ 4,116.60		
				5671.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanjung 97495749

W Ex: to be advise.

Not Authorise

5/6/18 @ 1430

End 4 days.

Lumpsum

Resurvey after repair.

8/6/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18010094/T1sd3s2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 27-06-2018



Code : GAI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	FBG 6013M
Policy No.	MT20171640	Coverage (\$)	0.00
Claim No.	CLMOMVM000000291	Excess (\$)	750.00
Assign From	RACHEL TAN	Assign Date	04/06/2018

2. Vehicle Particulars & Condition

Make & Model	YAMAHAYBR 125	c.c	124
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	LBPKE1786D0009064	Colour	WHITE
Odometer	25646	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	2.75-18	METZELER	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	3.00-16	METZELER	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/05/2018	Inspection Date	05/06/2018
Survey held at	LEONG SENG MOTOR PTE LTD BLK 1006, BUKIT MERAH LANE 2 #01-08 ALEXANDRA VILLAGE SINGAPORE 159762.		

5a. Remarks

A)THE MARKET VALUE IS S\$5,500.00 (EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 6013M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TOP COWLING	CRACKED	180.00	180.00
1	WIND SHIELD	CRACKED	75.00	75.00
1	HEADLAMP ASSY	CUT	220.00	220.00
1	HEADLAMP STAY	BENT	96.00	96.00
1	FRONT SIGNAL LAMP	CRACKED	30.00	30.00
1	METER ASSY	CUT	480.00	480.00
1	FRONT FENDER	CUT	120.00	120.00
1	FRONT WHEEL AXLE	DENTED	85.00	85.00
1	FRONT WHEEL RIM	CUT	395.00	395.00
2	FRONT WHEEL BEARING	NECESSARY	50.00	50.00
1	FRONT FORK ASSY	BENT	720.00	720.00
1	FORK UNDER BRACKET	BENT	285.00	285.00
1	HANDLE BAR	BENT	105.00	105.00
1	HANDLE GRIP	TORN	25.00	25.00
1	BRAKE LEVER	BROKEN	30.00	30.00
1	MIRROR	BROKEN	40.00	40.00
1	FRONT FOOTREST BAR	BENT	120.00	120.00
1	FRONT FOOTREST RUBBER	TORN	30.00	30.00
1	BRAKE PEDAL	DENTED	90.00	90.00
1	FUEL TANK PROTECTOR	TO REPAIR SEE LABOUR	195.00	-
1	TAIL COVER	CRACKED	235.00	235.00
1	EXHAUST PROTECTOR	CUT	98.00	98.00
1	EXHAUST PIPE	DENTED	520.00	520.00
1	REAR FOOTREST	NOT NECESSARY	25.00	-
1	REAR SHOCK ABSORBER	NOT NECESSARY	325.00	-
	LESS 10% DISCOUNT		-457.40	-402.90
			4,116.60	3,626.10
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BLINKER LAMP (SN)	CRACKED	150.00	100.00
1	FRONT NO PLATE (SN)	BENT	15.00	15.00
1	SIDE BOX BRACKET (SN)	BENT	160.00	160.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SIDE BOX (SN)	DISTORTED	280.00	280.00
			605.00	555.00
	LABOUR			
	RESPRAY FRONT FENDER,TANK PROTECTOR,SIDE COVER.		250.00	150.00
	REPAIR ALIGNMENT.		250.00	150.00
	TOWING 2 WAY.		100.00	80.00
	LABOUR.INCLUSIVE OF THE REPAIR OF FUEL TANK PROTECTOR.		350.00	200.00
			950.00	580.00
	GRAND TOTAL		5,671.60	4,761.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00
	LESS EXCESS			-750.00
	NETT LIABILITY			3,050.00

Report Ref No. CS/GAI18010094/T1sd3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.