

Surveyor

Rusul

ASSIGNMENT (Office)

Menimen

From (Person)

Jasmine lok

of

MSG

Date/Time:

01/06/2018 @ 4:14pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 4250 A

Insured:

SFZ 4544M

at Workshop m/s:

Comfort Delgro (Pandan)

Tel:

68676919/97239882

of

45 Pandan Rd

Policy No:

A28626158TMP

Claim No:

558162

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/05/2018

CA / REV / REP. / REV 24 HRS (up)

05/06/2018

I.E.O.D. Endorsement:

Date/Time:

10:03am @ 4/6/18

Person Contacted:

Ken

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJS 4250 A - NA / INC 12000436/wlk

D.O.A.: 6/01/2012

06/06/2018 @ 3:59pm

revised to Jasmine lok via Menimen.

Finalised \$699.96: (Red 850.61; 54%)

Pam

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **33B 4250A**
 at Workshop mis: **COMFORT ORCHARD**
 of: **45, PANDAN RD**
MSH
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted _____

Vehicle: IN / OUT

Veh No: **SJS 4250A** Yr Regn: **2009 / ANH**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **SUZUKI SWIFT 1.2XGA** cc **1242**
 Colour: **RED** A/C Insured / Std / NI / NA
 Sp.Reading: **31416** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **2C 715 434 171**
 Gen. Cond: Good ☒ / Poor / Burnt
 Steering: ☒ / Jammed / Leaked / Burnt or
 Brake: ☒ / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **185/60R15**
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Kumho**

Front: _____ Rear: _____
 R/Bal: **5** mm R/Bal: **5** mm
 L/Bal: **5** mm L/Bal: **5** mm
 D.O.A: **06/05/18** D.O.L: **05/06/18**

Survey held at **COMFORT ORCHARD**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

p/s Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 01 OCT 2018

Date/Time: File Pass to?

1/28/9 Typist

Date/Time: File Return to?

2)

Report Format :

Lump Sum / (B): (\$

TP

699.96

Days Of Repair: **3**

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee:

Transportation:

☐ S + RS. ☐ SI

☐ Photos:

☐ Others:

TOTAL

150

10

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2018 11:14 Sendback Est	28 May 2018 11:18 S\$1,467.62	01 Jun 2018 16:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	WONG CHYE HOE PETER, ID: S1707749Z			
Main Claimant:	FIRDAUS BIN ASWEN			
Vehicle Reg. No.:	SJS4250A	Date of Loss:	06/05/2018 20:00 - :59 [104 Months and 21 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 558162	Policy/Cover Note No.:	A28626158TMP (Third Party Only) Coverage: 19/10/2017 - 18/10/2018	
Vehicle Reg. No. (Insured):	SFZ4544M	Policy No. (Claimant):		
		Excess:		
Repairer:	ComfortDelGro Engineering Pte Ltd (Pandan) 45 Pandan Road, 609286 Eunos - Tel: 6338 8778			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/06/2018]			
Adj Asg. Remarks:	on WP. SJE Agree Please appoint LKK and contact Wong Chee Wei @ 6867 6919 . 9723 9882 Liability (Not clear)			

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ▢

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Low Yi Qian

From: CDGE Pandan Private Cars Crash Repair Counter <pandan_cr@sparkcarcare.com>
Sent: Wednesday, 30 May, 2018 12:32 PM
To: Low Yi Qian
Cc: Jasmine Lok Kheng Kwei
Subject: RE: Advice liability accident involving for our client vehicle no. SJS4250A and Your insured vehicle no. SFZ4544M .DOA @ 06 May 2018 (Your ref :M558162)

Follow Up Flag: Follow up
Flag Status: Completed

Hi Ms Low ,

Ok ,We agree for LKK .Kindly pls arrange .

Best Regards,

Wong Chae Wei
Crash Repair Pandan
DID 68676919
HP 97239882

From: Low Yi Qian <yiqian_low@sg.msig-asia.com>
To: "pandan_cr@sparkcarcare.com" <pandan_cr@sparkcarcare.com>
Cc: Jasmine Lok Kheng Kwei <jasmine_lok@sg.msig-asia.com>
Date: 05/30/2018 09:35 AM
Subject: RE: Advice liability accident involving for our client vehicle no. SJS4250A and Your insured vehicle no. SFZ4544M .DOA @ 06 May 2018 (Your ref :M558162)

Dear Sir/Madam

We would like to appoint the following surveyor, LKK Auto Consultancy Pte. Ltd for your claim.

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert)

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

- 1) Adrian Ling
- 2) Kenneth Kong
- 3) Marcus Chua
- 4) Henry Ng
- 5) Lau Kwok Kwong
- 6) Frankie Pang
- 7) Ng You han
- 8) Gary Soon
- 9) Chow Bo Xiong
- 10) Axel Lee

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB: If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor

surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

Thank you.

Best Regards

Low Yi Qian

Administrative Officer

Claims Services Department

Direct line +65 6594 2525 | Direct fax +65 6225 7402 | yiqian_low@sg.msig-asia.com



MSIG



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on @MSIG_SG

A member of **MS&AD** INSURANCE GROUP

From: Clara Milah Yeo

Sent: Monday, 28 May, 2018 5:57 PM

To: Jasmine Lok Kheng Kwei <jasmine_lok@sg.msig-asia.com>; Low Yi Qian <yiqian_low@sg.msig-asia.com>

Cc: Jason Sim <Jason_Sim@sg.msig-asia.com>; Foo Ai Ngoh <aingoh_foo@sg.msig-asia.com>

Subject: FW: Advice liability accident involving for our client vehicle no. SJS4250A and Your insured vehicle no. SFZ4544M .DOA @ 06 May 2018 (Your ref :M558162)

Dear Both,

For your attention.

Thank you.

Sincerely,

Clara Milah Yeo

Senior Admin Officer, Claims Services (Motor)

Direct line +65 6594 2560 | Direct fax +65 6225 7402 | milah@sg.msig-asia.com



MSIG



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on

A member of **MS&AD** INSURANCE GROUP

From: Koh Lay Hoon

Sent: Monday, 28 May 2018 5:21 PM

To: Clara Milah Yeo <Milah@sg.msig-asia.com>

Subject: FW: Advice liability accident involving for our client vehicle no. SJS4250A and Your insured vehicle no. SFZ4544M .DOA @ 06 May 2018 (Your ref :M558162)

From: CDGE Pandan Private Cars Crash Repair Counter [mailto:pandan_cr@sparkcarcare.com]

Sent: Monday, May 28, 2018 2:49 PM

To: Claims <claims@sg.msig-asia.com>

Cc: Jasmine Lok Kheng Kwei <jasmine_lok@sg.msig-asia.com>; firdaus_aswen@hotmail.com
Subject: RE: Advice liability accident involving for our client vehicle no . SJS4250A and Your insured vehicle no. SFZ4544M .DOA @ 06 May 2018 (Your ref :M558162)

Dear sir / madam,

Please arrange survey for SJS4250A on 4 June 2018, at 45 Pandan Road.

Thank you.

Kent Vo Yung Khong
Pandan Crash Repair
ComfortDelgro Engineering

From: Jasmine Lok Kheng Kwei <jasmine_lok@sg.msig-asia.com>
To: CDGE Pandan Private Cars Crash Repair Counter <pandan_cr@sparkcarcare.com>
Date: 05/24/2018 01:57 PM
Subject: RE: Advice liability accident involving for our client vehicle no . SJS4250A and Your insured vehicle no. SFZ4544M .DOA @ 06 May 2018 (Your ref :M558162)

Dear Chee Wei,

We are prepared to direct settle on a without prejudice basis. Quantum will be as per our surveyor's recommendations and subject to the consistency of the damage to the accident.

Our offer is made without admission of liability on the part of our insured and / or insured driver.

Thank you.

Have a nice day ahead.

Jasmine Lok

Executive, Claims Services (Motor)

Direct line +65 6594 2550 | Direct fax +65 6225 7402 | jasmine_lok@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on



A member of **MS&AD** INSURANCE GROUP

From: CDGE Pandan Private Cars Crash Repair Counter [mailto:pandan_cr@sparkcarcare.com]
Sent: Monday, 21 May, 2018 7:38 PM
To: Jasmine Lok Kheng Kwei <jasmine_lok@sg.msia.com>
Subject: Advice liability accident involving for our client vehicle no . SJS4250A and Your insured vehicle no. SFZ4544M .DOA @ 06 May 2018 (Your ref :558162)
Importance: High

Hi Jasmine ,

Please advice on liability for above mentioned vehicle accident involving .

Thanks ,

Best Regards,

Wong Chee Wei
Crash Repair Pandan
DID 68676919
HP 97239882

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 06 Jun 2018

Preliminary Advice

Insured Vehicle No	: SFZ4544M	Accident Date	: 06/05/2018
TP Vehicle No	: SJS4250A	Assignment Date	: 01/06/2018
Make	: SUZUKI SWIFT	Est. Duration of Repair	: 3.00
Date of Inspection	: 05/06/2018		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (PANDAN) 45 PANDAN ROAD SINGAPORE 609286		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,467.62
Revised Amount	:S\$	903.56
Check Items (Estimated)	:S\$	0.00
Total	:S\$	903.56

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/05/2018 09:10
Date Of Accident	06/05/2018 20:40
Exact Location Of Accident	SULTAN ISKANDAR COMPLEX CUSTOM CLEARANCE TO SINGAP
Country/State of Loss	MALAYSIA/WILAYAH PERSEKUTUAN

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS4250A
Insured/Policyholder	
Name Of Registered Owner	FIRDAUS BIN ASWEN
NRIC No	S8309438I
Email Address	FIRDAUS_ASWEN@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-93283800
Alternative Phone No	OTHERS-93283800

Vehicle Particulars

Manufacturer	SUZUKI
Model	SWIFT-1.2 X (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA317684/1
Cover Note Number	

Driver

Name of Driver	FIRDAUS BIN ASWEN
NRIC No	S8309438I
Date Of Birth	23/03/1983
Occupation	INDOOR
Date Of Driving Pass	09/01/2009
Driving Experience	9 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93283800
Fax Number	
Contact Number	OTHERS-93283800
Email Address	FIRDAUS_ASWEN@HOTMAIL.COM

Address	BLK 413 SAUJANA ROAD #03-10
Postcode	670413
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	FBB3743P
	-
	-
Insurance Company of Driver's Own Vehicle	NTUC INCOME INSURANCE CO-OPERATIVE LTD
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFZ4544M
Vehicle Make/Model/Colour	TOYOTA ALTIS/BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

07/05/18
08:15 hrs.

GENRIC-SAS-SP-Form-611- V2

Driver's Signature


(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving and ~~waiting~~ queueing for my turn at the Johor Malaysia customs & immigration towards Singapore. There were around 3 to 4 vehicles in front of me. Vehicle SF34544M was in queue at the time beside my queue when he tried to change lane into my queue, he hit the right-hand rear area of my car. Third party offered to do private settlement. Driver got no NRIC or Driving license with him at the point of accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

09/05/18 08:15 hrs.

CAUTION: Statement Form 102

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S83094381**

Name: **FIRDAUS BIN ASWEN**

Birth Date: **25 Mar 1983**

Issue Date: **12 Aug 2008**

0016307325

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S83094381**



Name
FIRDAUS BIN ASWEN

Race:
MINANGKABAU
Date of birth: **25-03-1983** Sex: **M**
Country of birth:
SINGAPORE

S83094381

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class	Description	Valid Date
Class 1A	Motorcycles up to 240 CC	08 Jun 2009
Class 1B	Motorcycles between 241 CC and 400 CC	08 Jun 2009
Class 2	Motorcycles > 400 CC	12 Aug 2008
Class 3	Motor cars up to 3500 kg with not more than 7 passengers, exclusive of the driver's seat motor Motorcycles up to 250 kg	08 Jun 2009

MP 425A

S / N: **9000086060**

License No: **S83094381**



4450486



License No: **S83094381**

Date of issue:
08-04-2013

Address
**APT BLK 413 SAUJANA ROAD
#03-10
SINGAPORE 670413**



redefining / insurance

AXA Insurance Pte Ltd
 1900 890 4888 (Within Singapore)
 (65) 6280 4888 (International)
 (65) 6280 4740
 customer.care@axa.com.sg
 www.axa.com.sg

Certificate of Insurance

account number
 03926

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1987 (Road Transport Act, 1987 (Malaysia))
 Motor Vehicles (Third-Party Risks and Compensation) Rules, 1987 (Malaysia)

Policy details

Policyholder name	RISDAUS BIN ASWEN	Certificate number	0A317064 / 1
Cover	Comprehensive	Chassis number	EC71S434171
Plan name	Essential	Engine number	H12B1055874
NCD applicable	65		
Vehicle registration number	SIS4290A		
Period of insurance	from 31/01/2018 to 30/01/2019 (both dates inclusive)		
Finance loan company	MAYBANK		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or while the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered operative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	S\$0 800.00
	Windscreen Excess	S\$0 300.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorized Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if you have chosen AXA Premium Workshop.

Additional clauses & endorsements to your policy

Nil

(We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insured company, if the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).
 The Premium Warranty Clause requires the premium to be paid in full within a specific period falling within which there would be no liability under the policy, renewal certificate, endorsement etc.

AXA Insurance Pte Ltd (199003513M)
 8 Shenton Way, #24-01, AXA Tower,
 Singapore 068811
 Customer Centre, #B1-01

Maxurance Venture
 8 Burn Road #04-10 S(369977)
 Trivex | enquiry@maxurance.com
 Tel 6100 2392 | Fax 6280 9878

1 of 3





Accident Photo



Accident Photo



Accident Photo



Accident Photo



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6841057F



Name

NG BEE HOON

黄美云

Race

CHINESE

Date of birth

26-10-1968

Sex

F

Country/Place of birth

SINGAPORE



REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 May 2018)**Parts:** 144 SUZUKI SWIFT 1.2 XG (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SJS4250A/28/05/2018 11:18**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*L/R BUMPER BRACKET	0.00	0.00	*25.00 F
2	1	NA	*R/R BUMPER BRACKET	0.00	0.00	*25.00 F
3	1	NA	*R/R SIDE PANEL	0.00	0.00	*123.00 F
4	1	NA	*REAR BUMPER	0.00	0.00	*350.00 F
5	1	NA	*REAR BUMPER MNTG KIT	0.00	0.00	*30.00 F
6	1	NA	*SUNDRY PARTS	0.00	0.00	*11.06 F

F=Franchise part.

Total Parts (S\$)**564.06**

ComfortDelGro Engineering Pte Ltd/SJS4250A/28/05/2018 11:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Total Paint Labour	New	275.00 ✓
2	Total Paint Materials	New	84.96 98.56
3	Total Panel/Mechanical Labour	New	340 530.00
Gross Labour Cost (S\$)			903.56

ComfortDelGro Engineering Pte Ltd/SJS4250A/28/05/2018 11:18. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**ComfortDelgro Engineering
Pte Ltd (Spark Car Care)
Pandan Branch
45 Pandan Road
Singapore 609286**

Claim Reference:
Assessment Number: RM000066
Version: COM-DGRO/1
Date Calculated: 26/05/2018 03:06

Full Report - V1
Registration: SJS4250A
Printed: 05/06/2018 13:52

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	CDGE Pandan	Date of Incident:	06/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	SUZUKI
Model:	Swift
Sub Model:	GL
Model Sheet Number:	R03 07
Registration:	SJS4250A
Registration Month:	August
Registration Year:	2009
VIN Number:	ZC71S434171
Manufacture Month:	August
Manufacture Year:	2008
Odometer:	Not Known
Colour:	
Engine Number:	K12B1056874
Fuel Level:	%

Model Specs

FROM VIN ...400001	1.3 LTR 67/68KW
4-SPEED AUTOMATIC	TYRES 185/60 HR 15
WHEELS 5.5J X 15 ALU	SINGAPORE VERSION
5-DOOR	PAINTING OFF VEHICLE
TWO COAT PEARL/MICA	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	25/05/2018
Pre-Accident Damage:	
Tyres Condition:	
Tyres - Tread Depth (MM):	

		Left Tyre		Right Tyre	
		Depth		Depth	
LHF	0	0.0		0.0	RHF

ComfortDelgro Engineering Pte Ltd (Spark Car Care)

Claim Reference:

Assessment Number: RM000066

Version: COM-DGRO/1


Date Calculated: 26/05/2018 03:06

Full Report - V1


Registration: SJS4250A

Printed: 05/06/2018 13:52

LHR 1 0.0 0.0
Damage Areas:



RHR
Direction of Impact:



Primary Impact
Secondary Impact

Addresses

Insured

Name : FIRDAUS BIN ASWEN

Address :

413 SAUJANA ROAD

#03-10

Post Code : 670413

Repairer

Name : COMFORTDELGRO ENGINEERING PTE LTD

Address :

45 PANDAN ROAD

Post Code : 609286

Cost Summary

Total Labour	\$805.00
Total Paint/Material	\$98.56
Total Parts	\$647.01
Excess:	TBA
Grand Total Exc GST:	\$1,550.57
7 % GST:	\$108.54
Grand Total Inc GST:	\$1,659.11

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$50.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
OP 500	RENEW R/R SIDE PANEL INCLUDES: R + R BUMPER, TAILLAMP, SEALS AND ALL TRIMS IN THE REPAIR SECTION	94.0	470.00
OP 681	R + R TAILGATE	9.0	45.00
OP 501	RENEW REAR BUMPER (REMOVED)	2.0	10.00
	INCLUDES: CONVERT ATTACHED PARTS		
OP 621	R + R REAR BUMPER CARRIER	1.0	5.00
LABOUR COST			
	Total Work Units	106.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	10.6HRS	\$530.00
	Paint Labour	5.5HRS	\$275.00
	Total Labour	16.1HRS	\$805.00

ComfortDelgro Engineering Pte Ltd (Spark Car Care)

Claim Reference:

Assessment Number: RM000066

Version: COM-DGRO/1

Date Calculated: 26/05/2018 03:06

Full Report - V1

Registration: SJS4250A

Printed: 05/06/2018 13:52

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- PAINTING OFF VEHICLE		
	- TWO COAT PEARL/MICA		
3482	R/R SIDE PANEL NEW PART PAINTING	18.0	
2581	REAR BUMPER NEW PART PAINT K1R	11.0	
LABOUR COST - PAINT			
	TIME(PAINT)	29.0	
	Preparation Main Work Metal	21.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	55.0	
	Total Paintwork Labour	5.5HRS	\$275.00
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$19.80
	New Part Painting - Plastic K1R		\$51.66
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$98.56
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$98.56

PARTS

Guide No. Qty		Description	Part Number	Supplier	Bet.	Price (\$)
2617	1	L/R BUMPER BRACKET	7182263J00000		0%	25.00*
2618	1	R/R BUMPER BRACKET	7182163J00000		0%	25.00*
3482	1	R/R SIDE PANEL	6411163J00P32		0%	123.00*
2581	1	REAR BUMPER	7181162J00799		0%	350.00*
2650	1	REAR BUMPER MNTG KIT	USE SINGLE PARTS		0%	30.00*
f: OEM Parts		Sub Total				\$553.00
g: Original		Mark Up From Cost		(15 %)		\$82.95
h: Secondhand		Sundry Parts		(2 %)		\$11.06
p: Parallel		Total Parts				\$647.01
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras \$0.00

Final Calculation

Total Parts		\$647.01
Labour		
Total Panel/Mechanical		
Total Paintwork		
Total Labour		\$805.00
Total Paint/Material Costs		\$98.56
Grand Total Excludes GST		\$1,550.57
GST @ 7 %		\$108.54
Grand Total Includes GST		\$1,659.11

05/06/18 @ 1350

Assessment Notes

Repair after repair

Claim Reference:

Full Report - V1

Assessment Number: RM000066

Registration: SJS4250A

Version: COM-DGRO/1

Printed: 05/06/2018 13:52

Date Calculated: 26/05/2018 03:06

**ComfortDelgro Engineering
Pte Ltd (Spark Car Care)
Pandan Branch
45 Pandan Road
Singapore 609286**

Claim Reference:
Assessment Number: RM000066
Version: COM-DGRO/2
Date Calculated: 05/06/2018 06:58

Full Report - V1
Registration: SJS4250A
Printed: 28/09/2018 16:59

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	06/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:	LKK	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	SUZUKI
Model:	Swift
Sub Model:	GL
Model Sheet Number:	R03 07
Registration:	SJS4250A
Registration Month:	August
Registration Year:	2009
VIN Number:	ZC71S434171
Manufacture Month:	August
Manufacture Year:	2008
Odometer:	Not Known
Colour:	
Engine Number:	K12B1056874
Fuel Level:	%

Model Specs

FROM VIN ...400001	1.3 LTR 67/68KW
4-SPEED AUTOMATIC	TYRES 185/60 HR 15
WHEELS 5.5J X 15 ALU	SINGAPORE VERSION
5-DOOR	PAINTING OFF VEHICLE
TWO COAT PEARL/MICA	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	25/05/2018
Pre-Accident Damage:	
Tyres Condition:	
Tyres - Tread Depth (MM):	

		Left Tyre	Right Tyre	
	Axles	Depth	Depth	
LHF	0	0.0	0.0	RHF
LHR	1	0.0	0.0	RHR
Damage Areas:				Direction of Impact:

ComfortDelgro Engineering Pte Ltd (Spark Car Care)

Claim Reference:

Full Report - V1



Assessment Number: RM000066

Registration: SJS4250A

Version: COM-DGRO/2

Printed: 28/09/2018 16:59

Date Calculated: 05/06/2018 06:58



Primary Impact
Secondary Impact

Addresses

Insured

Name : FIRDAUS BIN ASWEN

Address :

413 SAUJANA ROAD

#03-10

Post Code : 670413

Repairer

Name : COMFORTDELGRO ENGINEERING PTE LTD

Address :

45 PANDAN ROAD

Post Code : 609286

Cost Summary

Total Labour	\$615.00
Total Paint/Material	\$84.96
Excess:	TBA
Grand Total Exc GST:	\$699.96
7 % GST:	\$49.00
Grand Total Inc GST:	\$748.96

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$50.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	R + R RIGHT REAR WHEELHOUSE SHELL	3.0	15.00
NO NUMBER	R + R REAR NUMBER PLATE	2.0	10.00
OP 677	R + R RIGHT TAIL LAMP	2.0	10.00
SB11R0 ZAX	R + R NO-PLATE LAMP	2.0	10.00
OP 661	R + R REAR BUMPER	6.0	30.00
OP 621	R + R REAR BUMPER CARRIER	1.0	5.00
NO NUMBER	R + R REAR FOGLAMP	2.0	10.00
2581	REPAIR REAR BUMPER	20.0*	100.00
3482	REPAIR R/R SIDE PANEL	30.0*	150.00

LABOUR COST

Total Work Units	68.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	6.8HRS	\$340.00
Paint Labour	5.5HRS	\$275.00
Total Labour	12.3HRS	\$615.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number Description

- PAINTING OFF VEHICLE

WU Cost Price (\$)

ComfortDelgro Engineering Pte Ltd (Spark Car Care)

Claim Reference:

Assessment Number: RM000066

Version: COM-DGRO/2

Date Calculated: 05/06/2018 06:58

Full Report - V1

Registration: SJS4250A

Printed: 28/09/2018 16:59

	- TWO COAT PEARL/MICA		
2581	REAR BUMPER REPAIR PAINT PLASTIC	15.0	
3482	R/R SIDE PANEL REPAIR PAINTING <50%	11.0	
	LABOUR COST - PAINT		
	TIME(PAINT)	26.0	
	Preparation Main Work Metal	21.0	
	Preparation Comp. Work Plastic	8.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	55.0	
	Total Paintwork Labour	5.5HRS	\$275.00
	MATERIAL COST - PAINT		Cost Price
	Repair Painting		\$11.63
	Repair Painting Plastic		\$42.53
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$84.96
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$84.96

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/2015	Bet.	Price (\$)
f:		OEM Parts					\$0.00
g:		Original					\$0.00
h:		Secondhand					\$0.00
p:		Parallel					\$0.00
x:		Exchange					\$0.00

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras \$0.00

Final Calculation

Total Parts		\$0.00
Labour		
Total Panel/Mechanical	\$340.00	
Total Paintwork	\$275.00	
Total Labour		\$615.00
Total Paint/Material Costs		\$84.96
Grand Total Excludes GST		\$699.96
GST @ 7 %		\$49.00
Grand Total Includes GST		\$748.96

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	28 May 2018 11:14 Sendback Est	28 May 2018 11:18 S\$1,467.62	01 Jun 2018 16:14 Edit Adj Rpt	S\$699.96 Edit Estimates	S\$699.96 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: WONG CHYE HOE PETER , ID: S1707749Z									
Main Claimant: FIRDAUS BIN ASWEN									
Vehicle Reg. No.: SJS4250A		Date of Loss: 06/05/2018 20:00 - :59 [104 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 558162		Policy/Cover Note No.: A28626158TMP (Third Party Only) Coverage: 19/10/2017 - 18/10/2018							
Vehicle Reg. No. (Insured): SFZ4544M		Policy No. (Claimant):							
		Excess:							
Repairer: ComfortDelGro Engineering Pte Ltd (Pandan) 45 Pandan Road, 609286 Eunos - Tel: 6338 8778									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL ... [Final Rpt due 01/07/2018]									
Adj. Ass. Remarks: on WP. SJE Agree Please appoint LKK and contact Wong Chee Wei @ 6867 6919 . 9723 9882 Liability (Not clear)									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJS4250A (558162)
[SFZ4544M]
TP
FIRDAUS BIN ASWEN
May 6 2018 8:00PM
[WONG CHYE HOE PETER]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/05/18 14:53	Video - Accident From: TP - Reg. No: SJS4250A, Claimant: FIRDAUS BIN ASWEN	Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
1	28/05/18 11:18	Repairer Estimates	Load HTM	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/05/18 14:53	Accident Statement Addm. #1 From: TP - Reg. No: SJS4250A, Claimant: FIRDAUS BIN ASWEN	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/06/18 15:59	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
2	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
3	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
4	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
5	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
6	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
7	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
8	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
9	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
10	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
11	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
12	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
13	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
14	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
15	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
16	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
17	28/09/18 17:41	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/05/18 14:53	E-FILE REPORT (SJS4250A) From: TP - Reg. No: SJS4250A, Claimant: FIRDAUS BIN ASWEN	Load PDF	
2	30/05/18 15:05	EMAIL TO ARRANGE SURVEYOR PRI	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	-----------------------	----------------------	-----------------------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18010097/R1TD3E2

Date: 01/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28626158TMP

Claimant Vehicle No : SJS4250A

Insured Vehicle No : SFZ4544M

Date of Loss: 06/05/2018

Nature of Claim: TP

Claim No: 558162

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS4250A

Make & Model: SUZUKI SWIFT, 1.2 XG (A)

Engine No: K12B1056874

Reg. Date: 15/08/2009 (Man. Year: 2008)

Chassis No: ZC71S434171

Colour: Red

Odometer: 31416 km

Engine Capacity: 1242 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Kumho 5 mm

Rear Left Side: Kumho 5 mm

Front Right Side: Kumho 5 mm

Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	564.06	0.00	564.06	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	903.56	699.96	203.60	22.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,467.62	699.96	767.66	52.31
+ GST 7.00/7.00% (S\$)	102.73	49.00	53.73	52.30
Nett Amount (S\$)	1,570.35	748.96	821.39	52.31

INSPECTION

Date of Assignment: 01/06/2018 Present Location:

ComfortDelGro Engineering Pte Ltd (Pandan)

Date Inspected: 05/06/2018 Inspected At:

ComfortDelGro Engineering Pte Ltd (Pandan)
45 Pandan Road
Singapore 609286

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Oct 2018)
Parts:	144	SUZUKI SWIFT 1.2 XG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS4250A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*L/R BUMPER BRACKET	Not Necessary	25.00 F	*- F
2	1	NA	*R/R BUMPER BRACKET	Not Necessary	25.00 F	*- F
3	1	NA	*R/R SIDE PANEL	Repair	123.00 F	*- F
4	1	NA	*REAR BUMPER	Repair	350.00 F	*- F
5	1	NA	*REAR BUMPER MNTG KIT	Not Necessary	30.00 F	*- F
6	1	NA	*SUNDRY PARTS	Not Necessary	11.06 F	*- F
Total Parts (S\$)					564.06	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	275.00	275.00
2	Total Paint Materials	New	98.56	84.96
3	Total Panel/Mechanical Labour	New	530.00	340.00
Gross Labour Cost (S\$)			903.56	699.96

Report was unsubmitted during this print-out.

< END OF ESTIMATES >