

## CITY CAB PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHA 8152S

MAKE :

MODEL : HYUNDAI i40

DATE 4/6/2018 11:25

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Door (RH) <i>X rep-2</i>			\$ 1,351.10
	Front Door (RH) <i>— dent</i>			\$ 1,403.05
	Rocker Panel Outer Garnish (RH) <i>X rep-2</i>			\$ 483.60
	Rear Wheel Hup-Cap (RH) <i>— dent</i>			\$ 150.70
	<i>Per Bumper X repair</i>			
	<i>Per RH Fender X repair</i>			
	<b>SUB TOTAL</b>			<b>\$ 3,388.45</b>
	<b>LESS 20%</b>			<b>\$ 677.69</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 2,710.76</b>
	Rear Bumper Rubber Mat <i>X "</i>			\$ 50.00 <b>Nett</b>
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>— "</i>			\$ 80.00 <b>Nett</b>
	Front Door Coloured Comfort Logo (RH) <i>— "</i>			\$ 75.00 <b>Nett</b>
				<b>\$ 205.00</b>
	<b>Labour Charge</b>			
	Panel Beating-Repair Rear Fender			\$ <del>560.00</del> <i>400</i>
	Spray Painting Charge-Door x2, Fender/Bumper			\$ <del>1,250.00</del> <i>1000</i>
	Wiring Charge			\$ <del>50.00</del> <i>X "</i>
	Tuff Kote			\$ <del>50.00</del> <i>20</i>
	Remove/Refix Reverse Sensor			\$ <del>120.00</del> <i>X "</i>
	Transfer of Door		\$ 120.00	\$ <del>240.00</del> <i>50</i>
	Rear Wheel Alignment			\$ <del>120.00</del> <i>X "</i>
	<b>TOTAL LABOUR</b>			<b>\$ 2,390.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 5,305.76</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Our Job Ref No 305169011  
Date : 11/06/18

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK

Fax :

Attn : Mr KALVIN ANG

Vehicle Reg No. SHA8152S CCPL

02.06.18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG --- SJS79E
2. The finalized amount shall be:
  - (a) Spare Parts after List discount
  - (b) Labour Charges
  - Total for Part-By-Part Repair Cost**
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
**Final Lumpsum Repair cost** \$ 2300.00

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : KALVIN ANG

Date : 13/6/18

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: