

Surveyor: KSC DOI: 5/6/18 Date / Time: 5/6/18
Registered in Merimen: 5/6/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SLE 32645 Claim No. : _____
Name of Insured : Blue Star Limousine Management. Policy No. : 0999994960 *fx*
Insured Tel No. : _____ HP: _____ Make / Model : _____
Excess Sec II :SS D.O.A: 3/6/2018 Place of Accident : Jin Tun Kong.
Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : _____ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Driver Tel No. : _____ (V/L: YES / NO) Insured Liability : % Final ? Yes / No



INSRS: _____
WSP: Copy Auto.
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
	LOD	<input type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

SLE 3980P. X; SLE 32645. X
13/6 OI.M. Cont out first letter.
12/6/18 - Rec'd email from TP: P's withdraw the claim as OI will do private settlement.
14/6/18 - Email to Satika: To close file & submit up.

RECEIVED 18 JUN 2018

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____
Repair Cost: \$S (_____ days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email Call

Final Liability: % (Agreed / Assessed) BOLA S/N No. : _____ If NO or B 28, Ass. Lin. : _____
Repair Cost: \$S
Loss of Rental (LOR): \$S (_____ days)
Loss of Use (LOU): \$S (\$ x days)
Loss of Income (LOI): \$S (\$ x days)
LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
GIA/LTA Search \$S
Medical: \$S
Disbursement: \$S (e.g. Tow/ Independent)
Legal Cost \$S

1) Claim status: Normal/Reject/Private Settle UP
2) Report Format: TP TP withdraw
3) Survey fee: \$250-00

Total: \$S **Global Sum \$S:** _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$S Name 1: _____
Payee 2: (Strike if N.A.) \$S Name 2: _____
Payee 3: (Strike if N.A.) \$S Name 3: _____

COPY SENT 8/6/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18010155/Kpa3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 05-06-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLE 3264S	Veh. Inspected	SLR 3980P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	03/06/2018	Inspection Date	05/06/2018
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201806-000069(00)

AIG ASIA PACIFIC INSURANCE PTE. LTD
NO. 78
SHENTON WAY
SINGAPORE 079120
Attention: Seow Chi Hou Nelson
Contact : 97231349

Fax No. : 68357416

Date : 05/06/2018
Vehicle No. : SLR3980P
Make/Model : HYUNDAI ELANTRA AD 1.6 GLS AT
Mileage (km) : 0
Chassis No. : KMHD841CMJU527392
Accident Date : 03/06/2018 00:00:00
Claim No. : SLE3264S
Reference : SLR3980P
Policy No. : 5094004364

*Not Notified
L1 Prop & ?
Resurvey After Paint 3 days*

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Front bonnet	1.0	1,740.70	<i>R₁</i> 1,740.70 ✓
2	Front bumper	1.0	474.40	474.40 ?
3	Front grille assy	1.0	460.20	460.20 ?
	List Total :			2,675.30
	20% Discount S\$			535.06
				<u>2,140.24</u>
SPECIAL NET :				
1	Front number plate	1.0	20.00	<i>R₁</i> 20.00 } ✓
2	Front number plate garish	1.0	25.00	25.00 }
	SPECIAL NET Total S\$:			<u>45.00</u>
LABOUR :				
	- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	350.00	350.00 <i>2500</i>
	- Spray painting on affected & replace parts	1.0	600.00	600.00 <i>4000</i>
				<u>950.00</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

E. & O.E. Signature:	Total S\$:	3,135.24
Date:	GST 7% S\$:	219.47
	Amount Due S\$:	<u><u>3,354.71</u></u>

MA
for CITY AUTO PTE LTD

- Pre repair inspection request - SLR3980P VS SLE3264S (OI) DOA: 03/06/2018

From: Chan, Yoke Shi
To: ASSIGNMENTS@LKKAUTO.COM, adm-a@lkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Bajji, Chri, Lea-Ying, Abu Kassim, Noor Mariasa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Supramaniam, Darshana, Mithoosingh, Aashweenjeetkaur, A
Sent: Tuesday, 5 June 2018 10:39:25 AM
Attachments: GIA report.pdf

Hi,

Please refer to the enclosed request from **City Auto Pte Ltd.**

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-0)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel: +6 03 2719 6000 | Ext: 1012102

yokeshi.chan@aig.com | www.aig.com

05062018 @ 1:27pm
Vronica veh in
Kameth.

From: City Auto [mailto:cityauto@singnet.com.sg]
Sent: Tuesday, June 05, 2018 10:27 AM
To: AIG SGP, Claims-Survey
Subject: Arrange survey of SLR3980P D.O.A: 03/06/2018

Dear Arrangement survey dept,

Kindly arrange LKK AUTO CONSULTANTS PTE LTD survey on following vehicle:

TP Survey.

Your vehicle : SLE3264S

Our vehicle : SLR3980P

D.O.A : 03/06/2018

LOCATION : BLK 160, Sing Ming Drive, Sin Ming Auto City #05-01 Singapore 575722

Thank you.

Best Regards,

*Vronica Law
City Auto Pte Ltd
Blk 8 Sin Ming Industrial Estate,
#01-60 62 Sin Ming Road,
Singapore 575643
Tel : 6453 1235
Fax : 6453 7944*

IMPORTANT NOTICE:
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

View Received Message

This mail is associated with :

***SLR3980P (0156374100SG)**
[SLE32645]
TP
SEOW CHI HOU NELSON
Jun 3 2018 12:00AM
[BLUE STAR LIMOUSINE MANAGEMENT]
City Auto Pte Ltd (Sin Ming)

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward
-------	-----------	----------------	---------------	----------------	---------

From: AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 06/06/2018 13:04 PM.
To: LKK_HQ
Subject: No OI GIA Report

Hi

Pls be advice that no OI GIA report received
Pls find OI details below for your further actions

OI name : BLUE STAR LIMOUSINE MANAGEMENT

Address :
12
Little Road
#05-01
Lian Cheong Industrial Building
Singapore 536986

Thank you.

Regards,
Aashween,

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG18010155/Kpa3

13th Jun 2018

BLUE STAR LIMOUSINE MANAGEMENT

12 Little Road
#05-01 Lian Cheong Industrial Building
Singapore 536986

Dear Sirs,

**ACCIDENT INVOLVING SLE 3264S AND SLR 3980P ON 03/06/2018 ALONG/
AT JALAN TUA KONG**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Hsiao Tong
Claims
Tel : 6742 3197
Fax: 6741 4108
Email : chewht@lkkauto.com

c.c. *Claims Manager
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

Mei Kwan (LKKAuto)

From: City Auto <cityauto@singnet.com.sg>
Sent: Tuesday, 12 June, 2018 3:30 PM
To: Mei Kwan (LKKAuto)
Cc: Bevan Lim (LKK Auto); Joy Irene (LKKAuto); Admin A; Hsiao Tong (LKKAuto); Asher Sng (LKKAuto)
Subject: RE: Liability of SLR3980P Your ref: SLE3264S Our ref: SLR3980P D.O.A: 03/06/2018 *** LKK REF: CC4/AIG18010155/Kpa3

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Mei Kwan,

As spoken, please withdraw this claim since our client will make private settle with your insured.

Thank you.

Best Regards,

Tronica Law
City Auto Pte Ltd
Blk 8 Sin Ming Industrial Estate,
#01-60/62 Sin Ming Road,
Singapore 575643
Tel : 6453 1235
Fax : 6453 7944

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Thursday, 7 June, 2018 5:23 PM
To: City Auto
Cc: Bevan Lim (LKK Auto); Joy Irene (LKKAuto); Admin A; Hsiao Tong (LKKAuto); Asher Sng (LKKAuto)
Subject: RE: Liability of SLR3980P Your ref: SLE3264S Our ref: SLR3980P D.O.A: 03/06/2018 *** LKK REF: CC4/AIG18010155/Kpa3

Dear Sir / Madam,

We refer to the above matter.

Please be informed that OI has yet to report the accident.

Please provide us evidence i.e. video and scene photo.

Please note that for liability, claim negotiation and settlement, please contact Hsiao Tong at 6742 3197.

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 14 June 2018 8:23 AM
To: Syed-Yusoff, Saliha
Cc: Admin A
Subject: Your ref: 0156374100SG *Our Ref: CC4/AIG18010155/Kpa3 [ACCIDENT INVOLVING SLE 3264S(OI) & SLR 3980P(TP) ON 03/06/2018]
Attachments: EMAIL FROM TP WKSP DD 120618.pdf

Your ref: **0156374100SG**
Our Ref: CC4/AIG18010155/Kpa3

Dear Sir/Madam,

ACCIDENT INVOLVING SLE 3264S(OI) & SLR 3980P(TP) ON 03/06/2018

We refer to the above matter.

We have received survey assignment from AIG on 05 June 2018 and conducted survey on the same day.

On 12 June 2018, we were informed by third party repairer that their client withdraw third party claim as insured will private settle the matter with them(see attached).

In view of this, we will proceed to close file and submit report to you good office.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Jun 2018 Edit Reg		05 Jun 2018 00:00 Edit Adj Rpt	S\$1,650.00 Edit Estimates	S\$1,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	BLUE STAR LIMOUSINE MANAGEMENT, Co. Reg. No.: -								
Main Claimant:	SEOW CHI HOU NELSON, ID: S7919182E								
Vehicle Reg. No.:	SLR3980P	Date of Loss:	03/06/2018 00:00 - :59 [9 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0156374100SG	Policy/Cover Note No.:	0999994960						
Vehicle Reg. No. (Insured):	SLE3264S	Policy No. (Claimant):	5094004364						
		Excess:							
Repairer:	City Auto Pte Ltd (Sin Ming) (HQ) Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est, 575643 Sin Ming - Tel: 64531235								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 14/06/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (06/06/2018): No OI GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR3980P (0156374100SG)
[SLE3264S]
TP
SEOW CHI HOU NELSON
Jun 3 2018 12:00AM
[BLUE STAR LIMOUSINE MANAGEMENT]
City Auto Pte Ltd (Sin Ming)

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser ▼
Photos/Images					3 per page ▼ <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/06/18 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
2	14/06/18 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
3	14/06/18 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
4	14/06/18 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
5	14/06/18 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
6	14/06/18 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
7	14/06/18 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
8	14/06/18 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
9	14/06/18 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
10	14/06/18 08:17	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
11	14/06/18 08:17	General View		Load JPG	<input checked="" type="checkbox"/>
12	14/06/18 08:17	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
Documentation					1 per page ▼ <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/06/18 14:46	ACKNOWLEDGEMENT EMAIL TO AIG DD 05.06.2018		Load PDF	
2	05/06/18 14:46	EMAIL FROM AIG DD 05.06.2018		Load PDF	
3	05/06/18 14:46	TP GIA REPORT		Load PDF	
4	12/06/18 13:31	TP ESTIMATE - MARKED		Load PDF	
5	13/06/18 10:37	Ltr to Insured -non reporting		Load PDF	
6	13/06/18 13:28	EMAIL ROM WKSP DD 12.06.2018		Load PDF	
7	14/06/18 08:24	Email to Saliha dd 14061		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18010155/KPA3Q2

Date: 19/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994960
Claimant Vehicle No : SLR3980P	Insured Vehicle No :	SLE3264S
Date of Loss: 03/06/2018	Nature of Claim:	TP
		Claim No: 0156374100SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR3980P	Engine No:	G4FGHU687100
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMJU527392
Reg. Date:	15/08/2017 (Man. Year: 2017)	Odometer:	21868 km
Colour:	Metallic Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,185.24	1,437.56	747.68	34.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	650.00	300.00	31.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,135.24	2,087.56	1,047.68	33.42
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	3,135.24	1,650.00	1,485.24	47.37
+ GST 7.00/7.00% (S\$)	219.47	115.50	103.97	47.37
Nett Amount (S\$)	3,354.71	1,765.50	1,589.21	47.37
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	05/06/2018	
Date Inspected:	06/06/2018	Inspected At:
		City Auto Pte Ltd (Sin Ming) (HQ)
		Block 8 Sin Ming Road #01-58/60/62 Sin
		Ming Est
		Singapore 575643
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BONNET	Bent	1,740.70 FL	*1,740.70 FL	
2	1		*FRONT BUMPER	*Check	474.40 FL	*- FL	
3	1		*FRONT GRILLE ASSY	*Check	460.20 FL	*- FL	
4	1		*FRONT NUMBER PLATE	Bent	20.00 FS	*20.00 FS	
5	1		*FRONT NUMBER PLATE GARNISH	Bent	25.00 FS	*25.00 FS	
					Sub Total (\$\$)	2,720.30	1,785.70
					- List Item Discount on L Items 20.00/20.00% (\$\$)	535.06	348.14
					Total Parts (\$\$)	2,185.24	1,437.56

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS	New	350.00	250.00
2	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	600.00	400.00
Gross Labour Cost (\$\$)			<u>950.00</u>	<u>650.00</u>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >