15/5/2010

INS. CASE OWNER: | CC 3/AIG1801 0175, K1pbb | LKK: IDAC:

ASSIGNMENT

Surveyor: Kalvin | DOI: 4/6/18 | Date / Time : 4/6/18

Registered in Merimen: 5/6/18

Pre-assign / CCU / FTE

Insured Vehicle No. : SLZ733P		Claim No. :	
Name of Insured :		Policy No. :	
Insured Tel No. :	HP:	Make / Model :	
Excess Sec II :S$	D.O.A : 3/6/18	Place of Accident :	
Is driver the owner? (YES / NO)	Nature of Accident :		

If **NO**, Driver Name / Age :

Driver Tel No. : (V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % **Final ? Yes / No**

SHC2783A → ______ → ______ → ______

INSRS:
WSP: NGE
Tel :
Liability : NJ.
RMKS:

INSRS:
WSP:
Tel :
Liability :
RMKS:

INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	
	SHC2783A – NS | IMC170047281 | K5qberout. 4/6/18

STAGE	**DATE / PIC**
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	

Documentation Check List:	**Handler**	**Typist**
Notification ltr (if non-pickup)	☐	☐
After call ltr to OI:	☐	☐
Authorisation To Act:	☐	☐
Release Voucher:	☐	☐
Final Repair Bill:	☐	☐
Car Rental Invoice:	☐	☐
Towing Invoice	☐	☐
LTA / GIA :	☐	☐
Medical Bill:	☐	☐
PIR:	☐	☐
Mandate/Reject Instruction:	☐	☐
LOD	☐	☐
Payment Breakdown Form:		☐
Post-Repair Photos:	☐	☐
Others:	☐	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S$ (days) Reduction: %		Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with	Email ☐ Call ☐
Final Liability:	% (Agreed / Assessed) BOLA S/N No. :		If NO or B 28, Ass. Lia :
Repair Cost:	S$		
Loss of Rental (LOR):	S$ (days)		
Loss of Use (LOU):	S$ (S x days)		
Loss of Income (LOI):	S$ (S x days)		
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐ **[Tick only one]**		
GIA/LTA Search	S$		
Medical:	S$		1) Claim status: Normal/Reject/Private Settle
Disbursement:	S$	(e.g. Tow/ Independent)	2) Report Format:
Legal Cost	S$		3) Survey fee:
Total:	**S$**	**Global Sum S$:**	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	S$	Name 1:	
Payee 2: (Strike if N.A.)	S$	Name 2:	
Payee 3: (Strike if N.A.)	S$	Name 3:	

(08/11/13)

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP INS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC 2783A Yr Regn: 6 Jly, 213

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes Benz E220 c.c 2143

Colour White A/C: Insured / Std / NI / NA

Sp.Reading 80694 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2120022A797674

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD Rim or _____

Tyre Size; F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Westlake.

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	3/6/18	D.O.I.	4/6/18

Survey held at CDGE (Loyang)

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	AZG 4/6

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Prell. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

☐ : Weekend ($ _____)

Report Format : _____

Lump Sum / I.B.I: ($ _____)

Survey Fee:	
Transportation:	
___S + RS___SI	
Photos	
Others	
TOTAL	

COMFORTDELGRO ENGINEERING
member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755
Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
6 Defu Avenue 1 Singapore 539537

Date/Time: 04.06.2018 09:52 Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: JC NO 305168942

OMER
IS COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

OUNT CARD NO.

AIG

REGN NO.: SHC2783A	MILEAGE
MAKE: MERCEDES BENZ	FUEL E.....1/2.....F
MODEL E220CDI(E5)	DATE/TIME IN 03.06.2018 09:20
YR OF MANU. 06.06.2013	TARGET DATE
CHASSIS CODE WDD2120022A757674	COMPLETION DATE/TIME:

JOB DESCRIPTION

ccident Date: 03.06.2018
ATURE: 3P 03.06.2018

/NO LABOR CODE DESCRIPTION

CKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ledgement Slip

No.: SHC2783A LKE

f Service Advisor

Signature/Date

eturned to Service Reception upon collection

Exit Pass

Vehicle No.: SHC2783A

Name of Service Advisor

Date

To be kept by Security Guard