

13/5/2018

INS. CASE OWNER:

CC

4, Asm 180

10/80, K 0034

LKK:

IDAC:

49123

Surveyor:

Kenneth

DOI:

ASSIGNMENT

Date / Time:

4/6/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLV157

Name of Insured:

KAREN DEANNE WONG

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A: 2/6/18

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

TAN MW HER

Driver Tel No.:

93673312

(VA: YES / NO)

Claim No.:

58m00jok

Policy No.:

1. Wsh.

Make / Model:

Loti Paym

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Vinc motor



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

12/6  
ALWSLV 2518C - X; SLV 25157 - X  
\* O/S policy & CI attached.

27-06-18 @ 10:00 CAMEL DID NOT RESPOND.

27-06-18 @ 10:30 DID RETURN CALL. COMPENSATION ACCORDING TO POLICY ENCLOSED TP, INFROM TP CLAIM ATTEND TO SERVE AND ADVISE ABOUT NED ISSUE.  
SMITH WSP LIABILITY CLAIM.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

Email 57.18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

2/6

Sent By:

ALW

FINALIZATION

Date/Time: 05.03.19

Confirm with: RAYMOND

Confirm by: RAYMOND

Repair Cost:

\$5,750.00

( 10 days) Reduction:

40 %

Email

Call

FINAL SETTLEMENT

Date/Time: 12.3.19

Confirm with: RAYMOND

Email

Call

Final Liability:

100

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

0/67:

\$5,292.50

DID REPAIR ENCLOSED TP

Loss of Rental (LOR):

\$5,200.00

( 10 days) x

100

Loss of Use (LOU):

\$5

(\$

x days)

Loss of Income (LOI):

\$5

(\$

x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$52.00

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

Total:

\$5,444.50

Global Sum \$5,444.50

FINAL PAYMENT

Date/Time: 12.3.19

Confirm with: RAYMOND

Email

Call

Payee 1:

\$5,444.50

Name 1:

YWS MOTOR PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+350





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18010180/Kea3

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 05-06-2018



Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 515Z	Veh. Inspected	SLV 2518C
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00JDK	Excess (\$)	0.00
Assign From		Assign Date	05/06/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	02/06/2018	Inspection Date	05/06/2018
Survey held at	VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

He

160 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722. Tel: 6453 2121 (4 Lines) Fax: 6459 9795

Date : 4/6/2018

Not Authored  
Revised by B & P  
6/1/94 @ 7:50p 10 days

QTY	DESCRIPTION	UNIT PRICE	TOTAL PRICE
1	pc Rear windscreen moulding	Rear S 120.10	✓
1	pc Rear boot cover	Rear S 1,193.00	✓
2	pcs Rear boot cover hinge @ \$40.80/pc	Rear S 81.60	X
2	pcs Rear boot cover shocker bracket @ \$165/pc	Rear S 330.00	X
1	pc Rear boot cover lock	SH 157.10	✓
1	pc Rear boot cover lock motor	SH 490.00	✓
2	pcs Rear boot cover reflector @ \$395/pc	mgcmm S 790.00	✓
2	pcs Rear boot cover number plate lamp @ \$38.50/pc	sim 77.00	X
1	pc Rear boot cover moulding	SH 383.40	X
1	pc Rear boot cover "Shuttle" name plate	Rear S 55.00	✓
1	pc Rear boot cover emblem	Rear S 38.00	✓
1	pc Rear boot cover inner trim	mgcmm S 320.90	✓
1	pc Rear boot cover rubber	Dis Prod S 168.50	✓
2	pc Rear lamp @ \$520.60/pc	olism S 1,041.20	✓
1	pc Rear end panel	Rear S 560.80	✓
1	pc Rear end panel inner trim	Rear S 251.40	✓
1	pc Rear tool box	Rear S 587.30	✓
1	pc Rear spare tyre panel P 956.00	Prithu S 1,980.00	✓
1	pc Rear spare tyre panel top cover	nd S 585.50	✓
1	pc Rear bumper	Rear S 1,150.60	✓
1	pc Rear bumper sponge	nd S 170.60	X
2	pcs Rear bumper side retainer @ \$26.50/pc	SH 53.00	X
2	pcs Rear bumper reflector @ \$45.20/pc	nd S 90.40	✓
2	pcs Rear fender inner trim @ \$489.60/pc	mgcmm S 979.20	✓
1	pc Rear exhaust silence	SR 745.70	X
		S 12,400.30	
		S (2,480.06)	
		S 9,920.24	

**VIN'S MOTOR PTE LTD**

160 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722 Tel: 6453 2121 (4 Lines) Fax: 6459 9795

Our Ref : TP/062018/3594

Page 2

Balance b/d

\$ 9,920.24

1 pc Rear windscreen gum

rec \$ 60.00 N

1 set Rear bumper sensor

rec \$ 280.00 N

To remove and refix rear glass

\$ 150.00

To repair rear damage

\$ 1,400.00

To spray painting

\$ 1,200.00

\$ 13,010.24

VIN'S MOTOR PTE LTD

*Amber***LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**VIN'S MOTOR PTE LTD**

180 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722 Tel: 6453 2121 (4 Lines) Fax: 6459 9795

Our Ref : TP/062018/3594

Tax Invoice :

Accident date: 2/6/2018

Your Ref : SLV515Z

Date : 4/6/2018

MOTOR CLAIM DEPARTMENT  
AXA INSURANCE (S) PTE LTD  
8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811

*Not Authorized*  
*1 B.1*  
*Phony B & pain*  
*10 days*

ESTIMATE COST OF REPAIRS TO HONDA SHUTTLE SLV2518C

1 pc	Rear windscreen moulding	<i>Per</i> \$	120.10	✓
1 pc	Rear boot cover	<i>Per</i> \$	1,193.00	✓
2 pcs	Rear boot cover hinge @ \$40.80/pc	<i>R</i> \$	81.60	X
2 pcs	Rear boot cover shocker bracket @ \$165/pc	<i>R</i> \$	330.00	X
1 pc	Rear boot cover lock	<i>\$Per</i>	157.10	✓
1 pc	Rear boot cover lock motor	\$	490.00	?
2 pcs	Rear boot cover reflector @ \$395/pc	\$	790.00	?
2 pcs	Rear boot cover number plate lamp @ \$38.50/pc	<i>\$Per</i>	77.00	X
1 pc	Rear boot cover moulding	\$	383.40	?
1 pc	Rear boot cover "Shuttle" name plate	<i>Per</i> \$	55.00	✓
1 pc	Rear boot cover emblem	<i>Per</i> \$	38.00	✓
1 pc	Rear boot cover inner trim	\$	320.90	?
1 pc	Rear boot cover rubber	<i>Dis Per</i> \$	168.50	✓
1 pc	Rear lamp @ \$520.60/pc	<i>ol/1st</i> \$	1,041.20	✓
1 pc	Rear end panel	<i>Per</i> \$	560.80	✓
1 pc	Rear end panel inner trim	<i>Per</i> \$	251.40	✓
1 pc	Rear tool box	<i>Per</i> \$	587.30	✓
1 pc	Rear spare tyre panel	<i>Per/Per</i> \$	1,980.00	✓
1 pc	Rear spare tyre panel top cover	\$	585.50	?
1 pc	Rear bumper	<i>Per</i> \$	1,150.60	✓
1 pc	Rear bumper sponge	<i>MS?</i> \$	170.60	X?
2 pcs	Rear bumper side retainer @ \$26.50/pc	<i>Per</i> \$	53.00	X
2 pcs	Rear bumper reflector @ \$45.20/pc	<i>MS?</i> <i>ol/1st</i> \$	90.40	
2 pcs	Rear fender inner trim @ \$489.60/pc	<i>MS?</i> <i>ol/1st</i> \$	979.20	✓
1 pc	Rear exhaust silence	<i>\$Per</i>	745.70	X
		\$	12,400.30	
Less: 20%		\$	(2,480.06)	
		\$	9,920.24	

**VIN'S MOTOR PTE LTD**

160 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722 Tel: 6453 2121 (4 Lines) Fax: 6459 9795

Our Ref : TP/062018/3594

Page 2

Balance b/d	\$ 9,920.24	
1 pc Rear windscreen gum	<i>Rec</i> \$ 60.00 N	<i>4000</i>
1 set Rear bumper sensor	<i>Ref</i> \$ 280.00 N	<i>2000</i>
To remove and refix rear glass	\$ 150.00	<i>1200</i>
To repair rear damage	\$ 1,400.00	<i>1200</i>
To spray painting	\$ 1,200.00	<i>1000</i>
	<u>\$ 13,010.24</u>	

VIN'S MOTOR PTE LTD



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



AUTOMOTIVE GROUP

Our Ref : TP/062018/3594

Your Ref : SLV515Z

7-Mar-2019

**MOTOR CLAIM DEPARTMENT**

AXA INSURANCE (S) PTE LTD

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Dear Sir, Mdm,

Accident Involving Vehicles : SLV2518C & SLV515Z

Along : TOA PAYOH LORONG 6 (SLIP RD TO PIE)

DOA : 02/06/2018

We are the authorized repair workshop for the owner of motor vehicle no: SLV2518C, which was involved in the captioned accident with your insured vehicle: SLV515Z. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01)	Cost of Repair (inclusive of GST)	\$	8,292.50
02)	GIA Search fees	\$	2.00
06)	Loss of Rental_12 days x \$110/-	\$	1,320.00
		<u>\$</u>	<u>9,614.50</u>

We enclosed herewith the following documents to support the claims:-

- a) Letter of Authorisation / GIA report(s) / Insurance Certificate, etc...
- b) Final Repair Bill
- c) GIA search/ Car Rental Bill & Invoice

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

**Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.**

Thank you

Yours faithfully

VIN'S MOTOR PTE LTD

Vincent Khong

Sin Ming Autocity,  
160 Sin Ming Drive #03-03  
Singapore 575722  
6453 2121 (4 lines) / 6458 1111 (24 hrs)  
6459 9795 / 6459 0433  
admin@vinsautogroup.com.sg  
www.vinsautogroup.com.sg



**Asher Sng (LKKAUTO)**

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Thursday, 5 July 2018 2:59 PM  
**To:** 'GETJOHNTAN@GMAIL.COM'  
**Subject:** ACCIDENT INVOLVING SLV 515Z AND SLV 2518C ALONG TOA PAYOH ON 02/06/2018

05 JULY 2018

**KAREN DEANNE WAN ZI QI / TAN MIN HER**

Dear Sir/ Mdm

**OUR REF : CC4/ASM18010180/Kea3**  
**YOUR REF : SLV 515Z**  
**ACCIDENT INVOLVING SLV 515Z AND SLV 2518C ALONG TOA PAYOH ON 02/06/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s VIN'S MOTOR PTE LTD acting on behalf of the owner of SLV 2518C against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had rear-ended the Third Party vehicle SLV 2518C. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Asher  
Case Handler  
DID: 6841 6051  
FAX: 6741 4108  
Email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com)

c.c. AXA Insurance Pte Ltd (AXA)  
(Motor Claims Dept)


## AUTHORISATION TO ACT


I/We, Low Yong Yee, Eugene (the Third party claimant") of Blk 258  
Kim Keat Ave #09-34 <sup>S310258</sup> (address), owner of SLV2518C (vehicle no.) hereby  
authorize **VIN'S MOTOR PTE LTD** ("the workshop") to act for me with respect  
to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no.  
SLV2518C that was damaged pursuant to the accident which occurred on 02/06/18 (date)  
along Toa Payoh Loring 6 Slip Rd To PIE (location) involving  
vehicle no/s SLV5153 ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that  
they deem fit and the workshop is further authorized to receive payment further to  
settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a  
Without prejudice and without admission of liability basis insofar as the driver /owner/  
insurers of the other vehicle/s is concerned.

Dated this 2nd (day) of June (month) 20 18 (year)

  
Signed by "the third party claimant"  
(with company stamp if applicable)

  
Signed by "the workshop"  
(with company stamp)





redefining / insurance

CLAIM REF : S8M00JDK  
INSURED : KAREN DEANNE WAN ZI QI

DISCHARGE VOUCHER

We/I [LOW YONG YEE, EUGENE, NRIC NO. S8848803B] hereby agree to accept the sum of [NINE THOUSAND FOUR HUNDRED NINETY ONLY.] [S\$9,490.00] to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property and all costs and expenses that we/I have or may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. [SLV 5152] as a result of an accident at [TOA PAYOH LORONG 6 SLIP ROAD TO PIE] on [02/06/2018] of which we/I were/was the hirer/owner/driver/pillion/Passenger/ insurer of motor vehicle [SLV 2518C].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for all claim(s) whatsoever and whosoever present or future that we/I have or may have against the said Insurer, owner and/or driver of vehicle no. [SLV 5152] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [SLV 5152]

Dated this 14<sup>th</sup> day of March 2019

Claimant's Signature

: [Signature]

NRIC no./ Company Stamp

: S8848803B

Occupation/ Business

: Indoor

Address

: Blk 258 Kim Keat Ave #09-34 S310258

Telephone No.

: 9732 9772

Witness's Name

: Teo Yun Loong

Witness's Signature

: [Signature]

Witness's NRIC No.

: G8550750N



AUTOMOTIVE GROUP

Sin Ming Autocity,  
160 Sin Ming Drive #03-03  
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)

6459 9795 / 6459 0433

admin@vinsautogroup.com.sg

www.vinsautogroup.com.sg

Our Ref : TP/062018/3594

Accident date: 02/06/2018

Your Ref : SLV515Z

Tax Invoice : VM20193945

Date : 07/03/2019

MOTOR CLAIM DEPARTMENT  
AXA INSURANCE (S) PTE LTD  
8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811

FINAL REPAIR BILL TO

Vehicle No. : SLV2518C

Model : HONDA SHUTTLE 1.5G

To supply spare parts

To remove and refix rear glass

To repair rear damage

To spray painting

Total amount agreed as at Lum Sump repair


Add : 7% GST

\$ 7,750.00

\$ 542.50

\$ 8,292.50

VIN'S MOTOR PTE LTD



**Vin's**

**CAR RENTAL PTE LTD**

OFFICIAL RECEIPT

No: 11062

160 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722.  
TEL: 6453 2121 (4 LINES) FAX: 6459 9795  
Co. Reg. No.: 201533370W

Received from Low Yong Yee, Eugene

the sum of Dollars One thousand three hundred

twenty dollars only

being payment of rental SGV688S (02/06 - 14/06)

Date: 14/06/18

\$ 1320-00

Cash/Cheque No.



VIN'S CAR RENTAL PTE LTD

# Vin's

## CAR RENTAL PTE LTD

Sin Ming AutoCity, 160 Sin Ming Drive #03-03, Singapore 575722  
 Tel: 6453 2121 (4 Lines) Fax: 6459 9795  
 Co. Reg. No.: 201533370W

### RENTAL AGREEMENT

No: 12149

Date: 02.06.2018

Vehicle No.	Make/Model	Usage
SGV6885	HONDA SHUTTLE	<input checked="" type="checkbox"/> Self Drive <input type="checkbox"/> Private-Hire

#### HIRER'S PARTICULARS

Name : LOW YONG YEE, EUGENE  
 Address : BLK 258 KIM KEAT AVENUE  
 #09-34  
 151310258  
 Email :  
 Telephone (Home) :  
 (Office) :  
 (H/P) : 9732 9712  
 NRIC or Passport No. : 58848803B  
 Nationality : Singaporean  
 Date of Birth : 06.12.1988 Age :  
 Driving Licence No. : 58848803B Expires :  
 Type 3 : Local/Int'l Issued by : TP  
 Driving Experience : SINCE 02 May 2009  
 PDVL No. :

#### DRIVER'S PARTICULARS (if different from Hirer)

Name :  
 Address :  
 Email :  
 Telephone (Home) :  
 (Office) :  
 (H/P) :  
 NRIC or Passport No. :  
 Nationality :  
 Date of Birth : Age :  
 Driving Licence No. : Expires :  
 Type : Local/Int'l Issued by :  
 Driving Experience :  
 PDVL No. :

#### CHARGES


	\$	cts
12 Day(s) @ \$ 110 / day	1320	00
Week(s) @ \$ / week		
Month(s) @ \$ / month		
Collision Damage Waiver (CDW)		
Malaysia Entry Charges		
Others:		
Total:		
Security Deposit (Cash/Cheque: )		
Grand Total	1320	00

Recipient's Signature:  
 Date:

#### SECURITY DEPOSIT REFUND

Security Deposit Refund  
 Recipient's Signature:  
 Date:

#### VEHICLE CONDITION CHECK



I/We declare that the above particulars are true and correct in every respect, and have checked the vehicle and affirm that there are no other defects (if any) besides those listed in the diagram above. I/We have read and understood the terms and conditions of the hire agreement printed overleaf.

\*   
 Stamp & Signature of Hirer

Signature of Driver  
(if different from Hirer)

Date

Date

Date Out	02.06.2018	Date In	14.06.18
Time Out	10.45 AM / PM	Time In	4.40 AM / PM
Mileage at delivery / pick up		Mileage on returning	
Fuel level at delivery / pick up		Fuel level on returning	
Hire period expires on _____ at _____. If unstated, rental period will be calculated based on a 24 hr timeframe from the time of collection of vehicle.			
Surcharge of fuel will be at \$S\$ per 1/4 tank. There will be no refund for excess fuel upon return of the vehicle.			

Remarks: SLV2518C



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-083979  
Date of Request: 02/06/2018

Your Ref No: Online Purchase

Vin's Motor Pte Ltd  
160 Sin Ming Drive, #03-03  
Sin Ming AutoCity  
Singapore 575722

Dear Sir/Madam,

Enquiry Date 02/06/2018  
Enquiry By Yap Jin Hui  
TP Vehicle No. SLV515Z  
Accident Date 02/06/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLV515Z	AXA Insurance Pte Ltd	11/12/2017-10/12/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



6/2/2018

Invoice



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-083979  
Date of Request: 02/06/2018

Your Ref No: Online Purchase

Vin's Motor Pte Ltd  
160 Sin Ming Drive, #03-03  
Sin Ming AutoCity  
Singapore 575722

Dear Sir/Madam,

Enquiry Date: 02/06/2018  
Enquiry By: Yap Jin Hui  
TP Vehicle No: SLV515Z  
Accident Date: 02/06/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLV 515Z (Insd veh)	Model:	HONDA SHUTTLE (A)
	SLV 2518C (TP veh)		
Date of Accident:	02/06/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	:	\$		13,920.96
Final Repair Cost	:	\$		8,292.50
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		1,200.00 12 days
LTA / GIA Search Fee	:	\$		2.00
Others:	:	\$		0.00

	:	\$		
Final Settlement Sum (Global Sum)	:	\$		9,490.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)				
A) For Non GIA Registered Workshop: Agreed Liability <u>100</u> (%)				
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	MIN'S MOTOR PTE LTD	:	\$ 9,490.00

JOANNE LEE KHANG MIN  
LKK Auto Consultants Pte Ltd

09/04/2019  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18010180/Kea3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 09-04-2019



ATTN:VALE OH

Code : ASM

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SLV 515Z	Veh. Inspected	SLV 2518C
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00JDK	Excess (\$)	0.00
Assign From		Assign Date	04/06/2018

**2. Vehicle Particulars & Condition**

Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GK81200469	Colour	METALLIC BLACK
Odometer	9151	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	9 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	9 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	9 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	9 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	02/06/2018	Inspection Date	05/06/2018
Survey held at	VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 2518C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	120.10	120.10
1	REAR BOOT COVER (CONSISTENT)	BENT	1,193.00	1,193.00
2	REAR BOOT COVER HINGE @\$40.80 (CONSISTENT)	TO REPAIR SEE LABOUR	81.60	-
2	REAR BOOT COVER SHOCKER BRACKET @\$165.00 (CONSISTENT)	SERVICEABLE	330.00	-
1	REAR BOOT COVER LOCK (CONSISTENT)	DENTED	157.10	157.10
1	REAR BOOT COVER LOCK MOTOR (CONSISTENT)	JAMMED	490.00	490.00
2	REAR BOOT COVER REFLECTOR @\$395.00 (CONSISTENT)	MTG CRACKED	790.00	790.00
2	REAR BOOT COVER NUMBER PLATE LAMP @\$38.50 (CONSISTENT)	SERVICEABLE	77.00	-
1	REAR BOOT COVER MOULDING (CONSISTENT)	SERVICEABLE	383.40	-
1	REAR BOOT COVER 'SHUTTLE' NAME PLATE (CONSISTENT)	NECESSARY	55.00	55.00
1	REAR BOOT COVER EMBLEM (CONSISTENT)	NECESSARY	38.00	38.00
1	REAR BOOT COVER INNER TRIM (CONSISTENT)	MTG CRACKED	320.90	320.90
1	REAR BOOT COVER RUBBER (CONSISTENT)	DISTORTED /DENTED	168.50	168.50
2	REAR LAMP @\$520.60 (CONSISTENT)	O/S CRACKED	1,041.20	520.60
1	REAR END PANEL (CONSISTENT)	BENT	560.80	560.80
1	REAR END PANEL INNER TRIM (CONSISTENT)	BUCKLED	251.40	251.40
1	REAR TOOL BOX (CONSISTENT)	DENTED	587.30	587.30
1	REAR SPARE TYRE PANEL (CONSISTENT)	BENT / BUCKLED	1,980.00	956.00
1	REAR SPARE TYRE PANEL TOP COVER (CONSISTENT)	DENTED	585.50	585.50
1	REAR BUMPER (CONSISTENT)	BENT	1,150.60	1,150.60
1	REAR BUMPER SPONGE (CONSISTENT)	NO SUCH PARTS	170.60	-
2	REAR BUMPER SIDE RETAINER @\$26.50 (CONSISTENT)	SERVICEABLE	53.00	-
2	REAR BUMPER REFLECTOR @\$45.20 (CONSISTENT)	SERVICEABLE	90.40	-
2	REAR FENDER INNER TRIM @\$489.60 (CONSISTENT)	MTG CRACKED	979.20	979.20
1	REAR EXHAUST SILENCE (CONSISTENT)	TO REPAIR SEE LABOUR	745.70	-

Report Ref No. CC4/ASM18010180/Kea3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-2,480.06	-1,784.80
			9,920.24	7,139.20
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR WINDSCREEN GUM (SN) (CONSISTENT)	NECESSARY	60.00	40.00
1	SET REAR BUMPER SENSOR (SN) (CONSISTENT)	DENTED	280.00	200.00
			340.00	240.00
	<b><u>LABOUR</u></b>			
	TO REMOVE AND REFIX REAR GLASS.		150.00	120.00
	TO REPAIR REAR DAMAGE INCLUSIVE OF THE REPAIR OF REAR BOOT COVER HINGE AND REAR EXHAUST SILENCE.		1,400.00	1,200.00
	TO SPRAY PAINTING.		1,200.00	1,000.00
			2,750.00	2,320.00
	<b>GRAND TOTAL</b>		<b>13,010.24</b>	<b>9,699.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>7,750.00</b>

Report Ref No. CC4/ASM18010180/Kea3q2















**KONG SENG CHEONG**





Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 payment breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 LCO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 LKK Inspection [4].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 LKK Adjustment 1a (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 LKK PHOTO-3.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 LKK PHOTO-2.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 TP ESTIMATE-MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	9 June 2018
 TP Immediate Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	7 June 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 TP LUK SURVEY PHOTO.pdf	Reports & Statement	Others	LUK AUTO CONSULTANTS PTE.LTD.(TP)	6 June 2018
 P2037195_148_00001_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	OH Vale	4 June 2018
 P2037195_C1_00001_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	OH Vale	4 June 2018
 TP SLV251INC TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	4 June 2018
 DO SLV515Z INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	4 June 2018
 TP PRI RECEIVED FROM WORKSHOP WITH GIA AND ESTIMATE.mng	Letters and Correspondence	Workshop	DHAKAL Raghav	4 June 2018