

ASS. REC. BY:

REF: CS3 / ms618010203 / Gz4ber Special Instruction:

SURVEYOR:

EQ

ASSIGNMENT (Office)

Member

From (Person): Lionel Tan of MS6 Date/Time: 04062018 5:25pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGW 9142K Insured: SGA 3161K

at Workshop m/s MJE motor. Tel:

of Bik 7 Sin ming Ind Est #01-82

Policy No: 80099547 Smp Claim No: 539015

Sum Insured: Excess:

Make of Veh: D.O.A. 13-10-2017
(Client's Record)

CA / REV / REP. / REV 24 HRS Wpi H.O.D. Endorsement:

Date/Time: 05062018 10:18 am Person Contacted: Yy Vehicle: IN OUT

Date/Time	Action/Instruction (X) Estimate
	SGW 9142K - X
	SGA 3161K - CS/ms616018527 / K7h3n2 OIA: 120916
6/6/18	Dismantled

PRS

REF: MS2h

2476C (2021)

minimum

ASSIGNMENT

From: _____ Date: 05062018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHW 9142K

at Workshop m/s: JOE motor.

of: Blk 7 Sin Ming #01-82

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SHW9142K Yr Regn: 31 Rec 2elo

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: BMW 318i 2.0 cc 1995

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 132903 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAVF72050A794231

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / SRim / STD A/Rim or _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \$40k.

IDAC Accident Report: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Tyre Size: F: 235 / 35 R19

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	05-06-18

Survey held at: w/s 5pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	* Repair Estimate : S\$ 8500-9500
	* 3 days
12/6/18	Submit PRS report.

RECEIVED 13 JUN 2018

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

1) S+PS: (\$) _____

2) Photos: _____

3) Other: _____

4) _____

5) _____

TOTAL: 180

Add Fee: Site Insp (\$) _____

Interview (\$) _____

Tech Invs (\$) _____

Weighand (\$) _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Nov 2017		04 Jun 2018 17:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	GROUND & SHARP PRECISION ENGINEERING PTE LTD, Co. Reg. No.: 198701575R, Tel: +6596616400		
Main Claimant:	LIM TECK SENG JASON, ID: S7342476C		
Vehicle Reg. No.:	SGW9142K	Date of Loss:	13/10/2017 22:00 - :59 [81 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 535015	Policy/Cover Note No.:	80099547SMP (Comprehensive) Coverage: 29/09/2017 - 28/09/2018
Vehicle Reg. No. (Insured):	SGA3161K	Policy No. (Claimant):	
		Excess:	S\$1,250.00
Repairer:	Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/06/2018]		
Driver/Custodian (Insured):	MICHELLE NG WAN LING (41 / Female), NRIC: S7624834F, Tel: +6596610077		
Adj Asg. Remarks:	on WP. SJE - DISAGREED CAR IN WORKSHOP . Please appoint LKK AUTO CONSUKLTANTS to conduct the survey . Kindly contact YY / JO @ 9225 1391 or 6454 2203 to arrange for survey.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

0506 2018 @ 10:18am
YY veh in

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/10/2017 13:35
Date Of Accident	13/10/2017 22:05
Exact Location Of Accident	ALONG BEAUTY WORLD MRT STATION OPENSOURCE CP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGW9142K
Insured/Policyholder	
Name Of Registered Owner	LIM TECK SENG JASON
NRIC No	S7342476C
Email Address	JACK.IN.BOXX@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97490051
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	BMW
Model	318CI-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00000337
Cover Note Number	
Driver	
Name of Driver	LIM TECK SENG JASON
NRIC No	S7342476C
Date Of Birth	15/11/1973
Occupation	INDOOR
Date Of Driving Pass	14/05/1997
Driving Experience	20 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97490051
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	JACK.IN.BOXX@GMAIL.COM

Address	BLK 87 WEST COAST DRIVE #07-14
Postcode	128015
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	CLEMENTI NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UNABLE TO UPLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGA3161K
Vehicle Make/Model/Colour	BMW
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	



**SINGAPORE
POLICE FORCE**



T/20171014/2015

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

1 of 3

Report No. T/20171014/2015

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/10/2017 01:46	Vide Report No.:	Station Diary No.: 8
--	------------------	-------------------------

Informant's Particulars			
Name of Informant: LIM TECK SENG, JACKSON		Address: APT BLK 87 WEST COAST DRIVE #07-14 SINGAPORE 128015	
ID Type / ID No.: NRIC NO / S7342476C		Contact No.: Home/Office: Mobile: 97490051	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 43	Date of Birth: 16/11/1973	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: RISK MANAGER		Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 13/10/2017 22:05	Type of Location: Car Park
Location: CHUN TIN ROAD Beauty World MRT Station, Open space carpark. (Carpark Jalan Seh Chuan)				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGA3161K	Car		730I			0
SGW9142K	Car	BMW	318I 2.0 AT D/AB 2WD 4DR GAS/D SR DRL	Black	Slightly Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date



Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SGW9142K	FWD Singapore Pte. Ltd	PNPV2017-00000337	01/01/2017	31/12/2017

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LIM TECK SENG, JACKSON	ID No.	S7342476C
Related Vehicle	SGW9142K (Car)	Contact No.	97490051
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 13/10/17 at about 2000hrs, I parked my car (SGW 9142K) at the open space carpark along Chun Tin Rd near to Beauty World MRT Station.

At about 2205hrs later that day, when I returned back to my car, I noticed dents and some scratches on the right side of the front bumper (driver side).

Subsequently, I went back home and run through the in-car camera footage. I then realized that a dark coloured BMW 7 (SGA3161K) series car was caught hitting onto the front portion of my car while the driver was trying to maneuver around the carpark. I am unsure of the exact time the incident happened. No one was inside the parked car during the incident. I did not managed to get the particulars of the said BMW driver that hit onto my car.



**SINGAPORE
POLICE FORCE**



T/20171014/2015

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

3 of 3

Report No. T/20171014/2015

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
D /
Sgt 1 NUR WIRDAH BINTE MUHAMMAD
WAZIR

Signature Of Informant:


Signature Of Interpreter:
Not applicable

Date/Time:
14/10/2017 01:46

Officer In Charge Of Case:
TP / HRT /
SI ABDUL KAREEM BIN ABDUL HAGUE
Contact No.: 65476079

Classification Of Case:

Authentication Stamp
NP168  Signature: _____
Singapore Police Force

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2476C
Vehicle Details	
Vehicle No.:	SGW9142K
Vehicle to be Exported:	No
Intended De-registration Date:	06 Jun 2018
Vehicle Make:	B.M.W.
Vehicle Model:	318I 2.0 AT D/AB 2WD 4DR GAS/D SR DRL
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	B049I858N46B20BZ
Chassis No.:	WBAPF72050A794231
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$27,689.00
Original Registration Date:	31 Dec 2010
First Registration Date:	31 Dec 2010
Transfer Count:	0
Actual ARF Paid:	\$27,689.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Dec 2020
PARF Rebate Amount:	\$16,613.00
Intended COE Rebate Details	
COE Expiry Date:	30 Dec 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$76,102.00
COE Rebate Amount:	\$18,464.00
Total Rebate Amount:	\$35,077.00

The information contained herein is correct as at 06 Jun 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Nov 2017		04 Jun 2018 17:25 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	GROUND & SHARP PRECISION ENGINEERING PTE LTD, Co. Reg. No.: 198701575R, Tel: +6596616400								
Main Claimant:	LIM TECK SENG JASON, ID: S7342476C								
Vehicle Reg. No.:	SGW9142K	Date of Loss:	13/10/2017 22:00 - :59 [81 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 535015	Policy/Cover Note No.:	80099547SMP (Comprehensive) Coverage: 29/09/2017 - 28/09/2018						
Vehicle Reg. No. (Insured):	SGA3161K	Policy No. (Claimant):							
		Excess:	S\$1,250.00						
Repairer:	Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 05/06/2018]								
Driver/Custodian (Insured):	MICHELLE NG WAN LING (41 / Female), NRIC: S7624834F, Tel: +6596610077								
Adj Asg. Remarks:	on WP. SJE - DISAGREED CAR IN WORKSHOP . Please appoint LKK AUTO CONSUKLTANTS to conduct the survey . Kindly contact YY / JO @ 9225 1391 or 6454 2203 to arrange for survey.								
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All	Search Tasks						
		Create New Task	Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGW9142K (535015)**
[SGA3161K]
TP
LIM TECK SENG JASON
Oct 13 2017 10:00PM
[GROUND & SHARP PRECISION ENGINEERING PTE LTD]
Mje Motor

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Video									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print		
1	08/01/18 14:32	Video - Accident From:SC - Reg. No: SGA3161K, Claimant: GROUND & SHARP PRECISION ENGINEERING PTE LTD						Load MP4		
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	07/06/18 11:20	General View						Load JPG	<input checked="" type="checkbox"/>	
2	07/06/18 11:20	General View						Load JPG	<input checked="" type="checkbox"/>	
3	07/06/18 11:20	General View						Load JPG	<input checked="" type="checkbox"/>	
4	07/06/18 11:20	General View						Load JPG	<input checked="" type="checkbox"/>	
5	07/06/18 11:20	General View						Load JPG	<input checked="" type="checkbox"/>	
6	07/06/18 11:20	General View						Load JPG	<input checked="" type="checkbox"/>	
7	07/06/18 11:20	General View						Load JPG	<input checked="" type="checkbox"/>	
8	07/06/18 11:20	General View						Load JPG	<input checked="" type="checkbox"/>	
9	07/06/18 11:20	General View						Load JPG	<input checked="" type="checkbox"/>	
10	07/06/18 11:20	General View						Load JPG	<input checked="" type="checkbox"/>	
11	07/06/18 11:20	General View						Load JPG	<input checked="" type="checkbox"/>	
12	07/06/18 11:25	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
13	07/06/18 11:25	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
14	07/06/18 11:25	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
15	07/06/18 11:25	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
16	07/06/18 11:25	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
17	07/06/18 11:25	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
18	07/06/18 11:25	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
19	07/06/18 11:25	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
20	07/06/18 11:25	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
21	07/06/18 11:25	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
22	07/06/18 11:25	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
23	07/06/18 11:25	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
24	07/06/18 11:25	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
25	07/06/18 11:25	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
26	07/06/18 11:25	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
27	07/06/18 11:25	Dismantled Parts						Load JPG	<input checked="" type="checkbox"/>	
Documentation									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print		
1	04/06/18 13:18	TPD SGW9142K GIA REPORT From:SC - Reg. No: SGA3161K, Claimant: GROUND & SHARP PRECISION ENGINEERING PTE LTD						Load PDF		
2	04/06/18 13:18	Insured Police Report From:SC - Reg. No: SGA3161K, Claimant: GROUND & SHARP PRECISION ENGINEERING PTE LTD						Load PDF		
3	04/12/17 11:25	E-FILE REPORT (SGA3161K)						Load PDF		

Video		1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Thumbnail	Print
	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		
	From:SC - Reg. No: SGA3161K, Claimant: GROUND & SHARP PRECISION ENGINEERING PTE LTD		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18010203/GZ4BE2

Date: 14/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 80099547SMP
Claimant Vehicle No : SGW9142K	Insured Vehicle No : SGA3161K
Date of Loss: 13/10/2017	Nature of Claim: TP
	Claim No: 535015

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGW9142K			
Make & Model: BMW 318CI, 2.0 (A)	Engine No: B049I858N46B20BZ		
Reg. Date: 31/12/2010 (Man. Year: 2010)	Chassis No: WBAPF72050A794231		
Colour: Black	Odometer: 132903 km		
Engine Capacity: 1995 cc			
Market Value/New Car Price: N/A			
Sum Insured (S\$): Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35 R19	Rear Tyre Size: 235/35 R19
Front Left Side: Goodyear 6 mm	Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm	Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/06/2018	
Date Inspected: 05/06/2018	Inspected At: Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82 Singapore 575642
Estimated Period of Repair: 0.0 days	

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,500.00 -\$9,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jun 2018)

Parts: 143 BMW 318CI 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGW9142K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >