

22/03/2002

ASS. REC. BY:

REF:

CS/AWA18010214 / (73ber)

Special Instruction:

Surveyor:

GR

ASSIGNMENT (Office)

From (Person):

Hew Lee Fong

of

AWA

Date/Time:

05062018 11:06am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 493D

Insured:

GBG 3165D

at Workshop m/s

Allswell Motor

Tel:

6679 1146

of

25 Dafu Lane 9

Policy No:

AVCP SB 0088031700

Claim No:

NSV1800342 / TKL

Sum Insured:

Excess:

Make of Veh:

D.O.A.

03062018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi'

06062018

H.O.D. Endorsement:

Date/Time:

05062018 126pm

Person Contacted:

Chi Yee

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLR 493D - X
	GBG 3165D - X

RECEIVED

xBel.

REF:

AWA

B 2889J

ASSIGNMENT

(2018)

26 Sep 2008

From:

Date: 6/6/18

Estimated Cost:

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLQ 493D

at Workshop m/s

Allswell Motor

of

25 Defu Lane 9

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$12K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{lup}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

SLQ 493D

Yr Regn:

Type: ☒ M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota AHi's 1.6 c.c 1598

Colour

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

313361

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR05 38 EE 106117350

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

195/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MICY OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

06-06-18

Survey held at

w/s

1pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Finalized \$ 2221 2587.93

(\$ 3141.57 Red - 556)

RECEIVED 17 JUL 2018

Date/Time: File Pass to?

17/07/18

1) Typist

Date/Time: File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

200

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

200

Report Format :

Lump Sum / I.B.I: (\$ 2,587.93 p/p)

Catherine Chong (LKK Auto)

From: Hew, LeeFong <LeeFong.Hew@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Tuesday, 5 June, 2018 11:06 AM
To: 'assignments'
Cc: 'SUR'; 'account5 leasing'
Subject: TP Survey assignment for SLQ 493D - DOA: 03/06/2018 Our ref: NSV1800342/TKL

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us **do** have consensus in the appointment of **Mr Xing Guo Qiang** as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SLQ 493 D
Insured Vehicle	:	GBG 3165 C
Policy Number	:	AVCPSB0088031700
Name of Workshop	:	Allswell Motor Traders
Contact Number	:	6679 1146
Person to Contact	:	Chai Yee
Estimated Cost of repairs	:	\$ NA

Regards,
Claims Division

05062018 @ 12:46pm
Chai Yee veh in
06062018

Copy to Allswell Motor Traders via Email

Note -

- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Business
Owner ID:	2889J

Vehicle Details

Vehicle No.:	SLQ493D
Vehicle to be Exported:	No
Intended De-registration Date:	07 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	3ZZ4792753
Chassis No.:	MR053ZEE106117250
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,777.00
Original Registration Date:	26 Sep 2008
First Registration Date:	26 Sep 2008
Transfer Count:	1
Actual ARF Paid:	\$16,777.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Sep 2018
PARF Rebate Amount:	\$8,388.00

Intended COE Rebate Details

COE Expiry Date:	25 Sep 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,100.00
COE Rebate Amount:	\$423.00
Total Rebate Amount:	\$8,811.00

The information contained herein is correct as at 07 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/06/2018 14:08
Date Of Accident	03/06/2018 13:15
Exact Location Of Accident	CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ493D
-----------------------------	---------

Insured/Policyholder

Name Of Registered Owner	ALLSWELL MOTOR TRADERS
Co Reg No	53192889J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64625405

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	5095583051
Cover Note Number	

Driver

Name of Driver	LOH KHONG BENG
NRIC No	S8086346B
Date Of Birth	19/08/1980
Occupation	OUTDOOR
Date Of Driving Pass	11/04/2006
Driving Experience	12 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-92333163
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 677 WOODLANDS AVENUE 6 #04-748
Postcode	730677
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER & LEASEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : CHINESE PASSENGER GENDER: : MALE
Passenger 2	NAME: : CHINESE PASSENGER GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 03/06/2018 Afternoon 1:15 P.M. I drive grab SLQ493D at CTE to PIE (changi airport) direction , front car drive slowly. Suddenly , a car GBG3165C bang my car rear side.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG3165C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	LIM POH HUAT
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LOH KHONG BENG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by
ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 03/06/18 Afternoon 1:15pm. I drive grab (SLQ493D) at CTE. to PIE (Changi Airport) direction, front car drive slowly. suddenly, a car GB63165L bang my car rear side.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email:ben@allswellmotor.com.sg

(3rd party claim against

5 Days .
part by part lamp sun.
before paint photos.
Luo Qiaop
06/6/18

Estimate repair

Vehicle No. : SLQ493D
Make & Model : Toyota Aulis
Chassis No. :
Date of survey :

Submitted by : Ben
COE expiry : 25-09-2018
Engine No. :

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	Rear bumper / RL	01	\$899.1	476.2	
02	Rear tailgate / buc	01	\$952.6	680	
03	RH Rear lamp / CMA	01	\$279.3	160.7	
04	End panel / RL buc	01	\$475.0	x	
05	Reinforcement bar & repair	01	\$439.5		* repair
	Special net			216.9	
01	Bumper clips @ \$11.00 each	04	\$44.00	987.68	25%: 1343.92
	Labour Description				
01	Dismantle / Assembly of tailgate / bumper / rear lamp & etc	01	\$260.0	200	
02	Repair / knockback reinforcement bar	01	\$120.0	Xm	* repair
03	Repair / weld / panel beating of end panel elements	01	\$960.0	400	
04	Spray painting of tailgate / bumper / end panel including anti-rust paint	01	\$1200.0	600	
			Total =	\$5,729.50	2543.92
					1791.5
					25%: 1343.93

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

Acknowledged by Repairer

Signature:

Date:

2587.93




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD		Ref : CS/AWA18010214/Gsbe2		
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Date : 27-07-2018		
		Code : AWA		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 3165D	Veh. Inspected	SLQ 493D	
Policy No.	AVCPSPB0088031700	Coverage (\$)	0.00	
Claim No.	NSV1800342/TKL	Excess (\$)	0.00	
Assign From	HEW LEE FONG	Assign Date	05/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053ZEE106117350	Colour	SILVER	
Odometer	313361	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	6 mm	
L/H Front Tyre	195/65 R15	MICHELIN	6 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/06/2018	Inspection Date	06/06/2018	
Survey held at	25 DEFU LANE 9			
Repairer	ALLSWELL MOTOR TRADERS			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 493D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	899.10	476.20
1	REAR TAILGATE	BUCKLED	952.60	680.00
1	RH REAR LAMP	CRACKED	279.30	160.70
1	END PANEL	BUCKLED	475.00	475.00
1	REINFORCEMENT BAR	TO REPAIR SEE LABOUR	439.50	-
	LESS 25% DISCOUNT		-	-447.97
			3,045.50	1,343.93
	<u>SPECIAL NETT ITEMS</u>			
4	BUMPER CLIPS @\$11.00 (SN)	NECESSARY	44.00	44.00
			44.00	44.00
	<u>LABOUR</u>			
	DISMANTLE / ASSEMBLY OF TAILGATE / BUMPER / REAR LAMP & ETC.		360.00	200.00
	REPAIR / KNOCKBACK REINFORCEMENT BAR.	NOT NECESSARY	120.00	-
	REPAIR / WELD / PANEL BEATING OF END PANEL ELEMENTS. INCLUSIVE OF THE REPAIR OF REINFORCEMENT BAR.		960.00	400.00
	SPRAY PAINTING OF TAILGATE / FENDER / BUMPER / END PANEL INCLUDING ANTI-RUST PAINT.		1,200.00	600.00
			2,640.00	1,200.00
	GRAND TOTAL		5,729.50	2,587.93
	RECOMMENDED COST OF REPAIRS			2,587.93

Report Ref No. CS/AWA18010214/Gsbe2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.