

(06/1/13) waf

ASS. REC. BY: MORCUS

REF:

CS/TP18010262/urbnz

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: G3F9117Hat Workshop m/s Bun

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

DAC Accident Rep: 8

Consistent? : Yes or No

GA / PR Seen: 20

Consistent? : Yes or No

Est. Repairs: 8

days

Res.: Yes or No

Lump Sum: 20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

4512N

Vehicle: IN / OUT

Veh No: G3F9117HYr Regn: 4,17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CMMake: Toyota

hace

C.C.

2982Colour: White

A/C:

Insured / Std / NI / NA

Sp. Reading: 44304

T/Radio:

Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KDM20102H501Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt or OrderBrake: Order / Jammed / Leaked / Burnt or OrderModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60R15

R: \_\_\_\_\_

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6

mm

R/Bal: 6

mm

L/Bal: 6

mm

L/Bal: 6

mm

D.O.A: 22/5/18D.O.A: 5/6/18

Survey held at: \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/K Body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MUC Ajor ke 27A 13375  
1/5 85250Ord: 85887.37, 531.

RECEIVED 19 JUN 2018

Data/Time, File Pass to?

1) Input

Data/Time, File Return to?

2) \_\_\_\_\_



: Prel. Report



: Final Report

Days Of Repair: 8Resurvey No. of Trip: 1Add Fee: ☐

: Site Insp (\$ \_\_\_\_\_)



: Interview (\$ \_\_\_\_\_)



: Tech. Invs (\$ \_\_\_\_\_)






: Weekend (\$ \_\_\_\_\_)

Survey Fee: 170+15Transportation: 50: S & RS: 50Photos: 84Others: 80

TOTAL

449Report Format: TP-1 dependentLump Sum / I.B.H: (\$ 5250.00)

Ref. No :	Res. Date: 18/6/18	Date Received:
Veh. No : G1579117H	SP:	WKSP: 
C/No :		
<b>Action/Instruction:</b>		
1.File	2.Submit Photo? YES / NO	
3.Indicate Res. Date On Photo Page?	YES / NO	Message:
If No, due to	a) No authorisation b) Days of repair	
others: 		
Final Re-inspection or Progress Photos		
		Inspected By:

MYT218067257 / Yew Teo Automobile Tech Pte Ltd - Kund Built  
ENTRY DATE & TIME: 23/05/2018 17:03  
SUBMITTED BY: Tuh Lei Ming

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report 23/05/2018 17:03  
Date Of Accident 22/05/2018 15:00  
Exact Location Of Accident MAYO STREET  
Country/State Of Loss SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number GBF9117H

## Insured/Policyholder

Name Of Registered Owner MCONNECT CONSTRUCTION & ENGINEERING PTE LTD  
Co Reg No 201624512N  
Email Address NOEMAIL  
Mobile Phone No (LOCAL) +65-86068045  
Alternative Phone No OFFICE-86068045

Add: 19 Woodlands Ind. Park E1  
#01-03 S757719

## Vehicle Particulars

Manufacturer TOYOTA  
Model HIACE  
Exact Purpose for which vehicle was being used at time of accident WORK USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

## Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number 5090227969-01

Cover Note Number

## Driver

Name of Driver SAMYYAIAH ANANTHAN  
Passport No/FIN G6599201P  
Date Of Birth 17/03/1989  
Occupation OUTDOOR  
Date Of Driving Pass 23/04/2013  
Driving Experience 5 YEARS AND 0 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-86068045  
Fax Number  
Contact Number  
EMail Address NOEMAIL

Address 14 ROBINSON ROAD #08-01A FAR EAST FINANCE BUILDING  
 Postcode 048545  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle  
 Insurance Company of Driver's Own Vehicle

### General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD  
 Weather Conditions CLEAR  
 Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

### Circumstances of Accident

REFER TO ATTACHED

### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKB5397G  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver UNGLIN NA  
 NRIC/Passport Number S7676181G  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 23/5/18, 4:45pm

Driver's Signature

(if driver is not the policyholder)


Date & Time: 23/5/18, 4:45pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LOTS

I was driving along Mayo Street when suddenly Car B came out from the lot and hit my Van (B)

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 22/5/18, 445pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 23/5/18, 445pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	4512N

### Vehicle Details

Vehicle No.:	GBF9117H
Vehicle to be Exported:	No
Intended De-registration Date:	06 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 3.0 MANUAL
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2682214
Chassis No.:	KDH2010215501
Maximum Power Output:	-
Open Market Value:	\$32,171.00
Original Registration Date:	17 Apr 2017
First Registration Date:	17 Apr 2017
Transfer Count:	1
Actual ARF Paid:	\$1,609.00

### Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

### Intended COE Rebate Details

COE Expiry Date:	16 Apr 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$15,095.00
COE Rebate Amount:	\$13,375.00
<b>Total Rebate Amount:</b>	<b>\$13,375.00</b>

The information contained herein is correct as at 06 Jun 2018

OK



# BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28  
(Unit C) #01-28-33/55 Singapore 417883  
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088  
Website: www.bluwel.com.sg Email: bluwei2088@yahoo.com.sg  
Co. Reg. No. 200704951N  
GST Reg. No. 200704951N  
Must be resurveyed and  
approval from Insurance Company

not Affected  
1/55250  
87.

GBF9117H

Acknowledged by Repairer

Signature:

Date:

20/5/17 1799.12

Front door o/s		
Front door inner rubber o/s	RM	166.45
Front door inner lock o/s	RM	319.20 X
Front step garnish o/s	garnish	214.50
Front door rear pillar o/s	RM	645.10
Sliding door o/s	RM	1891.10
Sliding door inner lock o/s	RM	322.50 X
Rear bumper	RM	628.10
Rear shock absorber o/s	RM	282.30 X
Rear wheel hub bearing o/s	RM	488.50 X
Front wheel hub bearing o/s	RM	465.50 X
	(25%)	7222.37

5344.37

S. Not

Front door 'Roc' sticker o/s	RM	35.00
Front wheel hub cap o/s	RM	120.00
Front steel rim o/s	RM	100.00
Rear wheel hub cap o/s	RM	120.00
1 set Rear bumper clips	RM	50.00
Sliding door inner board clips o/s	RM	50.00

To check wiring	RM	80.00 - 20
To spray rust proofing	RM	120.00 - 80
To conduct wheel alignment	RM	100.00 - 80
To transfer front door & sliding door mechanism	RM	180.00 - 120
labour for panel beating & replacing parts	RM	1080.00 - 880
To putty & spray painting	RM	1500.00 - 900
To Dismantle & refix undercarriage	RM	380.00 X
TOTAL		11137.37





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP18010262/Urbn2

BLK 1 KAKI BUKIT AVE 6  
#01-28/51/53/55(MAIN OFFICE)SINGAPORE  
417883

Date : 21-06-2018



ON BEHALF OF MCONNECT CONSTRUCTION &  
ENGINEERING PTE LTD

Code : TP149

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	GBF 9117H
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	05/06/2018

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KDH2010215501	Colour	WHITE
Odometer	44304	Steering	AFFECTED
Brakes	IN ORDER	Modification	NIL
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	DUNLOP	6 mm
L/H Front Tyre	195/60 R15	DUNLOP	6 mm
R/H Rear Tyre	195/60 R15	DUNLOP	6 mm
L/H Rear Tyre	195/60 R15	DUNLOP	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	22/05/2018	Inspection Date	05/06/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 9117H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT DOOR O/S	DENTED / BENT	1,799.12	1,799.12
1	FRONT DOOR INNER RUBBER O/S	NECESSARY	166.45	166.45
1	FRONT DOOR INNER LOCK O/S	NOT NECESSARY	319.20	-
1	FRONT STEP GARNISH O/S	GRAZED	214.50	214.50
1	FRONT DOOR REAR PILLAR O/S	BADLY DENTED	645.10	645.10
1	SLIDING DOOR O/S	BADLY DENTED	1,891.10	1,891.10
1	SLIDING DOOR INNER LOCK O/S	NOT NECESSARY	322.50	-
1	REAR BUMPER	CUT	628.10	628.10
1	REAR SHOCK ABSORBER O/S	NOT NECESSARY	282.30	-
1	REAR WHEEL HUB BEARING O/S	NOT NECESSARY	488.50	-
1	FRONT WHEEL HUB BEARING O/S	NOT NECESSARY	465.50	-
	LESS 25% DISCOUNT		-	-1,336.09
			7,222.37	4,008.28
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT DOOR "ROC" STICKER O/S (SN)	NECESSARY	35.00	35.00
1	FRONT WHEEL HUB CAP O/S (SN)	DISTORTED	120.00	120.00
1	FRONT STEEL RIM O/S (SN)	DENTED	100.00	100.00
1	REAR WHEEL HUB CAP O/S (SN)	CUT	120.00	120.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SLIDING DOOR INNER BOARD CLIPS O/S (SN)	NECESSARY	50.00	50.00
			475.00	475.00
<b><u>LABOUR</u></b>				
	TO CHECK WIRING.		80.00	20.00
	TO SPRAY RUST PROOFING.		120.00	80.00
	TO CONDUCT WHEEL ALIGNMENT.		100.00	80.00
	TO TRANSFER FRONT DOOR & SLIDING DOOR MECHANISM.		180.00	120.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.		1,080.00	880.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	900.00
	TO DISMANTLE & REFIX UNDERCARRIAGE.	NOT NECESSARY	380.00	-
			3,440.00	2,080.00
<b>GRAND TOTAL</b>			<b>11,137.37</b>	<b>6,563.28</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,250.00
---	--	--	----------

Report Ref No. CS/TP18010262/Urbn2

RESURVEY INSPECTION DATE: 18/06/2018  
(DETAILS SEE PHOTOGRAPHS ENCLOSED)

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.