

INS/ CASE OWNER:

Ming Yao

CC6 / Ach 180

10263 Upas 9/

LKK:

IDAC:

Surveyor:

marcus

DOI:

ASSIGNMENT

6/6/18

Date / Time:

6/6/18

Registered in Merimen:

6/6/18

Pre-assign / CCU / FTE

SPW 6001R



Insured Vehicle No.:

SPW 6001R

Name of Insured:

Lau Yat Hong

Insured Tel No.:

HP: 98318968

Excess Sec II :SS

D.O.A 1/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

39 3000 201654

Policy No.:

1706009318

Make / Model:

Lia Corvo-to

Place of Accident:

Tung West Ave 5

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kim Chuan

41966



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

19/6

C47

STY 236L - C6/P21/600 P23/P24/P25/P26/P27/P28/P29/P30/P31/P32/P33/P34/P35/P36/P37/P38/P39/P40/P41/P42/P43/P44/P45/P46/P47/P48/P49/P50/P51/P52/P53/P54/P55/P56/P57/P58/P59/P60/P61/P62/P63/P64/P65/P66/P67/P68/P69/P70/P71/P72/P73/P74/P75/P76/P77/P78/P79/P80/P81/P82/P83/P84/P85/P86/P87/P88/P89/P90/P91/P92/P93/P94/P95/P96/P97/P98/P99/P100

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

24/6/18 Tung 29/6/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

ATA AGIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$ days Reduction: % Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with: Jason

Email ☒ Call ☐

Final Liability:

Repair Cost:

Loss of Rental (LOR):

Loss of Use (LOU):

Loss of Income (LOI):

LOR only ☐ LOU only ☐

GIA/LTA Search

Medical:

Disbursement:

Legal Cost

Total:

FINAL PAYMENT

Date/Time:

Global Sum S\$: 11200.00

Email ☐ Call ☐

Payee 1:

Payee 2: (Strike if N.A.)

Payee 3: (Strike if N.A.)

Name 1:

Name 2:

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320 + \$20

RECEIVED 21 SEP 2018

ASSIGNMENT

From: _____ Date: _____

Estimated Cost

QD / TR / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. _____

at Workshop m/a

of

Induced

Policy No.

Claims No.

Sum insured: Excess:

(Client's Record)

Model of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value

IPAC Accident Report

Consistent? : Yes or No

GLA PR Sean

Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Turn Sum: **10** % 3 Val.: Yes or No

CA 1 REV 1 REF 1 24 HRS

Date	Person Contacted
------	------------------

Vehicle: IN / OUT

Date / Time	Action / Instruction
-------------	----------------------

Have him LTA 56156

2/21/01 * new rods, replace.

4/11/18 Confirmed Kaperi Sum \$10200 with Alex

Cost \$ 96187 49%

Data/Time, File Page 10/10

☐ : Prel. Report

☐ : Final Report

Date/Time: File Return 102

Report Format :

Lump Sum / I.B.I.: (\$)

Days Of Repair:

Resurvey No. of Trio:

Add Fee:

☐ Site Insp (\$

☐ Interview (6)

Tech. Invs (\$

☐ Weekend (\$)

[Survey Fee:

Transportation:

Protein

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18010263/Upa3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 06-06-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SFW 6001R	Veh. Inspected	SJY 236L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/06/2018	Inspection Date	06/06/2018
Survey held at	KIM CHWEE AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6

#01-46/48/50 Autobay

SINGAPORE 417883

VEHICLE NO: SJY 236L

Repair sum \$10200

Not Authorized Sdy.

6/6/18

QTY	PARTICULAR	AMOUNT
1 PCS	REAR BUMPER STEP PLATE 160	Torn \$266.00 ✓
1 PCS	REAR BUMPER UPPER 1730	29/12 \$1,930.00 ✓
1 PCS	REAR BUMPER LOWER	2.5 \$990.00 ✓
1 PCS	REAR BUMPER CENTRE LOWER GARNISH (SILVER)	Torn \$390.00 ✓
1 PCS	REAR BUMPER TOWING COVER	2.5 \$25.00 ✓
2 PCS	REAR BUMPER REFLECTORS @\$85.00	0/5 B/W \$170.00 1 pc
1 PCS	REAR BUMPER REVERSE LAMP	one \$365.00 ✓
1 SET	REAR BUMPER REVERSE WIRING HARNESS	17 \$495.00 X
2 PCS	REAR BUMPER REVERSE SENSORS @\$195.00	Shhd \$390.00 ✓
2 PCS	REAR BUMPER SIDE RETAINERS @\$62.00	17 \$124.00 X
1 PCS	REAR BUMPER INNER TOP RETAINER	one \$195.00 ✓
1 PCS	TAILGATE 1850	Sody \$2,160.00 ✓
1 PCS	TAILGATE CHROME HANDLE	17 \$290.00 X
1 PCS	TAILGATE 'CHEVROLET' EMBLEM	one \$50.00 ✓
1 PCS	TAILGATE 'ORLANDO' EMBLEM	one \$48.00 ✓
1 PCS	TAILGATE 'TURBO' EMBLEM	one \$50.00 ✓
1 PCS	TAILGATE REFLECTOR O/S	one \$390.00 ✓
1 PCS	REAR WINDSCREEN	17 \$880.00 X
1 PCS	REAR WINDSCREEN MOULDING	one \$80.00 ✓
1 PCS	TAILGATE INNER LOCK	two \$245.00 ✓
1 PCS	TAILGATE INNER TRIM BOARD	one \$388.00 ✓
1 PCS	TAILGATE WEATHERSTRIP	two \$240.00 ✓
2 PCS	TAILLAMPS @\$750.00 729	0/5 one \$1,500.00 1 pc
1 PCS	REAR END PANEL 770	30/5 one \$970.00 ✓
1 PCS	REAR END PANEL TOP GARNISH	two \$315.00 ✓
1 PCS	REAR SPARE BRACKET & CARRIER	set \$462.00 ✓
1 PCS	REAR FLOOR PANEL	one \$1,560.00 X
1 PCS	REAR FLOOR PANEL TOP BOARD	17 \$490.00 X
		\$15,458.00
	S.NETT	
1SET	REAR BUMPER CLIPS	9947 one \$50.00 ✓
1 PCS	REAR WINDSCREEN SEALANT	8952-30 one \$50.00 40
1 PCS	REAR WINDSCREEN INNER SEAL	one \$50.00 40

107

9947
8952-30

1 PCS

REAR END PANEL SEALANT

17 \$30.00 X

LABOUR CHARGES:

TO CHECK WIRING

\$80.00 30

TO DISMENTLE & REPLACING REVERSE SENSOR

\$80.00 50

TO DISMENTLE & REFIX REAR WINDSCREEN

\$150.00 120

TO TRANSFER TAILGATE MECHANISM

\$120.00 60

TO DISMENTLE & REFIX SEAT, CUSHION UPHOLSTERY

\$150.00 80

TO DISMENTLE & REFIX REAR EXHAUST

17 \$100.00 X

TO SPRAY RUST PROOFING

\$120.00 60

TO MOUNT VEHICLE ON CAR O-LINER

17 \$380.00 X

LABOUR FOR PANEL BEATING & REPLACING PARTS

\$1,500.00 800

TO PUTTY & SPRAY PAINTING

\$1,500.00 1100

TOTAL \$19,818.00

113820

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No (legal modifications) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 4196G

Vehicle Details

Vehicle No.: SJY236L

Vehicle to be Exported: No

Intended De-registration Date: 06 Jun 2018

Vehicle Make: CHEVROLET

Vehicle Model: ORLANDO 1.4AT TURBO

Primary Colour: Grey

Manufacturing Year: 2016

Engine No.: A14NET162840030

Chassis No.: KL1YA7589HK609217

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$15,979.00

Original Registration Date: 27 Feb 2017

First Registration Date: 27 Feb 2017

Transfer Count: 0

Actual ARF Paid: \$15,979.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Feb 2027

PARF Rebate Amount: \$11,984.00

Intended COE Rebate Details

COE Expiry Date: 26 Feb 2027

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$50,621.00

COE Rebate Amount: \$44,172.00

Total Rebate Amount: \$56,156.00

The information contained herein is correct as at 06 Jun 2018

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	4196G

Vehicle Details

Vehicle No.:	SJY236L
Vehicle to be Exported:	No
Intended De-registration Date:	05 Jun 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	ORLANDO 1.4AT TURBO
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	A14NET162840030
Chassis No.:	KL1YA7589HK609217
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$15,979.00
Original Registration Date:	27 Feb 2017
First Registration Date:	27 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$15,979.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Feb 2027
PARF Rebate Amount:	\$11,984.00

Intended COE Rebate Details

COE Expiry Date:	26 Feb 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,621.00
COE Rebate Amount:	\$44,187.00
Total Rebate Amount:	\$56,171.00

The information contained herein is correct as at 05 Jun 2018

OK

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Friday, 3 August 2018 10:26 AM
To: Lee, Ming Yao (MingYao.Lee@aig.com)
Subject: <Seek Mandate> Your Ref: 3930002016SG *Our Ref: CC6/AIG18010263/Upa3
[ACCIDENT INVOLVING SFW 6001R(OI) AND SJY 236L(TP) ON 01/06/2018]

Your Ref: **3930002016SG**
Our Ref: CC6/AIG18010263/Upa3

Without Prejudice

Dear Sirs,

ACCIDENT INVOLVING SFW 6001R(OI) AND SJY 236L(TP) ON 01/06/2018

We refer to the above matter.

This is head-to-rear collision. Liability is not in our insured's favour.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, **Kim Chwee Auto Pte Ltd** is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$ 21,205.26	\$10,914.00
2. Loss of Use (6days x \$100.00)	\$ 600.00	\$ 360.00 (6days x \$60.00)
3. LTA/GIA Search Fee	\$ 2.00	\$ 2.00
TOTAL	\$ 21,807.26	\$11,276.00

Total amount of claim (**Liability 100%**) **\$11,276.00**

For your approval in Merimen please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SJY236L (3930002016SG)**

[SFW6001R]

TP

OW SING FATT

Jun 1 2018 8:00AM

[LAU LIAT BENG]

Kim Chwee Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 29/08/2018 14:27 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11276.00) - SJY236L - Claim Handler: Lee, Ming-Yao

Approved:11276.00:Hi, Please settle at best. Ensure all documents are in order. Regards, George

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 15 September 2018 1:40 PM
To: Jason Fastech Auto (jason@fastechauto.com.sg)
Subject: Your Ref: SJY 236L *Our Ref: CC6/AIG18010263/Upa3 [ACCIDENT INVOLVING SFW 6001R(AIG) & SJY 236L ON 01/06/2018]

Your Ref: **SJY 236L** *Without Prejudice*
Our Ref: CC6/AIG18010263/Upa3

Dear Sirs/Madam,

ACCIDENT INVOLVING SFW 6001R(AIG) & SJY 236L ON 01/06/2018

We refer to the above matter.

We propose settlement at a global sum of **\$11,200.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Jason Fastech Auto <jason@fastechauto.com.sg>
Sent: Monday, 17 September 2018 11:02 AM
To: Hsiao Tong (LKKAUTO)
Subject: RE: Your Ref: SJY 236L *Our Ref: CC6/AIG18010263/Upa3 [ACCIDENT INVOLVING SFW 6001R(AIG) & SJY 236L ON 01/06/2018]

Without Prejudice

Dear Hsiao Tong,

We are pleased to accept your offer of global sum of \$11,200.00(all-in).

Thank you.

Best Regards

Jason Tang
Kim Chwee Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Saturday, September 15, 2018 1:40 PM
To: Jason Fastech Auto (jason@fastechauto.com.sg) <jason@fastechauto.com.sg>
Subject: Your Ref: SJY 236L *Our Ref: CC6/AIG18010263/Upa3 [ACCIDENT INVOLVING SFW 6001R(AIG) & SJY 236L ON 01/06/2018]

Your Ref: **SJY 236L**
Our Ref: CC6/AIG18010263/Upa3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SFW 6001R(AIG) & SJY 236L ON 01/06/2018

We refer to the above matter.

We propose settlement at a global sum of **\$11,200.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18010263/Upa3

03 JULY 2018

LAU LIAT BENG
BLK 859 JURONG WEST ST 81
#08-584
SINGAPORE 640859

Dear Sir/Madam,

ACCIDENT INVOLVING SFW 6001R & SJY 236L ON 01/06/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SJY 236L against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG

Case Handler

DID: 6742 3197

FAX: 6741 4108

Email: chewht@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)


AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Ow Sing Fatt ("the third party claimant")
of BLK 861 Jurong West St 81 #12-606 S 640861 (address),
owner of SJY 236L (vehicle no.) hereby authorize
Kim Chuan Auto Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SJY 236L that was
damaged pursuant to the accident which occurred on 1/6/2018 (date) along
Jurong West Ave 5 (location)
involving vehicle no/s SFW 6001R ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 06 day of 06 (month) 20 18 (year)


Signed by "the third party claimant"


Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I, Kim Chwee Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK Auto Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 11200.00 (Global Sum) (repair costs), S\$ _____ (loss of use/rental) S\$ _____ (search fees) for vehicle no. SJY 236L that was damaged pursuant to the accident which occurred on 1/6/18 (date) along Jurong West Ave 5 (location) involving vehicle no/s SFW 6001R

This is pursuant to the inspection conducted on 06/06/18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner DW Sing Fatt ("third party claimant") of vehicle no. SJY 236L to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJY 236L (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.



Dated this 20 day of 09 (month) 20 18 (year)

CKS

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

TAX INVOICE

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

Tax Invoice : 20334

Date: 13.07.2018

Vehicle No: SJY236L

Make/Model: CHEVROLET ORLANDO

Chassis/Eng# :

Accident Date: 01.06.2018

Claim No : 0618-20334

:

		Amount
To proceed on repair sum	S\$	10,200.00

E. & O. E.

Total : S\$ 10,200.00

GST @ 7% : S\$ 714.00

Amount Due : **S\$ 10,914.00**


for KIM CHWEE AUTO PTE LTD

All Invoices are subjected to GST

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-085175

Date of Request: 05/06/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 05/06/2018
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. SFW6001R
Accident Date 01/06/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-085175

Date of Request: 05/06/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 05/06/2018
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. SFW6001R
Accident Date 01/06/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SFW6001R	AIG Asia Pacific Insurance Pte. Ltd.	26/05/2018-25/05/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING



















































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jun 2018 Edit Reg		06 Jun 2018 00:00 Edit Adj Rpt	\$510,200.00 Edit Estimates	\$510,200.00 View Rpt		Pending for Survey Report Cancel Case

























Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LAU LIAT BENG, ID: 56871574A, Tel: +6599999999								
Main Claimant:	OW SING FATT, ID: 51244196G								
Vehicle Reg. No.:	SJY236L	Date of Loss:	01/06/2018 08:00 - :59 [15 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3930002016SG	Policy/Cover Note No.:	1700009318 (Comprehensive) Coverage: 26/05/2018 - 25/05/2019						
Vehicle Reg. No. (Insured):	SFW6001R	Policy No. (Claimant):	5088279435-01						
		Excess:							
Repairer:	Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit, 417883 Eunos - Tel: 67465405/67417244								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 18/06/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (29/08/2018): Alert - Adj Mandate Approved (\$11276.00) - SJY236L - Claim Handler: Lee, Ming-Y... AIG_SG (11/06/2018): No Policy Found 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJY236L (3930002016SG)
[SFW6001R]
TP
OW SING FATT
Jun 1 2018 8:00AM
[LAU LIAT BENG]
Kim Chwee Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser	
Video														1 per page		<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail		Print	
1	29/06/18 16:44	Video - Accident From: OD - Reg. No: SPW6001R, Claimant: LAU LIAT BENG												Load MP4		
Letters/Correspondences														1 per page		<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown												Edit		
Photos/Images														3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print	
1	06/06/18 18:43	Chassis Number												Load JPG	<input checked="" type="checkbox"/>	
2	06/06/18 18:44	Odometer Reading												Load JPG	<input checked="" type="checkbox"/>	
3	06/06/18 18:44	General View												Load JPG	<input checked="" type="checkbox"/>	
4	06/06/18 18:44	General View												Load JPG	<input checked="" type="checkbox"/>	
5	06/06/18 18:44	General View												Load JPG	<input checked="" type="checkbox"/>	
6	06/06/18 18:44	General View												Load JPG	<input checked="" type="checkbox"/>	
7	06/06/18 18:44	General View												Load JPG	<input checked="" type="checkbox"/>	
8	06/06/18 18:44	General View												Load JPG	<input checked="" type="checkbox"/>	
9	06/06/18 18:44	General View												Load JPG	<input checked="" type="checkbox"/>	
10	06/06/18 18:44	General View												Load JPG	<input checked="" type="checkbox"/>	
11	06/06/18 18:44	General View												Load JPG	<input checked="" type="checkbox"/>	
12	06/06/18 18:44	General View												Load JPG	<input checked="" type="checkbox"/>	
13	06/06/18 18:44	General View												Load JPG	<input checked="" type="checkbox"/>	
14	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	
15	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	
16	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	
17	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	
18	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	
19	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	
20	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	
21	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	
22	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	
23	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	
24	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	
25	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	
26	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	
27	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	
28	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	
29	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	
30	06/06/18 18:45	General View												Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
31	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
32	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
33	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
34	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
35	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
36	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
37	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
38	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
39	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
40	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
41	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
42	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
43	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
44	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
45	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
46	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
47	06/06/18 18:45	General View	 Load JPG	<input checked="" type="checkbox"/>
48	06/06/18 18:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	06/06/18 18:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	06/06/18 18:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	06/06/18 18:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	06/06/18 18:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	06/06/18 18:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	06/06/18 18:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	06/06/18 18:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
81	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	06/06/18 18:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	08/06/18 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	08/06/18 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	08/06/18 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	08/06/18 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	08/06/18 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/06/18 17:16	TP GIA REPORT	 Load PDF	
2	01/08/18 15:15	LETTER TO OI	 Load PDF	
3	01/08/18 15:15	GIA SEARCH	 Load PDF	
4	03/08/18 10:18	TP ESTIMATE_MARKED	 Load PDF	
5	03/08/18 10:18	PARF_COE REBATE	 Load PDF	
6	26/09/18 09:02	WORKSHOP INVOICE	 Load PDF	
7	26/09/18 09:02	AUTHORISATION TO ACT FORM	 Load PDF	
8	26/09/18 09:02	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	14/06/18 09:18	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SFW6001R (Insd veh)	Model:	CHEVROLET ORLANDO 1.4
	SJY236L (TP veh)		TURBO (A)
Date of Accident:	01/06/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	21,205.26
Final Repair Cost	:	\$	11,200.00
Loss of Use	:	\$	6.00 days at \$60.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	11,200.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Kim Chwee Auto Pte Ltd	:	\$ 11,200.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

26 Sep
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co-Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18010263/UPA3Q2
Date: 26/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700009318
Claimant Vehicle No: SJY236L Insured Vehicle No: SFW6001R
Date of Loss: 01/06/2018 Nature of Claim: TP Claim No: 3930002016SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJY236L
Make & Model: CHEVROLET ORLANDO, 1.4 Turbo (A) Engine No: A14NET162840030
Reg. Date: 27/02/2017 (Man. Year: 2016) Chassis No: KL1YA7589HK609217
Colour: Grey Odometer: 37974 km
Engine Capacity: 1362 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Kumho 7 mm Rear Left Side: Kumho 7 mm
Front Right Side: Kumho 7 mm Rear Right Side: Kumho 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,638.00	9,082.30	6,555.70	41.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	2,300.00	1,880.00	44.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,818.00	11,382.30	8,435.70	42.57
Approved Total (Overridden) (\$\$)		10,200.00		
(\$\$)	19,818.00	10,200.00	9,618.00	48.53
+ GST 7.00/7.00% (\$\$)	1,387.26	714.00	673.26	48.53
Nett Amount (\$\$)	21,205.26	10,914.00	10,291.26	48.53
+ Loss of Use (6.0 x S\$60.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		11,276.00		
Global Sum Settlement (\$\$)		11,200.00		

INSPECTION

Date of Assignment: 06/06/2018
Date Inspected: 06/06/2018 Inspected At:

Kim Chwee Auto Pte Ltd (HQ)
1 Kaki Bukit Avenue 6 #01-48,
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER STEP PLATE	Torn	266.00 F	*160.00 FL
2	1		*REAR BUMPER UPPER	Dented / Deformed	1,930.00 F	*1,730.00 FL
3	1		*REAR BUMPER LOWER	Distorted	990.00 F	*990.00 FL
4	1		*REAR BUMPER CENTRE LOWER GARNISH (SILVER)	Torn	390.00 F	*390.00 FL
5	1		*REAR BUMPER TOWING COVER	Distorted	25.00 F	*25.00 FL
6	1		*REAR BUMPER REFLECTORS	O/S Broken	170.00 F	*85.00 FL
7	1		*REAR BUMPER REVERSE LAMP	Cracked	365.00 F	*365.00 FL
8	1		*SET REAR BUMPER REVERSE WIRING HARNESS	Not Necessary	495.00 F	*- FL
9	2		*REAR BUMPER REVERSE SENSORS	Shorted	390.00 F	*390.00 FL
10	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	124.00 F	*- FL
11	1		*REAR BUMPER INNER TOP RETAINER	Cracked	195.00 F	*195.00 FL
12	1		*TAILGATE	Badly Dented	2,160.00 F	*1,850.00 FL
13	1		*TAILGATE CHROME HANDLE	Not Necessary	290.00 F	*- FL
14	1		*TAILGATE CHEVROLET EMBLEM	Necessary	50.00 F	*50.00 FL
15	1		*TAILGATE ORLANDO EMBLEM	Necessary	48.00 F	*48.00 FL
16	1		*TAILGATE TURBO EMBLEM	Necessary	50.00 F	*50.00 FL
17	1		*TAILGATE REFLECTOR O/S	Cracked	390.00 F	*390.00 FL
18	1		*REAR WINDSCREEN	Not Necessary	880.00 F	*- FL
19	1		*REAR WINDSCREEN MOULDING	Necessary	80.00 F	*80.00 FL
20	1		*TAILGATE INNER LOCK	Twisted	245.00 F	*245.00 FL
21	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	388.00 F	*388.00 FL
22	1		*TAILGATE WEATHERSTRIP	Twisted	240.00 F	*240.00 FL
23	1		*TAILLAMPS	O/S Cracked	1,500.00 F	*729.00 FL
24	1		*REAR END PANEL	Badly Dented	970.00 F	*770.00 FL
25	1		*REAR END PANEL TOP GARNISH	Twisted	315.00 F	*315.00 FL
26	1		*REAR SPARE BRACKET & CARRIER	Bent	462.00 F	*462.00 FL
27	1		*REAR FLOOR PANEL	Repair	1,560.00 F	*- FL
28	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	490.00 F	*- FL
29	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
30	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
31	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
32	1		*REAR END PANEL SEALANT	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 15,638.00 10,077.00
 - List Item Discount on L Items 0.00/10.00% (S\$) 0.00 994.70

Total Parts (S\$) 15,638.00 9,082.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANISM	New	120.00	60.00
5	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	150.00	80.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO SPRAY RUST PROOFING	New	120.00	60.00
8	TO MOUNT VEHICLE ON CAR-O-LINER	New	380.00	0.00
9	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,500.00	800.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,100.00
Gross Labour Cost (S\$)			4,180.00	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >