

ASS. REC. BY:

REF: CS/FCI/1840270/T1cd3

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

CWS

From (Person):

Lurene jaw

of

FCI

Date/Time:

06/06/18 @ 10:17am

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 5067C

Insured:

8HA 8080R

at Workshop m/s

Tan Chong Motor

Tel:

6469 4091

of

913 Bkt timah Rd

Policy No:

Claim No:

D18004169MFST

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/05/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

10:21pm @ 6/6/18

Person Contacted:

Zuhri

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT 5067C -x
	8HA 8080R - CS/FCI/11004812/T1fn
	DoA: 4/12/2010

Tan

REF: FCI

ASSIGNMENT

From

Date: 6/6/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLT 5067C
Tan chong Motor
913 Bkt Timah Rd

at Workshop m/s

of

Insured

Policy No.

Claim No.

Sum Insured

Excess:

(Client's Record)

Make of Veh.

Zuhri

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3 days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLT 5067C

Yr Regn: 2017 Oct

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Qashqai 1.2

G.C. 1197

Colour:

white

A/C

Insured / Std / NI / NA

Sp. Reading

12329

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SJNFEAJ1142050456

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

6/6/18 @ 120

Survey held at

Tan Chong Bkt Timah

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/2/19

91787.56, 3 days

e-mail w/s; Sipah. (Red. 660f, 26%)

RECEIVED 20 MAR 2019

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation

3 + RS SI

Photos

Others

Report Format:

TP

Lump Sum / (B): IS 1787.56

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

110

50

50

21

231



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18010270/T1rd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 06-06-2018



Code : FCI2

Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	SHA 8080R	Veh. Inspected	SLT 5067C
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18004169MFSH	Excess (\$)	0.00
	Assign From	CWS (LURENE JAW)	Assign Date	06/06/2018

Vehicle Particulars & Condition

2.	Make & Model	c.c	0
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.		Colour
	Odometer	-	Steering
	Brakes		Modification
	General		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

Description of Damages

4.	
----	--

General Information

5.	Accident Date	22/05/2018	Inspection Date	06/06/2018
	Survey held at	TAN CHONG MOTOR SALES PTE LTD 913 BUKIT TIMAH RD, SINGAPORE 589623.		

Remarks

5a.	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
-----	--

MOTOR SURVEY ASSIGNMENT

Date	24-05-2018	Our Ref No. D18004169MFSH
Accident Date	22-05-2018	Claim Type. Third Party
Insured Vehicle	SHA8080R	Third Party Vehicle. SLT5067C
Survey Location	913 BUKIT TIMAH ROAD	
Contact Person.	M.ZUHRI	
Contact No.	64694091/ 67038916	Fax No. 64697472
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TAN CHONG MOTOR SALES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240733)



PRI Documents



Close



PRI Header Details

Claim No	D18004169MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TAN CHOI
Workshop Name	TAN CHONG MOTOR SALES PTE LTD (Contact Person : M.ZUHRI)	Survey Location & Contact Details	913 BUKIT TIMAH ROAD Mobile: 67038916 , Phone: 64694091 , Fax: 6469747 EmailId: ZUHRI@TANCHONG.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA8080R	TP Vehicle No	SLT5067C
PRI Recieved Date	04-06-2018 04:48:46 PM	Surveyor Appointed Date	06-06-2018 10:16:40 AM	Surveyor Accept Date	06-06-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	06-06-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5095360245

Cover : drive PREMIUM

1. Index mark and Registration Number of Vehicle : **SLT5067C**
 Chassis Number : **SJNFEAJ11U2050456**
2. Name of Policyholder : **CHIAM TAT WEI MARK**
3. Effective Date of Insurance : **31 Oct 2017**
4. Expiry Date of Insurance : **30 Oct 2018**
5. Persons or Classes of Persons entitled to drive#
 (a) The Policyholder.
 (b) Any other person who is driving on the Policyholder's order or with his/her permission.
 Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
 (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: YES
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: CHIAM TAT WEI MARK
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: OCBC BANK LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : KINETIC INSURANCE AGENCY (00000573090)
 Date of Issue : 30 Oct 2017 13:30 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S8415199H**

Name **CHIAM TAT WEI, MARK**

Birth Date **02 May 1984**

Issue Date **25 Feb 2005**

001324405E



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8415199H



Name **CHIAM TAT WEI, MARK**

詹达伟

Race **CHINESE**

Date of birth **02-05-1984**

Country/Place of birth **SINGAPORE**

Sex **M**

S8415199H




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor cars $\leq$ 3000 kg with $\leq$ 7 passengers, exclusive of the driver; and motor tractors / vehicles $\leq$ 2500 kg

PASS DATE **25 Feb 2005**

NP 428A

Licence No: S8415199H




5404975



NRIC No. **S8415199H**



Date of issue **30-12-2014**

Address **APT BLK 138A YUAN CHING ROAD
#04-115
SINGAPORE 611138**

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0203/2018
DATE : 31-MAY-2018

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR CHIAM TAT WEI, MARK
ADDRESS : BLK 138A YUAN CHING ROAD
#04-115
S(611138)
TELEPHONE NO : 94308960

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : TP-SHA8080R
VEHICLE NO : SLT5067C
MODEL CODE : FRLARDWJ11USA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017
ENGINE NO : HRA2504230A
CHASSIS NO : SJNFEAJ11U2050456
MILEAGE : 1 KM
DATE IN : 31/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ZUHRI
ACCIDENT DATE : 22/05/2018

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

01/06/2018

Taufik 97495749
WP 6/6/18 @ 1120
sur@kkauto.com
* Resurvey before paint
3 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLT5067C

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	✓
2 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	50.
3 WAP1	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	✓
4 Z2/001	REPAIR FRONT DOOR RH & RENEW FENDER RH	500.00	390.
5 Z2/002	S/PAINT FRONT FENDER RH SIDE & FRONT DOOR RH	750.00	250.
TOTAL LABOUR CHARGES		1563.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLT5067C

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 FENDER-OVER,FR	63810-4EA0A	483.00	de ✓	
2 FENDER-FRONT RH	F3100-4EAMB	622.70	bt ✓	
SUB TOTAL		1105.70	0.00	0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		221.14	0.00	0.00
GRAND TOTAL		884.56	0.00	0.00
OVERALL TOTAL		884.56		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLT5067C

TOTAL LABOUR CHARGES	1563.00
TOTAL SPARE PARTS CHARGES	884.56

GRAND TOTAL	2447.56 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0203/2018
DATE : 31-MAY-2018

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT.

OWNER'S NAME : MR CHIAM TAT WEI, MARK
ADDRESS : BLK 138A YUAN CHING ROAD
#04-115
S(611138)
TELEPHONE NO : 94308960

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SHA0080R
VEHICLE NO : SLT5067C
MODEL CODE : PHLARDNJ11USA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017
ENGINE NO : HRA2504230A
CHASSIS NO : SJNFEAJ11U2050456
MILEAGE : 1 KM
DATE IN : 31/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 22/05/2018

TATFIK LKK

DS

ZHR

LAI

\$90 X 3days

\$ 270.00

TAN CHONG MOTOR SALES PTE. LTD.

DUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLT5067C

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	120.00
2 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	50.00
3 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	93.00
4 ZZ/001	REPAIR FRONT DOOR RH & RENEW FENDER RH	500.00	390.00
5 ZZ/002	S/PAINT FRONT FENDER RH SIDE & FRONT DOOR RH	750.00	250.00
TOTAL LABOUR CHARGES		1563.00	903.00

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/S/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLT5067C

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 FENDER-OVER, FR	63810-4EA0A	483.00		OK
2 FENDER-FRONT RH	F3100-4EAMB	622.70		OK
SUB TOTAL		1105.70	0.00	0.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		221.14	0.00	0.00
GRAND TOTAL		884.56	0.00	0.00
OVERALL TOTAL		884.56		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLT5067C

NETT ITEM	1105.70
LESS 20.00%)	-221.14
NETT AMOUNT	884.56
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	0.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	0.00
TOTAL LABOUR CHARGES	903.00
TOTAL SPARE PARTS CHARGES	884.56
TOTAL CHARGES	1787.56
ADD 7 % GST	125.13
GRAND TOTAL	1912.69



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010270/T1cd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-03-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8080R	Veh. Inspected	SLT 5067C	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18004169MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	06/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI 1.2	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	SJNFEAJ11U2050456	Colour	WHITE	
Odometer	12329	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	CONTINENTAL	6 mm	
L/H Front Tyre	215/60 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/05/2018	Inspection Date	06/06/2018	
Survey held at	TAN CHONG MOTOR SALES PTE LTD 913 BUKIT TIMAH RD, SINGAPORE 589623.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 5067C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FENDER-OVER,FR (N)	DEFORMED	483.00	483.00
1	FENDER-FRONT RH (N)	BENT	622.70	622.70
	LESS 20% DISCOUNT		-221.14	-221.14
			884.56	884.56
LABOUR				
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.		120.00	120.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.		100.00	50.00
	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION-PASSENGER.		93.00	93.00
	REPAIR FRONT DOOR RH & RENEW FENDER RH.		500.00	390.00
	S/PAINT FRONT FENDER RH SIDE & FRONT DOOR RH.		750.00	250.00
			1,563.00	903.00
GRAND TOTAL			2,447.56	1,787.56
RECOMMENDED COST OF REPAIRS				1,787.56

Report Ref No. CS/FCI18010270/T1cd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.