

W/11213 wal
ASS. REC. BY: Marcus

REF:

MS14/ CC3/MS61/8010271/USb yv

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SLK 657ET
at Workshop nite: PL
of: _____
Insured: 6777406
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SLK 657ET Yr Regn: 1/17
Type: M.Car / M.Cyola / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CAI
Make: Mercedes Mobilio 1497
Colour: Blue A/C: Insured / Std / Nil / NA
Sp. Reading: 35543 T/Radio: Insured / Std / Nil / NA
Eng No: _____
C/Nr: M R H D D 4 8 7 0 6 P 0 0 0 3 4 8
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or ok
Brake: In order / Jammed / Leaked / Burnt or _____
Mod: Nil / STD A/Rim or _____
Tyre Size: F: 185/65 R15
R: _____
BS / EXNOVA / GY / FS / LIZA / MIC / OHTSU / FIR / SUMI /
TOYO / YOKO or _____

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: _____
IDAC Accident Report Consistent?: Yes or No
Q/R PR Seen Consistent?: Yes or No
Est. Repairs: 4 days Res: Yes or No
Lum Sum: 5 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front: _____ Rear: _____
R/Bal: 7 mm R/Bal: 7 mm
L/Bal: 7 mm L/Bal: 7 mm
D.O.A: stable D.O.A: 6/6/18
Survey held at: _____
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Recfry or
MS Rpt
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction
* note new parts replacement.
1/2/18 confirm repair sum \$4000 with Alan (\$3,522.30 Red - 68%).
* parts prices checked by Marcus.
* undercarriage checked by Simon

Date/Time, File Pass to/ 23/07/18
1: Typist
Date/Time, File Return to/

Days Of Repair: 4
Resurvey No. of Trip: 2

Report Format: _____
Lump Sum / I.B.I: (\$ 4,000.00 Hs)

Add Fee: Site Insp (\$ _____)
 Interview (\$ _____)
 Tech. Inv (\$ _____)
 Weekend (\$ _____)

Survey Fee:	
Transportation:	
\$ > RS: \$	
Food:	
Others:	
TOTAL:	

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8323J
Vehicle Details	
Vehicle No.:	SLK6575T
Vehicle to be Exported:	No
Intended De-registration Date:	06 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	MOBILIO SV 1.5 CVT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	L15Z12874015
Chassis No.:	MRHDD4870GP000348
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,980.00
Original Registration Date:	23 Jan 2017
First Registration Date:	23 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$18,980.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jan 2027
PARF Rebate Amount:	\$14,235.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,751.00
COE Rebate Amount:	\$42,916.00
Total Rebate Amount:	\$57,151.00

The information contained herein is correct as at 06 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/06/2018 11:44
Date Of Accident	05/06/2018 08:40
Exact Location Of Accident	@ WAN LEE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK6575T
Insured/Policyholder	
Name Of Registered Owner	LIM HONG SENG JACKSON
NRIC No	S8518323J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96221763
Alternative Phone No	OFFICE-96221763

Vehicle Particulars

Manufacturer	HONDA
Model	MOBILIO SV 1.5 CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097186596
Cover Note Number	

Driver

Name of Driver	LIM HONG SENG JACKSON
NRIC No	S8518323J
Date Of Birth	11/06/1985
Occupation	INDOOR
Date Of Driving Pass	07/03/2011
Driving Experience	7 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96221763
Fax Number	
Contact Number	OFFICE-96221763
EMail Address	NOEMAIL

Address	BLK 342A #15-1912 YISHUN RING ROAD YISHUN NATURA
Postcode	761342
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ7740G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

05 JUN 2018



Driver's Signature

(If driver is not the policyholder)
Date & Time:

05 JUN 2018

IDAC KAKI BUKIT(VAC)

23 KAKI BUKIT AVE 4

Singapore 415933


Reporting Centre Personnel's Signature

Name: Tel: 67492305

Fax: 67492305

NRIC/IN No. Email: vacb@singnet.com.sg

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the above date and time. I was at Wan Lee
Road behind of vehicle B. Suddenly the van reversed
and hit on my LH portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Jaisan

Policyholder's Signature
Date & Time:

Jaisan

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 415933
Tel: 67416607
Fax: 67492905
Reporting Centre Personnel's Signature
Name: Email: vackb@singnet.com.sg
NRIC/FIN NO.:

05 JUN 2018

05 JUN 2018

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6
 #01-46/48/50 Autobay
 SINGAPORE 417883

NOT ALLOWED
 Repair Sum \$4000
 6/6/18
 Ydy.

VEHCILE NO:SLK 6575T

QTY	PARTICULAR	AMOUNT
1 PCS	HEADLAMP N/S	11 \$645.20 X
1 PCS	FRONT BUMPER 481.20	Rep/cur \$815.30 ✓
1 PCS	FRONT BUMPER SIDE HOLDER N/S	but \$28.50 ✓
1 PCS	FRONT BUMPER CLIPS	ner \$39.00 ✓
1 PCS	FRONT FENDER N/S 270.60	in/ner \$365.30 ✓
1 PCS	FRONT FENDER INNER SHIELD N/S 92.40	re/ner \$188.20 ✓
1 SET	FRONT FENDER INNER SHIELD CLIPS N/S	ner \$30.00 ✓
1 PCS	FRONT DOOR N/S 650	body/ner \$866.20 ✓
1 PCS	FRONT DOOR INNER LOCK N/S	11 \$395.30 X
1 PCS	FRONT DOOR INNER RUBBER N/S 111.20	ner \$182.30 ✓
1 PCS	FRONT DOOR INNER TRIM BOARD N/S	11 \$606.20 X
1 PCS	FRONT DOOR GLASS REGULATOR N/S	11 \$311.30 X
1 PCS	FRONT DOOR GLASS REGULATOR MOTOR N/S	11 \$420.50 X
1 PCS	FRONT DOOR MIRROR COVER N/S	cur \$120.80 ✓
1 PCS	FRONT DOOR MIRROR ASSY N/S 227.90	daye \$365.30 ✓
1 SET	FRONT DOOR FRAME BLACK STICKER	ner \$68.00 ✓
2 PCS	FRONT DOOR HINGES @\$88.50	11 \$179.00 X
1 PCS	FRONT DOOR CHECKER N/S	11 \$66.30 X
1 PCS	FRONT DOOR OUTER PILLAR N/S	ner \$522.30 X
1 PCS	FRONT SPORT RIM N/S	cur/ner \$880.00 3505w
1 PCS	FRONT LOWER ARM N/S	11 \$392.30 X
1 PCS	FRONT KNUCKLE ARM N/S 366.20	but \$488.20 ✓
1 PCS	FRONT KNUCKLE ARM BEARING N/S 111.80	ner \$285.00 ✓
1 PCS	FRONT SHOCK ABSORBER N/S	11 \$322.30 X
		\$8,582.80
	LABOUR CHARGES:	
	TO CHECK WIRING	\$80.00 30
	TO CONDUCT WHEEL ALIGNMENT	\$120.00 60
	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE	\$180.00 120
	TO TRANSFER FRONT DOOR MECHANISM	\$100.00 60
	TO SPRAY RUST PROOFING	\$150.00 80
	TO DISMANTLE & REFIX FRONT WINDSCREEN	11 \$150.00 X
	TO DISMANTLE & REFIX FRONT DASHBOARD	11 \$380.00 X

297
 2597.3
 2077.84

LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$1,280.00 530
\$1,500.00 900

TOTAL

\$12,522.80

4227.84
57

4016

UK's Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party involvement on a "Without Prejudice" basis
- No legal notification (9) is allowed
- Supplemental work(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Jun 2018		08 Jun 2018 15:27 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GOLDBELL LEASING PTE LTD , Co. Reg. No.: 199001196N								
Main Claimant:	LIM HONG SENG JACKSON , ID: S85183233								
Vehicle Reg. No.:	SLK6575T	Date of Loss:	05/06/2018 08:00 - :59 [16 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 560644	Policy/Cover Note No.:	29004183MKF (Third Party Only) Coverage: 20/08/2017 - 31/08/2018						
Vehicle Reg. No. (Insured):	GZ7740G	Policy No. (Claimant):							
		Excess:	S\$5,000.00						
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Daniel Chong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 09/06/2018]								
Driver/Custodian (Insured):	MUHAMMAD SYAFIL BIN ARSHAD (), NRIC: S84073493, Tel: +6597567586								
Adj Asg. Remarks:	100% AGAINST OI - OI REVERSE ONTO TP DIRECT SURVEY BY LKK								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLK6575T (560644)**
[GZ7740G]
TP
LIM HONG SENG JACKSON
Jun 5 2018 8:00AM
[GOLDBELL LEASING PTE LTD]
Fastech Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="checkbox"/>
Assessment Reports			1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/06/18 09:28	Accident Statement From: SC - Reg. No: GZ7740G, Claimant: GOLDBELL LEASING PTE LTD	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/07/18 16:10	Chassis Number	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	23/07/18 16:10	Odometer Reading	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
30	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
31	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
32	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
33	23/07/18 16:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	23/07/18 16:10	General View	Load JPG	<input checked="" type="checkbox"/>
35	23/07/18 16:10	General View	Load JPG	<input checked="" type="checkbox"/>
36	23/07/18 16:10	General View	Load JPG	<input checked="" type="checkbox"/>
37	23/07/18 16:10	General View	Load JPG	<input checked="" type="checkbox"/>
38	23/07/18 16:10	General View	Load JPG	<input checked="" type="checkbox"/>
39	23/07/18 16:10	General View	Load JPG	<input checked="" type="checkbox"/>
40	23/07/18 16:10	General View	Load JPG	<input checked="" type="checkbox"/>
41	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	23/07/18 16:11	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/06/18 09:28	TPD SLK6575T GIA REPORT.PDF	Load PDF	
2	08/06/18 09:28	DIRECT SURVEY EMAIL - SLK6575T.pdf	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18010271/USBQ2

Date: 23/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29004183MKF
 Claimant Vehicle No: SLK6575T Insured Vehicle No: GZ7740G
 Date of Loss: 05/06/2018 Nature of Claim: TP Claim No: 560644

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK6575T**
 Make & Model: HONDA MOBILIO SV, 1.5 CVT (A) Engine No: L15Z12874015
 Reg. Date: 23/01/2017 (Man. Year: 2016) Chassis No: MRHDD4870GP000348
 Colour: Blue Odometer: 35543 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
 Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm
 Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,582.80	2,428.08	6,154.72	71.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,940.00	1,800.00	2,140.00	54.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,522.80	4,228.08	8,294.72	66.24
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	12,522.80	4,000.00	8,522.80	68.06
+ GST 7.00/7.00% (S\$)	876.60	280.00	596.60	68.06
Nett Amount (S\$)	13,399.40	4,280.00	9,119.40	68.06

INSPECTION

Date of Assignment: 08/06/2018
 Date Inspected: 06/06/2018 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Jul 2018)
Parts: M1-MPV	HONDA MOBILIO SV 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK6575T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP N/S	Not Necessary	645.20 F	*- FL
2	1		*FRONT BUMPER	Deep Cut	815.30 F	*481.20 FL
3	1		*FRONT BUMPER SIDE HOLDER N/S	Bent	28.50 F	*28.50 FL
4	1		*FRONT BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
5	1		*FRONT FENDER N/S	Dented / Bent	365.30 F	*270.60 FL
6	1		*FRONT FENDER INNER SHIELD N/S	Deformed / Warped	188.20 F	*92.40 FL
7	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	30.00 F	*30.00 FL
8	1		*FRONT DOOR N/S	Badly Dented	866.20 F	*650.00 FL
9	1		*FRONT DOOR INNER LOCK N/S	Not Necessary	395.30 F	*- FL
10	1		*FRONT DOOR INNER RUBBER N/S	Necessary	182.30 F	*111.20 FL
11	1		*FRONT DOOR INNER TRIM BOARD N/S	Not Necessary	606.20 F	*- FL
12	1		*FRONT DOOR GLASS REGULATOR N/S	Not Necessary	311.30 F	*- FL
13	1		*FRONT DOOR GLASS REGULATOR MOTOR N/S	Not Necessary	420.50 F	*- FL
14	1		*FRONT DOOR MIRROR COVER N/S	Cut	120.80 F	*120.80 FL
15	1		*FRONT DOOR MIRROR ASSY N/S	Damaged	365.30 F	*227.90 FL
16	1		*SET FRONT DOOR FRAME BLACK STICKER	Necessary	68.00 F	*68.00 FL
17	2		*FRONT DOOR HINGES	Not Necessary	179.00 F	*- FL
18	1		*FRONT DOOR CHECKER N/S	Not Necessary	66.30 F	*- FL
19	1		*FRONT DOOR OUTER PILLAR N/S	Repair	522.30 F	*- FL
20	1		*FRONT SPORT RIM N/S	Cut / Bent	880.00 FS	*350.00 FS
21	1		*FRONT LOWER ARM N/S	Not Necessary	392.30 F	*- FL
22	1		*FRONT KNUCKLE ARM N/S	Bent	488.20 F	*366.20 FL
23	1		*FRONT KNUCKLE ARM BEARING N/S	Necessary	285.00 F	*111.80 FL
24	1		*FRONT SHOCK ABSORBER N/S	Not Necessary	322.30 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,582.80	2,947.60
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	519.52
Total Parts (S\$)	8,582.80	2,428.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
3	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE	New	180.00	120.00
4	TO TRANSFER FRONT DOOR MECHANISM	New	100.00	60.00
5	TO SPRAY RUST PROOFING	New	150.00	80.00
6	TO DISMANTLE & REFIX FRONT WINDSCREEN	New	150.00	0.00
7	TO DISMANTLE & REFIX FRONT DASHBOARD	New	380.00	0.00
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,280.00	550.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	900.00
Gross Labour Cost (S\$)			3,940.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >