

ASS. REC. BY:

REF: es/FCI18010290/ T1sdb 02

Special Instruction:

Surveyor: Tauhitch
CWS
From (Person): Eileen lee

ASSIGNMENT (Office)

of FCI

Date/Time: 6/6/18

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLW 853S

Insured: SHA 1728C

at Workshop m/s

Cycle & Carriage Automotive
209 Pandan Gardens

Tel: 65684501 / 65684555

Policy No:

Claim No: D18004485 MPST

Sum Insured:

Excess:

Make of Veh:

D.O.A. 01/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

11.06.2018 @ after 1pm

H.O.D. Endorsement:

Date/Time: 2:07pm @ 6/6/18

Person Contacted: Tay

Vehicle IN OUT

Date/Time	Action/Instruction (✓) : Estimate
	<u>SLW 853S - X</u>
	<u>SHA 1728C - CS/FCI 16014560/h3</u>
<u>12/06/18 @ 17:34 p.m.</u>	<u>revised PA to Eileen via email.</u>

NOA: 02/08/16

Signature: *Tauflich*

REF: FCI

ASSIGNMENT

From: _____ Date: 11/6/18

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: STW 853S

at Workshop m/s Cycle & Carriage Automotive

of 209 Pandan Gardens

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record) after 1pm

Make of Veh: Tay

N/S		O/S	
<input checked="" type="checkbox"/>			

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (w/p)

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLW 853S Yr Regn: 2/18 Jan.

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Mitsubishi Attrage C.C. 1193

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 3958 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MWBST.A13A.J400092

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 185/55R17 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 11/6/18

Survey held at C&C Pandan Gdn

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

05/09/18 | Confirmed P/P \$ 2,902.00 @ 3 days with Tauflich

(\$ 3,906.00 Red - 57%)

RECEIVED 06 SEP 2018

Date/Time. File Pass to? 05/09/18

1) Typist : Preli. Report : Final Report

Date/Time. File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$ 2,902.00 r/p)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech Invs (\$)
 Weekend (\$)

Survey Fee:	145
Transportation:	50
S + RS + SI	50
Photos:	31
Others:	
TOTAL:	276



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18010290/T1sd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 06-06-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 1728C	Veh. Inspected	SLW 853S
Policy No.		Coverage (\$)	0.00
Claim No.	D18004485MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	06/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	01/06/2018	Inspection Date	
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	05-06-2018	Our Ref No. D18004485MFSH
Accident Date	01-06-2018	Claim Type. Third Party
Insured Vehicle	SHA1728C	Third Party Vehicle. SLW853S
Survey Location	209 PANDAN GARDENS	
Contact Person.	TAY JIAN YE	
Contact No.	65684555/ 0	Fax No. 65691056
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241121)



PRI Documents



Close



PRI Header Details

Claim No	D18004485MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CYCLE & (LIMITED
Workshop Name	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (Contact Person : TAY JIAN YE)	Survey Location & Contact Details	209 PANDAN GARDENS Mobile: 0 , Phone: 65684555 , Fax: 65691056 EmailId: JIANYE.TAY@CYCLECARRIAGE.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA1728C	TP Vehicle No	SLW853S
PRI Recieved Date	05-06-2018 06:33:47 PM	Surveyor Appointed Date	06-06-2018 12:53:53 PM	Surveyor Accept Date	06-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	06-06-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------

NOTICE OF REPORTING

This is to confirm that GOH WEE CHUANG IVAN, FIN: S7426742D, has reported to the Police a non-injury traffic accident which occurred at PAN ISLAND EXPRESSWAY (PIE) near to Eunos Link on 01/06/2018 at 10:10p.m. involving the following vehicles:

- a) SLW853S (Mitshubishi/ Silver)
- b) SHA1728C (Hyundai/ Blue)

2. If accident was reported to the Police within 24 hrs of its occurrence, then he has complied with Sec 84(2) of the Road Traffic Act, Cap 276.



Rank / Name of Issuing officer: **Sgt (2) T170002 Koh Wen Rui**

Date: 01/06/2018

Time: 2230hrs

S/D Ref: 124

Police Post/ Unit: BEDOK NORTH NPC

Bedok North NPC
No. 30 Bedok North Road
Singapore 469676
Tel: 1800-2449999

Original - To be issued to informant
Duplicate- to be submitted to Traffic Police

Handwritten note:
2230hrs ✓
IVAN GOH
S7426742D



CERTIFICATE OF INSURANCE

CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Goh Wee Chuang Ivan (Wu Weichuan Ivan)
Period of Insurance : 29 Jan 2018 To 28 Jan 2019
Engine No. : 3A92UGP2603
Chassis No. : MMBSTA13AJH000992

Vehicle No. : SLW853S
Policy No. : 1800008273
Endorsement No. :
Issued Date : 09 Feb 2018

ABOUT THE COVER

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT
Engine Capacity/Tonnage : 1,193.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Goh Wee Chuang Ivan (Wu Weichuan Ivan - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Customer Service Centres (For windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708888
2. Cycle & Carriage Customer Service Centre (For windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67481000
3. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65884501

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1969 (Malaysia).

0500722050

C&C FULCO-CORPORATE
 22 UBI ROAD 4 FULCO BUILDING
 SINGAPORE 408617 ANSP-MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S7426742D**

Name: **GOH WEE CHUANG IVAN
(WU WEICHUAN IVAN)**

Birth Date: **18 Aug 1974**
Issue Date: **07 Apr 2003**

000358783D




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S7426742D**

Name: **GOH WEE CHUANG IVAN
(WU WEICHUAN IVAN)**
吴伟川

Race: **CHINESE**

Date of birth: **18-08-1974** Sex: **M**

Country of birth: **SINGAPORE**






YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 **Motor Cars and Motor Tractors the weight of which unladen does not exceed 3500 kilograms**

PASS DATE: **18 May 1998**

NP 426A

License No: **S7426742D**



3804373

NRIC No. **S7426742D**

Date of issue: **25-08-2004**

APT BLK 482 TAMPINES STREET 44 #05-76
SINGAPORE 520462

NRIC No: **S7426742D** Date: **25/01/2016**






CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED*
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for MR GOH WEE CHUANG IVAN (WU WEICHUAN IVAN) and vehicle specifications like SLW853S, MMBSTA13AJH000992.

Main items table with columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No, Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various repair services and parts with handwritten notes and calculations.

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for MR GOH WEE CHUANG IVAN and vehicle specifications like Reg No, Date, Chassis No, Engine No, Make/Model, and Colour/Trim.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: CSM00041, Cash, 04/06/2018/ 13:46, 465 / Tay Jian Ye, 26635

Table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Row 1: M ANT,KEYLESS OPERATION,RR, 1.00, 95.00, 00.00, 95.00

Estimate

SURVEYOR NAME: Tanjun 97425349
SURVEYOR SIGNATURE: [Signature]
DATE: 11/6/18 5pm
REMARKS: Resurvey before paint 02 days
SVC@thelinks.com

[Signature] 13/6/18

Table with 2 columns: Confirm & accepted by, LKK Auto Consultants notice. Includes a list of conditions for resurvey and a summary of costs: Net 6,808.00, 7% GST on 476.56, Total Payable 7,284.56.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



Exceptional Journeys

Surveyor : Taufikh

Company : LKK

VEHICLE NO : SLW853S

MODEL : MIT/18MY ATTRAGE 1.2 CVT

WIP : 26635

Material	:	\$	857.00
Labour	:	\$	2,045.00
Sub-Total	:	\$	2,902.00
	:		
Less Excess	:	\$	-
Total	:	\$	2,902.00
GST 7%	:	\$	203.14
Grand Total	:	\$	3,105.14
Finalise By/Date	:	<u>JoJo dtd 29/08/2018</u>	

Email :

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 3 WORKING DAYS + Days () Weekends
+ Days () Public Holiday
TOTAL DAYS REPAIR TOOK = 3


TP Claim FIRST CAPITAL - SHA1728C

Claim GIA / LTA fee

Claim Loss Use Rental

Claim Medical Fee / Others

Third Party Report



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MS FIRST CAPITAL INSURANCE LIMITED MOTOR CLAIMS DEPARTMENT 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 Contact No 12/06/	Cust No/Name /MR GOH WEE CHUANG IVAN (WU WEIC Reg No/Reg Date SLW853S / 29/01/2018 Date In/Mileage 12/06/2018/ 39581 Chassis/Package MMBSTA13AJH000992 /DC17S3C Engine No 3A92UGP2603 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	29/08/2018/ 12:28	TLT	881 / Jojo Cheng	26635

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				✓ 30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 200.00
M SUNDRY SUNDRIES				✓ 20.00
S SPECIALISTJOB RENEW REAR BUMPER & REPAIR LH REAR FENDER (550 + 225)				775.00
S SPECIALISTJOB RESPRAY REAR BUMPER & LH REAR FENDER (420 + 420)				840.00
S SPECIALISTJOB TRANSFER REAR PARKING SENSOR TO NEW PART				✓ 60.00
S SPECIALISTJOB REMOVE AND REFIT REAR BOOT TRIM TO FACILIATE FOR REPAIR				✓ 120.00
X BRACKET,RR BUMPER,LH	1.00	27.00	00.00	✓ 27.00
X FACE,RR BUMPER	1.00	740.00	00.00	✓ 740.00
X BUZZER,KEYLESS OPERATIO,RR	1.00	90.00	00.00	✓ 90.00
Z TEXT FIRST CAPITAL TP CLAIM SHA1728C DOA: 01/06/2018 SURVEYOR: TAUFIKH LKK 11/06/2018				

"Guarantee your warranty, maintain with Cycle & Carriage."

Parts	857.00	Nett	2,902.00
Labour	230.00	7% GST on	2902.00
Standard Menu	0.00		
Specialist Job	1,795.00	Total Payable	3,105.14
Diagnostics Job	0.00		
Sundry/Others	20.00		
Total(w/o GST)	2,902.00		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010290/T1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-09-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 1728C	Veh. Inspected	SLW 853S
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18004485MFSH	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	06/06/2018
2. Vehicle Particulars & Condition			
Make & Model	mitsubishi attrage	c.c	1193
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MMBSTA13AJH000992	Colour	SILVER
Odometer	3958	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/55 R15	BRIDGESTONE	6 mm
L/H Front Tyre	185/55 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	185/55 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	185/55 R15	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/06/2018	Inspection Date	11/06/2018
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 853S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BRACKET,RR BUMPER,LH (SN)	NECESSARY	27.00	27.00
1	BRACKET,RR BUMPER,RH (SN)	NOT NECESSARY	27.00	-
1	FACE,RR BUMPER (SN)	DEFORMED	740.00	740.00
10	CLIP,FR BUMPER (SN)	NOT NECESSARY	30.00	-
1	PANEL,RR END (SN)	TO REPAIR SEE LABOUR	421.00	-
1	TRIM,RR END (SN)	NOT NECESSARY	65.00	-
1	BOARD,TRUNK ROOM FLOOR (SN)	NOT NECESSARY	193.00	-
1	DUCT,RR VENTILATOR (SN)	NOT NECESSARY	30.00	-
1	COVER,RR VENTILATOR (SN)	NOT NECESSARY	40.00	-
1	BUZZER,KEYLESS OPERATIO,RR (SN)	CRACKED	90.00	90.00
1	ANT,KEYLESS OPERATION,RR (SN)	NOT NECESSARY	95.00	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	BODY SEALANT (SN)	NOT NECESSARY	120.00	-
1	PARKING SENSOR (SN)	NOT NECESSARY	220.00	-
			2,148.00	877.00
LABOUR				
	TO SUPPLY ZENOTNA PAINT PROTECTION.	NOT NECESSARY	240.00	-
	TO RENEW REAR BUMPER WELD AND CUT END PANEL AND REPAIR LH REAR FENDER.INCLUSIVE OF THE REPAIR OF PANEL,RR END.		2,200.00	775.00
	PAINT WORK SPRAY REAR BUMPER,END PANEL,REAR LH FENDER.		1,680.00	840.00
	TO TRANSFER REAR PARKING SENSOR TO NEW PART.		60.00	60.00
	TO REMOVE AND REFIT REAR BOOT TRIM TO FACILITATE FOR REPAIR.		150.00	120.00
	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.		50.00	30.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
	TO APPLY ANTI COROSSION.	NOT NECESSARY	80.00	-
			4,660.00	2,025.00
GRAND TOTAL			6,808.00	2,902.00



RECOMMENDED COST OF REPAIRS			2,902.00
-----------------------------	--	--	----------

Report Ref No. CS/FCI18010290/T1sd3n2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.