

INSRS  
WSP:  
Tel:  
Liability  
BMS

<b>PRELIMINARY ADVICE</b>		Date/Time:	Sent By:	Post-Repair Photos:	Others:
<b>FINALIZATION</b>		Date/Time:	Confirm with:	Confirm by:	
Repair Cost:	\$5	days	Reduction:	%	Email <input type="checkbox"/> Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b>		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	%	100	(Agreed / Assessed)	BOLA S/N No.:	15
Repair Cost:	\$5	1,295.82			
Loss of Rental (LOR):	\$5	250.80	2 days	125.40	VIDEO
Loss of Use (LOU):	\$5	100	50	2 days	
Loss of Income (LOI):	\$5	100	50	2 days	
LOR only <input type="checkbox"/>	LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LO <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search:	\$5	7.49			
Medical:	\$5	-			
Disbursement:	\$5	-	(e.g. Tow/ Independent)		
Legal Cost:	\$5	7,654.11			
<b>Total:</b>	\$5		<b>Global Sum \$5:</b>	1,650	
<b>FINAL PAYMENT</b>		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	\$5	1,650	Name 1:	COMFORTABLE GLO ENGINEERING PTE LTD	
Payee 2: (Strike if N.A.)	\$5	X	Name 2:	X	
Payee 3: (Strike if N.A.)	\$5		Name 3:		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18010300/K1jb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 06-06-2018		
		Code : ASM		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YM 4495P	Veh. Inspected	SHA 4441J	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	06/06/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	03/06/2018	Inspection Date	05/06/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

A member of COMFORTDELGRO

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: JC NO305169626

STOMER	REGN NO: SHA4441J	MILEAGE
COMFORT TRANSPORTATION PTE LTD VARS	MAKE: TOYOTA	FUEL
7010045	MODEL: PRIUS HYBRID(G4)04.06.2018 12:30	E 1/2 F
STOMER NO. 383 SIN MING DRIVE	YR OF MANU. 14.09.2016	DATE/TIME IN
ADDRESS Singapore SINGAPORE 575717	CHASSIS CODE JTDKB3FU503529425	TARGET DATE
65508755 (R) (P)		COMPLETION DATE/TIME
COUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 03.06.2018  
NATURE: 3P 03.06.2018

S/NO LABOR CODE DESCRIPTION

AXIA - Left Side Mirror

CHECKED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHA4441J LARRY

Vehicle No.: SHA4441J

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305169626

Date : 7. Jun. 2018

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No : SHA4441J

Date of Accident: 03/06/18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AXA YM4495P

2. The finalized amount shall be:

(a) Spare Parts after List discount \$1,111.05

(b) Labour Charges \$100.00

**Total for Part-By-Part Repair Cost \$1,211.05**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: \_\_\_\_\_

**Final Lumpsum Repair cost** \_\_\_\_\_

3. Estimated normal period for repairs: 1 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : Larry Ng

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : Kahl

Name : Kahl

Date : 7/6/18

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Final Amount Subject to Insurance Approval

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305169626  
REGN NO : SHA4441J  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4)  
DATE OF REGN : 14.09.2016  
DATE/TIME IN : 04.06.2018 12:30  
ACCIDENT DATE : 03.06.2018

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0302-0600-G	PRIG4 MIRROR ASSY OUTER R	1	1,374.00	25.00	1,030.50
0002 04-01-0302-0897-G	PRIG4 COVER OUTER MIRROR	1	107.40	25.00	80.55

SUB-TOTAL : 1,111.05

## JOB NATURE

0000 L	PANEL BEATING				50.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA				50.00

SUB-TOTAL : 100.00

TOTAL : 1,211.05

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE\***

VEHICLE NO : SHA4441J

MAKE : TOYOTA

MODEL : PRIUS

AXA

DoA: 03-06-18

Date: 05.06.2018

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Side Mirror Assy - LH <i>one</i>			\$ 1,374.00
1	Side Mirror Cover - LH <i>missing</i>			\$ 107.40
SUB TOTAL				\$ 1,481.40
LESS 25%				370.35
DISCOUNTED TOTAL				\$ 1,111.05
				\$ 0.00
<b>Labour Charge</b>				
1	Panel Beating			\$ <del>150.00</del> <sup>50</sup>
1	Spray Painting Charge			\$ <del>200.00</del> <sup>50</sup>
1	Wiring Charge			\$ <del>50.00</del> <sup>50</sup> <i>Xm</i>
TOTAL LABOUR				\$ 400.00
ESTIMATE TOTAL				\$ 1,511.05

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*Kahin (Clerk)*  
*5/6/18 1505hrs*  
*1 Day*  
*PIP*  
*Before part photo*

Page 1 of 1

LKK Auto Consultants hence notify

the Repairer to be aware of the following conditions:

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





## Joy Irene (LKKAUTO)

---

**From:** Joy Irene (LKKAUTO)  
**Sent:** Friday, 13 July 2018 3:39 PM  
**To:** 'transcon@singnet.com.sg'; 'cychen@transconcorde.com';  
'trabsconcorde@singnet.com.sg'  
**Cc:** Admin A  
**Subject:** ACCIDENT INVOLVING YM 4495P AND SHA 4441J ALONG KILLINEY ROAD ON 03.06.2018  
  
**Importance:** High

### TRANS CONCORDE SERVICES PTE LTD

Policy Holder

Dear Sir/Madam,

**OUR REF : CC4/ASM18010300/K1jb3**  
**YOUR REF : YM 4495P**

### ACCIDENT INVOLVING YM 4495P AND SHA 4441J ALONG KILLINEY ROAD ON 03.06.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s COMFORTDELGRO ENGINEERING PTE LTD, acting on behalf of the owner of SHA 4441J against your motor insurance policy.

Based on the accident reports, there is an available video evidence from SHA 4441J. As such, we will be reviewing the evidence presented and should the scene showed that our liability is down, we will be proceeding to negotiate for an amicable settlement of the claim.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [jovirene@lkkauto.com](mailto:jovirene@lkkauto.com) within 7 days from the date of this letter if not provided at AXA's reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license
- Letter of Authorization that your driver is allowed to drive

- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact the undersigned.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,  
 Joy Irene | Case Handler  
 LKK Auto Consultants Pte Ltd  
 DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

**LETTER OF AUTHORISATION**

(NAF / PAF)

**ACCIDENT INVOLVING  
ALONG****TOYOTA PRIUS SHA4441J , YM4495P  
KILLINEY RD TWDS SOMERSET RD****ON 03-Jun-18 20:15**

I / We

**LOW KWONG YEW**(Hirer) NRIC No.: **S1298279H**

and/or

**HO ROBERT PERRY**(Relief) NRIC No.: **822120**

Taxi Number

**SHA4441J**

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date

**04-Jun-2018**

Name of Hirer

**LOW KWONG YEW**

Hirer NRIC

**S1298279H**

Signature :



Address

**232 TAMPINES STREET 21 #05-639  
521232**

Contact No.

**90084612**

Name of Relief

**HO ROBERT PERRY**

Relief NRIC

**822120**

Signature :



Address

**120B EDGEALE PLAINS 08-285  
822120**

Contact No.

**91699661**



redefining / insurance

CLAIM REF : S8M00JLH  
INSURED : TRANS CONCORDE SERVICES PTE LTD

# DISCHARGE VOUCHER

We, **ComfortDelgro Engineering Pte Ltd** confirm that by letter of authorisation dated **04 June 2018**, we are authorised to and do hereby give this discharge for ourselves and on behalf of **Comfort Transportation Pte Ltd** and the Hirer **LOW KWONG YEW** of vehicle no. **SHA 4441J**

Now we **ComfortDelgro Engineering Pte Ltd** for ourselves and the said Hirer and the driver jointly and severally:-

- agree to accept the sum of Singapore Dollars **ONE THOUSAND SIX HUNDRED FIFTY ONLY (S\$1,650.00)** in the aggregate in full and final settlement of all claims of whatever kind including damages for personal injuries and/or damage to property that all and any of us may have against **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no **(YM 4495P)** arising out of an accident with **(SHA 4441J)** on **03.06.2018**.
- declare that **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of the Insured vehicle shall not be liable for any further claim(s) whatsoever or howsoever present or future that any of us may have against **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no. **(YM 4495P)** arising directly/indirectly as a consequence of the accident and hereby give our full and final discharge.
- We hereby declare that I/we am/are the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made in favour of **ComfortDelgro Engineering Pte Ltd** is made without any admission of liability whatsoever on the part of **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no. **(YM 4495P)**.

Dated this 16<sup>th</sup> day of August 2018

Signed by \_\_\_\_\_  
(AUTHORISED SIGNATORY)

Company Stamp \_\_\_\_\_

Witness : \_\_\_\_\_

Name : \_\_\_\_\_

I/C No : \_\_\_\_\_

Address : \_\_\_\_\_

Please forward your cheque made payable to:  
**COMFORTDELGRO ENGINEERING PTE LTD**

AXA Insurance Pte Ltd (Company Reg. No. 199903512M)  
8 Shenton Way, #24-01 AXA Tower, Singapore 068811  
Customer Centre #B1-01  
Tel: +65 6880 4868 Fax: +65 6336 2522 Website: www.axa.com.sg

"The contents of this document apply to vehicle damages only.  
All personal injuries and damages arising therefrom are excluded  
from the ambit and application of this document"

GST REG. NO. M2-8921817-3

## TAX INVOICE

COMPANY REG. NO.: 199506046W

Page: 1

8010010

AXA INSURANCE PTE LTD

#24-01 8 SHENTON WAY AXA TOWER  
SINGAPORE SG 068811

CONTACT NO: 63387288

Description : 3P 03.06.2018

VEHICLE NO  
SHA4441J

MARK  
TOYOTA

MODEL  
PRIUS HYBRID(G4)

DATE OF REG  
14.09.2016

CHASSIS CODE  
JTDKB3PU503529425

INV. NO/DATE  
91381190 30.06.2018

JOB NO.  
305169626

ODOMETER READING

DATE/TIME IN  
04.06.2018 12:30

S/No	Part No.	Qty	Unit Price	%Disc	Net
PART REQUISITION					
0001	04-01-0302-0600 PRIG4 MIRROR ASSY OUTER R	1	1,374.00	25.00	1,030.50
0002	04-01-0302-0897 PRIG4 COVER OUTER MIRROR	1	107.40	25.00	80.55
SUB-TOTAL:				:	1,111.05

### JOB NATURE

0001	L	PANEL BRATING	50.00	50.00
0002	23-502	SPRAYPAINT ON AFFECTED AREA	50.00	50.00
SUB-TOTAL:			:	100.00

1. WHILE TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARE OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE SAID TO BE UNDER OWNERS' RISK.

2. CUSTOMERS SHALL INSPECT THEIR VEHICLE IMMEDIATELY UPON DELIVERY AND SIGN WITHIN TEN DAYS FROM DELIVERY AND NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLE WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.

3. INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT, I.E. AFTER 30 DAYS FROM THE INVOICE DATE OF PERIOD OF DEFAULT.

4. PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd  
A member of COMFORTDELGRO

Head Office:  
205 Braddell Road  
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010010	91381190	1,295.82	

GST REG. NO. M2-8921817-3

## TAX INVOICE

COMPANY REG. NO.: 199506048W  
Page: 2

8010010

AXA INSURANCE PTE LTD

#24-01 8 SHENTON WAY AXA TOWER  
SINGAPORE SG 058811

CONTACT NO: 63387288

VEHICLE NO  
SHA44417

MAKE  
TOYOTA

MODEL  
PRIUS HYBRID(G4)

DATE OF REG  
14.09.2016

CHASSIS CODE  
JTDKB3PU503529425

INV. NO/DATE  
91381190 30.06.2018

JOB NO.  
305169626

ODOMETER READING

DATE/TIME IN  
04.06.2018 12:30

Items total		1,211.05
Add GST @	7.000 %	84.77
Invoice amount		1,295.82

Issued by : KATHERINETAN 30.06.2018 12:43:48  
Repair type : CLSO/57/57  
Payment Type/Term: /Credit 30 days

1. WHILE TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR LOSS OF OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DELIVERED AND RETURNED ON OWNER'S RISK.

2. CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.

3. INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND UNPAID TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT OR AFTER 30 DAYS FROM THE DUE DATE, AND FOR THE PERIOD OF DEFAULT.

4. PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd  
A member of COMFORTDELGRO

Head Office:  
205 Braddell Road  
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010010	91381190	1,295.82	

Our Ref: CT18060117

Date: 11 June 2018



**TO WHOM IT MAY CONCERN**

Dear Sir/Madam

ACCIDENT ON 03/06/2018 @ 20:15 hrs  
ALONG KILLINEY RD TWDS SOMERSET RD  
INVOLVING YM4495P

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHA4441J** (the "Taxi"). The Taxi was hired to **LOW KWONG YEW IC NO S1298279H** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$125.40** per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay  
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

## SHA 4441D

DATE	NAME OF DRIVER	MILEAGE READING					MILEAGE TRAVELLED (KM)	HOURS OPERATED (TM)		DATE	NAME OF
								FROM	TO		
30/5/18	Leong	3	3	4	6	30	143	1600	0105		
31-05-18	Low	3	3	4	9	20	290	400	1500		
31/5/18	Leong	3	3	5	0	86	166	1600	0100		
01-06-18	Low	3	3	5	4	11	326	400	1500		
1/6/18	Leong	3	3	5	5	2	141	1600	0115		
02-06-18	Low	3	3	5	9	09	357	400	1500		
2/6/18	1/2	3	3	6	2	67	357	1600	0200		
3/6/18	1/1	3	3	6	4	12					
3/6/18	1/1	3	3	6	8	23	381	1520	0800		
04-06-18	ACCIDENT						IN	1230	-		
06-06-18	REPAIR						OUT	1030	-		



### Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
YM4495P	03 Jun 2018 / 20:15:00	Successful	A12	AXA INSURANCE PTE LTD

[Previous](#)

OK

SHA 4441J

<< Service Request Details

Claim	SBR0001JH
Reference	CC4/A3M18010000/K1B3q2
Loss Date	3 June 2018
Request Date	5 June 2018
Due Date	
Vendor Name	LKX AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Steps

Wait for Approve Invoice

Add Remarks

Vehicle Information	
Incident Vehicle Registration #	SHA4441J
Make	TMVD TOYOTA
Model	PRUIS
Service Address	
...	

Primary Contact/Insured

TRANS CONCORDE SERVICES PTE LTD  
151 PASIR PANJANG ROAD, #02-19 PASIR PANJANG, DISTRIKPARK, 110480, Singapore

Claim Handler

NG Stacey  
656804051  
stacey.ng@axa.com.sg

Additional Instructions















- Messages
- Invoices
- History
- Documents
- Assessment
- Mobiles
- Notes

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKX Invoice 1 (2).pdf	Invoice	Surveyor/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	30 September 2018

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
 payment breakdown SHIA 44411.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2018
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2018
 LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2018
 LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2018
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2018
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2018
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2018
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	20 September 2018
 DOL-BACK.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 July 2018
 DOL.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 July 2018
 LETTER OF AUTHORITY TO DRIVE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 July 2018
 DRIVERS DL AND WORK PERMIT.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 July 2018
 TP VIDEO - SHIA44411.mpg	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	16 July 2018
 TP ESTIMATE- MARKED - SHIA44411.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	7 June 2018

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
 Immediate Advice.pdf	Reports & Statement	Estimate / Quotation	L&K AUTO CONSULTANTS PTE LTD (TP)	7 June 2018
 P1801755_CL_TP XS \$1K.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	NG Stacy	6 June 2018
 P1801755_JN_00003_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	NG Stacy	6 June 2018
 YH4495P INS GUA PDF	Reports & Statement	GIA Report	KUMAR Shalendra	5 June 2018
 EMAIL FOR PRO WITH SH44441J TP GUA.mig	Forms / Claim Documents	Others	KUMAR Shalendra	5 June 2018

Assessment Details

Add

Approve

Deny

Submit All

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPN/ RTTR%	DISC QUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1			SIDE MIRROR ASSY - LH			Cracked	1374		25		1030.5	Approve	
	2	1			SIDE MIRROR COVER, LH			Missing	107.4		25		80.55	Approve	

Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR RAR	LABOUR REPAIR	PART	ACTION (LABOUR)	COMMENT	REMOVE
	1		PANEL BEATING	50	0	0	Approve		
	2		SPRAY PAINTING CHANGE	50	0	0	Approve		
	3		WIRING CHARGE	0	0	0	Deny		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Rollo

Parts & Labour

Miscellaneous

Summary

Act

Approve

Decline

Withdraw App

EDIT

SR NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE

	1	DAYS OF REPAIR:1 DAYS	Approve			
--	---	-----------------------	---------	--	--	--

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition		Taxes & Fajils		Parts & Labour		Miscellaneous		Summary		Claim Amount	
Claim Amount		\$1,211.05												\$1,211.05	
CATEGORY		ESTIMATE				REVISED AMOUNT									
Spare Parts														\$1,111.05	
Labour														\$100.00	

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	YM 4495P (Insd veh)	Model:	TPVD TOYOTA
	SHA 4441J (TP veh)		PRIUS
Date of Accident:	03/06/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	1,616.82
Final Repair Cost	:	\$	1,295.82
Loss of Token Sum	:	\$	100.00
Rental (if any)	:	\$	250.80
LTA / GIA Search Fee	:	\$	7.49

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum (Global Sum)	:	\$	1,650.00

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ 100 \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	COMFORTDELGRO ENGINEERING PTE LTD	:	\$ 1,650.00

JOANNE LEE KHANG MIN  
LKK Auto Consultants Pte Ltd

20/09/2018  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))