

INS. CASE OWNER

Sathya

CC 3, ALG 180 10310, Vua39

LKK:  
IDAC:

Surveyor:

Sathya

DOI:

ASSIGNMENT

5/6/18

Date / Time:

5/6/18

Registered in Merimen:

6/6/18

Pre-assign / CCU / FTE

SLE 7496m



Insured Vehicle No.:

Claim No.:

466n 5729256

Name of Insured:

HOPE FIRST RESPONSE P/L

Policy No.:

09AA94976

Insured Tel No.:

HP:

Make / Model:

Mr Bente

Excess Sec II :SS

D.O.A: 31/05/18

Place of Accident:

B7B Rd

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

MD. Nazim Bin Muzam

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

82242319 (V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SHE 5946H



INSRS:

WSP:

Tel:

Liability:

RMKS:

Smrt, w



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

13/6

21H

SHE 5946H, CC 3, ALG 180 10310, Vua39, Mr. Bente

SLE 7496m - X

Spoke to George, he confirmed the accident details. Informed TP claim and he agree to settle TP claim.

RECEIVED 29 AUG 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

7 MIN By Email 24/8

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

27/8/18

Confirm with:

Lee Gek

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost:

SS 4650.00

Loss of Rental (LOR):

SS 783.24

(

6

days)

x 130.54

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

7.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

5440.24

Global Sum SS:

5440.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

5440.00

Name 1:

SMRT TAXIS PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

## ASSIGNMENT

From \_\_\_\_\_ Date \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop No: \_\_\_\_\_

of \_\_\_\_\_

Insured \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess \_\_\_\_\_

(Client's Record)

Make of Vehicle: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Ball or Market Value \_\_\_\_\_

JDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: SHB 5946 H Reg: Jan 2013Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SSANGYONG RODUS-SUV cc: 2696Colour: White Insured / Std / NI / NASp Reading: 635782 T Read: Insured / Std / NI / NAEng No: 66592622546464C No: KPTV081FSCP066731Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim orTyre Size F: 215/65 R16R: 215/65 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake (Rear), Giti (Front)

Front

Rear

R/Bal: 6 mm R/Bal: 6 mmL/Bal: 6 mm L/Bal: 6 mmD.O.A: 31/5/2012 DO: 5/6/2012

Survey held at: \_\_\_\_\_

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

LIS - \$46501 (Red: \$2261.54 / 33%)

TAX/05/18/2143

AIG

- SLE7446 M

Date/Time File Pass to:

☐

: Preli. Report

☐

: Final Report

Date/Time File Return to:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Lump Sum - Fee

Other

Total

Total Fee

Total

Report Format:

Lump Sum / I.B.I. /

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Technician: \$

☐

Weekend: \$



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315


Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                                      |                            |            |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|----------------------------|------------|-------------------------------------------------------------------------------------|
| AIG ASIA PACIFIC INSURANCE PTE LTD                                                                                                        |                                                                                      | Ref : CC3/AIG18010310/Vua3 |            |                                                                                     |
| 78 SHENTON WAY #08-16<br>CHARTIS BUILDING<br>SINGAPORE 079120                                                                             |                                                                                      | Date : 06-06-2018          |            |  |
|                                                                                                                                           |                                                                                      | Code : AIG                 |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                                      |                            |            |                                                                                     |
| Insured Veh.                                                                                                                              | SLE 7496M                                                                            | Veh. Inspected             | SHB 5946H  |                                                                                     |
| Policy No.                                                                                                                                |                                                                                      | Coverage (\$)              | 0.00       |                                                                                     |
| Claim No.                                                                                                                                 |                                                                                      | Excess (\$)                | 0.00       |                                                                                     |
| Assign From                                                                                                                               |                                                                                      | Assign Date                | 06/06/2018 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                                      |                            |            |                                                                                     |
| Make & Model                                                                                                                              |                                                                                      | c.c                        | 0          |                                                                                     |
| Engine No.                                                                                                                                | HIDDEN                                                                               | Year of Reg.               |            |                                                                                     |
| Chassis No.                                                                                                                               |                                                                                      | Colour                     |            |                                                                                     |
| Odometer                                                                                                                                  | -                                                                                    | Steering                   |            |                                                                                     |
| Brakes                                                                                                                                    |                                                                                      | Modification               |            |                                                                                     |
| General                                                                                                                                   |                                                                                      |                            |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                                      |                            |            |                                                                                     |
|                                                                                                                                           | Size                                                                                 | Make                       | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                            |                                                                                      |                            | mm         |                                                                                     |
| L/H Front Tyre                                                                                                                            |                                                                                      |                            | mm         |                                                                                     |
| R/H Rear Tyre                                                                                                                             |                                                                                      |                            | mm         |                                                                                     |
| L/H Rear Tyre                                                                                                                             |                                                                                      |                            | mm         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                          |                                                                                      |                            |            |                                                                                     |
|                                                                                                                                           |                                                                                      |                            |            |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                                      |                            |            |                                                                                     |
| Accident Date                                                                                                                             | 31/05/2018                                                                           | Inspection Date            | 05/06/2018 |                                                                                     |
| Survey held at                                                                                                                            | SMRT AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 |                            |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                                      |                            |            |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                      |                            |            |                                                                                     |

# SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty office at Accident Reporting Centre

Reg. No : SHB5946H  
 Ref. No : TAX/05/18/2143  
 Reg. Date : 31/01/2013  
 Vehicle Type : TAXI  
 Make : SSANGYONG  
 Model : RODIUS-SV270  
 Name of Driver : HO WEI SENG  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 31/05/2018 07:13:00 AM  
 Accident Reported Date / Time : 01/06/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : Sebastian  
 Vehicle is Towed Back? : Yes  
 Towed Back Date/Time : 04/06/2018  
 Replacement Vehicle Issued? : No  
 Accident Repair Job Card No : 000024096386  
 Special Instruction to ARC, if any :



TOWED \$40 / SLE7496M (AIG) - LKK  
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL  
 SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang@lkkauto.com HP: 90036121  
 LUMP SUM REPAIR

Prepared Date : 01/06/2018 03:17:06 PM

QC 8/6/18 15:49 PASC

Recording Camera ☐ ☒  
 Radio Antenna ☐ ☒  
 1st witness M Date 5-6-18  
 2nd witness \_\_\_\_\_ Date \_\_\_\_\_

E 1/20 F  
 KM 635782

|                               |         |
|-------------------------------|---------|
| Vehicle to be repaired        | 5/6     |
| Wega Job No:                  | 06/0354 |
| Vehicle sent to SMRT Date for | 8/6/18  |
| Time to                       | 11:55   |
| Specify if                    | Ch      |

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : KPTV0B1FSCP066731

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

|                              | Quotation from ARC       | Adjusted by Surveyor, if applicable |
|------------------------------|--------------------------|-------------------------------------|
| Total Labour Charges         | : 1,014.00               | 700.00                              |
| Total Spray Painting Charges | : 1,306.00               | 700.00                              |
| Total Material Charges       | : 3,695.54               | 2,845.38                            |
| Other Charges                | : 896.00                 | 390.00                              |
| <b>TOTAL</b>                 | <b>: 6,911.54</b>        | <b>4,635.38</b>                     |
| Lump Sum Total               | : 6,900.00               | 4,650.00                            |
| No. of Repair Days           | : 6.00                   | 4.00 ✓                              |
| Prepared / Adjusted By       | :                        | SEBASTIAN (LKK)                     |
| Arc / Surveyor Sign Off Date | : 05/06/2018 10:24:25 AM | 05/06/2018 03:37:09 PM              |



Prepared / Adjusted Date :

Remarks :

Prepared Date : 05/06/2018 08:43:17 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : QN-1806-0379

Invoice No :

Quotation Date : 18/6

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 6/5/2018 10:24:36 AM

3556.73 ✓

- 20%

2845.38 ✓

+ 700.00 ✓

+ 1090.00 ✓

---

4635.38 ✓

US \$4650/- ✓

Confirmed

## Section D - Details of Repair Estimates

### Part 1 - Labour Works

| Job Scope              | Quotation from ARC | Adjusted by Surveyor, if applicable |
|------------------------|--------------------|-------------------------------------|
| TO REPAIR REAR PORTION | 1,014.00           | 700.00 ✓                            |
| <b>Total Labour</b>    | <b>1,014.00</b>    | <b>700.00 ✓</b>                     |

### Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO REPSRAY REAR BUMPER                          | 473.00             | 300.00 ✓                            |
| TO RESPRAY BUMPER BEAM                          | 180.00             | 0.00                                |
| TO RESPRAY TAIL GATE                            | 473.00             | 300.00 ✓                            |
| TO RESPRAY REAR PANEL                           | 180.00             | 100.00 ✓                            |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>1,306.00</b>    | <b>700.00 ✓</b>                     |

### Part 3 - Other Costs - Accident and Accident Repair Related Expenses

| Job Scope                                                            | Quotation from ARC | Adjusted by Surveyor, if applicable |
|----------------------------------------------------------------------|--------------------|-------------------------------------|
| TOWING CHARGE                                                        | 56.00              | 50.00 ✓                             |
| TO CHECK WIRING AND SYSTEM FUNCTION                                  | 80.00              | 30.00 ✓                             |
| TO TRANSFER REAR TAILGATE MECHANISM                                  | 120.00             | 60.00 ✓                             |
| TO REMOVE AND REFIX REAR WINDSCREEN                                  | 120.00             | 60.00 ✓                             |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM                              | 120.00             | 60.00 ✓                             |
| TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR. | 120.00             | 60.00 ✓                             |
| TO REMOVE AND REFIT WIRE HARDESS                                     | 120.00             | 50.00 ✓                             |
| TO REPLACE SUNDRY PARTS                                              | 100.00             | 20.00 ✓                             |
| TO WASH AND VACUUM                                                   | 60.00              | 0.00                                |
| <b>Total Other Costs</b>                                             | <b>896.00</b>      | <b>390.00 ✓</b>                     |

# Part 4 - Spare Parts / Material Usage

| Part Number                 | Portion | Stock No | Part Name                      | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommendation | Surveyor Approved | Photos Attached |     |
|-----------------------------|---------|----------|--------------------------------|-----|-----------------|--------------|------------------|--------------------|-------------------|-----------------|-----|
| 7881A21000                  | REAR    |          | Rear Bumper Assy               | 1   | 925.27          | 10.00        | 832.74           | Replace            | Replace           | No              | DMG |
|                             | COMMON  |          | REAR BUMPER CLIP               | 10  | 4.25            | 10.00        | 38.25            | Replace            | Replace           | No              | NEL |
| 8390121100                  | BODY    |          | LAMP ASSY, REFLEX REFLECTOR LH | 1   | 10.52           | 10.00        | 9.47             | Replace            | Replace           | No              | SCR |
| 8390221100                  | BODY    |          | LAMP ASSY, REFLEX REFLECTOR RH | 1   | 10.52           | 10.00        | 9.47             | Replace            | Check             | No              | NN  |
|                             | REAR    |          | REVERSE SENSOR                 | 1   | 165.10          | 10.00        | 148.59           | Replace            | Replace           | No              | MS  |
| 7882121000                  | BODY    |          | ABSORBER ENERGY RR BUMPER      | 1   | 111.73          | 10.00        | 100.56           | Replace            | Check             | No              | NN  |
| 7883021000                  | COMMON  |          | BEAM ASSY-IMPACT RR BUMPER     | 1   | 513.97          | 10.00        | 462.57           | Replace            | Replace           | No              | DT  |
| 6401121000                  | REAR    |          | REAR TAILGATE ASSY             | 1   | 1,355.08        | 10.00        | 1,219.57         | Replace            | Replace           | No              | DT  |
|                             | REAR    |          | REAR NUMBER PLATE              | 1   | 15.00           | 0.00         | 15.00            | Replace            | Replace           | No              | DT  |
|                             | REAR    |          | REAR NUMBER PLATE FRAME        | 1   | 35.00           | 0.00         | 35.00            | Replace            | Replace           | No              | DT  |
| 8379021001                  | REAR    |          | LAMP ASSY-LICENSE PLATE        | 2   | 49.25           | 10.00        | 88.65            | Replace            | Replace           | No              | DMG |
| 7141021000                  | BODY    |          | LATCH ASSY, T/GATE             | 1   | 59.98           | 10.00        | 53.98            | Replace            | Replace           | No              | DMG |
| 7141521000                  | BODY    |          | STRIKER ASSY, T/GATE           | 1   | 9.89            | 10.00        | 8.90             | Replace            | Replace           | No              | NEL |
| 7145021001                  | REAR    |          | WEATHER STRIP T/GATE OPENING   | 1   | 97.67           | 10.00        | 87.90            | Replace            | Check             | No              | NN  |
| 6617403093                  | REAR    |          | Handle assy-T/gate O/S         | 1   | 14.16           | 10.00        | 12.74            | Replace            | Replace           | No              | BR  |
| 7381021002ABU               | Body    |          | Trim assy-T/gate lwr           | 1   | 199.92          | 10.00        | 179.93           | Replace            | Check             | No              | X   |
| 7963021002                  | REAR    |          | Garnish assy-T/gate ctr        | 1   | 300.19          | 10.00        | 270.17           | Replace            | Check             | No              | X   |
| 8837021100                  | BODY    |          | ACTUATOR ASSY, DR LOCK T/GATE  | 1   | 74.55           | 10.00        | 67.10            | Replace            | Check             | No              | X   |
| 8360121201                  | REAR    |          | COMBI LAMP ASYS-RR T/GATE LH   | 1   | 288.57          | 10.00        | 259.71           | Replace            | Replace           | No              | CRK |
| 8360221201                  | REAR    |          | COMBI LAMP ASYS-RR T/GATE RH   | 1   | 288.57          | 10.00        | 259.71           | Replace            | Replace           | No              | CRK |
|                             |         |          | EMBLEM REAR                    | 1   | 48.94           | 10.00        | 44.05            | Replace            | Replace           | No              | NEL |
|                             | COMMON  |          | SMRT LOGO                      | 1   | 7.80            | 0.00         | 7.80             | Replace            | Replace           | No              | NEL |
|                             | COMMON  |          | STICKER PRESTIGE               | 1   | 60.00           | 0.00         | 60.00            | Replace            | Replace           | No              | NEL |
| 7934021001                  | BODY    |          | RUBBERSEAL GLASS RR QTR        | 0   | 11.04           | 10.00        | 0.00             | Replace            | Not given         | No              | X   |
|                             | COMMON  |          | SEALANT W/SCREEN               | 0   | 37.00           | 0.00         | 0.00             | Replace            | Not given         | No              | X   |
|                             |         |          | PANEL END INNER                | 1   | 239.33          | 10.00        | 215.40           | Replace            | Check             | No              | X   |
|                             |         |          | PANEL END OUTER                | 1   | 105.74          | 10.00        | 95.17            | Replace            | Check             | No              | X   |
|                             | COMMON  | 4006314  | SEALANT SIKAFLEX               | 1   | 37.00           | 0.00         | 37.00            | Replace            | Check             | No              | X   |
| TOTAL MATERIALS             |         |          |                                |     |                 |              | 4,619.43         | 3,556.73           |                   |                 |     |
| TOTAL MATERIALS(Discounted) |         |          |                                |     |                 |              | 3,695.54         | 2,845.38           |                   |                 |     |

Added Spare Parts / Material Usage After Surveyor Signed off

|                      |                          |                          |                |
|----------------------|--------------------------|--------------------------|----------------|
| Contractor:          | WEGA ENGINEERING PTE LTD |                          |                |
| Accident Case Number | TAX / 05 / 18 / 2143     | Date of Collection       | 5 / 6 / 18     |
| Vehicle No           | SHB 5946 H               | Date of Request          | 6 / 6 / 18     |
| Vehicle Model        | SSANG YONG               | Number of Days to Extend | 2 DAYS + 1 day |

**REQUEST FOR SUPPLYMENT PARTS**

| S/N | Number photos              | Part Description               | Quantity | Unit Price   |
|-----|----------------------------|--------------------------------|----------|--------------|
| 1   | 8173, 74, 75, 80<br>81, 82 | Beam Assy - Impact RR Bumper ✓ |          | # 513.97     |
| 2   | 8183, 84, 85               | To repair Rear End Panel.      |          | # 200.00 100 |
| 3   |                            | To Respray Rear End Panel      |          | # 150.00 100 |
| 4   |                            |                                |          |              |
| 5   |                            |                                |          |              |
| 6   |                            |                                |          |              |
| 7   |                            |                                |          |              |
| 8   |                            |                                |          |              |

I, (Name) CHIA

<<<Please submit photographs for damaged parts>>>

Sebastian  
7/6/2018

(Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.



Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

|                 |                                                |                                           |
|-----------------|------------------------------------------------|-------------------------------------------|
| Acknowledge By  | ARC Executive / Supervisor / SA                |                                           |
| Approval By     | Surveyor / In-house Staff                      |                                           |
| Parts Ordering  | SMRT Store / Contractor Supply / Form 22 / WOC | Form 22 / PO / WOC / Reservation / Number |
| Photo Submitted |                                                | Date of submission                        |

For SMRT Staff

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5946H  
 Ref. No : TAX/05/18/2143  
 Reg. Date : 31/01/2013  
 Vehicle Type : TAXI  
 Make : SSANGYONG  
 Model : RODIUS-SV270  
 Name of Driver : HO WEI SENG  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 31/05/2018 07:13:00 AM  
 Accident Reported Date / Time : 01/06/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : Yes  
 Towed Back Date/Time : 04/06/2018  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024096386  
 Special Instruction to ARC, if any :  
 TOWED \$40 / SLE7496M (AIG) - LKK  
 Prepared Date : 01/06/2018 03:17:06 PM



Sathya S

5/6/2018

sebastianyang@lkkauto.com

- Lump Sum Repair
- Question mark item photo
- Photo after paint.

3 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : KPTV0B1FSCP066731

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

|                                | Quotation from ARC     | Adjusted by Surveyor, if applicable |
|--------------------------------|------------------------|-------------------------------------|
| Total Labour Charges :         | 1,014.00               | 0.00                                |
| Total Spray Painting Charges : | 1,306.00               | 0.00                                |
| Total Material Charges :       | 3,770.63               | 3,770.63                            |
| Other Charges :                | 896.00                 | 0.00                                |
| <b>TOTAL :</b>                 | <b>6,986.63</b>        | <b>0.00</b>                         |
| <b>Lum Sum Total :</b>         | <b>7,000.00</b>        | <b>0.00</b>                         |
| No. of Repair Days :           | 6.00                   | <del>0.00</del> 3 days              |
| Prepared / Adjusted By :       |                        |                                     |
| Arc / Surveyor Sign Off Date : | 05/06/2018 10:24:25 AM | 01/01/1900 12:00:00 AM              |



Prepared / Adjusted Date :

Remarks :

Prepared Date : 05/06/2018 08:43:17 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 6/5/2018 10:24:36 AM

## Section D - Details of Repair Estimates

### Part 1 - Labour Works

| Job Scope              | Quotation from ARC | Adjusted by Surveyor, if applicable |
|------------------------|--------------------|-------------------------------------|
| TO REPAIR REAR PORTION | 1,014.00           | 0.00 600                            |
| <b>Total Labour</b>    | <b>1,014.00</b>    | <b>0.00</b>                         |

### Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO REPSRAY REAR BUMPER                          | 473.00             | 0.00 300                            |
| TO RESPRAY BUMPER BEAM                          | 180.00             | 0.00 ?                              |
| TO RESPRAY TAIL GATE                            | 473.00             | 0.00 300                            |
| TO RESPRAY REAR PANEL                           | 180.00             | 0.00 ?                              |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>1,306.00</b>    | <b>0.00</b>                         |

### Part 3 - Other Costs - Accident and Accident Repair Related Expenses

| Job Scope                                                            | Quotation from ARC | Adjusted by Surveyor, if applicable |
|----------------------------------------------------------------------|--------------------|-------------------------------------|
| TOWING CHARGE                                                        | 56.00              | 0.00 50                             |
| TO CHECK WIRING AND SYSTEM FUNCTION                                  | 80.00              | 0.00 30                             |
| TO TRANSFER REAR TAILGATE MECHANISM                                  | 120.00             | 0.00 60                             |
| TO REMOVE AND REFIX REAR WINDSCREEN                                  | 120.00             | 0.00 60                             |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM                              | 120.00             | 0.00 60                             |
| TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR. | 120.00             | 0.00 60                             |
| TO REMOVE AND REFIT WIRE HARDESS                                     | 120.00             | 0.00 50                             |
| TO REPLACE SUNDRY PARTS                                              | 100.00             | 0.00 20                             |
| TO WASH AND VACUUM                                                   | 60.00              | 0.00 X                              |
| <b>Total Other Costs</b>                                             | <b>896.00</b>      | <b>0.00</b>                         |

**Part 4 - Spare Parts / Material Usage**

| Part Number                 | Portion | Stock No | Part Name                            | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommendation | Surveyor Approved | Photos Attached |
|-----------------------------|---------|----------|--------------------------------------|-----|-----------------|--------------|------------------|--------------------|-------------------|-----------------|
| 7881A21000                  | REAR    |          | Rear Bumper Assy ✓ DMG               | 1   | 925.27          | 10.00        | 832.74           | Replace            | Replace           | No              |
|                             | COMMO N |          | REAR BUMPER CLIP ✓ NEC               | 10  | 4.25            | 10.00        | 38.25            | Replace            | Replace           | No              |
| 8390121100                  | BODY    |          | LAMP ASSY, REFLEX REFLECTOR LH ✓ DCR | 1   | 10.52           | 10.00        | 9.47             | Replace            | Replace           | No              |
| 8390221100                  | BODY    |          | LAMP ASSY, REFLEX REFLECTOR RH ?     | 1   | 10.52           | 10.00        | 9.47             | Replace            | Replace           | No              |
|                             | REAR    |          | REVERSE SENSOR ✓ MS                  | 1   | 165.10          | 10.00        | 148.59           | Replace            | Replace           | No              |
| 7882121000                  | BODY    |          | ABSORBER ENERGY? RR BUMPER           | 1   | 111.73          | 10.00        | 100.56           | Replace            | Replace           | No              |
| 7883021000                  | COMMO N |          | BEAM ASSY-IMPACT? RR BUMPER          | 1   | 513.97          | 10.00        | 462.57           | Replace            | Replace           | No              |
| 5401121000                  | REAR    |          | REAR TAILGATE ASSY ✓ DT              | 1   | 1,355.08        | 10.00        | 1,219.57         | Replace            | Replace           | No              |
|                             | REAR    |          | REAR NUMBER PLATE ✓ DT               | 1   | 15.00           | 0.00         | 15.00            | Replace            | Replace           | No              |
|                             | REAR    |          | REAR NUMBER PLATE FRAME ✓ DT         | 1   | 35.00           | 0.00         | 35.00            | Replace            | Replace           | No              |
| 8379021001                  | REAR    |          | LAMP ASSY-LICENSE PLATE ✓ DMG        | 2   | 49.25           | 10.00        | 88.65            | Replace            | Replace           | No              |
| 7141021000                  | BODY    |          | LATCH ASSY, T/GATE ✓ DMG             | 1   | 59.98           | 10.00        | 53.98            | Replace            | Replace           | No              |
| 7141521000                  | BODY    |          | STRIKER ASSY T/GATE ✓ NEC            | 1   | 9.89            | 10.00        | 8.90             | Replace            | Replace           | No              |
| 7145021001                  | REAR    |          | WEATHER STRIP T/GATE OPENING ?       | 1   | 97.67           | 10.00        | 87.90            | Replace            | Replace           | No              |
| 8617403093                  | REAR    |          | Handle assy-T/gate O/S ✓             | 1   | 14.16           | 10.00        | 12.74            | Replace            | Replace           | No              |
| 7381021002ABU               | Body    |          | Trim assy-T/gate lwr ?               | 1   | 199.92          | 10.00        | 179.93           | Replace            | Replace           | No              |
| 7963021002                  | REAR    |          | Garnish assy-T/gate ctr ?            | 1   | 300.19          | 10.00        | 270.17           | Replace            | Replace           | No              |
| 8837021100                  | BODY    |          | ACTUATOR ASSY, DR ? LOCK T/GATE      | 1   | 74.55           | 10.00        | 67.09            | Replace            | Replace           | No              |
| 8360121201                  | REAR    |          | COMBI LAMP ASYS- RR T/GATE LH ✓ CRK1 | 1   | 288.57          | 10.00        | 259.71           | Replace            | Replace           | No              |
| 8360221201                  | REAR    |          | COMBI LAMP ASYS- RR T/GATE RH ✓ CRK  | 1   | 288.57          | 10.00        | 259.71           | Replace            | Replace           | No              |
|                             |         |          | EMBLEM REAR ✓ NEC                    | 1   | 48.94           | 10.00        | 44.05            | Replace            | Replace           | No              |
|                             | COMMO N |          | SMRT LOGO ✓ NEC                      | 1   | 7.80            | 0.00         | 7.80             | Replace            | Replace           | No              |
|                             | COMMO N |          | STICKER PRESTIGE ✓ NEC               | 1   | 60.00           | 0.00         | 60.00            | Replace            | Replace           | No              |
| 7934021001                  | BODY    |          | RUBBERSEAL GLASS RR QTR X            | 2   | 11.04           | 10.00        | 19.87            | Replace            | Replace           | No              |
|                             | COMMO N |          | SEALANT W/SCREEN X                   | 2   | 37.00           | 0.00         | 74.00            | Replace            | Replace           | No              |
|                             |         |          | PANEL END INNER ?                    | 1   | 239.33          | 10.00        | 215.40           | Replace            | Replace           | No              |
|                             |         |          | PANEL END OUTER ?                    | 1   | 105.74          | 10.00        | 95.17            | Replace            | Replace           | No              |
|                             | COMMO N | 4008314  | SEALANT SIKAFLEX ?                   | 1   | 37.00           | 0.00         | 37.00            | Replace            | Replace           | No              |
| TOTAL MATERIALS             |         |          |                                      |     |                 |              |                  | 4,713.30           | 4,713.29          |                 |
| TOTAL MATERIALS(Discounted) |         |          |                                      |     |                 |              |                  | 3,770.63           | 3,770.63          |                 |

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number                   | Portion | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check | LT Check |
|-------------------------------|---------|-----------|-----|-----------------|--------------|------------------|-----------|----------------|----------|
| TOTAL SUPPLEMENTARY MATERIALS |         |           |     |                 |              |                  |           |                |          |

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5946H  
 Ref. No : TAX/05/18/2143  
 Reg. Date : 31/01/2013  
 Vehicle Type : TAXI  
 Make : SSANGYONG  
 Model : RODIUS-SV270  
 Name of Driver : HO WEI SENG  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 31/05/2018 07:13:00 AM  
 Accident Reported Date / Time : 01/06/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : Yes  
 Towed Back Date/Time : 04/06/2018  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024096386  
 Special Instruction to ARC, if any :  
 TOWED \$40 / SLE7496M (AIG) - LKK  
 Prepared Date : 01/06/2018 03:17:06 PM



Sathya Sai

5/6/2018

sebastianyeang@lkkauto.com

- Lump Sum Repair
- Question mark item photo
- Photo after paint

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Chassis No : KPTV0B1FSCP066731

Mileage

0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

|                              | Quotation from ARC       | Adjusted by Surveyor, if applicable |
|------------------------------|--------------------------|-------------------------------------|
| Total Labour Charges         | : 1,014.00               | 0.00                                |
| Total Spray Painting Charges | : 1,306.00               | 0.00                                |
| Total Material Charges       | : 3,770.63               | 3,770.63                            |
| Other Charges                | : 896.00                 | 0.00                                |
| <b>TOTAL</b>                 | <b>: 6,986.63</b>        | <b>0.00</b>                         |
| <b>Lum Sum Total</b>         | <b>: 7,000.00</b>        | <b>0.00</b>                         |
| No. of Repair Days           | : 6.00                   | <del>0.00</del> 3 days              |
| Prepared / Adjusted By       | :                        |                                     |
| Arc / Surveyor Sing Off Date | : 05/06/2018 10:24:25 AM | 01/01/1900 12:00:00 AM              |



Prepared / Adjusted Date :

Remarks :

Prepared Date : 05/06/2018 08:43:17 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

|                       |                                      |
|-----------------------|--------------------------------------|
| Quotation No :        | Invoice No :                         |
| Quotation Date :      | Invoice Date :                       |
| Invoice Amount : 0.00 | Prepared Date : 6/5/2018 10:24:36 AM |

**Part 1 - Labour Works**

| Job-Scope              | Quotation from ARC | Adjusted by Surveyor, if applicable |
|------------------------|--------------------|-------------------------------------|
| TO REPAIR REAR PORTION | 1,014.00           | <del>0.00</del> 600                 |
| <b>Total Labour</b>    | <b>1,014.00</b>    | <b>0.00</b>                         |

**Part 2 - Spray Painting & Panel Beating Related Works**

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO REPSRAY REAR BUMPER                          | 473.00             | <del>0.00</del> 300                 |
| TO RESPRAY BUMPER BEAM                          | 180.00             | 0.00 ?                              |
| TO RESPRAY TAIL GATE                            | 473.00             | <del>0.00</del> 300                 |
| TO RESPRAY REAR PANEL                           | 180.00             | 0.00 ?                              |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>1,306.00</b>    | <b>0.00</b>                         |

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

| Job Scope                                                            | Quotation from ARC | Adjusted by Surveyor, if applicable |
|----------------------------------------------------------------------|--------------------|-------------------------------------|
| TOWING CHARGE                                                        | 56.00              | <del>0.00</del> 50                  |
| TO CHECK WIRING AND SYSTEM FUNCTION                                  | 80.00              | <del>0.00</del> 30                  |
| TO TRANSFER REAR TAILGATE MECHANISM                                  | 120.00             | <del>0.00</del> 60                  |
| TO REMOVE AND REFIX REAR WINDSCREEN                                  | 120.00             | <del>0.00</del> 60                  |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM                              | 120.00             | <del>0.00</del> 60                  |
| TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR. | 120.00             | <del>0.00</del> 60                  |
| TO REMOVE AND REFIT WIRE HARDESS                                     | 120.00             | <del>0.00</del> 50                  |
| TO REPLACE SUNDRY PARTS                                              | 100.00             | <del>0.00</del> 20                  |
| TO WASH AND VACUUM                                                   | 60.00              | 0.00 X                              |
| <b>Total Other Costs</b>                                             | <b>896.00</b>      | <b>0.00</b>                         |

LKH Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Part 4 - Spare Parts / Material Usage

| Part Number                 | Portion | Stock No | Part Name                            | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommended | Surveyor Approved | Photos Attached |
|-----------------------------|---------|----------|--------------------------------------|-----|-----------------|--------------|------------------|-----------------|-------------------|-----------------|
| 7881A2100                   | REAR    |          | Rear Bumper Assy ✓ DMG               | 1   | 925.27          | 10.00        | 832.74           | Replace         | Replace           | No              |
|                             | COMMON  |          | REAR BUMPER CLIP ✓ NEC               | 10  | 4.25            | 10.00        | 38.25            | Replace         | Replace           | No              |
| 339012110                   | BODY    |          | LAMP ASSY, REFLEX REFLECTOR LH ✓ SCR | 1   | 10.52           | 10.00        | 9.47             | Replace         | Replace           | No              |
| 339022110                   | BODY    |          | LAMP ASSY, REFLEX REFLECTOR RH ?     | 1   | 10.52           | 10.00        | 9.47             | Replace         | Replace           | No              |
|                             | REAR    |          | REVERSE SENSOR ✓ MS                  | 1   | 165.10          | 10.00        | 148.59           | Replace         | Replace           | No              |
| 788212100                   | BODY    |          | ABSORBER ENERGY RR BUMPER ?          | 1   | 111.73          | 10.00        | 100.56           | Replace         | Replace           | No              |
| 788302100                   | COMMON  |          | BEAM ASSY-IMPACT RR BUMPER ?         | 1   | 513.97          | 10.00        | 462.57           | Replace         | Replace           | No              |
| 340112100                   | REAR    |          | REAR TAILGATE ASSY ✓ DT              | 1   | 1,355.08        | 10.00        | 1,219.57         | Replace         | Replace           | No              |
|                             | REAR    |          | REAR NUMBER PLATE ✓ DT               | 1   | 15.00           | 0.00         | 15.00            | Replace         | Replace           | No              |
|                             | REAR    |          | REAR NUMBER PLATE FRAME ✓ DT         | 1   | 35.00           | 0.00         | 35.00            | Replace         | Replace           | No              |
| 337902100                   | REAR    |          | LAMP ASSY-LICENSE PLATE ✓ DMG        | 2   | 49.25           | 10.00        | 88.65            | Replace         | Replace           | No              |
| 14102100                    | BODY    |          | LATCH ASSY, T/GATE ✓ DMG             | 1   | 59.98           | 10.00        | 53.98            | Replace         | Replace           | No              |
| 14152100                    | BODY    |          | STRIKER ASSY, T/GATE ✓ NEC           | 1   | 9.89            | 10.00        | 8.90             | Replace         | Replace           | No              |
| 14502100                    | REAR    |          | WEATHER STRIP T/GATE OPENING ?       | 1   | 97.67           | 10.00        | 87.90            | Replace         | Replace           | No              |
| 617403003                   | REAR    |          | Handle assy-T/gate O/S ✓             | 1   | 14.16           | 10.00        | 12.74            | Replace         | Replace           | No              |
| 138102100                   | Body    |          | Trim assy-T/gate lwr ?               | 1   | 199.92          | 10.00        | 179.93           | Replace         | Replace           | No              |
| 196302100                   | REAR    |          | Garnish assy-T/gate ctr ?            | 1   | 300.19          | 10.00        | 270.17           | Replace         | Replace           | No              |
| 183702110                   | BODY    |          | ACTUATOR ASSY, DR LOCK T/GATE ?      | 1   | 74.55           | 10.00        | 67.09            | Replace         | Replace           | No              |
| 136012120                   | REAR    |          | COMBI LAMP ASYS-RR T/GATE LH ✓ CRK   | 1   | 288.57          | 10.00        | 259.71           | Replace         | Replace           | No              |
| 136022120                   | REAR    |          | COMBI LAMP ASYS-RR T/GATE RH ✓ CRK   | 1   | 288.57          | 10.00        | 259.71           | Replace         | Replace           | No              |
|                             |         |          | EMBLEM REAR ✓ NEC                    | 1   | 48.94           | 10.00        | 44.05            | Replace         | Replace           | No              |
|                             | COMMON  |          | SMRT LOGO ✓ NEC                      | 1   | 7.80            | 0.00         | 7.80             | Replace         | Replace           | No              |
|                             | COMMON  |          | STICKER PRESTIGE ✓ NEC               | 1   | 60.00           | 0.00         | 60.00            | Replace         | Replace           | No              |
| 934021001                   | BODY    |          | RUBBERSEAL GLASS RR QTR X            | 2   | 11.04           | 10.00        | 19.87            | Replace         | Replace           | No              |
|                             | COMMON  |          | SEALANT W/SCREEN X                   | 2   | 37.00           | 0.00         | 74.00            | Replace         | Replace           | No              |
|                             |         |          | PANEL END INNER ?                    | 1   | 239.33          | 10.00        | 215.40           | Replace         | Replace           | No              |
|                             |         |          | PANEL END OUTER ?                    | 1   | 105.74          | 10.00        | 95.17            | Replace         | Replace           | No              |
|                             | COMMON  | 4006314  | SEALANT SIKAFLEX ?                   | 1   | 37.00           | 0.00         | 37.00            | Replace         | Replace           | No              |
| TOTAL MATERIALS             |         |          |                                      |     |                 |              |                  | 4,713.30        | 4,713.29          |                 |
| TOTAL MATERIALS(Discounted) |         |          |                                      |     |                 |              | 3,770.63         | 3,770.63        |                   |                 |

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number                          | Portion | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check | LT Check |
|--------------------------------------|---------|-----------|-----|-----------------|--------------|------------------|-----------|----------------|----------|
| <b>TOTAL SUPPLEMENTARY MATERIALS</b> |         |           |     |                 |              |                  |           |                |          |

## Thin Thin (LKKAUTO)

---

**From:** Thin Thin (LKKAUTO)  
**Sent:** Friday, 24 August 2018 11:14 AM  
**To:** 'ops@hopeambulance.com'  
**Subject:** ACCIDENT INVOLVING SLE 7496M & SHB 5946H ON 31/05/2018



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18010310/Vua3

24 AUGUST 2018

### HOPE FIRST RESPONSE PTE LTD

Dear Sir/Madam,

#### ACCIDENT INVOLVING SLE 7496M & SHB 5946H ON 31/05/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING  
Case Handler  
DID: 6841 2360  
FAX: 6741 4108  
Email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

**AUTHORISATION TO ACT**  
**(AIG Asia Pacific - Express Third Party Claim)**

I, SMRT TAXIS PTE LTD (the third party claimant") of 60 WOODLANDS INDUSTRIAL PARK E4, SINGAPORE 757705 (address), owner of SHB 5946H (vehicle no.) hereby authorize SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SHB 5946H that was damaged pursuant to the accident which occurred on 31/05/2018 (date) along BUKIT BATOK ROAD (location) involving vehicle no/s SLE 7496M ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the SMRT TAXIS PTE LTD.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 27 (day) of August (month) 20 18 (year)



Signed by "the third party claimant"  
(with chop if applicable)



Signed by "the workshop"  
(with chop)

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**



"We/I, SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for SS 5,440.00 (Global Sum) for vehicle no. SHB 5946H that was damaged pursuant to the accident which occurred on 31/05/2018 (date) along BUKIT BTOAK ROAD (location) involving vehicle no/s SLE 7496M.

This is pursuant to the inspection conducted on 05/06/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SMRT TAXIS PTE LTD ("the third party claimant") of vehicle no. SHB 5946H make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHB 5946H (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 27 (day) of August (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

Our acceptance of your offer of settlement would not negate or prejudice our driver's right of recovery for his/her losses.



SMRT Automotive Services Pte Ltd  
251 North Bridge Road Singapore 179102  
Tel: 65 63311000 Fax: 65 63340247

### Tax Invoice

GST Reg No. : MR-8500001-7  
CRN : 1990042802  
Invoice No. : IV180600366  
Date : 20.06.2018  
Vehicle No. : SHB5946H  
Your Ref No. : TAX/05/18/2143  
Our Ref No. : 24096386  
Terms : 30 Days



Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4  
SINGAPORE 757705

| Description                                                    | Qty  | Unit<br>Cost | Add<br>% | (Discount)<br>Amount | Amount      |
|----------------------------------------------------------------|------|--------------|----------|----------------------|-------------|
| LUMP SUM AMOUNT FOR REPAIR<br>AS PER SURVEYOR'S RECOMMENDATION | 1.00 |              |          |                      | \$ 4,650.00 |
| GRAND TOTAL                                                    |      |              |          |                      | \$ 4,650.00 |

Remark :

Make/Model : SSANGYONG PREMIER RO  
Accident Date : 31.05.2018

N.B. Payment by cheque should be crossed and  
made payable to 'SMRT Automotive Services Pte Ltd'.  
No receipt will be issued unless requested.

Authorized Signature  
for SMRT Automotive Services Pte Ltd



SMRT Taxis Pte Ltd

**MEMORANDUM**

To: Claims Dept

Our Ref: TAX/05/18/2143

From: SMRT Taxis Pte Ltd

Date: 11/06/2018

**ACCIDENT ON 31/05/2018 INVOLVING SHB 5946H & SLE 7496M  
ALONG BUKIT BATOK ROAD**

This is to confirm that the daily rental rate for SHB 5946H is \$130.54 per day.

Please proceed to recover any rental loss from the third party as a result of the above accident.

Thank you.

Yours sincerely  
SMRT TAXIS PTE LTD



for Manager



# Accident Vehicle Laid-Up Report

Registration No. : SHB5946H                      Accident Case No. : TAX/05/18/2143  
Make / Model : SSANGYONG PREMIER RODIUS SV270                      Ref. No. : 24096386

Date and Time Vehicle off-road for Accident Repair : 31.05.2018 07:14:00  
Date and Time Repair Completed : 09.06.2018 08:27:31

Remarks :

Generated by : POHSUAN

Printed on : 10.06.2018



## Enquire Transaction History

Transaction History Details

|                   |                                        |                                     |                      |
|-------------------|----------------------------------------|-------------------------------------|----------------------|
| Log Date/Time:    | 02 Jun 2018 / 08:42:37                 | Transaction Amount:                 | \$7.49               |
| Asset Type:       | Vehicle                                |                                     |                      |
| Asset ID:         | SLE7496M                               |                                     |                      |
| Transaction Type: | 18.32 Insurance Enquiry (GIRO Payment) | Channel:                            | External Agency      |
| User ID:          | ESASBAHO - BALQISH BINTE ABDUL HALIL   | Business Transaction Reference No.: | 20180602084236958831 |

Search Date / Time: 31 May 2018 07:13:00  
Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Information displayed is correct as at the log date and time.

Enquire Related Logs

OK



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

| CLAIM SUBFOLDER TRACKING |                                         |               |                                                   |                                                      |                                                |            |                                                                 |
|--------------------------|-----------------------------------------|---------------|---------------------------------------------------|------------------------------------------------------|------------------------------------------------|------------|-----------------------------------------------------------------|
| Case                     | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'd | Status                                                          |
| Main                     | 07 Jun 2018<br><a href="#">Edit Reg</a> |               | 05 Jun 2018 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$4,650.00</b><br><a href="#">Edit Estimates</a> | <b>S\$4,650.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                           | Reference                                                                                                                                         | Claim Details          | Documents                                                        | Show All |         |             |              |            |       |
|--------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span>[Created by adjuster]</span>                                                              |                                                                                                                                                   |                        |                                                                  |          |         |             |              |            |       |
| Insured:                                                                                                                       | <b>HOPE FIRST RESPONSE PTE LTD</b> , Co. Reg. No.: 200915893N                                                                                     |                        |                                                                  |          |         |             |              |            |       |
| Main Claimant:                                                                                                                 | <b>SMRT TAXIS PTE LTD</b> , Co. Reg. No.: 198905369K                                                                                              |                        |                                                                  |          |         |             |              |            |       |
| Vehicle Reg. No.:                                                                                                              | <b>SHB5946H</b>                                                                                                                                   | Date of Loss:          | 31/05/2018 07:00 - :59<br>[64 Months From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:                                                                                                                    | <b>TP / 4662157292SG</b>                                                                                                                          | Policy/Cover Note No.: | 0999994976 (Comprehensive)                                       |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):                                                                                                    | <b>SLE7496M</b>                                                                                                                                   | Policy No. (Claimant): | D-18090213MFSH                                                   |          |         |             |              |            |       |
|                                                                                                                                |                                                                                                                                                   | Excess:                |                                                                  |          |         |             |              |            |       |
| Repairer:                                                                                                                      | <b>SMRT Automotive Services Pte Ltd (Woodlands)</b> 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628                             |                        |                                                                  |          |         |             |              |            |       |
| Handling Insurer:                                                                                                              | <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Syed-Yusoff, Saliha</b> ] Saliha.Syed-Yusoff@aig.com |                        |                                                                  |          |         |             |              |            |       |
| Claimant's Insurer:                                                                                                            | <b>MS First Capital Insurance Ltd (HQ)</b> - Tel: 62222311                                                                                        |                        |                                                                  |          |         |             |              |            |       |
| Adjuster:                                                                                                                      | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Sathya Sai Kathirrasen</b> ] ... [Final Rpt due 18/06/2018]          |                        |                                                                  |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span>View All</span> <span>Compose Case Mail</span>                                           |                                                                                                                                                   |                        |                                                                  |          |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>AIG_SG (07/06/2018): Request To Upload TP GIA Report</li> </ul>                         |                                                                                                                                                   |                        |                                                                  |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span>View All</span> <span>Search Tasks</span> <span>Create New Task</span> <span>Complete</span> |                                                                                                                                                   |                        |                                                                  |          |         |             |              |            |       |
| Due Date                                                                                                                       | Priority                                                                                                                                          | Type                   | Task Group                                                       | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                    |                                                                                                                                                   |                        |                                                                  |          |         |             |              |            |       |

## Claim Documents

\*SHB5946H (4662157292SG)  
[SLE7496M]  
TP  
SMRT TAXIS PTE LTD  
May 31 2018 7:00AM  
[HOPE FIRST RESPONSE PTE LTD]  
SMRT Automotive Services Pte Ltd

|                                |                 |                                                    |  |                    |  |              |  |              |          |                                                         |                                     |
|--------------------------------|-----------------|----------------------------------------------------|--|--------------------|--|--------------|--|--------------|----------|---------------------------------------------------------|-------------------------------------|
| Upload Documents               |                 | Upload Photos                                      |  | Compose New Letter |  | Upload Video |  | Upload Audio |          | View <span style="float: right;">View in Browser</span> |                                     |
| <b>Letters/Correspondences</b> |                 |                                                    |  |                    |  |              |  |              |          | 1 per page                                              | <input checked="" type="checkbox"/> |
| No                             | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)                  |  |                    |  |              |  | Thumbnail    | Print    |                                                         |                                     |
| 1                              | (Draft)         | Third Party Express Settlement - Payment Breakdown |  |                    |  |              |  |              | Edit     |                                                         |                                     |
| <b>Photos/Images</b>           |                 |                                                    |  |                    |  |              |  |              |          | 3 per page                                              | <input checked="" type="checkbox"/> |
| No                             | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                  |  |                    |  |              |  | Thumbnail    | Print    |                                                         |                                     |
| 1                              | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 2                              | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 3                              | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 4                              | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 5                              | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 6                              | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 7                              | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 8                              | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 9                              | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 10                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 11                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 12                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 13                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 14                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 15                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 16                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 17                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 18                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 19                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 20                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 21                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 22                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 23                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 24                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 25                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 26                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 27                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 28                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 29                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 30                             | 06/06/18 18:01  | General View                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 31                             | 06/06/18 18:01  | Odometer Reading                                   |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 32                             | 06/06/18 18:01  | Chassis Number                                     |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| <b>Documentation</b>           |                 |                                                    |  |                    |  |              |  |              |          | 1 per page                                              | <input checked="" type="checkbox"/> |

| Letters/Correspondences |                 |                                           | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|-----------------|-------------------------------------------|------------|-------------------------------------|
| No                      | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)         |            | Thumbnail Print                     |
| No                      | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         |            | Thumbnail Print                     |
| 1                       | 09/06/18 16:30  | TP ESTIMATE-MARKED                        |            | Load PDF                            |
| 2                       | 09/06/18 16:30  | TP GIA REPORT                             |            | Load PDF                            |
| 3                       | 12/09/18 08:41  | WORKSHOP INVOICE                          |            | Load PDF                            |
| 4                       | 12/09/18 08:41  | AUTHORISATION TO ACT FORM                 |            | Load PDF                            |
| 5                       | 12/09/18 08:41  | Release Voucher                           |            | Load PDF                            |
| 6                       | 12/09/18 08:41  | RENTAL RECEIPT                            |            | Load PDF                            |
| 7                       | 12/09/18 08:41  | LTA SEARCH                                |            | Load PDF                            |
| 8                       | 12/09/18 08:41  | LETTER TO OI                              |            | Load PDF                            |
| No                      | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG) |            | Thumbnail Print                     |
| 1                       | 07/06/18 12:09  | OI GIA REPORT                             |            | Load PDF                            |

## Documents Checklist

| DOCUMENTS CHECKLIST                                                                                                                                | Reset | Save | Print |
|----------------------------------------------------------------------------------------------------------------------------------------------------|-------|------|-------|
| There are no document checklists configured.                                                                                                       |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>       |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                     |        |                        |
|-------------------|---------------------|--------|------------------------|
| Vehicle No:       | SLE7496M (Insd veh) | Model: | SSANGYONG RODIUS SV270 |
|                   | SHB5946H (TP veh)   |        | 2.7 D (A)              |
| Date of Accident: | 31/05/2018          |        |                        |

|                                   |   |                                         |                             |
|-----------------------------------|---|-----------------------------------------|-----------------------------|
| Global Sum Settlement             | : | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| Repair Estimate                   | : | \$                                      | 8,379.54                    |
| Final Repair Cost                 | : | \$                                      | 5,440.00                    |
| Loss of Use                       | : | \$                                      | days at \$0.00 per day      |
| Rental (if any)                   | : | \$                                      | 6 days                      |
| LTA / GIA Search Fee              | : | \$                                      |                             |
| Others:                           | : | \$                                      |                             |
|                                   | : | \$                                      |                             |
| Final Settlement Sum (Global Sum) | : | \$                                      | 5,440.00                    |

**Is Third Party Workshop GIA Registered?** ☐ YES ☒ NO (Kindly indicate below)

**A) For Non GIA Registered Workshop:** Agreed Liability \_\_\_\_\_ 100 \_\_\_\_\_ (%)

**B) For GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

| Payment Instruction: Payee's Breakdown |                    |   |             |
|----------------------------------------|--------------------|---|-------------|
| 1)                                     | SMRT Taxis Pte Ltd | : | \$ 5,440.00 |
| 2)                                     |                    | : | \$          |
| 3)                                     |                    | : | \$          |

JOANNE LEE KHANG MIN

12 Sep  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18010310/VUA3Q2

Date: 12/09/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994976

Claimant Vehicle No : SHB5946H

Insured Vehicle No : SLE7496M

Date of Loss: 31/05/2018

Nature of Claim:

TP

Claim No: 4662157292SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB5946H

Make &amp; Model: SSANGYONG RODIUS SV270, 2.7 D (A)

Engine No: 66592622546464

Reg. Date: 31/01/2013 (Man. Year: 2011)

Chassis No: KPTV0B1FSCP066731

Colour: White

Odometer: 635782 km

Engine Capacity: 2696 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/65 R16

Rear Tyre Size:

215/65 R16

Front Left Side: Giti 6 mm

Rear Left Side:

West Lake 6 mm

Front Right Side: Giti 6 mm

Rear Right Side:

West Lake 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                  | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                                           | 5,163.54        | 3,556.73        | 1,606.81        | 31.12        |
| Miscellaneous Items                             | 0.00            | 0.00            | 0.00            |              |
| Labour                                          | 3,216.00        | 1,790.00        | 1,426.00        | 44.34        |
| Paintwork Labour                                | 0.00            | 0.00            | 0.00            |              |
| Towing                                          | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>             | <b>8,379.54</b> | <b>5,346.73</b> | <b>3,032.81</b> | <b>36.19</b> |
| <b>Approved Total (Overridden) (S\$)</b>        |                 | <b>4,650.00</b> |                 |              |
| <b>Nett Amount (S\$)</b>                        | <b>8,379.54</b> | <b>4,650.00</b> | <b>3,729.54</b> | <b>44.51</b> |
| <b>+ Car Rental (6.0 x S\$130.54/day) (S\$)</b> |                 | 783.24          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 7.00            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>5,440.24</b> |                 |              |
| <b>Global Sum Settlement (S\$)</b>              |                 | <b>5,440.00</b> |                 |              |

### INSPECTION

Date of Assignment: 05/06/2018

Date Inspected: 05/06/2018 Inspected At:

 SMRT Automotive Services Pte Ltd  
 (Woodlands)  
 60 Woodlands Industrial Park E4  
 Singapore 757705

Estimated Period of Repair: 4.0 days

---

**Adjuster:** Sathya Sai Kathirrasen

**Manager:** THIN THIN HLAING

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                                    | Condition     | Repairer's | Amount      |
|-----|-----|----------|------------------------------------------------|---------------|------------|-------------|
| 1   | 1   |          | *REAR BUMPER ASSY (DISC 10%)                   | Damaged       | 925.27 F   | *832.74 F   |
| 2   | 1   |          | *REAR BUMPER CLIP (DISC 10%)<br>(10 PCS)       | Necessary     | 42.50 F    | *38.25 F    |
| 3   | 1   |          | *LAMP ASSY ,REFLEX REFLECTOR LH (DISC 10%)     | Scratched     | 10.52 F    | *9.47 F     |
| 4   | 1   |          | *REVERSE SENSOR (DISC 10%)                     | Missing       | 165.10 F   | *148.59 F   |
| 5   | 1   |          | *BEAM ASSY -IMPACT RR BUMPER (DISC 10%)        | Dented        | 513.97 F   | *462.57 F   |
| 6   | 1   |          | *REAR TAILGATE ASSY (DISC 10%)                 | Dented        | 1,355.08 F | *1,219.57 F |
| 7   | 1   |          | *LAMP ASSY -LICENSE PLATE (DISC 10%)<br>(2PCS) | Damaged       | 98.50 F    | *88.65 F    |
| 8   | 1   |          | *LATCH ASSY ,T/GATE (DISC 10%)                 | Damaged       | 59.98 F    | *53.98 F    |
| 9   | 1   |          | *STRIKER ASSY ,T/GATE (DISC 10%)               | Necessary     | 9.89 F     | *8.90 F     |
| 10  | 1   |          | *HANDLE ASSY-T/GATE O/S (DISC 10%)             | Broken        | 14.16 F    | *12.74 F    |
| 11  | 1   |          | *COMBI LAMP ASSY-RR T/GATE LH (DISC 10%)       | Cracked       | 288.57 F   | *259.71 F   |
| 12  | 1   |          | *COMBI LAMP ASSY-RR T/GATE RH (DISC 10%)       | Cracked       | 288.57 F   | *259.71 F   |
| 13  | 1   |          | *EMBLEM REAR (DISC 10%)                        | Necessary     | 48.94 F    | *44.05 F    |
| 14  | 1   |          | *REAR NUMBER PLATE (SN)                        | Dented        | 15.00 F    | *15.00 F    |
| 15  | 1   |          | *REAR NUMBER PLATE FRAME (SN)                  | Dented        | 35.00 F    | *35.00 F    |
| 16  | 1   |          | *SMRT LOGO (SN)                                | Necessary     | 7.80 F     | *7.80 F     |
| 17  | 1   |          | *STICKER PRESTIGE (SN)                         | Necessary     | 60.00 F    | *60.00 F    |
| 18  | 1   |          | *LAMP ASSY ,REFLEX REFLECTOR RH                | Not Necessary | 10.52 F    | *- F        |
| 19  | 1   |          | *ABSORBER ENERGY RR BUMPER                     | Not Necessary | 111.73 F   | *- F        |
| 20  | 1   |          | *WEATHER STRIP T/GATE OPENING                  | Not Necessary | 97.67 F    | *- F        |
| 21  | 1   |          | *TRIM ASSY -T/GATE LWR                         | Not Necessary | 199.92 F   | *- F        |
| 22  | 1   |          | *GARNISH ASSY -T/GATE CTR                      | Not Necessary | 300.19 F   | *- F        |
| 23  | 1   |          | *ACTUATOR ASSY ,DR LOCK T/GATE                 | Not Necessary | 74.55 F    | *- F        |
| 24  | 1   |          | *RUBBERSEAL GLASS RR QTR                       | Not Necessary | 11.04 F    | *- F        |
| 25  | 1   |          | *SEALANT W/SCREEN                              | Not Necessary | 37.00 F    | *- F        |
| 26  | 1   |          | *PANEL END INNER                               | Not Necessary | 239.33 F   | *- F        |
| 27  | 1   |          | *PANEL END OUTER                               | Not Necessary | 105.74 F   | *- F        |
| 28  | 1   |          | *SEALANT SIKAFLEX                              | Not Necessary | 37.00 F    | *- F        |

F=Franchise part.

|                    |          |          |
|--------------------|----------|----------|
| Total Parts (\$\$) | 5,163.54 | 3,556.73 |
|--------------------|----------|----------|

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                       | Particulars                                                            | Lab.Type | Repairer's | Amount   |
|--------------------------|------------------------------------------------------------------------|----------|------------|----------|
| <u>Labour Items</u>      |                                                                        |          |            |          |
| 1                        | PANEL BEATING & BODY WORK                                              | New      | 1,014.00   | 700.00   |
| 2                        | SPRAY PAINT                                                            | New      | 1,306.00   | 700.00   |
| 3                        | TOWING CHARGE                                                          | New      | 56.00      | 50.00    |
| 4                        | TO CHECK WIRING AND SYSTEM FUNCTION                                    | New      | 80.00      | 30.00    |
| 5                        | TO TRANSFER REAR TAILGATE MECHANISM                                    | New      | 120.00     | 60.00    |
| 6                        | TO REMOVE AND REFIX REAR WINDSCREEN                                    | New      | 120.00     | 60.00    |
| 7                        | TO TEST AND REFIX REVERSE SENSOR SYSTEM                                | New      | 120.00     | 60.00    |
| 8                        | TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM<br>TO FACILITATE REPAIR | New      | 120.00     | 60.00    |
| 9                        | TO REMOVE AND REFIT WIRE HARDESS                                       | New      | 120.00     | 50.00    |
| 10                       | TO REPLACE SUNDRY PARTS                                                | New      | 100.00     | 20.00    |
| 11                       | TO WASH AND VACUUM                                                     | New      | 60.00      | 0.00     |
| Gross Labour Cost (\$\$) |                                                                        |          | 3,216.00   | 1,790.00 |

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;