

INSURANCE CASE OWNER

Anchor

CC 6, LER 180

10349, Unwashed

LKK

IDAC

Surveyor:

interview

DOI:

6/6/18

Date / Time:

6/6/18

Registered in Merimen:

8/6/18

Pre-assign / CCU / FTE

SLH 982 G



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :S\$

D.O.A.:

Place of Accident:

Is driver the owner?

( YES (NO) )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

STY 3196 Z



INSRS:

WSP:

Tel:

Liability:

RMKS:

V Fix



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

1/6/18  
unaru

STY 3196 Z - C6/11/12/25/9/11/10/20/18: 01/12/18  
SLH 982 G - X

11/6

RENT. 4 to send letter to LER.

Email to workshop liability under

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

7/5/19 email.

After call ltr to OI:

unaru

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

( days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

749.00

Loss of Rental (LOR):

S\$

( days)

Loss of Use (LOU):

S\$

100.00 (\$ 50 x 2 days)

Loss of Income (LOI):

S\$

( \$ x days)

LOR only ☐ LOU only ☐

LOR + LOU ☐

LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

7.45

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

856.45

Global Sum S\$:

850.00

FINAL PAYMENT

Date/Time:

Confirm w/it:

Email

Call

Payee 1:

S\$

850.00

Name 1:

V Fix Auto Service Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

2/6/18

Signature

REF:

A16/

# ASSIGNMENT

From: Date: 6/6/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJY31962

at Workshop m/s Vix Auto

of 60 kuli Bkt Ave 6

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

1pm

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS <sup>1up</sup>

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJY31962 Yr Regn: 8 10

Type: M.Chr / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota corolla Altis cc 1598

Colour: Gold A/C: Insured / Std / NI / NA

Sp. Reading: 139143 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRU532EE106179073

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 195/65-2.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MLC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 6 mm

L/Bal: 8 mm

D.O.A.

Rear

R/Bal: 6 mm

L/Bal: 6 mm

D.O.I. 6/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/5/19 Confirm US \$700.00 with 2 working day

(Red) \$663.50  
(49.1)

Date/Time: File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time: File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

3 - RS - SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech Invs (\$

☐ Weekend (\$




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile   |                |   |                 |   |
|---|----------------|---|-----------------|---|
| AIG ASIA PACIFIC INSURANCE PTE LTD  |                | Ref : CC6/LCR18010349/Uwa3  |                 |   |
| 78 SHENTON WAY #08-16<br>CHARTIS BUILDINGS SINGAPORE 079120   |                | Date : 07-06-2018   |                 |  |
|   |                | Code : LCR  |                 |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>   |                |   |                 |   |
|   | Insured Veh.   | SLH 982G  | Veh. Inspected  | SJY 3196Z   |
|   | Policy No.     |   | Coverage (\$)   | 0.00  |
|   | Claim No.      |   | Excess (\$)     | 0.00  |
|   | Assign From    |   | Assign Date     | 07/06/2018  |
| <b>2. Vehicle Particulars &amp; Condition</b>   |                |   |                 |   |
|   | Make & Model   | c.c 0   |                 |   |
|   | Engine No.     | HIDDEN  | Year of Reg.    |   |
|   | Chassis No.    |   | Colour          |   |
|   | Odometer       | -   | Steering        |   |
|   | Brakes         |   | Modification    |   |
|   | General        |   |                 |   |
| <b>3. Conditions of Tyres</b>   |                |   |                 |   |
|   |                | Size  | Make            | Balance   |
|   | R/H Front Tyre |   |                 | mm  |
|   | L/H Front Tyre |   |                 | mm  |
|   | R/H Rear Tyre  |   |                 | mm  |
|   | L/H Rear Tyre  |   |                 | mm  |
| <b>4. Description of Damages</b>  |                |   |                 |   |
|   |                |   |                 |   |
| <b>5. General Information</b>   |                |   |                 |   |
|   | Accident Date  | 26/05/2018  | Inspection Date | 06/06/2018  |
|   | Survey held at | VFIX AUTO SERVICE PTE LTD<br>60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT<br>SINGAPORE 417892 |                 |   |
| <b>5a. Remarks</b>  |                |   |                 |   |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                |   |                 |   |

M/S AIG ASIA PACIFIC INS PTE LTD  
CHARTIS BUILDING  
78 SHENTON WAY #08-16  
SINGAPORE 079120

## ESTIMATE

DATE : 31/05/2018  
ACC DATE : 26/05/2018  
REF NO. : VFIX-TP20180478  
POLICY NO :

### Attention: Motor Claim Department

RE : VEHICLE NO.SJY3196Z TOYOTA ALTIS

| DESCRIPTION               | AMOUNT S\$ |
|---------------------------|------------|
| 1 1 REAR BUMPER           | 532.00     |
| 2 1 REAR SIDE RETAINER LH | 86.00      |
|                           | 618.00     |
| LESS 25%                  | 154.50     |
|                           | \$ 463.50  |

| LABOUR & MISCELLANEOUS:   | AMOUNT S\$ |
|---|------------|
| 1 To remove damaged parts with all necessary components/attachments                                 | 400.00     |
| 2 To spray paint replaced/repared body panels inclusive of preparatory works and painting materials | 400.00     |
| 3 To transfer reverse sensor check funtion  | 100.00     |
|   | \$ 900.00  |

GRAND TOTAL : \$ 1,363.50

813.5

SINGAPORE DOLLARS : ONE THOUSAND THREE HUNDRED SIXTY THREE & CENTS  
FIFTY ONLY

Vfix Auto Service Pte Ltd



as + Abdul  
Lbr  
1/5 = 700  
247.

As a result, the Insured hereby notify the Insurer of the following:

- To resurvey before/after spray painting
- To replace damaged part(s) during resurvey
- All amounts are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Replacement part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repainer:

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 8679A

**Vehicle Details**

Vehicle No.: SJY3196Z

Vehicle to be Exported: No

Intended De-registration Date: 06 Jun 2018

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 AUTO

Primary Colour: Beige

Manufacturing Year: 2010

Engine No.: 3ZZB010486

Chassis No.: MR053ZEE106179073

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$16,680.00

Original Registration Date: 20 Aug 2010

First Registration Date: 20 Aug 2010

Transfer Count: 1

Actual ARF Paid: \$16,680.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 19 Aug 2020

PARF Rebate Amount: \$10,008.00

**Intended COE Rebate Details**

COE Expiry Date: 19 Aug 2020

COE Category: A - Car (1600cc &amp; below)

COE Period(Years): 10

QP Paid: \$29,000.00

COE Rebate Amount: \$6,384.00

**Total Rebate Amount: \$16,392.00**

The information contained herein is correct as at 06 Jun 2018

OK

13 JUL 2018

Our Ref. No. : VFIX-TP20180478

**MOTOR CLAIMS DEPT**  
**AIG ASIA PACIFIC INSURANCE PTE LTD**  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120

 **vfix**  
Vfix Auto Service Pte Ltd  
60 Kakit Bukit Ave 6 Ark@KB  
Singapore 417892  
Email: contact@vfixauto.com.sg  
Tel: +65 6455 2957 F: +65 6445 2368  
UEN/GST Reg No: 201602964H

**WITHOUT PREJUDICE**

Dear Sir / Madam

**PROPERTY CLAIM ONLY**

**ACCIDENT INVOLVING SJY3196Z AND SLH982G ON 26 MAY 2018  
ALONG PIE TOWARDS JURONG (AFTER EUNOS EXIT)**

We refer to the above-mentioned accident.

We are writing on behalf of **MR CHUA KAY HOCK** the registered owner  
of motor vehicle number **SJY3196Z** which was involved in the above accident.

We are instructed that the above accident was caused by the negligence and management of your  
insured's vehicle number **SLH982G**. As a result of the above accident, our client's vehicle  
was damaged and our client's has been put to loss and expense, particulars of which are as follows :-

|                      |                                    |             |               |
|----------------------|------------------------------------|-------------|---------------|
| 1                    | Cost of Repair                     | :S\$        | 749.00        |
| 2                    | Loss of Use ( 2 days X \$ 120.00 ) | :S\$        | 240.00        |
| 3                    | LTA Fees                           | :S\$        | 7.45          |
| <b>TOTAL AMOUNTS</b> |                                    | <b>:S\$</b> | <b>996.45</b> |

We enclosed a list of the supporting documents :-

- (a) Original Final Repair Bill
- (b) LTA Tax Invoice
- (c) GIA / Police Report lodged by Our Client
- (d) Letter of Authority

Kindly acknowledge receipt of the above said documents and your favourable reply is greatly  
appreciated.

**Any settlement reached is strictly without prejudice to and shall not affect any other claims arising  
from this accident. Settlement is solely for the items claimed only.**

Yours Faithfully,  
VFIX AUTO SERVICE PTE LTD

  
Ken Tan



**Vivian Lau (LKKAuto)**

---

**From:** Vivian Lau (LKKAuto)  
**Sent:** Friday, 17 May, 2019 10:39 AM  
**To:** eyap@lioncityrentals.com.sg; insurance@lioncityrentals.com.sg  
**Cc:** Hsiao Tong (LKKAuto)  
**Subject:** ACCIDENT INVOLVING SLH 982G and SJY 3196Z on 26/05/2018

Our Ref: CC6/LCR18010349/Uwa3

17 May 2019

**LION CITY RENTALS PTE LTD**

Dear Sir/Madam,

**ACCIDENT INVOLVING SLH 982G and SJY 3196Z on 26/05/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

**Vivian Lau** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-8625 | email: [Vivianlau@lkkauto.com](mailto:Vivianlau@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

To: AIG ASIA PACIFIC INS PTE LTD  
78 SHENTON WAY  
#07-16 AIG BLDG  
SINGAPORE 079120

Dear Sir / Madam,

Claimant:

ACCIDENT INVOLVING SJY3196Z AND SLH982G ON 28/05/2018 AT  
PIE TOWARDS JURONG (AFTER EUNOS EXIT)

I/We, CHUA KAY HOCK, am/are the registered owner of  
motor car no SJY3196Z

Please be informed that I have assigned all compensation monies due to me/us in the above  
accident to VFIX AUTO SERVICE PTE LTD.

I/We hereby authorized you to release all monies pertaining to the above mentioned accident  
to VFIX AUTO SERVICE PTE LTD and forward the settlement cheque to VFIX AUTO SERVICE PTE  
LTD whom I/we have authorized to collect the said compensation monies.

Thank you,



Signature of Claimant &  
Company Stamp if applicable

IC no.: S1618679A

Date: 13/07/18



Signature of Witness

IC no.: S1527552I

Date: 13/07/18



**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, VFIX AUTO SERVICE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for \$850.00 (Global Sum) for vehicle no. SJY 3196Z that was damaged pursuant to the accident which occurred on 26/05/2018 (date) along PIE TWDS JURONG (location) involving vehicle no/s SLH 982G.

This is pursuant to the inspection conducted on 06/06/2018 (date) at "the workshop".


We/I confirm that we/I are/am authorized by the owner CHUA KAY HOCK ("the third party claimant") of vehicle no. SJY 3196Z make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".



We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJY 3196Z (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 19 (day) of Jun (month) 2019 (year)

CVS  
  
Signed by appointed surveyor

  
  
Signed by "the workshop" (with chop)

\*\*\* This Discharge Voucher applies only to the claimant's claim for his property damage and will not affect his personal injuries claim and/or uninsured losses claim on a later date.

Further, the settlement terms herein shall not be used as evidence to prejudice the claimant's personal injuries claim and/or other uninsured losses claim arising out of the subject matter in this action.



Vfix Auto Service Pte Ltd  
60 Kaki Bukit Ave 6 Ark@KB  
Singapore 417892  
Email : contact@vfixauto.com.sg  
Tel: +65 6455 2957 F: +65 6445 2368  
UEN/GST Reg No: 201602964H

#### FINAL REPAIR BILL

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120

DATE : 13/07/2018  
VEHICLE NO : SJY3196Z  
MAKE/MODEL : TOYOTA COROLLA  
ACC DATE : 26/05/2018  
CLAIM NO : VFIX-TP20180478  
POLICY NO :

---

AMOUNT S\$

#### LUMP SUM REPAIR COST

|               |               |
|---------------|---------------|
| Repair Amount | 700.00        |
| 7% GST        | 49.00         |
| Total         | <u>749.00</u> |

SINGAPORE DOLLARS: SEVEN HUNDRED & FORTY NINE  
ONLY

VFIX AUTO SERVICE PTE LTD

  
Ken Tan





Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701

GST Registration No. : M4-0006529-2

SY 3196 Z

Print Date/Time : 30 May 2018 / 11:56:16

Receipt Date/Time : 30 May 2018 / 11:53:31

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-180530-000795

Previous Receipt No. :

| S/N   | Item Description/<br>Business Transaction Reference<br>No.         | Amount<br>Before<br>GST (S\$)    | GST<br>Amount<br>(S\$) | Amount<br>After GST<br>(S\$) |
|---|--|----------------------------------|------------------------|------------------------------|
| Result of Insurance Enquiry - SLH982G<br>As at 26 May 2018/14:40:00<br>Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD. |  |                                  |                        |                              |
| 1   | Insurance Enquiry - SLH982G<br>Enquiry Fee<br>20180530115207015809 | 7.00                             | 0.49                   | 7.49                         |
| <b>Sub-Total</b>  |  | 7.00                             | 0.49                   | 7.49                         |
| <b>Total Before Rounding</b>  |  | 7.00                             | 0.49                   | 7.49                         |
| <b>Rounding Difference</b>  |  |                                  |                        | 0.04                         |
| <b>Total Amount Payable</b>   |  |                                  |                        | 7.45                         |
| <b>Paid By</b>  |  |                                  |                        |                              |
|   | xxxxxxxxxxxx0101   | Credit Card: Visa<br>/MasterCard |                        | 7.45                         |
| <b>Total</b>  |  |                                  |                        | 7.45                         |
| <b>Cash Change</b>  |  |                                  |                        | 0.00                         |
| <b>Tendered Amount</b>  |  |                                  |                        | 7.45                         |
| <b>Excess Refundable Amount</b>   |  |                                  |                        | 0.00                         |

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

| CLAIM SUBFOLDER TRACKING |   |               |   |  |  |            |   |
|--------------------------|---|---------------|---|--|--|------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt  | Adj Submitted                                | Ins Auth'd | Status  |
| Main                     | 11 Jun 2018<br><a href="#">Edit Reg</a> |               | 06 Jun 2018 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$700.00</b><br><a href="#">Edit Estimates</a> | <b>S\$700.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |


  

| Main  | Reference | Claim Details   | Documents  | Show All |         |             |              |            |       |
|---|-----------|---|------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>   |           |   |            |          |         |             |              |            |       |
| Insured: <b>LCRF Pte Ltd</b> , Co. Reg. No.: 201624597K   |           |   |            |          |         |             |              |            |       |
| Main Claimant: <b>CHUA KAY HOCK</b> , ID: S1618679A   |           |   |            |          |         |             |              |            |       |
| Vehicle Reg. No.: <b>SJY3196Z</b>   |           | Date of Loss: 26/05/2018 14:00 - :59<br>[93 Months and 6 Days From LTA Reg Date (Man Yr)] |            |          |         |             |              |            |       |
| Claim Type: <b>TP / 8735879204SG</b>  |           | Policy/Cover Note No.: 0999994790 (Comprehensive)   |            |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured): <b>SLH982G</b>  |           | Policy No. (Claimant): 5084875351-01CLASSIC   |            |          |         |             |              |            |       |
|   |           | Excess:   |            |          |         |             |              |            |       |
| Repairer: <b>Vfix Auto Service Pte Ltd - Kaki Bukit (HQ)</b> 60 KAKI BUKIT AVE 6, ARK@KB, 417892 Kaki Bukit - Tel:  |           |   |            |          |         |             |              |            |       |
| Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Ng, Hai-Chuan</b> ] Hai-Chuan.Ng@aig.com                       |           |   |            |          |         |             |              |            |       |
| Claimant's Insurer: <b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:   |           |   |            |          |         |             |              |            |       |
| Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 19/06/2018]                                       |           |   |            |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>   |           |   |            |          |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>AIG_SG (11/06/2018): No OI GIA Report</li> </ul>   |           |   |            |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |           |   |            |          |         |             |              |            |       |
| Due Date  | Priority  | Type  | Task Group | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.   |           |   |            |          |         |             |              |            |       |

## Claim Documents

**\*SJY3196Z (8735879204SG)**  
**[SLH982G]**  
**TP**  
**CHUA KAY HOCK**  
**May 26 2018 2:00PM**  
**[LCRF Pte Ltd]**  
**Vfix Auto Service Pte Ltd - Kaki Bukit**

|                         |                 |   |               |  |  |                    |  |  |              |  |  |              |  |           |            |                                     |                                  |                                     |  |  |
|-------------------------|-----------------|---|---------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|-----------|------------|-------------------------------------|----------------------------------|-------------------------------------|--|--|
| Upload Documents        |                 |   | Upload Photos |  |  | Compose New Letter |  |  | Upload Video |  |  | Upload Audio |  |           | View       |                                     |                                  | View in Browser                     |  |  |
| Video                   |                 |   |               |  |  |                    |  |  |              |  |  |              |  |           | 1 per page |                                     | <input type="button" value="v"/> | <input checked="" type="checkbox"/> |  |  |
| No                      | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)   |               |  |  |                    |  |  |              |  |  |              |  | Thumbnail |            | Print                               |                                  |                                     |  |  |
| 1                       | 17/10/18 16:30  | Video - Accident  |               |  |  |                    |  |  |              |  |  |              |  |           | Load MP4   |                                     |                                  |                                     |  |  |
|                         |                 |   |               |  |  |                    |  |  |              |  |  |              |  |           |            |                                     |                                  |                                     |  |  |
| Letters/Correspondences |                 |   |               |  |  |                    |  |  |              |  |  |              |  |           | 1 per page |                                     | <input type="button" value="v"/> | <input checked="" type="checkbox"/> |  |  |
| No                      | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)   |               |  |  |                    |  |  |              |  |  |              |  | Thumbnail |            | Print                               |                                  |                                     |  |  |
| 1                       | (Draft)         | Third Party Express Settlement – Payment Breakdown                        |               |  |  |                    |  |  |              |  |  |              |  |           | Edit       |                                     |                                  |                                     |  |  |
|                         |                 |   |               |  |  |                    |  |  |              |  |  |              |  |           |            |                                     |                                  |                                     |  |  |
| Assessment Reports      |                 |   |               |  |  |                    |  |  |              |  |  |              |  |           | 1 per page |                                     | <input type="button" value="v"/> | <input checked="" type="checkbox"/> |  |  |
| No                      | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG)                                 |               |  |  |                    |  |  |              |  |  |              |  | Thumbnail |            | Print                               |                                  |                                     |  |  |
| 1                       | 16/10/18 09:27  | Accident Statement<br>From: SC - Reg. No: SLH982G, Claimant: LCRF PTE LTD |               |  |  |                    |  |  |              |  |  |              |  |           | Load HTM   |                                     |                                  |                                     |  |  |
|                         |                 |   |               |  |  |                    |  |  |              |  |  |              |  |           |            |                                     |                                  |                                     |  |  |
| Photos/Images           |                 |   |               |  |  |                    |  |  |              |  |  |              |  |           | 3 per page |                                     | <input type="button" value="v"/> | <input checked="" type="checkbox"/> |  |  |
| No                      | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)   |               |  |  |                    |  |  |              |  |  |              |  | Thumbnail |            | Print                               |                                  |                                     |  |  |
| 1                       | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 2                       | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 3                       | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 4                       | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 5                       | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 6                       | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 7                       | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 8                       | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 9                       | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 10                      | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 11                      | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 12                      | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 13                      | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 14                      | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 15                      | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 16                      | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 17                      | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 18                      | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 19                      | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 20                      | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 21                      | 24/10/18 16:33  | General View  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 22                      | 24/10/18 16:33  | Reinspection Photo  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 23                      | 24/10/18 16:33  | Reinspection Photo  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 24                      | 24/10/18 16:33  | Reinspection Photo  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
| 25                      | 24/10/18 16:33  | Reinspection Photo  |               |  |  |                    |  |  |              |  |  |              |  |           | Load JPG   | <input checked="" type="checkbox"/> |                                  |                                     |  |  |
|                         |                 |   |               |  |  |                    |  |  |              |  |  |              |  |           |            |                                     |                                  |                                     |  |  |
| Documentation           |                 |   |               |  |  |                    |  |  |              |  |  |              |  |           | 1 per page |                                     | <input type="button" value="v"/> | <input checked="" type="checkbox"/> |  |  |

| Video |                 |   | 1 per page   | <input checked="" type="checkbox"/> |
|-------|-----------------|---|--|-------------------------------------|
| No    | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)   | Thumbnail  | Print                               |
| No    | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)   | Thumbnail  | Print                               |
| 1     | 09/06/18 17:23  | TP GIA REPORT   |  Load PDF |                                     |
| 2     | 12/06/18 10:42  | Email non reporting letter ACCIDENT INVOLVING SLH 982G AND SJY 3196Z ON 26.05.2018 1440 Hrs ALONG P |  Load PDF |                                     |
| 3     | 24/10/18 16:35  | ESTIMATE  |  Load PDF |                                     |
| 4     | 17/05/19 10:48  | Email letter to OI ACCIDENT INVOLVING SLH 982G and SJY 3196Z on 26.05.2018.                         |  Load PDF |                                     |
| 5     | 03/07/19 16:31  | WORKSHOP INVOICE  |  Load PDF |                                     |
| 6     | 03/07/19 16:31  | AUTHORISATION TO ACT FORM   |  Load PDF |                                     |
| 7     | 03/07/19 16:31  | Release Voucher   |  Load PDF |                                     |
| 8     | 03/07/19 16:31  | LTA SEARCH  |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                          | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. |       |      |       |

|   |
|---|
| <p><b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b></p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <p><b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p> |
|---|

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                    |        |                      |
|-------------------|--------------------|--------|----------------------|
| Vehicle No:       | SLH982G (Insd veh) | Model: | TOYOTA COROLLA ALTIS |
|                   | SJY3196Z (TP veh)  |        | 1.6 (A)              |
| Date of Accident: | 26/05/2018         |        |                      |

|                                   |   |   |                                 |                              |
|-----------------------------------|---|---|---------------------------------|------------------------------|
| Global Sum Settlement             | : | <input checked="" type="checkbox"/> [ X ] Yes | <input type="checkbox"/> [ ] No |                              |
| Repair Estimate                   | : | \$  |                                 | 1,458.95                     |
| Final Repair Cost                 | : | \$  |                                 | 850.00                       |
| Loss of Use                       | : | \$  |                                 | 2.00 days at \$50.00 per day |
| Rental (if any)                   | : | \$  |                                 | days                         |
| LTA / GIA Search Fee              | : | \$  |                                 |                              |
| Others:                           | : | \$  |                                 |                              |
|                                   | : | \$  |                                 |                              |
| Final Settlement Sum (Global Sum) | : | \$  |                                 | 850.00                       |

**Is Third Party Workshop GIA Registered?**    ☐ [ ] YES    ☒ [ X ] NO    (Kindly indicate below)

**A) For Non GIA Registered Workshop:**    Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

**B) For GIA Registered Workshop:**    BOLA Applicable: Yes/ No    BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%)    Assessed Liability (\*): \_\_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

| Payment Instruction: Payee's Breakdown |                           |      |        |
|--|---------------------------|------|--------|
| 1)                                     | Vfix Auto Service Pte Ltd | : \$ | 850.00 |
| 2)                                     |                           | : \$ |        |
| 3)                                     |                           | : \$ |        |
| 4)                                     |                           | : \$ |        |

JOANNE LEE KHANG MIN

03 Jul  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18010349/UWA3Q2

Date: 03/07/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994790

Claimant Vehicle No: SJY3196Z

Insured Vehicle No: SLH982G

Date of Loss: 26/05/2018

Nature of Claim: TP

Claim No: 8735879204SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJY3196Z

Make &amp; Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZB010486

Reg. Date: 20/08/2010 (Man. Year: 2010)

Chassis No: MR053ZEE106179073

Colour: Gold

Odometer: 139143 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                  | Repairer's      | Adjuster's    | Difference    | Diff %       |
|---|-----------------|---------------|---------------|--------------|
| Parts   | 463.50          | 463.50        | 0.00          | 0.00         |
| Miscellaneous Items                             | 0.00            | 0.00          | 0.00          |              |
| Labour  | 900.00          | 450.00        | 450.00        | 50.00        |
| Paintwork Labour                                | 0.00            | 0.00          | 0.00          |              |
| Towing  | 0.00            | 0.00          | 0.00          |              |
| <b>Calculated Gross Total (S\$)</b>             | <b>1,363.50</b> | <b>913.50</b> | <b>450.00</b> | <b>33.00</b> |
| <b>Approved Total (Overridden) (S\$)</b>        |                 | <b>700.00</b> |               |              |
| (S\$)   | 1,363.50        | 700.00        | 663.50        | 48.66        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 95.45           | 49.00         | 46.45         | 48.66        |
| <b>Nett Amount (S\$)</b>                        | <b>1,458.95</b> | <b>749.00</b> | <b>709.95</b> | <b>48.66</b> |
| <b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b> |                 | 100.00        |               |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 7.45          |               |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>856.45</b> |               |              |
| <b>Global Sum Settlement (S\$)</b>              |                 | <b>850.00</b> |               |              |

### INSPECTION

Date of Assignment: 06/06/2018

Date Inspected: 06/06/2018 Inspected At:



VFIX AUTO SERVICE PTE LTD  
60 KAKI BUKIT AVE 6, ARK@KB, 417892  
KAKI BUKIT  
SINGAPORE 417892

Estimated Period of Repair: 2.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** VIVIAN LAU PEI FENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars            | Condition         | Repairer's   | Amount        |
|-----|-----|----------|------------------------|-------------------|--|---------------|
| 1   | 1   |          | *REAR BUMPER           | Dented / Deformed | 532.00 FL  | *532.00 FL    |
| 2   | 1   |          | *REAR SIDE RETAINER LH | Bent              | 86.00 FL   | *86.00 FL     |
|     |     |          |                        |                   | <b>Sub Total (\$\$)</b>                                    | <b>618.00</b> |
|     |     |          |                        |                   | <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | <b>154.50</b> |
|     |     |          |                        |                   | <b>Total Parts (\$\$)</b>                                  | <b>463.50</b> |

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                       | Particulars   | Lab.Type | Repairer's | Amount |
|--------------------------|---|----------|------------|--------|
| <u>Labour Items</u>      |   |          |            |        |
| 1                        | TO REMOVE DAMAGED PARTS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS                                  | New      | 400.00     | 200.00 |
| 2                        | TO SPRAY PAINT REPLACED /REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS | New      | 400.00     | 200.00 |
| 3                        | TO TRANSFER REVERSE SENSOR CHECK FUNCTION   | New      | 100.00     | 50.00  |
| Gross Labour Cost (\$\$) |   |          | 900.00     | 450.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >