

ASS. REC. BY:

REF: CS3/MSG18010354/Pk4d302 Special Instruction: ✓

Survey of Menimen

Jesul

ASSIGNMENT (Office)

From (Person): Lionel Tan

of MSIG

Date/Time: 06/06/18 @ 4:45pm

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SBU 9699R Insured: SFX 4291C

at Workshop m/s Autowerke Automotive Tel: 9630 1281

of 8 Kaki Bukit Ave 4 #05-01/02

Policy No: 277 47 272 QMX Claim No: 560374

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 03/06/2018

CA / REV / REP. / REV 24 HRS (up) H.O.D. Endorsement:

Date/Time: 9:30am @ 7/6/18 Person Contacted: Alex Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SBU 9699R - X
	SFX 4291C - X

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted: Vehicle: IN/OUT

D.O.A. 05/06/18 D.O.I. 20/06/18

Survey held at Autowerke Automotive

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Estimated repair range \$4,000 - \$5,000
23/6/18	Submit PRS Report.

22/6/2018

RECEIVED 25 JUN 2018

Date/Time. File Pass to? : Preli. Report

1) : Final Report

Date/Time. File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add-Fee: : Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:	120
Transportation	30
) S + RS. SI	
) Photos	
) Others	10
TOTAL	180