

22/03/2001

ASS. REC. BY:

REF: CS/FCI 18010358 / T17d3

Special Instruction:

Surveyor:

(WS)

ASSIGNMENT (Office)

From (Person):

Lurene jaw

of

FCI

Date/Time:

06/06/18 @ 7:41pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SIX 910D

Insured:

SHC 0477Y

at Workshop m/s

Wearnes Automotive

Tel:

9129 4556

of

45 Leng Kee Rd

Policy No.:

Claim No.:

D18001487MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/06/2018

CA / REV / REP. / REV 24 HRS

WP

H.O.D. Endorsement:

Date/Time:

9:11am 7/6/18

Person Contacted:

Michelle

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SIX 910D - X

SHC 477Y - CS / INC 09011089 / Yh

DOA: 18/5/2009

26/6 @ 5:01pm report via preli advise.

Part by Part \$7317.48 (Red: 6600.02 : 47%)

Est. Repairs:

days

Res: Yes or No

D.O.A.

DOI: 22/6/18 @ 1:30

Lump Sum:

%

3 Val: Yes or No

Survey held at

Wearnes

CA / REV / REP. / 24 HRS

WP

Des. of Damages: Frt (Rear / O/S / N/S / U/C / Rooftop) or

Date

Person Contacted:

Vehicle: IN / OUT
Michelle

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 16 JUL 2018

Date/Time: File Pass 107

16/7 Typist

Date/Time: File Return 107



Preli. Report



Final Report

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



Site Insp. \$



Interview. \$



Tech. Insp. \$



Weekend \$

Survey Fee:

Transportation:

V. S + P. \$

T. Thins

I. Other:

TOTAL

3x15=45

170+45

50

24


289

Report Format:

TP

Lump Sum / I.B. \$

7317.48

Job Sheet (/ClaimWS/Surveyor/JobSheet/241127)  PRI Documents  Close 

PRI Header Details

Claim No	D18004487MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & WEARNES
Workshop Name	WEARNES AUTOMOTIVE PTE LTD (Contact Person : MICHELLE ONG)	Survey Location & Contact Details	45 LENG KEE ROAD Mobile: 91294556 , Phone: 0 , Fax: 62647137 EmailId: MICHELLE.ONG@WEARNES.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0477Y	TP Vehicle No	SJX910D
PRI Recieved Date	06-06-2018 03:57:30 PM	Surveyor Appointed Date	06-06-2018 07:40:28 PM	Surveyor Accept Date	07-06-2018 0


Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	07-06-2018	Upload Survey Report *:	
-----------------------------	---	----------------------	------------	-------------------------	---

Vehicle Particulars


Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload



File Name	Action
-----------	--------

Surveyor Job Remarks

Remarks	
---------	---

Driving Date Pass	10 06/12 mmv / 1420Y
Year of Driving Experience	04dd/10 mmv / 200Y
Occupation	Year(s) Month(s)
Gender	<input checked="" type="radio"/> Indoor <input type="radio"/> Outdoor
Contact Number / Mobile Phone / Fax No	<input checked="" type="radio"/> Male <input type="radio"/> Female
	96966642

WEARNES AUTO PROTECTOR (VOLVO) PRIVATE VEHICLE

Name of Policyholder : Malini Kapur
 Period of Insurance : 30 Mar 2018 To 29 Mar 2019
 Engine No. : B5254T4411574
 Chassis No. : YV1CZ5957A1544439

Vehicle No. : SJX910D
 Policy No. : 2100201381-08
 Endorsement No. :
 Issued Date : 21 Mar 2018

ABOUT THE COVER

Make/Model : VOLVO XC90 2.5T
 Engine Capacity/Tonnage : 2,521.00 CC
 Driver Restriction : NA

Sum Insured : Market Value
 Off Peak Car : No

First Year of Registration : 2010
 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*:

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*:

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 2000cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Malini Kapur - \$1800 (Own Damage), Atul Kapur - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Wearnes Automotive Pte Ltd Add: 249 Alexandra Road, Singapore 159935 64304890 63789350

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1969 (Malaysia).

0603485716

WEARNES AUTOMOTIVE - RL (V)

45 LENG KEE ROAD

SINGAPORE 159103

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Malini

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSC/17

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7247579H



AIRI BIN IBRAHIM

Sex: **M**
Date of Birth: **16-12-1972**
Country of Birth: **SINGAPORE**




REPUBLIC OF SINGAPORE DRIVING LICENCE



Licensee Name: **AIRI BIN IBRAHIM**
Licence Number: **S7247579H**

Birth Date: **16 Dec 1972**
Expiry Date: **10 Oct 2003**




2338880



NRIC No. **S7247579H**

Health Group: **A+** Date of Issue: **08-08-1994**

Address: **APT BLK 504 WOODLANDS DRIVE 14 #07-130 SINGAPORE 730604**


NRIC No: **S7247579H** Date: **08-08-1994** No: **2704268**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	Pass Date
Class 2B	Motorcycles not exceeding 200 cc	13 Oct 1993
Class 2	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	04 Oct 2000

NP 425A

Licence No: **S7247579H**



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/06/2018 19:09
Date Of Accident	04/06/2018 11:30
Exact Location Of Accident	ALONG ORCHARD LINK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX910D
Insured/Policyholder	
Name Of Registered Owner	MALINI KAPUR
NRIC No	S7077350C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96966642
Alternative Phone No	OTHERS-96966642

Vehicle Particulars

Manufacturer	VOLVO
Model	XC90-2.0 T5 (A)
Exact Purpose for which vehicle was being used at time of accident	SOCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100201381
Cover Note Number	

Driver

Name of Driver	AIRI BIN IBRAHIM
NRIC No	S7247579H
Date Of Birth	16/12/1972
Occupation	INDOOR
Date Of Driving Pass	04/10/2000
Driving Experience	17 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96966642
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	504 WOODLANDS DRIVE 14
	07-130
Postcode	730504
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC477Y
Vehicle Make/Model/Colour	YELLOW TAXI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TAN THIAM SIEW
NRIC/Passport Number	S6940864H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

enaling Kapur 4/6/18
Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Stationary @ traffic light along Orchard Link.
Vehicle behind STE4774 did not stop in time & collided
into the rear of my car.


IMPORTANT NOTE

Under General Condition – Conduct of Claim of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

We declare the foregoing particulars are true in every respect.

Wahini Kypur
Policyholder's Signature / Date & Time


Driver's Signature (if buyer is not the policyholder) / Date
& Time

Witnessed by Reporting Centre Personnel



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003076MFSH

Date: 25/6/2018

Our Ref: CS/FCI18010910/Utd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJX 910D

Please be informed that we had conducted the inspection of the abovementioned vehicle 22/06/2018 at the premises of M/s Wearnes and have the following to report: -

Workshop Estimate Amount	: S\$ <u>13,917.50</u>
Revised Estimate Amount	: S\$ <u>7,658.50</u>
"Check" Items Amount	: S\$ <u>1,726.50</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Taufikh

Automotive Assessor

SERVICE ESTIMATE

45573 - C00001
 Ms Malini Kapur
 21 Holland Park
 #07-21 Lien Towers

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1
 Inv.date : 06/06/2018
 WIP No. : 64613
 Veh.In/Out:

Singapore 249476

*Tel.No. : Home: 97281477-ANNIE
 Reg.No. : SJX9100
 Reg.date : 30/03/2010
 Mileage : 0
 Chassis No: YV1CZ5957A1544439

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Ms Malini Kapur

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR LOWER SPOILER, REAR SKID PLATE, REAR LOWER TAILGATE, REAR EMBLEM, ETC	0	3200.00	0		3,200.00	S ✓ 1600
800	TO PUTTY SPRAY PAINT ON REAR LOWER TAILGATE, REAR BUMPER, ETC	0	2100.00	0		2,100.00	S ✓ 1400
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00	S ✓
	BUMPER COVER REAR UP	1.0 EA	1402.70	1262.43		1,402.70	S de
	BUMPER COVER LOWER R	1.0 EA	1402.70	1262.43		1,402.70	S de
	BUMPER PLATE SILVER	1.0 EA	642.70	578.43		642.70	S ant
	BUMPER BRACKET SIDE	1.0 EA	88.70	79.83		88.70	S new
	BUMPER BRACKET SIDE	1.0 EA	88.70	79.83		88.70	S new
	BUMPER BRACKET CORNE	1.0 EA	54.30	48.81		54.30	S new
	BUMPER BRACKET CORNE	1.0 EA	54.30	48.81		54.30	S new

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanpin 97-125749
 4 days
 'WP' 22/6/18 @ 1630
 Resurvey before paint
 send @ lkk auto.com

[Signature]
 21/6/18

SERVICE ESTIMATE

45573 - C00001
 Ms Malini Kapur
 21 Holland Park
 #07-21 Lien Towers
 Singapore 249476

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page: 2

Inv.date. : 06/06/2018

WIP No. : 64613

Veh.In/Out:

*Tel.No. : Home: 97281477-ANNIE

Reg.No. : SJX9100

Reg.date. : 30/03/2010

Mileage : 0

Chassis No: YV1CZ5957A1544439

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Ms Malini Kapur

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	BUMPER SECTION REAR	1.0 EA	325.70			325.70 S	? x m
	BUMPER RAIL (BEAH) R	1.0 EA	1400.50			1,400.50 S	? x m
	TAILGATE LOWER XC90	1.0 EA	2144.10			2,144.10 S	R x X
	EMBLEM <2.5T> XC90/S	1.0 EA	84.00	75.60		84.00 S	net
	EMBLEM <AWD> S80 07-	1.0 EA	84.00	75.60		84.00 S	net
	EMBLEM <XC90> XC90 C	1.0 EA	84.00	75.60		84.00 S	net
	TOW COVER REAR XC90	1.0 EA	73.90	66.51		73.90 S	net
	BLIND RIVET 4.0*21MM	10.0 EA	3.00	24.00		30.00 S	net
	BUMPER CLIP	10.0 EA	4.80	43.20		48.00 S	net
	BUMPER INSTALLING MT	1.0 EA	83.40	79.06		83.40 S	net
	ADHESIVE TUBE CHEMIC	1.0 EA	75.80	68.22		75.80 S	net

Gross Total. 13,917.50

Labour Total	5,750.00
Parts Total	8,167.50
Package Total	0.00

Net.....	13,917.50
GST @ 7.0%	974.23
Total.....	14,891.75
Paid.....	0.00
Please Pay..	14,891.75

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1
 Inv.date. : 07/07/2018
 WIP No. . : 64613
 Veh.In/Out: 22/06/2018 06/07/2018
 *Tel.No. . :
 Reg.No. . : SJX9100
 Reg.date . : 30/03/2010
 Mileage . : 143,770
 Chassis No: YV1CZ5957A1544439

Closed by : Michelle Ong Siew Be
 Svc Consultant : ACC
 Remarks : Ms Malini Kapur

Op.No	Description	Mech	Qty	Price	Disc%	PKg	Amount	G
802	TO REPLACE REAR BUMPER, REAR LOWER SPOILER, REAR SKID PLATE, REAR LOWER TAILGATE, REAR EMBLEM, ETC	0		1600.00	0		1,600.00	S
800	TO PUTTY SPRAY PAINT ON REAR LOWER TAILGATE, REAR BUMPER, ETC	0		1400.00	0		1,400.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0		450.00	0		450.00	S
	① BUMPER COVER REAR UP	1.0	EA	1402.70	10		1,262.43	S
	② BUMPER COVER LOWER R	1.0	EA	1402.70	10		1,262.43	S
	③ BUMPER PLATE SILVER	1.0	EA	642.70	10		578.43	S
	④ BUMPER BRACKET SIDE	1.0	EA	88.70	10		79.83	S
	⑤ BUMPER BRACKET SIDE	1.0	EA	88.70	10		79.83	S
	⑥ BUMPER BRACKET CORNE	1.0	EA	54.30	10		48.87	S
	⑦ BUMPER BRACKET CORNE	1.0	EA	54.30	10		48.87	S

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD
FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01, CITY HOUSE
SINGAPORE
Singapore 068877

GST Reg.No:M28920628X
Inv.No. : B&P 0 Page 2
Inv.date. : 07/07/2018
WIP No. : 64613
Veh.In/Out: 22/06/2018 06/07/2018
*Tel.No. :
Reg.No. : SJX9100
Reg.date. : 30/03/2010
Mileage : 143,770
Chassis No: YV1CZ5957A1544439

Closed by : Michelle Ong Siew Be
Svc Consultant : ACC
Remarks : Ms Malini Kapur

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
11	EMBLEM <2.5T> XC90/B	1.0 EA	84.00	10		75.60	S
12	EMBLEM <AWD> S80 07-	1.0 EA	84.00	10		75.60	S
14	TOW COVER REAR XC90	1.0 EA	73.90	10		66.51	S
15	BLIND RIVET 4.0*21MM	10.0 EA	3.00	10		27.00	S
16	BUMPER CLIP	10.0 EA	4.80	10		43.20	S
17	BUMPER INSTALLING MT	1.0 EA	83.40	10		75.06	S
18	ADHESIVE TUBE CHEMIC	1.0 EA	75.80	10		68.22	S
19	EMBLEM <XC90> XC90 C	1.0 EA	84.00	10		75.60	S

Labour Total 3,450.00
Parts Total 3,867.48
Package Total 0.00

Gross Total. 7,317.48
Net..... 7,317.48
GST @ 7.0% 512.22
Total..... 7,829.70
Paid..... 0.00
Please Pay.. 7,829.70

GST: S=StdRated; O=OutOfScope; Z=ZeroRated



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18010358/T1td3q2

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 17-07-2018



Code : FCI2

1.

Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 477Y	Veh. Inspected	SJX 910D
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18004487MFSH	Excess (\$)	0.00
Assign From	LURENE JAW	Assign Date	06/06/2018

2.

Vehicle Particulars & Condition

Make & Model	VOLVO XC90	c.c	2521
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	YV1CZ5957A1544439	Colour	BEIGE
Odometer	143766	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3.

Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/60 R18	MICHELIN	6 mm
L/H Front Tyre	235/60 R18	MICHELIN	6 mm
R/H Rear Tyre	235/60 R18	MICHELIN	6 mm
L/H Rear Tyre	235/60 R18	MICHELIN	6 mm

4.

Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5.

General Information

Accident Date	04/06/2018	Inspection Date	22/06/2018
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.		

5a.

Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b.

Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 910D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR UP (SN)	DEFORMED	1,402.70	1,262.43
1	BUMPER COVER LOWER R (SN)	DEFORMED	1,402.70	1,262.43
1	BUMPER PLATE SILVER (SN)	CUT	642.70	578.43
1	BUMPER BRACKET SIDE (SN)	NECESSARY	88.70	79.83
1	BUMPER BRACKET SIDE (SN)	NECESSARY	88.70	79.83
1	BUMPER BRACKET CORNE (SN)	NECESSARY	54.30	48.87
1	BUMPER BRACKET CORNE (SN)	NECESSARY	54.30	48.87
1	BUMPER SECTION REAR (SN)	NOT NECESSARY	325.70	-
1	BUMPER RAIL (BEAM) R (SN)	NOT NECESSARY	1,400.50	-
1	TAILGATE LOWER XC90 (SN)	TO REPAIR SEE LABOUR	2,144.10	-
1	EMBLEM (2.5T) XC90/8 (SN)	NECESSARY	84.00	75.60
1	EMBLEM (AWD) S80 07- (SN)	NECESSARY	84.00	75.60
1	EMBLEM (XC90) XC90 C (SN)	NECESSARY	84.00	75.60
1	TOW COVER REAR XC90 (SN)	CUT	73.90	66.51
10	BLIND RIVET 4.0*21MM (SN)	NECESSARY	30.00	27.00
10	BUMPER CLIP (SN)	NECESSARY	48.00	43.20
1	BUMPER INSTALLING MT (SN)	NECESSARY	83.40	75.06
1	ADHESIVE TUBE CHEMIC (SN)	NECESSARY	75.80	68.22
LABOUR			8,167.50	3,867.48
TO REPLACE REAR BUMPER, REAR LOWER SPOILER, REAR SKID PLATE, REAR LOWER TAILGATE, REAR EMBLEM, ETC. INCLUSIVE OF THE REPAIR OF TAILGATE LOWER XC90.			3,200.00	1,600.00
TO PUTTY SPRAY PAINT ON REAR LOWER TAILGATE, REAR BUMPER, ETC.			2,100.00	1,400.00
TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.			450.00	450.00
GRAND TOTAL			5,750.00	3,450.00
			13,917.50	7,317.48

Report Ref No. CS/FCI18010358/T1td3q2



RECOMMENDED COST OF REPAIRS

Page No. 2 of 2

Report Ref No. CS/FCI18010358/T1td3q2

7,317.48

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B. Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.