

ASS. REC. BY:

REF:

CS3/CTI18010387R124d302

Special Instructions:

Survivor:

Menmen

ASSIGNMENT (Office)

From (Person):

Rani  
Chong Boon Sen

of

CTI

Date/Time:

7/6/18 @ 12:56 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

Bicycle

Insured:

SKD 3744

at Workshop m/s

Tel:

9068 3911

of

B1K 224B Compassvale Walk # 02-645

Policy No:

DMPCSN 3063 821700

Claim No:

SNM18D01841C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/04/2018

CA / REV / REP. / REV 24 HRS 'wp'

8/6/18 @ after 3pm.

H.O.D. Endorsement:

Date/Time:

2:59pm @ 7/6/18

Person Contacted:

Desmond

Vehicle:

IN OUT

Date/Time

Action/Instruction

(X)

Estimate

Reconfirm make and model of the bike

(call owner before go)

Bicycle - X

SKD 3744 - X

REF: CTI

## ASSIGNMENT

From

Date

8/6/18

Veh No

Yr Regn:

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Bicycle

Make:

BUFFALO

C.C.

at Workshop m/s

Colour

Black

A/C: Insured / Std / NI / NA

of BIK 224B Compassvale Walk #02-645

Sp. Reading

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No:

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Reconfirm make &amp; model of the bike.

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Desmond @ 9068 3911

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

after 3pm

Tyre Size:

F:

700C

R:

700C

Remark: The veh had commenced its

repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

G/A / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

3

days

Res:

Yes or No

D.O.A.

D.O.I.

08/06/18

Lump Sum:

%

3 Val:

Yes or No

Survey held at

BIK 224B Compassvale walk

CA / REV / REP. / 24 HRS (up)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Estimated repair range \$3,200 - \$4,000

2/6/18

Submit PRS report.

  
 2/6/2018

Date/Time: File Pass to?

☐

Preli. Report

Days Of Repair:

To:

☐

Final Report

Resurvey No. of Trip:

Survey Fee:

150

Date/Time: File Return to?

Transportation

) 3 + PR \$

Photos

Others

TOTAL

150

Report Format:

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week-end (\$



China Taiping Insurance (Singapore) Pte. Ltd.  
3 Ardmore Road #10-00 Springdale Tower  
Singapore 079425  
Auto Motor Claim Department  
Date: 19th May 2018

Claus YiRong  
A/Lik 22411  
#02-346  
Chin Joo Seng wdk  
Singapore 242224  
Tel: 93552911

Re: Accident claims against Veh. No. SKD3740

Report on Credibility of bicycle

A. What impacted the cyclist:

- Bicycle was involved in an accident with a motor vehicle
- Cyclist involved was hurt

B. Observation:

- Frame suffers from high impact collision with vehicle causing the fork to break
- Common GPS lost in accident
- Shilling (wheel) damaged
- Handle (rear) damaged

C. Conclusion:

- Frame and fork shall be replaced as it suffer from high impact collision
- All above mentioned parts must be replaced

Yours faithfully  


Signature Francis Yip Siu  
Name/Designation Francis Yip Siu  
Company Name Singapore Springdale



# ycleWhere Pte Ltd

22 Seletar Harbour Road Singapore 674003  
Tel: 58400243  
Email: CycleWhere@cyclewhere.com

TAX INVOICE  
Ref: 20141003BK  
Invoice No: 0022318

Customer Details:	DATE: 18 May 2014
SOLD BY: Tony Wee	DE: RRPV

DESCRIPTION	TOTAL
5 x 20 FXA Frame Set	\$4,600
Shimano Ultegra 6800 9 speed groupset	\$2,400
Shimano Ultegra 6800 9 speed groupset	\$600
Garmin 510c 12.2	\$850
Labour	\$472
<b>Total</b>	<b>\$8,922</b>

Tony Wee

Signature:  
Tony Wee  
Cycling World



# CycleWhere Pte Ltd

62 Upper Thomson Road Singapore 574389

Tel: 98450246

Email: Cyclewhere@zoho.com

TAX INVOICE  
Reg. 201418935K  
Invoice no. 002/2018

PAYMENT TERMS:	DATE: 19 May 2018
SOLD BY: Foong WeiSheng	DELIVERY:

DESCRIPTION	TOTAL
Bufalo FXX Frame Set	\$4500
Shimano Ultegra 6800 shifter levers	\$ 400
Specialized saddle	\$400
Garmin edge 820	\$550
Labour	\$400
Total	\$6250

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jun 2018		07 Jun 2018 12:56 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHOO YU YI, DANILE		
Main Claimant:	CHUA YIRONG		
Vehicle Reg. No.:	BICYCLE	Date of Loss:	07/04/2018 13:00 - :59
Claim Type:	TP / SNM18D01841C02	Policy/Cover Note No.:	DMPCSN3063821700
Vehicle Reg. No. (Insured):	SKD374U	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	- Not Applicable - (-)		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/06/2018]		
Adj Asg. Remarks:	Please survey third party vehicle & let us have your recommendation on estimated amount required to repair the vehicle if there is NO estimate provided during pre-repair inspection PLEASE RE-CONFIRM MAKE AND MODEL OF THE BIKE.		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Hwang Shiang Yi

---

**From:** Claims <claims@esthermoey.com>  
**Sent:** Thursday, 7 June, 2018 12:30 PM  
**To:** Hwang Shiang Yi  
**Subject:** RE: Your insured's vehicle no. SKD374U - PRI Notice (SNM18D01841C02/4)

Your Attention is Drawn to the Confidentiality Notice Below:

Dear Shiang Yi,

Kindly note that our client's vehicle is a bicycle which was damaged due to the accident.

You may arrange for LKK to contact our client directly to conduct the survey:

Chua Yirong @ 9068 3911  
Blk 224B Compassvale Walk  
#02-645  
Singapore 542224

Thank you.

Yours sincerely,

*Justin Yap*

Secretary to Esther Moey  
Amy Lim Law Practice  
[claims@esthermoey.com](mailto:claims@esthermoey.com)

Tel: (+65) 9625 8742 (Justin) / (+65) 9639 3110 (Esther)  
Fax: (+65) 6491 5638

### CONFIDENTIALITY NOTICE

This e-mail from Amy Lim Law Practice (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

Amy Lim Law Practice DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18010387/R1z4d3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 07-06-2018



Code : CTI

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKD 374U	Veh. Inspected	BICYCLE
Policy No.	DMPCSN3063821700	Coverage (\$)	0.00
Claim No.	SNM18D01841C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	07/06/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	07/04/2018	Inspection Date
Survey held at	-	

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

#### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jun 2018		07 Jun 2018 12:56 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

#### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>CHOO YU YI, DANILE</b> , Co. Reg. No.: -		
Main Claimant:	<b>CHUA YIRONG</b>		
Vehicle Reg. No.:	<b>BICYCLE</b>	Date of Loss:	07/04/2018 13:00 - :59
Claim Type:	<b>TP / SNM18D01841C02</b>	Policy/Cover Note No.:	DMPCSN3063821700
Vehicle Reg. No. (Insured):	<b>SKD374U</b>	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	<b>- Not Applicable - (-)</b>		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 19/06/2018]</b>		
Adj Asg. Remarks:	Please survey third party vehicle & let us have your recommendation on estimated amount required to repair the vehicle if there is NO estimate provided during pre-repair inspection PLEASE RE-CONFIRM MAKE AND MODEL OF THE BIKE.		

#### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.




#### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*BICYCLE (SNM18D01841C02)**  
**[SKD374U]**  
**TP**  
**CHUA YIRONG**  
**Apr 7 2018 1:00PM**  
**[CHOO YU YI, DANILE]**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>	
<b>Documentation</b>			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		<b>Thumbnail</b> <b>Print</b>
1	07/06/18 12:53	<b>TP NOTIFICATION</b>		<a href="#">Load PDF</a>
2	07/06/18 12:54	<b>INSURED REPORT</b>		<a href="#">Load PDF</a>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		<b>Thumbnail</b> <b>Print</b>
1	11/06/18 09:33	<b>LKKPhotosIn6-1.pdf</b>		<a href="#">Load PDF</a>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118010387/R1Z4D3E2  
Date: 27/06/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3063821700
Claimant Vehicle No:	BICYCLE	Insured Vehicle No:	SKD374U
Date of Loss:	07/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D01841C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	BICYCLE	Engine No:	HIDDEN
Make & Model:	ELECTRIC BICYCLE SUV-7, (A)	Chassis No:	HIDDEN
Reg. Date:	(Man. Year: )	Odometer:	0 km
Colour:	Black		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	700C	Rear Tyre Size:	700C
Front Left Side:	0 mm	Rear Left Side:	0 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	07/06/2018	Inspected At:
Date Inspected:	08/06/2018	
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,200.00 - \$4,000.00



## REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 27 Jun 2018)	
Parts:	N/A	ELECTRIC BICYCLE SUV-7 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for BICYCLE)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >