

hummie

6, AIG 180 10389

Awas 9-1

ADRIAN

ASSIGNMENT

DOI:

5/6/2018

Date / Time:

5/6/2018

Registered in Merimen:

5/6/2018

Surveyor:

Pre-assign / CCU / FTE

SKZ 6596R

Claim No.:

700450598

Policy No.:

KIA FORTE

Make / Model:

Clementine Ave

Place of Accident:

Insured Vehicle No.:

Name of Insured:

SEAH MIN FANN

Insured Tel No.:

HP:

D.O.A.:

4/6/2018

Excess Sec II :S\$

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

John Leo Cairnes

Driver Tel No.:

9179730

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SKU 65306



INSRS:

WSP:

Tel:

Liability:

RMKS:

Modern



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

12/6

12/6/18

SKU 65306 X; SKZ 6596R X

Confirm accident details inform TP  
Claim after mid out

RECEIVED 13 AUG 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

MIS chin

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

8

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

7169.00

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

700.00

(S 100 x 7 days)

Loss of Income (LOI):

S\$

-

(S

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

7871.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Counter with:

Payee 1:

S\$

7871.00

Payee 1:

Modern Automotive Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Payee 2:

Payee 3: (Strike if N.A.)

S\$

Payee 3:

REF:

ASS. REC. BY: Adrian King

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SK46530G.

Yr Regn:

2010 May

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Alphard

cc 2362

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

226661

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTEGD21H50812495

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/63R16

R:

215/65R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

05/06/18

Survey held at

Modern

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TPA/G

23/11/18

Confirm US \$6700.00 with 6 working days.

~~TPA/G~~  
~~TPA/G~~  
~~TPA/G~~

(Ref: #8929.13  
57.1)

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.I. (%)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs. (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18010389/Awa3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 07-06-2018	
		Code : AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SKZ 6596R	Veh. Inspected	SKU 6530G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	07/06/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	04/06/2018	Inspection Date	05/06/2018
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MODERN AUTOMOTIVE PTE LTD  
BLK 3023A UBI ROAD 1 #01-61  
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building  
78 Shenton Way #07-16  
Singapore 079120  
Tel : 6419 - 3000  
Fax : 6835 - 7416

Vivian

Quotation  
DATE : 05.06.2018  
VEH NO : SKU6530G  
MODEL : Toyota Alphard  
D O A : 04.06.2018  
YR REF : SKZ6596R

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKU6530G (Toyota Alphard)

Item	Description	Qty	Am't
NO	LIST ITEMS		
1	Front Door - RH <i>Distorted</i>	1	1,685.80 ✓
2	Front Door Lock - RH <i>Distorted</i>	1	595.40 ✓
3	Front Door Weatherstripe - RH <i>new</i>	1	225.80 ✓
4	Front Door Lower Cover - RH <i>Distorted</i>	1	239.70 ✓
5	Sliding Door - RH <i>Distorted</i>	1	2,120.00 ✓
6	Sliding Door Lock - RH <i>Distorted</i>	1	660.40 ✓
7	Front Sliding Door Weatherstripe <i>new</i>	1	170.70 ✓
8	Rear Sliding Door Weatherstripe <i>new</i>	1	195.90 ✓
9	Sliding Door Inner Trim Board - RH <i>Distorted</i>	1	895.40 ✓
10	Sliding Door Inner Trim Board Clips <i>new</i>	1 set	30.00 ✓
11	Sliding Door Lower Cover <i>Distorted</i>	1	294.60 ✓
12	Sliding Door Lock Motor <i>new</i>	1	1,288.40 ✓
13	Sliding Door Lower Roller <i>Distorted</i>	1	245.60 ✓
14	Rear Wheel Hub c/w Bearing <i>new</i> 7621	1	565.60 ✓
15	Rear Axle 5715.75	1	2,393.50 ✓
16	Rear Fender - RH <i>Distorted</i>	1	1,514.00 ✓
17	Sliding Door Glass Regulator <i>Distorted</i>	1	261.70 ✓
18	Sliding Door Glass Regulator Motor <i>new</i>	1	763.00 ✓

14,145.50

(3,536.38)

\$ 10,609.13

S/NETT ITEMS

- Front Door Visor - RH *new*
- Sliding Door Visor *new*
- Rear Wheel Rim - RH *new*
- Rear Fender Glass Sealant - RH *new*

60.00 ✓

60.00 ✓

900.00 *500*

50.00 ✓

Less 25% hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

620

RE : ESTIMATE FOR ACCIDENT REPAIR SKU6530G (Toyota Alphard)

Total Parts		\$	11,679.13
<u>LABOUR CHARGE</u>			
1	To knocking & pull out front & rear portion & renew above parts	\$	<del>1,400.00</del> 700
2	To putty & spray up paint works	\$	<del>1,200.00</del> 950
3	To check wiring	\$	50.00 30
4	To underseal	\$	150.00 X
5	To remove rear fender glass	\$	120.00 X
6	To transfer front door fittings	\$	<del>150.00</del> 80
7	To transfer sliding door fittings	\$	<del>200.00</del> 120
8	To remove upholstery	\$	<del>150.00</del> 80
9	To remove rear undercarriage	\$	380.00 X
10	To perform wheel alignment	\$	<del>150.00</del> 80
Total Labour		\$	3,950.00
Grand Total		\$	15,629.13

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 8375.75  
N/S: 6.71C.

06 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 #01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748-4422 / 6745-4422 FAX : 6-747-6720

Email: chin@modernautomotive.com.sg

Your Ref : SKZ6596R  
Our Ref : SKU6530G

Date : 02.07.2018

The Claims Manager  
AIG Asia Pacific Insurance Pte Ltd  
AIG Building  
78, Shenton Way #07-16  
Singapore 079120  
Tel : 6-419-300 Fax : 6-415-3727

Attn : The Motor Claim Dept

RE : ACCIDENT INVOLVING SKU6530G & SKZ6596R ON 04.06.2018  
ALONG CLEMENCEAU AVENUE N


We refer to the above matter.

We have been authorized by our client M/s Clifford Classic Services to make claim against your insured vehicle No. SKZ6596R in respect of the above accident for the following :

Repair Cost	\$ 7,169.00 (Incl GST)
Loss of use (\$150 x 7 days)	\$ 1,050.00 (1 Sunday)
Search fee	\$ 2.00
<b>Total :</b>	<b>\$ 8,221.00</b>

Enclosed herewith a copy each of the supporting documents for your perusal.  
Kindly process the above and remit the payment to us asap

Yours faithfully

  
Modern Automotive Pte Ltd



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18010389/Awa3

13 June 2018

**Seah Min Fann**  
Blk 1 Lorong Lew Lian  
#05-14  
Singapore 531001

Dear Sir/Madam,

**ACCIDENT INVOLVING SKZ 6596R AND SKU 6530G ON 04/06/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau  
Case Handler  
DID: 6841 8625  
FAX: 6741 4108  
EMAIL: Vivianlau@lkkauto.com

c.c AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)



# LETTER OF AUTHORIZATION

Date: 4/6/18

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

SKU 6530 G & SKZ6596 R

ON 4/6/18 ALONG Clemenceau Avenue N

This letter is to authorize **MODERN AUTOMOTIVE PTE LTD** at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, **MODERN AUTOMOTIVE PTE LTD** has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of **MODERN AUTOMOTIVE PTE LTD**.

**MODERN AUTOMOTIVE PTE LTD** is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully



Signature of Owner

CLIFFORD CLASSIC SERVICES /  
53032213 K

Name / NRIC



**RELEASE VOUCHER**  
**(AIG ASIA PACIFIC-EXPRESS THIRD PARTY CLAIM)**

"We/I, MODERN AUTOMOTIVE PTE LTD (the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 7,169.00 (repair cost), S\$ 700.00 (loss of rental/use), S\$ 2.00 (disbursement), for vehicle no. SKU 6530G that was damaged pursuant to the accident which occurred on 04/06/2018 (date) along CLEMENCEAU AVE (location) involving vehicle no/s SKZ 6596R.

This is pursuant to the inspection conducted on 05/06/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CLIFFORD CLASSIC SERVICES (the third party claimant") of vehicle no. SKU 6530G make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKU 6530G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 07 (day) of August (month) 2018 (year)

*Wsp*



Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

# MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 #01-58 / 61 SINGAPORE 408717  
TEL : 67474422, 67454422 FAX : 67476720  
GST REG. NO : 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY #07-16  
SINGAPORE 079120


Attention : Motor Claim Department  
Contact : 6415-3727 6419-3000

## Tax Invoice : TP001223

Date : 02/07/2018  
Vehicle Num. : SKU 6530G  
Make/Model : TOYOTA ALPHARD-2010  
Chassis/Eng# : JTEGD21H908121495/2AZC872725  
Accident Date : 04/06/2018  
Claim No. :  
Reference :  
Policy No. : 5096304287

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		6,700.00
		ACCIDENT REPAIR (LUMPSUM)		
				<u>6,700.00</u>
		Labour Total S\$ :		

Total S\$ :	6,700.00
GST @ 7% S\$ :	469.00
Amount Due S\$ :	<u>7,169.00</u>

  
MODERN AUTOMOTIVE PTE LTD

Invoice



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**  
6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

## Third Party Insurer Enquiry

Our Ref No: GR-18-085225  
Date of Request: 05/06/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd  
Blk 3023A Ubi Road 1  
#01-61 & #01-58  
Singapore 408717

Dear Sir/Madam,

Enquiry Date 05/06/2018  
Enquiry By Chin Sol Shong  
TP Vehicle No. SKZ6596R  
Accident Date 04/06/2018

Enquiry Result		Period of Insurance	Insurer Tel. No.
TP Vehicle No.	Insurer	29/01/2018-28/01/2019	65-6419-3000
SKZ6596R	AIG Asia Pacific Insurance Pte. Ltd.		

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

Invoice



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**  
6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-085225  
Date of Request: 05/06/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd  
Blk 3023A Ubi Road 1  
#01-61 & #01-58  
Singapore 408717

Dear Sir/Madam,

Enquiry Date 05/06/2018  
Enquiry By Chin Soi Shong  
TP Vehicle No. SKZ6596R  
Accident Date 04/06/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Pending for Survey Report
Main	08 Jun 2018 <a href="#">Edit Reg</a>		05 Jun 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$6,700.00</b> <a href="#">Edit Estimates</a>	<b>S\$6,700.00</b> <a href="#">View Rpt</a>		<a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>[Created by adjuster]</b>									
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	<b>SEAH MIN FANN</b> , ID: S1415058G								
Main Claimant:	<b>CLIFFORD CLASSIC SERVICES</b> , Co. Reg. No.: 53032213K								
Vehicle Reg. No.:	<b>SKU6530G</b>	Date of Loss:	04/06/2018 08:00 - :59 <b>[96 Months and 20 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>TP / 8108972405SG</b>	Policy/Cover Note No.:	2100450598 (Comprehensive) Coverage: 29/01/2018 - 28/01/2019						
Vehicle Reg. No. (Insured):	<b>SKZ6596R</b>	Policy No. (Claimant):	5096304287						
		Excess:							
Repairer:	<b>Modern Automotive Pte Ltd (HQ)</b> Bldg 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Tan, Bennie-WZ</b> - 6419 1718] Bennie-								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... <b>[Final Rpt due 19/06/2018]</b>								
		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>						
<b>ASSOCIATED MAIL RECEIVED</b>									
<ul style="list-style-type: none"> <li>AIG_SG (08/06/2018): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKU6530G (81089724055G)  
[SKZ6596R]  
TP  
CLIFFORD CLASSIC SERVICES  
Jun 4 2018 8:00AM  
[SEAH MIN FANN]  
Modern Automotive Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

**View** View in Browser

**Letters/Correspondences**

1 per page

☒
















































No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit

**Photos/Images**

3 per page

☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
2	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
3	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
4	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
5	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
6	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
7	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
8	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
9	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
10	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
11	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
12	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
13	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
14	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
15	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
16	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
17	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
18	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
19	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
20	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
21	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
22	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
23	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
24	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
25	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
26	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
27	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
28	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
29	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
30	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
31	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
32	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
33	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>
34	20/06/18 19:18	General View	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	20/06/18 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
36	20/06/18 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
37	20/06/18 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
38	20/06/18 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/06/18 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
40	20/06/18 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
41	20/06/18 19:18	General View	 Load JPG	<input checked="" type="checkbox"/>
42	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	20/06/18 19:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/06/18 17:26	TP GIA REPORT	 Load PDF	<input checked="" type="checkbox"/>



Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
		LKK Auto Consultants Pte Ltd (HQ)		
2	15/08/18 16:54	WORKSHOP INVOICE		Load PDF
3	15/08/18 16:54	AUTHORISATION TO ACT FORM		Load PDF
4	15/08/18 16:54	Release Voucher		Load PDF
5	15/08/18 16:54	GIA SEARCH		Load PDF
6	15/08/18 16:54	LETTER TO OI		Thumbnail Print
		AIG Asia Pacific Insurance Pte. Ltd. (SG)		Load PDF
1	08/06/18 13:12	OI GIA REPORT		

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKZ6596R (Insd veh)	Model:	TOYOTA ALPHARD 2.4 (A)
	SKU6530G (TP veh)		
Date of Accident:	04/06/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	16,723.16
Final Repair Cost	:	\$	7,169.00
Loss of Use	:	\$	700.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	7,871.00

7.00 days at \$100.00 per day

days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Modern Automotive Pte Ltd	:	\$ 7,871.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

15 Aug  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18010389/AWA3Q2

Date: 15/08/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100450598  
**Claimant Vehicle No :** SKU6530G **Insured Vehicle No :** SKZ6596R  
 Date of Loss: 04/06/2018 Nature of Claim: TP Claim No: 8108972405SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SKU6530G**  
 Make & Model: TOYOTA ALPHARD, 2.4 (A) Engine No: 2AZC872725  
 Reg. Date: 15/05/2010 (Man. Year: 2010) Chassis No: JTEGD21H908121495  
 Colour: Blue Odometer: 226661 km  
 Engine Capacity: 2362 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 215/65 R16 Rear Tyre Size: 215/65 R16  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,679.12	6,335.75	5,343.37	45.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,950.00	2,040.00	1,910.00	48.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,629.12</b>	<b>8,375.75</b>	<b>7,253.37</b>	<b>46.41</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,700.00</b>		
(S\$)	15,629.12	6,700.00	8,929.12	57.13
<b>+ GST 7.00/7.00% (S\$)</b>	1,094.04	469.00	625.04	57.13
<b>Nett Amount (S\$)</b>	<b>16,723.16</b>	<b>7,169.00</b>	<b>9,554.16</b>	<b>57.13</b>
<b>+ Loss of Use (7.0 x S\$100.00/day) (S\$)</b>		700.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>7,871.00</b>		

## INSPECTION

Date of Assignment: 05/06/2018  
 Date Inspected: 05/06/2018 Inspected At:

Modern Automotive Pte Ltd (HQ)  
 Blk 3023A Ubi Road 1, #01-61 & #01-58  
 Singapore 408717

Estimated Period of Repair: 6.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** VIVIAN LAU PEI FENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -RH	Distorted	1,685.80 FL	*1,685.80 FL
2	1		*FRONT DOOR LOCK -RH	Damaged	595.40 FL	*595.40 FL
3	1		*FRONT DOOR WEATHERSTRIP -RH	Necessary	225.80 FL	*225.80 FL
4	1		*FRONT DOOR LOWER COVER -RH	Deformed	239.70 FL	*239.70 FL
5	1		*SLIDING DOOR -RH	Distorted	2,120.00 FL	*2,120.00 FL
6	1		*SLIDING DOOR LOCK -RH	Damaged	660.40 FL	*660.40 FL
7	1		*FRONT SLIDING DOOR WEATHERSTRIP	Necessary	170.70 FL	*170.70 FL
8	1		*REAR SLIDING DOOR WEATHERSTRIPE	Necessary	195.90 FL	*195.90 FL
9	1		*SLIDING DOOR INNER TRIM BOARD -RH	Deformed	895.40 FL	*895.40 FL
10	1		*SET SLIDING DOOR INNER TRIM BOARD CLIPS	Necessary	30.00 FL	*30.00 FL
11	1		*SLIDING DOOR LOWER COVER	Deformed	294.60 FL	*294.60 FL
12	1		*SLIDING DOOR LOCK MOTOR	Not Necessary	1,288.40 FL	*- FL
13	1		*SLIDING DOOR LOWER ROLLER	Damaged	245.60 FL	*245.60 FL
14	1		*REAR WHEEL HUB C/W BEARING	Not Necessary	565.60 FL	*- FL
15	1		*REAR AXLE	Not Necessary	2,393.50 FL	*- FL
16	1		*REAR FENDER -RH	Repair	1,514.00 FL	*- FL
17	1		*SLIDING DOOR GLASS REGULATOR	Damaged	261.70 FL	*261.70 FL
18	1		*SLIDING DOOR GLASS REGULATOR MOTOR	Not Necessary	763.00 FL	*- FL
19	1		*FRONT DOOR VISOR -RH	Necessary	60.00 FS	*60.00 FS
20	1		*SLIDING DOOR VISOR	Necessary	60.00 FS	*60.00 FS
21	1		*REAR WHEEL RIM -RH	Cut	900.00 FS	*500.00 FS
22	1		*REAR FENDER GLASS SEALANT -RH	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>15,215.50</b>	<b>8,241.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>3,536.38</b>	<b>1,905.25</b>
<b>Total Parts (\$\$)</b>	<b>11,679.12</b>	<b>6,335.75</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCKING & PULL OUT FRONT & REAR PORTION & RENEW ABOVE PARTS	New	1,400.00	700.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,200.00	950.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	0.00
5	TO REMOVE REAR FENDER GLASS	New	120.00	0.00
6	TO TRANSFER FRONT DOOR FITTINGS	New	150.00	80.00
7	TO TRANSFER SLIDING DOOR FITTINGS	New	200.00	120.00
8	TO REMOVE UPHOLSTERY	New	150.00	80.00
9	TO REMOVE REAR UNDERCARRIAGE	New	380.00	0.00
10	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (\$\$)			3,950.00	2,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >