

ASS. REC. BY:

REF:

CS3 / FWD18010391 / N240362

Special Instruction:

Surveyor
menmen

N92

ASSIGNMENT (Office)

From (Person):

josey loh

of

FWD

Date/Time:

7/6/18 @ 1:02pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDN 892

Insured:

SIG 8855 S

at Workshop m/s

Target Auto

Tel:

9383 5100 / 8228 8881

of

160 Sin Ming Drive #07-17

Policy No:

Claim No:

1201800006914

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4/6/2018

CA / REV / REP. / REV 24 HRS

lup

8/6/18 @ Morning

H.O.D. Endorsement:

Date/Time:

2:47pm @ 7/6/18

Person Contacted:

Anna

Vehicle:

☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SDN 892-x
	SIG 8855S-x
11/6/18	Dismantled
12/6/18	After repair

NAZ

REF: FWD

ASSIGNMENT

From Date: 8/6/18

Estimated Cost:

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDN 892

at Workshop n/s

of 160 Sin Ming Drive #07-17

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS / up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SDN 892 Yr Regn: 25/NOV/2013

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: AUDI A3 SPOTBACK

c.c. 1395

Colour: WHITE

A/C: ☒ Insured / Std / NI / NA

Sp. Reading: 17,506

T/Radio: ☒ Insured / Std / NI / NA

Eng/No:

C/No: W44ZZZ8V7DA075440

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 225/40 R18

R: 11

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 08/06/2018

Survey held at: TARGET AUTO

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S FRONT & CENTRE

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Repair Estimate = \$\$\$ 13000 - 15000

* 4 days

13/6/18 Submit PRS Report.

RECEIVED 13 JUN 2018

Date/Time File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time File Return to?

3)

Add Fee: ☐ : Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

80

50

50

180

Nivitha (LKK Auto)

From: josey.loh@fwd.com
Sent: Thursday, 7 June 2018 1:02 PM
To: sur@lkkauto.com; assignments@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Subject: FW: Your Ref: TKS/T896-ACC-40427.18/kc Our Ref: 1201800006914
Attachments: 20180607113802831.pdf

Hi LKK team,

Please refer to the attached and liaise with TP repairer for PRS.

Please create the case in Merimen.

Thank you.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind Regards

Josey Loh
Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872
E josey.loh@fwd.com
W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg save now
--	--	--	--

From: Josey Loh Kah Wai - SGUser
Sent: Thursday, 7 June, 2018 11:37 AM
To: 'Kelly Cheng'
Cc: Motor Claims SG - SG Common
Subject: RE: Your Ref: TKS/T896-ACC-40427.18/kc Our Ref: 1201800006914

WITHOUT PREJUDICE

Dear Sir/ Madam,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK Auto Consultants Pte Ltd, to conduct the pre-repair survey (PRS) on your client's vehicle, SDN89Z. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind Regards

Josey Loh
Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872
E josey.loh@fwd.com
W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg save now
--	--	--	--

From: Kelly Cheng [<mailto:kelly.cheng@ksteoptr.com>]
Sent: Thursday, 7 June, 2018 11:22 AM
To: Josey Loh Kah Wai - SGUser
Cc: Motor Claims SG - SG Common
Subject: Re: Your Ref: TKS/T896-ACC-40427.18/kc Our Ref: 1201800006914

WITHOUT PREJUDICE

Dear Sirs/Mdm,

We refer to your email dated 6 June 2018.

We have our client's instructions to reject your proposal on your Single Joint Expert.

We enclosed herewith the list of our client's proposal on single joint expert for your necessary action.

Kindly let us hear from you within the stipulated time frame as per the new NIMA protocol failing which we will proceed with the necessary.

Thank you.

On Wed, Jun 6, 2018 at 5:05 PM, <josey.loh@fwd.com> wrote:

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to your letter dated 06 June 2018 of the PRI Notice of your client's vehicle SDN89Z.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd
5. VICOM Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind Regards

Josey Loh

Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872

E josey.loh@fwd.com

W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!	 2.02% p.a. fwd.com.sg save now
---	---	--

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

--

Best Regards,
Kelly Cheng
Tel: 6333 4222 ext 72
Fax: 6333 5675

Teo Keng Siang LLC
111 North Bridge Road
Peninsula Plaza, #29-07/08
Singapore 179098

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

张景祥大律師樓
(律師兼公証及宣誓官)

TEO KENG SIANG LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098. Tel: 6333 4222 Fax: 6333 5676/5688
ROC: 201510228C GST Reg No.: 201510228C Email: KSTEOCO@singnet.com.sg
(FAX - NOT FOR SERVICE OF COURT DOCUMENTS)

Our Ref : TKS/T896-ACC-40427.18/kc
Your Ref : SDN 89 Z
Date : 6th June 2018

Secretary in charge: Kelly
Tel: 6333 4222 (ext 72)
Fax: 6333 5676 / 5688
Email: Kelly.cheng@ksteoptr.com
BY HAND & EMAIL

FWD Singapore Pte Ltd
6 Temasek Boulevard
#18-01, Suntec Tower Four
Singapore 038986
Attn: Motor Claims Dept

LIM FATT SENG
15 Lorong Kismis
#01-02
Singapore 598008

BY POST

1201800006914

RECEIVED 06 JUN 2018

Dear Sirs

NOTIFICATION OF ACCIDENT

RE: ACCIDENT INVOLVING SDN 89 Z / SJG 8855 S ON 4th JUNE 2018 ALONG ORCHARD ROAD AT OG SHOPPING CENTRE CARPARK ENTRANCE

We act for LOOI CHENG SIN ROBERT in the accident above.

We are instructed by the abovenamed Claimant to notify you of a road traffic accident on 4th JUNE 2018 at 15:00PM along ORCHARD ROAD AT OG SHOPPING CENTRE CARPARK ENTRANCE involving our client's motor vehicle SDN 89 Z and motor vehicle SJG 8855 S driven by you or your authorized driver at the material time. A copy of the GIA/Traffic Police Report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damage vehicle, please let us know within **2 working days** of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. **If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.**

Please note that our client's motor vehicle SDN 89 Z is now at the following workshop: -

TARGET AUTO PTE LTD

160 Sin Ming Drive
#07-17, Sin Ming AutoCity
Singapore 575722

Person I/C : Robert
Contact : 9363 5100

Yours faithfully,

M/S TEO KENG SIANG LLC
cc. Clients - By Fax 6458 7172

Teo Keng Siang
LL.M(Singapore),
LL.B (Hons) (Singapore)

Wong Yong Sheng, Kenneth
LL.B (Hons) University of Bristol



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS3/FWD18010391/Nz4d3

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 07-06-2018



Code : FWD

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJG 8855S	Veh. Inspected	SDN 89Z
Policy No.		Coverage (\$)	0.00
Claim No.	1201800006914	Excess (\$)	0.00
Assign From	JOSEY LOH	Assign Date	07/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	04/06/2018	Inspection Date	
Survey held at	TARGET AUTO PTE LTD 160 SIN MING DRIVE #07-17 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/06/2018 15:04
Date Of Accident	04/06/2018 15:00
Exact Location Of Accident	ORCHARD RD(OG SHOPPING CTR CARPARK ENTRANCE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDN89Z
Insured/Policyholder	
Name Of Registered Owner	LOOI CHENG SIN ROBERT
NRIC No	S2171482H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91280263
Alternative Phone No	OFFICE-67336868

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SPORTBACK-1.4 TFSI (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100357335-04
Cover Note Number	

Driver

Name of Driver	LOOI SWEE LIN LINDA
NRIC No	S7401055E
Date Of Birth	18/01/1974
Occupation	INDOOR
Date Of Driving Pass	18/08/1993
Driving Experience	24 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93637821

Fax Number

Contact Number

Email Address LINDALOOI2009@YAHOO.COM.SG

Address	68 DALVEY ROAD
Postcode	259468
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	FAIRUZ
Phone Number	88089651
Email Address	


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJG8855S/
Vehicle Make/Model/Colour	NISSAN /GREY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM FATT SENG
NRIC/Passport Number	S0210253F
Contact Number	98185816
Address	9 LITTLE ROAD#07-00
Postcode	536985
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving in orchard road near D& shopping centre carpark
 entrance / exit ^{towards building} When a car on my right bang / back into the
 right side of my car on my right, as I was on the steering
 wheel; the there was a loud bang; the car driver ^{crashed my car}
 I didn't decelerate but kept on accelerating until the
 right side of my car door is damaged with side window
 crushing sound of the car door was heard.
 Luckily I wasn't hurt, I was traumatized & the car driver
 apologised & said he didn't see my car & just
 drove straight onto my car.
 His columners damaged my car door side (driver seat)
 & side window & security system
 car lock.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Signature

Li 5/6/18

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:






































...CLAIM SUBFOLDER...(Pending for Survey Report)





























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jun 2018 Edit Reg		07 Jun 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Lim Fatt Seng, ID: S0210253F								
Main Claimant:	LOOI CHENG SIN ROBERT, ID: S2171482H								
Vehicle Reg. No.:	SDN89Z	Date of Loss:	04/06/2018 14:00 - :59 [54 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201800006914	Policy/Cover Note No.:	PNPV2018-00002858 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJG8855S	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Target Auto Pte Ltd (Autocity) 160 SIN MING DRIVE, #07-17 SIN MING AUTOCITY, 575722 Sin Ming - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 03/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDN89Z (1201800006914)**
[SJG8855S]
TP
LOOI CHENG SIN ROBERT
Jun 4 2018 2:00PM
[Lim Fatt Seng]
Target Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/06/18 14:58	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	22/06/18 15:01	General View	 Load JPG	<input checked="" type="checkbox"/>
3	22/06/18 15:01	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
4	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
5	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
6	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
7	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
8	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
9	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
10	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
11	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
12	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
13	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
14	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
15	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
16	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
17	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
18	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
19	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
20	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
21	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
22	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
23	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
24	22/06/18 15:05	Front View Right	 Load JPG	<input checked="" type="checkbox"/>
25	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
26	22/06/18 15:05	General View	 Load JPG	<input checked="" type="checkbox"/>
27	22/06/18 15:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	22/06/18 15:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	22/06/18 15:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	22/06/18 15:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	22/06/18 15:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	22/06/18 15:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	22/06/18 15:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	22/06/18 15:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	22/06/18 15:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	22/06/18 15:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	22/06/18 15:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/06/18 15:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	22/06/18 15:08	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	22/06/18 15:12	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	22/06/18 16:52	Insured GIA Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD18010391/NZ4D3E2

Date: 25/06/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00002858
Claimant Vehicle No : SDN89Z **Insured Vehicle No :** SJG8855S
 Date of Loss: 04/06/2018 Nature of Claim: TP Claim No: 1201800006914

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDN89Z**
 Make & Model: AUDI A3, 1.4 TFSI (A) Engine No: CMB143257
 Reg. Date: 25/11/2013 (Man. Year: 2013) Chassis No: WAUZZZ8V7DA075440
 Colour: White Odometer: 17506 km
 Engine Capacity: 1395 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
 Front Left Side: Bridgestone 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/06/2018
 Date Inspected: 08/06/2018 Inspected At: Target Auto Pte Ltd (Autocity)
 160 SIN MING DRIVE, #07-17 SIN MING
 AUTOCITY
 Singapore 575722
 Estimated Period of Repair: 4.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$13,000.00 - \$15,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jun 2018)
Parts:	143	AUDI A3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDN89Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >