

SMRT Accident Vehicle Repair Estimates

QBE
C114

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB21J
 Ref. No : TAX/05/18/2126
 Reg. Date : 18/06/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : ONG SENG WEI
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 28/05/2018 06:55:00 AM
 Accident Reported Date / Time : 28/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 28/05/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096321
 Special Instruction to ARC, if any :
 TOWED \$60/ GBB9643B
 Prepared Date : 28/05/2018 04:09:17 PM



Sebastian.
 30/5/18.
 - Imp Sur Repair.
 - Question Mark Item
 Photo
 - Photo After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U105746515

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	338.00	0.00
Total Spray Painting Charges :	558.00	0.00
Total Material Charges :	1,386.75	1,386.75
Other Charges :	224.00	0.00
TOTAL :	2,506.75	0.00
Lum Sum Total :	2,500.00	0.00
No. of Repair Days :	3.00	0.00
Prepared / Adjusted By :		2 days
Arc / Surveyor Sign Off Date :	28/05/2018 06:29:47 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/05/2018 06:27:45 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 5/28/2018 6:29:42 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	338.00	0.00 200
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00 X
Total Spray Painting & Panel Beating	558.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	84.00	0.00 * Receipt
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	224.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No ☒ (plan)
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace	No ☐
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace	No ☐
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace	No ☒
81511-47050			LENS & BODY, FR TURN RH	1	511.80	10.00	460.62	Replace	Replace	No ☐
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace	No ☐
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Replace	No ☐
TOTAL MATERIALS								1,733.45	1,733.44	
TOTAL MATERIALS(Discounted)								1,386.75	1,386.75	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									