

ASS. REC. BY:

REF: CS3/LPC18004212/R/9/21

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Gerald Poh

of LPC

Date/Time: 07062018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV 7 CS

To Inspect Vehicle No: SLW 4116K

Insured: YP 5070J

at Workshop m/s Z-One Automotive

Tel: 97 55 2115

of 7 Swan Lee Street # 01-27/47

Policy No:

Claim No: 17118/18/VCOO/020423

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 22/2/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:23am 5/3/18

Person Contacted: Yvonne

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLW 4116K - X
	YP 5070J - X
	base metal removal - 02/4/18 - XGD
	body paint - 04/4/18 - Rasul
06/4/18	submit RFI

06/6/18 submit final invoice \$7696.24, 3 days (net \$460, 302)

[Signature]
8/6/2018

RECEIVED 08 JUN 2018

No bill /
By email first
urgent.

John

REF:

C
4430H

Year: **2018**

Estimated Cost: **SLW 4116 K**

OD / TP / WS / TP RES / OO RES / EVA / BV / MV

Foreign Vehicle No: **SLW 4116 K**

At Work / Shop No: **Z-one**

Autobody # **#01-5207**

Completed **Complete**

Policy No:

Class No:

Date Insured: Error:

Claim's Receipt:

Make of Veh:

Policy Condition:

Remarks: The veh had commenced its repair at the time of inspection.

INS	OK

Date of Market Value:

IBAC Accident Report: Consistent? Yes or No

OD / PR / Sew: Consistent? Yes or No

Est. Repair: days: Res: Yes or No

Est. Cost: %: 3 Val: Yes or No

UA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Date / Time: Action / Instruction:

Year: **2018** Make: **MAZDA**

Model: **HONDA FREED 1.5 GA 1496**

Color: **BLUE**

Cap No: **007386**

Engine: **GB71043519**

Gen Cond: **Good**

Electrical: **Good**

Brake: **Good**

Mod: **Nil**

Tyre Size: **F: 185/65R15**

R: **185/65R15**

BS / OUV / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO

Front: **6** mm R/Bol: **6** mm

L/Bol: **6** mm

D.O.A: **22/02/18** D.O.T: **21/03/18 11:45 AM**

Survey held at: **Z-one**

Des. of Damages: **Front / Rear / O/S / N/S / U/C / Rooftop**

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 05 APR 2018

Final Report: Profit Report:

Final Report: Days Of Repair: _____

Resurvey No. of Trip: _____


Add Fee: Call-in Fee: _____

Balance: _____

Other: _____

Repair Center: **PR1**

Repair Start / End: _____



LONPAC INSURANCE BHD

(S98FC5635C)

Our Ref : 17/18/18/VC00/020423

Your Ref : CS3/LPC18004212/R1qd3s2

5 June 2018

M/s LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933

Dear Sirs/Madam

PAPER SURVEY OF SLW4116K

We refer to the above matter.

We enclose the following documents :-

- a) Survey report & photos of SLW4116K
- b) GIA report of SLW5070J
- c) GIA report & photos of YP5070J

Kindly study the documents and let us have your opinion on the adjusted repair cost within the next 10 days.

Yours faithfully

GERALD POH
SENIOR EXECUTIVE
(CLAIMS)
Email : mt_claim@lonpac.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/02/2018 14:40
Date Of Accident	22/02/2018 08:50
Exact Location Of Accident	TAMPINES AVE 10 EXPRESSWAY FILTER MERGING LANE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW4116K
Insured/Policyholder	
Name Of Registered Owner	OCEAN CARZ LEASING PTE LTD
Co Reg No	20174430H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91285353
Vehicle Particulars	
Manufacturer	HONDA
Model	FREED HYBRID 1.5G AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094397499-01
Cover Note Number	
Driver	
Name of Driver	SIM KHENG HIANG (SHEN QINGXIAN)
NRIC No	S7624037Z
Date Of Birth	10/08/1976
Occupation	OUTDOOR
Date Of Driving Pass	01/04/2005
Driving Experience	12 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90910148
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 148 RIVERVALE CRESCENT
#15-42
Postcode 540148
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 60 HOUGANG AVE 9 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-4890999 - FAX NO: 63128989
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT : T/20180222/2199.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: WITH Z-ONE AUTOMOTIVE
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP5070J
Vehicle Make/Model/Colour LORRY
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repeal policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in the accident (all insurer(s) who have insured vehicle(s) involved in the accident shall be collectively referred to as the "Insurers"), the Insurers, law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes (i) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims, including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages; and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers, law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may (can) be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan

Vehicle A : SLW4116K

Vehicle B : YP 5070J


Tampines Expressway Filter Merging Lane

Sketch Plan #2

Describe Circumstances of the Accident

2 refer to the Police Report T/2018 0222 /2199 2

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.

Please State

Claim Own Policy Claim Third Party Claim OD At other workshop Reporting only

Declaration

I/We declare the foregoing to be true to the best of my/our knowledge



X

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Police Report



**SINGAPORE
POLICE FORCE**



T/20180222/2199

Police Station Of Origin
Hougang N P C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No 1800-4890999

1 of 3

Report No: T/20180222/2199

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 22/02/2018 22 58	Vide Report No	Station Diary No 170
---	----------------	-------------------------

Informant's Particulars

Name of Informant SIM KHENG HIANG		Address APT BLK 148 RIVERVALE CRESCENT #15-42 SINGAPORE 540148	
ID Type / ID No NRIC NO / S7624037Z		Contact No. Home/Office Mobile 90910148	
Nationality SINGAPORE CITIZEN		Email	
Sex Male	Age 41	Date of Birth 10/08/1976	Type of Informant Driver
Race Chinese		Language	Institution / School Name
Occupation ASSISTANT ENGINEER		Driving Licence Information Class 3	Date of Expiry

General Information of the Accident

Type of Accident Non-Injury Hit and Run	Drink Drive No	Date/Time of Accident 22/02/2018 08 50	Type of Location Gradient
Location Along Road 1 Traveling Toward Road 2 TAMPINES AVENUE 10 TAMPINES EXPRESSWAY FILTER MERGING LANE			
Weather Clear	Road Surface Dry	Road Speed Limit	
Traffic Flow One Way	Traffic Control Not Controlled	Traffic Volume Heavy	
Type of Collision Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SLW4116K	Car	HONDA	FREED HYBRID 1.5G AUTO	Blue	Slightly Damaged	0
YP5070J	Lorry			Silver		0

Details of Person Involved

Any Pedestrian Involved: No	
No of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report



**SINGAPORE
POLICE FORCE**



T/20180222/2199

Police Station Of Origin
Hougang N P C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No 1800-4890999

2 of 3

Report No T/20180222/2199

CONTINUATION OF REPORT

Driver			
Name	SIM KHENG HIANG		ID No. S7624037Z
Related Vehicle	SLW4116K (Car)		Contact No 90910148
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class 3 Date of Expiry NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

Brief Details.

On 22/02/2018 at about 0851hrs. I was travelling in my vehicle bearing registration no SLW4116K along Tampines Avenue 10 on the outer most right lane as I intended to turn right towards the Tampines Expressway TP. Subsequently, after turning and entering the up slope of the expressway, there was a lorry bearing registration no YP5070J that was on my left.

Thereafter, when the road was merging, the said lorry rear right side portion collided onto my left side mirror and I slowed down. The said lorry then continued moving forward and did not stop. At that juncture, I was not able to trace the lorry and continued my journey.

I then made check after exiting the expressway and discovered that left side mirror was dislodged from my vehicle and broken. Additionally, there were some scratches on the left front portion of my vehicle. I wish to add that I have an on-board camera (facing the front) which recorded the accident and the lorry has "GS Logistic Services" on the vehicle body.

I wish to add that this is the first time I came across the said lorry and that I have the footages for investigation purpose. I wish to further add that there are no government property.

Police Report



SINGAPORE
POLICE FORCE



T/20180222/2199

Police Station Of Origin
Hougang N P C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No. 1800-4890999

3 of 3

Report No. T/20180222/2199

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

IMPORTANT Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report F / Sgt 3 SAIFUL ARIFFIN BIN BUANG	Signature Of Informant
Signature Of Interpreter Not applicable	Date/Time 22/02/2018 22:58
Officer In Charge Of Case TP / HRT / SI ABDUL KAREEM BIN ABDUL HAGUE Contact No. 65476079	Classification Of Case

Authentication Stamp
NP168

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/03/2018 13:51
Date Of Accident	22/02/2018 10:00
Exact Location Of Accident	TAMPINES AVE 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP5070J
Insured/Policyholder	
Name Of Registered Owner	GS LOGISTIC SERVICE
Co Reg No	-
Email Address	GSLOG@SINGNET.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64812550

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FM65M
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z/17/VC00/01010
Cover Note Number	

Driver

Name of Driver	THAM MAU CHOON
NRIC No	S7017432D
Date Of Birth	28/05/1970
Occupation	OUTDOOR
Date Of Driving Pass	11/10/1993
Driving Experience	24 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97477420
Fax Number	
Contact Number	
Email Address	GSLOG@SINGNET.COM.SG

Address BLK 972 HOUGANG ST 91 #07-192 S530792

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident NO COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED REPORT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLW4116K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver NA

NRIC/Passport Number

Contact Number NA

Address NA

Postcode NA

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time: 03/03/18
12:00



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


LONPAC INSURANCE BHD (S98FC5635C)

(Incorporated in Malaysia)

Singapore Office: 300, Beach Road #17-04/07, The Concourse, Singapore 189555.

Tel: (65) 6250 7388 Fax: (65) 6296 3767 Website: www.lonpac.com.sg

GST Reg No.: F0-0005635-C

MZ300

CERTIFICATE OF INSURANCE
Insured's Copy

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION ACT (CAP 189) REPUBLIC OF SINGAPORE.
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1960 (REPUBLIC OF SINGAPORE).
 ROAD TRANSPORT ACT 1987 (MALAYSIA).
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA).

Certificate No. : Z/17/vc00/101010-001

Type of Cover : COMPREHENSIVE

1. Index Mark and Vehicle Registration Number

 MITSUBISHI FM65FM2RDEB
 - YP 5070J

2. Name of Policy Holder

GS LOGISTIC SERVICES

3. Effective date of the Commencement of Insurance for the purpose of the Act.

01/12/2017

4. Date of Expiry of the Insurance

30/11/2018

5. Persons or Classes of Persons entitled to drive.

(A) THE POLICYHOLDER. (B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS/THEIR PERMISSION.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use

USE IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS. USE FOR THE CARRIAGE OF PASSENGERS (OTHER THAN FOR HIRE OR REWARD) IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS. USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES. THE POLICY DOES NOT COVER:- USE FOR HIRE OR REWARD OR FOR RACING, PACEMAKING, RELIABILITY TRIAL OR SPEED TESTING. USE WHILST DRAWING A TRAILER EXCEPT THE TOWING OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.

Excess

 : S\$2000.00 (SECTION 1) ALL EMPLOYEES
 S\$4000.00 (SECTION 1) NON EMPLOYEES
 S\$2000.00 (EACH FOR SECTION 1 & 2) ADDITIONAL EXCESS FOR ELDERLY OR YOUNG &/OR INEXPERIENCED DRIVERS
 S\$100.00 WINDSCREEN EXCESS

Condition

: ACCIDENT REPAIRS AT LONPAC'S AUTHORISED WORKSHOPS

* Limitations rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore are not included under heading.

I/We hereby certify that this covering Note is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and Motor Vehicles (Third-Party Risks and Compensation) Act (Cap 189) Republic of Singapore.

H.P. Owner : GOLDBELL FINANCIAL SERVICES PTE LTD

CHIEF EXECUTIVE
 (Singapore Branch)

 User ID : ambika / hazechen
 Date issued : 29-11-2017

17VC00Feb v-5.7.0 Z10120 - VM1

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7017432D



THAM MAU CHOON

覃茂春

CHINESE

28-05-1970 M

SINGAPORE

S7017432D

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: S7017432D
Name: THAM MAU CHOON

Birth Date: 28 May 1970
Issue Date: 08 Sep 2003

000810135C



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: [62502115](tel:62502115)/[66342112](tel:66342112) Fax: [66342122](tel:66342122)

Email: service@z-one.com.sg, enquiry@z-one.com.sg

AUTOMOTIVE ◉ PERFORMANCE Company Registration No. 201118055N

TAX INVOICE

Ocean Carz Leasing Pte Ltd
1 Bukit Batok Crescent #04-16 Wcega Plaza
Singapore 658064

Contact : 91285353 90910148

Date : 26/04/2018

Date in : 02/04/2018

Vehicle Num. : SLW4116K

Make/Model : Honda Freed Hybrid 1.5G Auto-2017

Chassis/Eng# : GB71043519/LEB5572437

Accident Date : 22/02/2018

Claim No : C101785

Reference :

Policy No. : 5094397499-01 (08/02/2019)

PART BY PART REPAIR
AS PER SURVEYOR REPORT
DATED 17/04/2018
BY Pal's Appraiser Pte Ltd

Amount \$

1,556.24

E. & O.E. Sub \$: 1,556.24

Add GST (7%) \$: 108.94

Total Amount \$: 1,665.18



Z-ONE AUTOMOTIVE PTE LTD

Z-One Automotive Pte Ltd

1 Kaki Bukit Ave 6, Blk D #01-87 AutoBay@Kaki Bukit Singapore 417883

Tel: 66342112 Fax: 66342122

Vehicle No: SLW 4116 K Date: 17-Apr-18
Model: Honda Freed
Name: Ocean Carz Leasing Pte Ltd
Address: c/o No.1 Kaki Bukit Ave 6, Blk D
#01-87 AutoBay@Kaki Bukit
Singapore 417883
Accident date: 22-Feb-18

Part By Part repair of SLW 4116 K

Qty	Descriptions	Amount (S\$)
-----	--------------	--------------

List Items

1	Front n/s door pillar	
1	Front n/s door 1/4 glass	
1	Front n/s door side mirror	
		\$ 770.30
		\$ 770.30
		Less 20.0% \$ 154.06
		\$ 616.24

S/No.	Labour	
1	To check wiring.	\$ 30.00
2	Panel beating	\$ 440.00
3	Spray painting	\$ 440.00
4	To underseal	\$ 30.00
		\$ 940.00

Grand - total : \$ 1,556.24

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883

Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Invoice No 03-18031/AY

Billing Name & Address

Ocean Carz Leasing Pte Ltd
c/o No.1 Kaki Bukit Ave 6, Blk D
#01-87 AutoBay@Kaki Bukit
Singapore 417883

Date 17 Apr 2018

Vehicle No : SLW 4116 K

Model : Honda Freed

Item	Descriptions	Amount S\$
1	Date of inspection : <u>21 Mar 2018</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>28</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 508.00</u>
	SDLS : FIVE HUNDRED AND EIGHT ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883

Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 03-18031/AY / 2018

Date of Report : 17 Apr 2018

Ocean Carz Leasing Pte Ltd
c/o No.1 Kaki Bukit Ave 6, Blk D
#01-87 AutoBay@Kaki Bukit
Singapore 417883

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 22 Feb 2018

As per your instruction dated 21 Mar 2018 with regard to the above matter. We have carried out a physical inspection on the said vehicle SLW 4116 K. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SLW 4116 K
Model : Honda Freed
Year / Capacity : 2018/1496
Chassis No : GB7-1043519
Engine No : LEB5572437
Mileage : 7386
Colour : Blue

2. TYRES CONDITION

		<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	: 185/65 R15	Dunlop	6.00	mm	Normal
REAR	O/S	: 185/65 R15	Dunlop	6.00	mm	Normal
FRONT	N/S	: 185/65 R15	Dunlop	6.00	mm	Normal
REAR	N/S	: 185/65 R15	Dunlop	6.00	mm	Normal

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the n/s portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Z-One Automotive Pte Ltd
No.1 Kaki Bukit Ave 6, Blk D
#01-87 AutoBay@Kaki Bukit
Singapore 417883

5. Estimated normal period of repair : 4 working days to complete.

6. Enclosed number of photograph : 28 copies.

7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a "**Without Prejudice**" basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SLW 4116 K**
 Report No: **TP/ 03-18031/AY / 2018**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
	<u>List Items</u>			
1	Front n/s door pillar	Repair	\$ 996.90	\$
1	Front n/s door 1/4 glass	Repair	\$ 403.70	\$
1	Front n/s door side mirror	Damage	\$ 770.30	\$ 770.30
			<u>\$ 2170.90</u>	<u>\$ 770.30</u>
	Discount	20.0%	\$ 434.18	\$ 154.06
			<u>\$ 1736.72</u>	<u>\$ 616.24</u>

Spare Parts Total \$ 1736.72 \$ 616.24

Vehicle No: **SLW 4116 K**
 Report No: **TP/ 03-18031/AY / 2018**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 1736.72	\$ 616.24
1	To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts.	\$ 50.00	\$ 30.00 ✓
2	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 700.00	\$ 440.00 250
3	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 700.00	\$ 440.00 200
4	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 100.00	\$ 30.00 X
Total		<u>\$ 3286.72</u>	<u>\$ 1556.24</u>

Recommended PART BY PART Repair Amount of: \$ **1556.24**

SDLS: ONE THOUSAND FIVE HUNDRED FIFTY SIX AND CENTS TWENTY FOUR ONLY



 Qualified Appraiser

616.24
 480.00

 1096.24

 3 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS3/LPC18004212/R1qbs2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 08-06-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 5070J	Veh. Inspected	SLW 4116K
Policy No.	Z/17/VC00/01010	Coverage (\$)	0.00
Claim No.	17/18/18/VC00/020423	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	07/06/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA FREED 1.5 G A	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GB71043519	Colour	BLUE
Odometer	007386	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65R15	DUNLOP	6 mm
L/H Front Tyre	185/65R15	DUNLOP	6 mm
R/H Rear Tyre	185/65R15	DUNLOP	6 mm
L/H Rear Tyre	185/65R15	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/02/2018	Inspection Date	21/03/2018
Survey held at	Z-ONE AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVE 6, BLK C, #01-52 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 4116K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT N/S DOOR PILLAR	TO REPAIR SEE LABOUR	996.90	-
1	FRONT N/S DOOR 1/4 GLASS	TO REPAIR SEE LABOUR	403.70	-
1	FRONT N/S DOOR SIDE MRROR LESS 20% DISCOUNT	DAMAGED	770.30 -434.18	770.30 -154.06
			1,736.72	616.24
LABOUR				
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING, HARNESS WIRES, SOCKETS, REPLACE DAMAGED PARTS.		50.00	30.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT N/S DOOR PILLAR AND FRONT N/S DOOR 1/4 GLASS.		700.00	250.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		700.00	200.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.	NOT NECESSARY	100.00	-
			1,550.00	480.00
GRAND TOTAL			3,286.72	1,096.24
RECOMMENDED COST OF REPAIRS				1,096.24

Report Ref No. CS3/LPC18004212/R1qbs2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.