

VEHICLE CONDITION REPORT FORM / JOB RECORD

Allianz 

Worldwide Partners

Date: 3/6/18 Time: 15:45

Customer Name:

Technician Name: D. 19

Customer Telephone:

Reg. No: SJW 1328K Job No:

Make/Model: BMW 1 520i

Odometer Reading (Customer Vehicle):

Location: Espinardo drive

KM Travelled by Assistance Vehicle: (1 way)

Time on Scene: 15:40

Fault Reported: Acc

Time Job Completed:

Fault Found:

Repaired at Breakdown Scene: Y/N

How was vehicle repaired?

VIN No:

Hubcaps Y/N

Spare Wheel Y/N

Tools Y/N

Audio System Y/N

Keys + Remote Y/N

Aerial Y/N

Cashcard (RM) Y/N

Fuel E ☐ F ☐

Interior Condition :

Front Seats

Rear Seats

Floor Covering

Headlining




Day/Night

Wet/Dry

Clean/Soiled

Please circle the above as appropriate

Place X on damaged area for scratch and Y for dent





Delivery to Dealership / Date and Time:

Vehicle received in the above condition YES/NO

If not stated as above specify difference:

CUSTOMER DECLARATION

1. I am entitled to the service requested. In the event of this subsequently not being the case I shall be responsible for the cost of any assistance provided.
2. I accept that any roadside repairs will be of a temporary nature and that advice of a franchised dealer should be sought by me as soon as possible.
3. In the case of forced entry, I confirm that I specifically requested that the operator forcefully enter the vehicle and that all damages occasioned thereby is and shall be my sole responsibility.
4. I accept that any removable items left in the vehicle will not be the responsibility of the emergency service or their agents.

Customers Signature (white copy)		Dealer/Workshop Signature (pink copy)		Operators Signature (yellow copy)	
--	---	---	--	---	---



SINGAPORE POLICE FORCE
ACKNOWLEDGEMENT SLIP

Ref: Report No: # A/20180603/0117

I, Sgt Norhafidah S92081784
(Recipient's Name, NRIC or Passport No. / Rank and No.)

of Trafic Police HQ
(Address / Police Station / NPC / NPP)

hereby acknowledge receipt of the below mentioned items of:

- 1 one SAN DISK 32GB MICROSD Card (S/N 6467DL FRG0M2)
- 2 _____
- 3 _____
- 4 _____
- 5 _____
- 6 _____
- 7 _____
- 8 _____
- 9 _____
- 10 _____

from Teng Kemin S7000560C
(Name, NRIC or Passport No. / Rank and No.)

of Blk 90 Tanglin Halt Rd, #31-328, S (141090)
(Address / Police Station / NPC / NPP)

on 3 Jun 2018 at 1600H
(Date) (Time)

Witnessed by / * Handed over by:
(* Delete if applicable)

[Signature]
(Signature)

(Name, NRIC or Passport No. / Rank and No.)

Received by:

[Signature]
(Signature)
S92081784 PS 7120202 Norhafidah
(Name, NRIC or Passport No. / Rank and No.)

Other Remarks: IO Rizwan Tel: 65476185



SINGAPORE POLICE FORCE



T/20180603/2092

1 of 4

Police Station Of Origin:
Alexandra NPP
46 Tanglin Halt Road #01-328 SINGAPORE
140462
Tel No: 1800-4739999

Report No. T/20180603/2092

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/06/2018 20:23	Vide Report No.: A/20180603/0117	Station Diary No.: 41
Informant's Particulars		
Name of Informant: TENG KERWIN	Address: APT BLK 90 TANGLIN HALT ROAD #31-328 SINGAPORE 141090	
ID Type / ID No.: NRIC NO / S7000560C	Contact No.: Home/Office:	Mobile: 81189331
Nationality: SINGAPORE CITIZEN	Email:	
Sex: Male	Age: 48	Date of Birth: 01/01/1970
Type of Informant: Driver		
Race: Chinese	Language: English	Institution / School Name:
Occupation: CONSULTANT	Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 03/06/2018 14:40	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 RAFFLES AVENUE STAMFORD ROAD Junction of Raffles Avenue/ Stamford Road				
Weather: Clear	Road Surface: Dry		Road Speed Limit:	
Traffic Flow: Two Way	Traffic Control: Traffic Light - Working		Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJE9545R	Car	HONDA	Vezel	Silver	Seriously Damaged	0
SLW1328K	Car	BMW	520i LED NAV	White	Seriously Damaged	2

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLW1328K	AXA INSURANCE SINGAPORE PTE LTD	GA313484	16/01/2018	12/12/2019



SINGAPORE POLICE FORCE



T/20180603/2092

2 of 4

Police Station Of Origin:
Alexandra NPP
46 Tanglin Halt Road #01-328 SINGAPORE
140462
Tel No: 1800-4739999

Report No. T/20180603/2092

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	TENG RYAN	ID No.	T0220726A
Related Vehicle	SLW1328K (Car)	Contact No.	81189331
Hospital/Clinic	GLENEAGLES HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	03/06/2018	Date Discharge	03/06/2018
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TENG KERWIN	ID No.	S7000560C
Related Vehicle	SLW1328K (Car)	Contact No.	81189331
Hospital/Clinic	GLENEAGLES HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	03/06/2018	Date Discharge	03/06/2018
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	ANGELINE TOH HWEE CHEN	ID No.	S7411973E
Related Vehicle	SLW1328K (Car)	Contact No.	97995552
Hospital/Clinic	GLENEAGLES HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	03/06/2018	Date Discharge	03/06/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 03/06/18 at about 1435hrs, I was travelling in my vehicle together with my wife and son SLW1328K along junction of Raffles Avenue and Stamford Road. I was at the junction waiting to make a turn to Stamford Road, there were 5 lanes for the opposite traffic and the extreme left lane was to only for vehicles to turn left, I checked the traffic to be clear however there was one vehicle bearing SJE9545R on the opposite extreme right lane turning left.

I proceeded to make the right turn and suddenly, the vehicle move straight instead of turning left and as a result the said vehicle collided to the front left of my vehicle. After the accident, both parties got down and



**SINGAPORE
POLICE FORCE**



T/20180603/2092

Police Station Of Origin:
Alexandra NPP
46 Tanglin Halt Road #01-328 SINGAPORE
140462
Tel No: 1800-4739999

3 of 4

Report No. T/20180603/2092

CONTINUATION OF REPORT

access damages to our vehicle. I called for ambulance.

Ambulance arrived and conveyed the driver of the said vehicle to hospital. Subsequently TP arrived and advised me to lodge a report regarding the accident, ref A/20180603/0117, IO RIZWAN, 65476185. I wish to state that I brought my family to Gleneagles Hospital and my wife was given 3 days of MC. I also wish to further state that I did not exchange particulars with the said driver.



**SINGAPORE
POLICE FORCE**



T/20180603/2092

4 of 4

Report No. T/20180603/2092

Police Station Of Origin:

Alexandra NPP

46 Tanglin Halt Road #01-328 SINGAPORE

140462

Tel No: 1800-4739999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 2 DYLAN CHIA CHOON KIAT

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

03/06/2018 20:23

Officer In Charge Of Case:

TP / GIT /

SI THABAGESH JEYATHESH

Contact No.: 65476232

Classification Of Case:

Authentication Stamp
NP168

